

Directorate General Technical Airworthiness

AUDIT FINDINGS (2 of 5)

NO.	FINDINGS	REGULATION	CATEGORY
<b>NO.</b> 2 of 5	Ref:  1. MMEA/CAMO/AMP/AS365N3 Issue 1 Revision 0 dated 21 June 23, 6.1.19 – 1 Year Inspection (Item No.1).  2. Installation of polycon wireless communication system on AS365N3 Series dated July 2008, ER 1310117 Rev. A.  3. Installation of Searchlight SX-16 with Infra-Red In-Flight Changeover Option on Eurocopter AS365N3 dated September 2008, ER 1310133 Rev B.  4. MMEA/CAMO/AMP/AS365N3 Issue 1 Revision 0 dated 21 June 23, Instruction for Continued Airworthiness (ICA) for MOD ER1310133.  The AMP shall contain details of all maintenance to be carried out. The Audit found as follows:  a. The reference for the Polycon Wireless Communication System inspection task is incorrect as stated in AMP as per Ref#1. The correct reference is ER 1310117 Rev. A, as per Ref#2.	REGULATION  M.A.302(e) Aircraft Maintenance Programme (AMP)  The AMP shall contain details, including frequency, of all maintenance to be carried out, including any specific tasks linked to the type and the specificity of operations.	Level 2
	b. There is requirement for inspection with several interval following the installation of the Searchlight SX-16 on the aircraft, as per Ref#3. However, according to Ref#4, the interval details for all maintenance activities have not been included in the AMP.		
	Thus, contrary with M.A.302(e).		



## Directorate General Technical Airworthiness

REF #1

**REF #2** 

**REF #3** 

**REF #4** 

