

## GALAXY AEROSPACE (M) SDN. BHD. [1040282-D]

Salte 11-14: Pertigopher Centre, Malaysia International Assospace Centre, Sutten Abdul Asia Shari Airpon, 47209 Subang, Selanger, Malaysia Tet. +603 7734 7276 | Fax. +603 7734 7520



CLIENT/OWNER: Royal Malaysian Navy (Super SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 1857-010 Lynx) AIRCRAFT 431 REFER WORKPACK WORK/INSP/DESC: ZONAL INSPECTION AIRCRAFT TYPE: SUPERLYNX MK100 P4N 008 REFER WORKPACK WORKPACK REF: #1 ENGINE: M501-3-1857 REGISTRATION: M501-3 AJL REF NO BASE/FACILITY: LUMUT #2 ENGINE: P4N 006 REFER WORKPACK NOT APPLICABLE DATE IN: REFER OUT: REFER WORKPACK SHEET: 2 NG/N1 NF/N2 Reason for raising: ZONAL INSPECTION TO BE CARRIED OUT IN ACCORDANCE WITH CIETP ISSUE 27.00.00 DATED Raised by and date: Other requirements/information: NORHUDA JUNE 2023 ZONAL INSPECTION TASKS - TASK 9 05/01/2024 Item Description Technician \* Eng. CRS Date 2. ZONE 3 SUB ZONE B TO DO AN INTENSIVE VISUAL INSPECTION BY USING MAGNIFYING GLASS OF: (1) RIGHT CABIN DOORS (2) RIGHT CABIN DOOR LATCH MECHANISM AND PANELS Ol (3) RIGHT CABIN DOOR TRANSPARENT PANELS (4)JETTISON MECHANISM AND PANELS FOR THE CABIN **WNDOWS** (5)UPPER ATTACHMENT BRACKETS OF THE CABIN DOORS (6) WINDOW AIR VENTS (MOD L1985) REFERENCE: CIETP LD-A-12-21-09-00A-281A-A MAN: 2 HOURS: 10.0 TOTAL MAN HOURS:20.0 CARRIED OUT INTENSIVE VISUAL INSPECTION OF RIGHT CABIN DOORS, RIGHT CABIN DOORS LATCH MECHANISM AND PANELS, RIGHT CABIN DOOR TRANSPARENT PANELS, JETTISON MECHANISM AND PANELS FOR THE CABIN WINDOWS, UPPER ATTACHMENT BRACKETS OF THE CABIN DOORS, WINDOW AIR VENTS (MOD L1985) OF ZONE 3 SUB ZONE B BY USING MAGNIFYING GLASS I.A.W: LD-A-12-21-09-00A-281-A (CHAPTER 12, SECTION 21, SUBJECT 09) CIETP ISSUE 27,00.00 DATED JUNE 2023. EMERGENCY RELEASE PULL DOWN' MARKING FOUND FADED AT STBD CABIN DOOR. REFER UMC-M501-3-24-045 AND UMC-M501-3-24-046 FOR RECTIFICATION. 1) PULL OFF LOAD TEST TEST SET: SPRING BALANCE (MODEL 25) SERIAL NUMBER:M501-03 CALIBRATION DUE DATE: 28-07-2024 PULL OFF LOAD FIGURE: 5.4 KG 2) PIP PIN MEASURE: PIP PIN FOUND BROKEN, ALL PIP PINS REPLACED NEW 3) SAFETY CATCH & THE DOOR CLEARANCE MEASURE:6mm MI/S:OSMAN MI/S:JAFRI DATE: 17/01/2024 The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication V (CIETP) and CTS800-4N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.