

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

## SERVICE BULLETIN

## № 139-601

**DATE:** December 21, 2021 **REV.:** A - May 11, 2022

## TITLE

## ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT

## **REVISION LOG**

Helicopters that have complied with previous issue of this Service Bulletin do not need any additional action.

Revision A is issued to:

- Define actions to be performed if "Ordine di Lavoro" is not visible;
- Improve reinforcements installation procedure.

If logistic P/N 139-601L1 has already been provided, new parts shall be ordered, in accordance with paragraph A – REQUIRED MATERIALS, in order to apply Rev. A of this SB.



## 1. PLANNING INFORMATION

## A. EFFECTIVITY

#### <u>NOTE</u>

If support searchlight assy P/N and/or related "Ordine di Lavoro" are not visible, contact Product Support Engineering (engineering.support.lhd@leonardo.com) to receive information on required actions.

Part I: Support searchlight assy P/N 3G3340A01133 installed on AW139 helicopters up to S/N 31939 and S/N 41576, equipped with Trakka A800 searchlight kits P/N 4G3340F02411, P/N 4G3340F02412, P/N 4G3340F02413, P/N 4G3340F02414 or Trakka searchlight kit P/N 4G3340F03011.

Support searchlight assy P/N3G3340A01133 kept in stock.

Support searchlight assy P/N 3G3340A01133 installed on AW139 helicopters that have installed the support searchlight assy after the issue of this Service Bulletin.

Part II: Support searchlight assy P/N 3G3340A01133 having an "Ordine di Lavoro" indicated in Table 1.

#### **NOTE**

The "Ordine di Lavoro" is marked inside the support searchlight assy (refer to Figure 1 Detail A).

426241	428797/1	429250/2	432080/3	434608	438918
426241/1	428797/2	429250/3	432080/4	434608/1	438918/1
426241/2	428797/3	429250/4	432080/5	434609	438918/2
426241/3	428797/4	429755	432156	434609/1	439285
426242	428953	429755/1	432156/1	434610	439285/1
426242/1	428953/1	429755/2	432156/2	434610/1	439285/2
427057	428953/2	429755/3	434349	435306	439924/1
427057/1	429250	432080	434607	436024	439925
428797	429250/1	432080/1	434607/3	436941	439925/1

Table 1: Affected support searchlight assy – Ordine di Lavoro



## **B. COMPLIANCE**

#### <u>Part I</u>

Within and not later than 100 flight hours or 3 months whichever occurs first after the issue of Rev./ of this Service Bulletin

Before the first installation for parts kept in stock.

#### <u>Part II</u>

Within and not later than 200 flight hours or 6 months whichever occurs first after the issue of Rev./ of this Service Bulletin

## **C. CONCURRENT REQUIREMENTS**

N.A.

## D. REASON

This Service Bulletin is issued in order to prescribe the inspection and, subsequently, the installation of searchlight support variant P/N3G3340P01011.

## E. DESCRIPTION

As a consequence of a recorded case of damaged Trakka searchlight support, Leonardo Helicopter has developed the searchlight support variant P/N 3G3340P01011 in order to improve the strength of the part.

The variant consists of an AFT reinforcement P/N 3G3340A17952 and a FWD reinforcement P/N 3G3340A17852 to be installed inside the searchlight support assy. Part I of this Service Bulletin provides information to identify affected parts and to perform a visual inspection of the searchlight support in order to find possible damages. Part II provides the instruction to install the searchlight support variant P/N 3G3340P01011.

#### F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives. If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on



the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

## **G. MANPOWER**

To comply with this Service Bulletin the following MMH are deemed necessary:

Part I: approximately two (2) MMH;

Part II: approximately thirty-five (35) MMH;

MMH are based on hands-on time and can change with personnel and facilities available.

## H. WEIGHT AND BALANCE

<u>PART I</u>

N.A.

<u>Part II</u>

WEIGHT (Kg)

0.835

	ARM (mm)	MOMENT (Kgmm)
LONGITUDINAL BALANCE	3591	2998.485
LATERAL BALANCE	-1266	-1057.11

#### I. REFERENCES

#### 1) PUBLICATIONS

Following Data Modules refer to AMP:

DATA	MODULE	DESCRIPTION	<u>PART</u>
DM01	39-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance	I, II
DM02	39-A-06-41-00-00A-010A-A	Access doors and panels - General data	I, II
DM03	39-L-33-49-05-00A-520A-K	Search light mount - Remove procedure	I, II
DM04	39-M-33-49-05-00A-520A-A	Search light mount - Remove procedure	I, II
DM05	39-L-33-49-04-00А-520А-К	Power Conditioning Interface Unit (PCIU) - Remove procedure	I, II
DM06	39-M-33-49-04-00A-520A-A	Power Conditioning Interface Unit (PCIU) - Remove procedure	I, II
DM07	39-L-33-49-04-00A-720A-K	Power Conditioning Interface Unit (PCIU) - Install procedure	I, II



	DATA	MODULE	DESCRIPTION	<u>PART</u>
	DM08	39-M-33-49-04-00A-720A-A	Power Conditioning Interface Unit	I, II
			(PCIU) - Install procedure	
	DM09	39-L-33-49-05-00A-720A-K	Search light mount - Install	I, II
			procedure	
	DM10	39-M-33-49-05-00A-720A-A	Search light mount - Install	I, II
			procedure	
	DM11	39-M-33-49-01-00A-520A-A	Search light assembly - Remove	Ш
			procedure	
	DM12	39-L-33-49-01-02A-520A-K	Dovetail mount (search light	Ш
	DINIE		assembly) - Remove procedure	
	DM13	39-L-33-49-01-00A-520A-K	Search light assembly - Remove	Ш
	DIVITS	39-L-33-49-01-00A-320A-K	• •	
		00 M 00 40 04 04 A 500 A A	procedure	
	DM14	39-M-33-49-01-01A-520A-A	Dovetail mount (search light	II
			assembly) - Remove procedure	
	DM15	39-L-33-49-01-02A-720A-K	Dovetail mount (search light	II
			assembly) - Install procedure	
	DM16	39-L-33-49-01-00A-720A-K	Search light assembly - Install	II
			procedure	
	DM17	39-M-33-49-01-01A-720A-A	Dovetail mount (search light	II
			assembly) - Install procedure	
	DM18	39-M-33-49-01-00A-720A-A	Search light assembly - Install	Ш
			procedure	
-	مالميشمعا	Data Madulaa rafar ta CCDD		

Following Data Modules refer to CSRP:

DATA I	MODULE D	ESCRIPTION	<u>PART</u>
DM19	CSRP-A-51-23-06-00A-663A-DW	et layup impregnation process	Ш
	- 5	Standard repair procedure	
DM20	CSRP-A-51-00-00-00A-013A-DLi	st of consumables for repairs -	II
	N	umeric index	
DM21	CSRP-A-51-21-02-00A-028A-D Pi	rimer application - General	II

#### 2) ACRONYMS & ABBREVIATIONS

AMDI Aircraft Material Data Information AMP **Aircraft Maintenance Publication** DM Data Module DOA **Design Organization Approval** EASA **European Aviation Safety Agency** IPD Illustrated Parts Data LH Leonardo Helicopters MMH Maintenance-Man-Hours



### 3) ANNEX

N.A.

## J. PUBLICATIONS AFFECTED

N.A.

## K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.



## 2. MATERIAL INFORMATION

#### A. REQUIRED MATERIALS

1) PARTS

#### PART I

N.A.

#### PART II

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL	NOTE	LOG P/N
1	3G3340P01011		SEARCHLIGHT SUPPORT VARIANT INSTALLATION	REF		-	-
2	3G3340P01131		SEARCHLIGHT SUPPORT ASSY REWORKED	REF		-	-
3	3G3340A17852		FWD reinforcement	1		-	139-601L1
4	3G3340A17952		AFT reinforcement	1		-	139-601L1
5	A298A04TW03		Rivet	60		-	139-601L1
6	NAS1720C4L5P		Rivet	1		(1)	139-601L1
7	NAS1720C4L4P		Rivet	3		(1)	139-601L1
8	NAS1721C4L4P		Rivet	2		(1)	139-601L1
9	NAS1721C4L3P		Rivet	2		(1)	139-601L1
10	AW001CL003AT-X1		Support	1		-	-
11	A407A3C2P		Anchornut	7		-	-
12	AW008TY-05-36		Washer	12		(4)	-
13	NAS1721C4L4P		Rivet	12		(4)	-

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

#### 2) CONSUMABLES

The following consumable materials, or equivalent, are necessary to accomplish this Service Bulletin:

#	SPEC./LHD CODE NUMBER	DESCRIPTION	Q.TY	NOTE	PART
14	199-05-002 Type I, Class 2	Hysol EA9309NA (C231)	AR	(2)(3)	11
15	MMM-A-132, Type 2, Class II	EA 9309.3NA AERO (C021)	AR	(2)(3)	II
16	A147A2209JB	Rubber	1.4 m	(4)(5)	11
17	199-05-002 Type 2, Class 3,	EA 956 AERO (C193)	AR	(2)	П
18	199-05-107 Type I, Class I	EC1357 (C455)	AR	(2)(4)	П

Refer also to AMDI for the consumable materials required to comply with the AMP DM referenced in the accomplishment instructions.



#### 3) LOGISTIC MATRIX

In order to apply this Service Bulletin, the following Logistic P/N can be ordered in accordance with the applicable notes:

LOGISTIC P/N	Q.TY (PER HELO)	NOTE	PART
 139-601L1	1		II
AW001CL003AT-X1	1		II
AW008TY-05-36	12	(4)	II
NAS1721C4L4P	12	(4)	II

#### NOTE

- (1) It is allowed to use over size rivet in case of ovalized holes.
- (2) Item to be procured as local supply.
- (3) The two adhesives are alternative.
- (4) Item to be ordered only if rubber removal is deemed necessary.
- (5) P/N A147A2209JB1320 is used in procedure. Last four digits indicate the rubber length in mm.

#### **B. SPECIAL TOOLS**

The following special tools, or equivalent, are necessary to accomplish this Service Bulletin:

#	P/N	DESCRIPTION	Q.TY	NOTE	PART
11	Commercial	Indeliblepen	1	(2)	II

Refer also to ITEP for the special tools required to comply with the DM referred to in the accomplishment instructions.

#### SPECIAL TOOLS NOTE

(B1) To be procured as local supply.

#### C. INDUSTRY SUPPORT INFORMATION

Owners/Operators who comply with the instructions of this Service Bulletin no later than the applicable date in the "Compliance" section will be eligible to receive required materials on free of charge basis, except for Consumable Materials and Special Tools. NOTE: Customers who fail to comply with the instructions in this Service Bulletin before the compliance date are not eligible for the aforementioned special policy. Please Issue relevant MMIR form to your Warranty Administration Dpt.

絵 LEONFI

## 3. ACCOMPLISHMENTINSTRUCTIONS

#### **GENERAL NOTES**

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- b) Protect properly all those equipment not removed from area affected by the modification during installation procedure.
- c) Let the adhesive cure at room temperature for at least 24 hours, unless otherwise specified.
- d) All lengths are in mm.

#### <u>PART I</u>

#### **NOTE**

## Perform following steps 1 thru 3 only if the searchlight support assy is installed on the helicopter.

1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A prepare the helicopteron ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.

#### <u>NOTE</u>

The removal of the searchlight assembly and the dovetail mount from the searchlight assy it's not required to perform the visual inspection.

#### <u>NOTE</u>

Refer to AMP DM 39-L-33-49-05-00A-520A-K for kit Trakka A800 searchlight P/N 4G3340F02411, P/N 4G3340F02412. P/N 4G3340F02413 or P/N 4G3340F02414 and to AMP DM 39-L-33-49-05-00A-520A-K for kit Trakka searchlight P/N 4G3340F03011.

- 2. In accordance with AMP DM 39-L-33-49-05-00A-520A-K or with AMP DM 39-M-33-49-05-00A-520A-A, remove the searchlight support assy from the helicopter.
- 3. If necessary, in accordance with AMP DM 39-L-33-49-04-00A-520A-K or with AMP DM



39-M-33-49-04-00A-520A-A remove the power conditioning interface unit from the searchlight support assy.

4. With reference to Figure 1 Detail A, check the "Ordine di Lavoro" marked inside the support searchlight assy.

#### **NOTE**

Perform following step 5 only if the "Ordine di Lavoro" is among those listed in the Table 1 in the Effectivity paragraph. Otherwise skip to step 7.

- 5. Perform a visual inspection of the searchlight support assy and check for any crack or damage in the FWD area of the support.
- In case of finding, record for compliance with Part I of this Service Bulletin on the helicopter logbook and immediately skip to Part II of this Service Bulletin. Otherwise, perform following Step 7.

#### **NOTE**

# Skip following steps 7 and 8 if the searchlight support assy is kept in stock.

 If necessary, in accordance with AMP DM 39-L-33-49-04-00A-720A-K or AMP DM 39-M-33-49-04-00A-720A-A, install the power conditioning interface unit on the searchlight support assy.

#### <u>NOTE</u>

 Refer to AMP DM 39-L-33-49-05-00A-720A-K for kit

 Trakka
 A800
 searchlight
 P/N 4G3340F02411,

 P/N 4G3340F02412,
 P/N 4G3340F02413
 or

 P/N 4G3340F02414
 and
 to
 AMP

 DM
 39-M-33-49-05-00A-720A-A
 for
 kit
 Trakka

 searchlight P/N 4G3340F02413
 or
 AMP
 AMP
 AMP

- 8. In accordance with AMP DM 39-L-33-49-05-00A-720A-K or AMP DM 39-M-33-49-05-00A-720A-A, install the searchlight support assy on the helicopter.
- 9. Return the helicopter to flight configuration, if required, and record for compliance with Part I of this Service Bulletin on the helicopter logbook.
- 10. Send the attached compliance form to the following mail box:

#### engineering.support.lhd@leonardo.com

As an alternative, gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".



#### <u>Part II</u>

#### **NOTE**

## Perform following steps 1 thru 3 only if the searchlight support assy is installed on the helicopter.

1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.

#### <u>NOTE</u>

Perform	following	step	2	if	helicopte	er is	
equipped	with	kit		Tra	ikka	A800	
searchlight P/N 4G3340F02411, P/N 4G3340F02412,							
P/N 4G3340F02413 or P/N 4G3340F02414.							

- 2. Remove the searchlight support assy from the helicopter as described in the following procedure:
  - 2.1 In accordance with AMP DM 39-L-33-49-01-00A-520A-K, remove the search light assembly from the search light support assy 3G3340A01133 from the helicopter.
  - 2.2 In accordance with AMP DM 39-L-33-49-01-02A-520A-K, remove the dovetail mount from the searchlight support assy.
  - 2.3 In accordance with AMP DM 39-L-33-49-05-00A-520A-K, remove the searchlight support assy from the helicopter.
  - 2.4 In accordance with AMP DM 39-L-33-49-04-00A-520A-K, remove the power conditioning interface unit from the searchlight support assy.

#### **NOTE**

Perform following step 3 if helicopter is equipped with kit Trakka searchlight P/N 4G3340F03011.

- 3. Remove the searchlight support assy from the helicopter as described in the following procedure:
  - 3.1 In accordance with AMP DM 39-M-33-49-01-00A-520A-A, remove the search light assembly from the search light support assy.
  - 3.2 In accordance with AMP DM 39-M-33-49-01-01A-520A-A, remove the dovetail mount from the searchlight support assy.
  - 3.3 In accordance with AMP DM 39-M-33-49-05-00A-520A-A, remove the searchlight support assy from the helicopter.
  - 3.4 In accordance with AMP DM 39-M-33-49-04-00A-520A-A remove the power conditioning interface unit from the searchlight support assy.



- 4. With reference to Figures 1 and 2, gain access to the area affected by the installation and perform searchlight support assy rework P/N 3G3340P01131 as described in the following procedure:
  - 4.1 With reference to Figure 1 View B, remove and retain for later reuse the cover P/N 3G3340A03452, n°5 screws P/N MS27039-1-09, n°3 screws P/N MS27039-1-11 and n°8 washers P/N NAS1149C0316R from the searchlight support assy.
  - With reference to Figure 1 View B1, remove and retain for later reuse the cover
     P/N 3G3340A01953, n°4 screws P/N MS27039-1-10 and n°4 washers
     P/N NAS1149C0316R from the searchlight support assy.
  - 4.3 With reference to Figure 1 View B, remove and discard support P/N AW001CL003AT-X1 from the searchlight support assy.
  - 4.4 With reference to Figure 1 View B1, remove n°7 anchor nut P/N A407A3C2P from the searchlight support assy.

#### **NOTE**

Perform following Step 4.5 only if the rubber removal is deemed necessary for make the rework easier.

4.5 With reference to Figure 1 Detail A, remove the rubber P/N A147A2209JB1320.

#### <u>NOTE</u>

Remove the support P/N 3G3340A03551 using a spatula. Pay attention to not damage the parts during the removal. Sand parts surfaces to remove extra material remained on them.

4.6 With reference to Figure 1 View B1, remove and retain for later reuse the support P/N 3G3340A03551 and remove and discard the rivet P/N NAS1720C4L5P, n°3 rivets P/N NAS1720C4L4P and n°2 rivets P/N NAS1721C4L4P from the searchlight support assy.

#### <u>NOTE</u>

If necessary, it is possible to trim the AFT reinforcement to let it fit with the internal part of the support. Make sure to maintain the minimum edge margin of the rivet holes. (Refer to Figure 3 Detail H).

- 4.7 With reference to Figure 2 Section F-F, temporarily locate the AFT reinforcement P/N 3G3340A17952 in its position inside the searchlight support assy.
- 4.8 With reference to Figure 3 Detail H, trim the AFT reinforcement on the gasket side



as indicated.

#### **NOTE**

If one or more AFT reinforcement existing holes do not match with support holes, perform following step 4.9 to align the two parts, otherwise skip to step 4.10.

4.9 Modify AFT reinforcement P/N 3G3340A17952 as described in the following procedure:

#### <u>NOTE</u>

For wet layup procedure refer to CSRP-A-51-23-06-00A-663A-D.

#### <u>NOTE</u>

As valid alternatives it is possible to use carbon fiber CC90 or a carbon fabric dry from Table 1 of CSRP-A-51-00-00-00A-013A-D.

#### **NOTE**

Layers dimensions indicated in figure are indicative. It is possible to slightly decrease dimensions in order not to cover other holes present on the reinforcement.

- 4.9.1 With reference to Figure 3 Section G-G, apply a layer (P1) of Carbon fiber dry fabric HexForce G0801 7 1020 and let it cure.
- 4.9.2 With reference to Figure 3 Section G-G, fill 7 screw holes with EA9309NA.
- 4.9.3 With reference to Figure 3 Section G-G, apply a layer (P2 and P3) of Carbon fiber dry fabric HexForce G0801 7 1020 and let them cure.
- 4.9.4 In accordance with CSRP-A-51-21-02-00A-028A-D, protect repaired area with primer.
- 4.9.5 With reference to Figure 2 Section F-F, countermark and drill n°7 anchor nuts holes Ø 5.74 ÷ 5.86 thru the aft reinforcement.

#### <u>NOTE</u>

If necessary, it is possible to temporary locate the reinforcement on the outer side of the support in order to countermark all the holes. Make sure to achieve the correct alignment.

4.10 With reference to figure 2 Section F-F, countermark 26 rivet holes on the searchlight support assy.



#### **NOTE**

Fill with adhesive all the possible empty spaces under the AFT reinforcement. It is possible to slightly trim the AFT reinforcement to let the central hole coincide with the support hole.

- 4.11 With reference to Figure 1 View B2 and in accordance with dimension shown, install the AFT reinforcement P/N 3G3340A17952 on the searchlight support assy by means of adhesive (C231).
- 4.12 With reference to Figure 1 View B2, fix the AFT reinforcement P/N 3G3340A17952 on the searchlight support assy by means of n°26 rivets P/N A298A04TW03.

#### **NOTE**

If necessary, it is possible to trim the FWD reinforcement to let it fit with the internal part of the support. Make sure to maintain the minimum edge margin of the rivet holes (Refer to Figure 3 Detail H).

- 4.13 With reference to Figure 2 Section E-E, temporarily locate the FWD reinforcement P/N 3G3340A17852 in its position inside the searchlight support assy.
- 4.14 With reference to Figure 3 Detail H, trim the FWD reinforcement on the gasket side as indicated.

#### **NOTE**

If necessary, it is possible to temporarily locate the reinforcement on the outer side of the support in order to countermark all the holes. Make sure to achieve the correct alignment.

- 4.15 With reference to figure 2 Section E-E, countermark 29 rivet holes on the searchlight support assy.
- 4.16 With reference to Figure 2 View C and in accordance with dimension shown, install the FWD reinforcement P/N 3G3340A17852 on the searchlight support assy by means of adhesive (C231).
- 4.17 With reference to Figure 2 View C, fix the FWD reinforcement P/N 3G3340A17852 on the searchlight support assy by means of n°29 rivets P/N A298A04TW03.
- 4.18 With reference to Figure 1 View B1, place and install the support P/N 3G3340A03551 previously removed on the searchlight support assy by means of adhesive (C231).



- 4.19 With reference to Figure 1 View B1, fix the support P/N 3G3340A03551 on the searchlight support assy by means of the rivet P/N NAS1720C4L5P and n°3 rivets P/N NAS1720C4L4P.
- 4.20 With reference to Figure 1 View B1, install n°7 anchor nuts P/N A407A3C2P on the searchlight support assy by means of adhesive EA 9309.3NA AERO.
- 4.21 With reference to Figure 1 View B1, install the cover P/N 3G3340A01953 previously removed on the searchlight support assy by means of n°4 screws P/N MS27039-1-10 and n°4 washers P/N NAS1149C0316R previously removed.
- 4.22 With reference to Figure 1 View B, install support P/N AW001CL003AT-X1 on the searchlight support assy by means of adhesive EA 956 AERO.

#### **NOTE**

## Perform following Step 4.23 only if the rubber has been removed.

4.23 With reference to Figure 1 Detail A, install rubber P/N A147A2209JB1320 on the searchlight support assy by means of adhesive EC1357, n°12 washers P/N AW008TY-05-36, n°12 rivets P/N NAS1721C4L4P.

#### <u>NOTE</u>

## Skip following Steps 5 and 6 if the searchlight support assy is kept in stock.

- 4.24 With reference to Figure 1 View B, install the cover P/N 3G3340A03452 previously removed on the searchlight support assy by means of n°5 screws P/N MS27039-1-09, n°3 screws P/N MS27039-1-11 and n°8 washers P/N NAS1149C0316R previously removed.
- 4.25 With reference to Figure 1 Detail A, remark the reworked searchlight support assy as P/N 3G3340P01131 by means of an indelible pen.
- 5. If necessary, in accordance with AMP DM 39-L-33-49-04-00A-720A-K, install the power conditioning interface unit on the searchlight support assy.

#### **NOTE**

Perform following step 6 only if helicopter is equipped with kit Trakka A800 searchlight P/N 4G3340F02411 or P/N 4G3340F02412 or P/N 4G3340F02413 or P/N 4G3340F02414.

- 6. Re-install the searchlight support assy on the helicopter as described in the following procedure:
  - 6.1 In accordance with AMP DM 39-L-33-49-05-00A-720A-K, install the searchlight



support assy on the helicopter.

- 6.2 In accordance with AMP DM 39-L-33-49-01-02A-720A-K, install the dovetail mount on the searchlight support assy.
- 6.3 In accordance with AMP DM 39-L-33-49-01-00A-720A-K, install the search light assembly on the search light support assy.


#### **NOTE**

Perform following step 7 only if helicopter is equipped with kit Trakka searchlight P/N 4G3340F03011.

- 7. Re-install the searchlight support assy on the helicopter as described in the following procedure:
  - 7.1 In accordance with AMP DM 39-M-33-49-05-00A-720A-A, install the searchlight support assy on the helicopter.
  - 7.2 In accordance with AMP DM 39-M-33-49-01-01A-720A-A, install the dovetail mount on the searchlight support assy.
  - 7.3 In accordance with AMP DM 39-M-33-49-01-00A-720A-A, install the search light assembly on the searchlight support assy.
- 8. In accordance with weight and balance changes, update the Chart A (see Rotorcraft Flight Manual, Part II, section 6).
- 9. Return the helicopter to flight configuration and record for compliance with Part II of this Service Bulletin on the helicopter logbook.
- 10. Send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

As an alternative, gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".




S.B. N°139-601 DATE: December 21, 2021 REVISION: A - May 11, 2022


Page 17 of 19











S.B. N°139-601 DATE: December 21, 2021 REVISION: A - May 11, 2022





Please send to the following address: LEONARDO S.p.A.		SERVICE BULLETIN COMPLIANCE FORM Date:				
CUSTOMER SUPPORT & SE		Number:				
PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520						
21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988		Revision:				
Customer Name and Addre	ess:			Telephone:		
				Fax:		
				B.T. Compli	ance Date:	
Helicopter Model	S/N		Total N	umber	Total Hours	T.S.O.
Remarks:						
nformation:						

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.