

SBS

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 1 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|----------------|--|--|------------|------------|---|---|
| SBs | | | • | | | |
| Types | SB Number | Subject | Last Done | Next Due | Interval | Limitation Notes |
| Repetitive SBs | 05A003 R3 PART 1.E.2.A PARA 2 (EASA AD F-2003-325 R1) | ENGINE-TO-MGB COUPLING TUBE ASSEMBLY - CHECK AND LIMITATION | 3843:06 | 3868:06 | FH ON 17-4 COMPLIED 2047.70 FH. 024. | NO 9M-GAS-15261 AT 3843:54 2023 WITH ON 07/04/2010 AT A.C REFER ECM WO# 2007 183 ISTAR AIRFRAME SERVICE |
| | | | | | BULLETIN | OMPLIANCE STATUS. |
| Repetitive SBs | SIN 2740-S-25 | KANNAD ELT . CHECK OF THE ATTACHMENT STRAP | 09/04/2023 | 09/05/2023 | | LIED ON 09/02/2023. REFER (9M-GAS-144330. |
| Repetitive SBs | SB 05-014 | COLLECTIVE PITCH CONTROL . CHECK OF THE DRIVE | 24/08/2022 | 24/10/2024 | 04/05/2018 / JC#4018. | NITIAL PARA 3.B.I ON AT A/C 3133.33FH. REF.: MYCAS |
| | | | | | | ISTAR AIRFRAME SERVICE COMPLIANCE STATUS. |
| Repetitive SBs | ASB 05A012 | MAIN ROTOR HUB . CHECK FOR CRACK | 3603:32 | 0:00 | 2054.20 FH. 029. REFER HEL | NITIAL ON 01/07/2010 AT A/C REFER ECM WO# 2007 183 ISTAR AIRFRAME SERVICE OMPLIANCE STATUS. |
| | | | | | INTEGRATE 2022.07.18 | D INTO ALS REV 003 |
| Repetitive SBs | EASB 05A020 R2 (15FH) | TAIL ROTOR HUB BODY - CHECK FOR CRACK | 3855:32 | 3870:32 | 15 COMPLIED | WITH PARA 3.B.1 & 3.B.2 ON NT A/C 3408.90 FH. REF. HRSB |
| | | | | | | ISTAR AIRFRAME SERVICE COMPLIANCE STATUS. |
| Repetitive SBs | EASB 05A020 R2 (1000FH) | TAIL ROTOR HUB BODY - REPLACEMENT OF BOLT, NUT AND WASHER | 2899:54 | 3899:54 | | WITH PARA 3.B.1 & 3.B.2 ON AT A/C 3408.90 FH. REF. HRSB |
| | | | | | | ISTAR AIRFRAME SERVICE COMPLIANCE STATUS. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 2 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|----------------|------------------------------------|--|------------|------------|------------------|--|
| Repetitive SBs | ASB 64A003 | INSPECTION OF THE DRAIN HOLES ALIGNMENT OF TRB | 31/01/2023 | 31/01/2025 | 24 | TO COMPLY WITH ASB PARA 3 WITHIN |
| | | | | | | 500H//24M FOR TRB P/N C642A0300102 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Repetitive SBs | ASB 64A003 | INSPECTION OF THE DRAIN HOLES ALIGNMENT OF TRB | 3743:04 | 4243:04 | 500 | TO COMPLY WITH ASB PARA 3 WITHIN |
| | | | | | | 500H//24M FOR TRB P/N C642A0300102 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Repetitive SBs | Inspection of outside skin panels. | IN 2853-I-52 (10H/7D) | - | 00/00/0000 | 7 | |
| Repetitive SBs | Corrosion of the Tail Boom Skin | IN 2856-I-53 (15H/7D) | 0:00 | 0:00 | 15 | LAST COMPLIED AT 3579:31FH. REFER |
| | | | | | | WORKPACK 9M-GAS-12205. |
| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
| Standard SBs | IN 2856-I-53 | TAIL BOOM . SKIN CORROSION INSPECTION | 19/08/2020 | 09/08/2022 | -/FOR INFO ONLY | |
| Standard SBs | ASB 05A006 R1 | REAR DRIVE SHAFT FRICTION RING . INSPECTION | 3433.20 | 3533.20 | -/NOT APPLICABLE | COMPLIED WITH ON 25/03/2014 AT A/C |
| | | | | | | 2396.80 FH. REFER ECM WO# 2014 025 001 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | ASB 05A019 R2 (EASA AD 2023-0036) | MRH INSPECTION ON ROTATING AND NON-ROTATING SCISSORS | 28/02/2023 | 07/03/2023 | -/NOT APPLICABLE | COMPLIED WITH 50H ASB 05A019 R1 |
| | (15H//7D) | BOLTS | | | | PARA 3.B.2.B AT A/C 3480.60H ON 15/10/ |
| | | | | | | 2020. REF. HRSB JC#HRSB/2020/0377. |
| | | | | | | REPETITIVE 15H//7D I.A.W. PARA 3.B.2.C |
| | | | | | | INCLUDED IN DAILY INSPECTION |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| | | | | | | TIC-EC120B-23-0002 |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 3 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------------------------------|--|------------|----------|------------------|---------------------------------------|
| Standard SBs | ASB 05A019 R2 (EASA AD 2023-0036) | MRH INSPECTION ON ROTATING AND NON-ROTATING SCISSORS | 3764.84 | 3779.84 | -/NOT APPLICABLE | COMPLIED WITH 50H ASB 05A019 R1 |
| | (15H//7D) | BOLTS | | | | PARA 3.B.2.B AT A/C 3480.60H ON |
| | | | | | | 15/10/2020. REF. HRSB |
| | | | | | | JC#HRSB/2020/0377. REPETITIVE 15H//7D |
| | | | | | | I.A.W. PARA 3.B.2.C INCLUDED IN DAILY |
| | | | | | | INSPECTION |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| | | | | | | TIC-EC120B-23-0002 |
| Airframe SBs | | | | | | |
| Standard SBs | ASB 53A017 R1 | REAR FUSELAGE - CHECK FOR CORROSION ON TAIL BOOM | 14/03/2022 | - | -/COMPLIED WITH | TO COMPLY WITH ASB PARA 3 TO CHECK |
| | | | | | | FOR CORROSION AND EMBODIMENT OF |
| | | | | | | MOD C008A0345050 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| | | | | | | 9M-GAS-8729-020 |
| Standard SBs | SB NO. EC120-00-002 REV. 2 | AIRBUS HELICOPTERS - EC120B SERVICE BULLETIN GENERAL - | - | - | -/NOT APPLICABLE | NOT APPLICABLE. REFER TIC-EC120B-22- |
| | | HARMONIZATION - INTRODUCTION TO ALERT SERVICE | | | , | 0007 |
| | | BULLETINS, SERVICE BULLETIN AND TECHNICAL DIRECTIVES | | | | |
| | | UPDATED FOR HARMONIZATION | | | | |
| Standard SBs | SB NO. EC120-62-021 | PRODUCT IMPROVEMENT- MAIN ROTOR INSTALLATION OF | - | - | -/NOT APPLICABLE | REFER TIC-EC120B-23-0001 |
| | | STEEL AMPEP BUSHES ON THE EQUIPPED SCISSORS LINKS | | | | |
| Standard SBs | SB NO. EC120-26-002 | PROTECTIVE MEASURE - FIRE PROTECTION - HAND FIRE | - | - | -/RECOMMENDED | REFER TIC-EC120B-22-0045 |
| | | EXTINGUISHER (HFE) - CHECK OF THE ABSENCE OF DISCHARGE | | | | |
| | | OF THE HFE | | | | RECOMMENDED TO COMPLY WITH THE |
| | | | | | | SB BEFORE NEXT YEARLY WEIGHT |
| | | | | | | CHECK. |
| Standard SBs | SB NO. 319 73 4850, VERSION B | PREVENTIVE FLAME-OUT CHECK VIA THE PREFERENCE | - | - | -/NOT APPLICABLE | REFER TIC-EC120B-22-0038 |
| | | INJECTOR VALVE TEST | | | | |
| Standard SBs | ASB NO. EC120B-63A024 | MAIN ROTOR DRIVE - MAIN GEAR BOX (MGB) MAIN MODULE | - | - | -/NOT APPLICABLE | REFER TIC-EC120B-22-0016 |
| | | REPLACEMENT OF THE LOWER HOUSING S/N M1274 | | | | |
| | | MANUFACTURER P/N (MP/N) C632A2117101 OF THE MGB | | | | NOT APPLICABLE DUE TO MAIN MODULE |
| | | | | | | MGB MPN C632A0201052 FITTED WITH |
| | | | | | | LOWE HOUSING MPN C632A2115102 S/N |
| | | | | | | M401 |



SBS

| Aircraft Re | gistration: | 9M-GAS | Serial No: | 1089 | Date: | 03/05/2023 | Page No: | 4 |
|-------------|-------------|---------|------------|---------|----------|------------|-----------|------|
| Aircraft Ho | ours: | 3858:16 | Landings: | 5169.00 | Engine 1 | : 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|----------------------------------|--|-----------|------------|------------------|------------------------------------|
| Standard SBs | EC120-24-015, REV. 2 | LECTRICAL POWER - ELECTRICAL MASTERBOX- SEPARATION OF | - | - | -/RECOMMENDED | REFER TIC-EC120B-22-0012 |
| | | THE DIRECT BATTERY DISTRIBUTION FROM THE ELECTRICAL | | | | |
| | | MASTER BOX | | | | |
| Standard SBs | SB NO. EC120-63-023 | OBSOLESCENCE MANAGEMENT - MAIN ROTOR DRIVE - ROTOR | - | - | -/OPTIONAL | REFER TIC-EC120B-22-0012 |
| | | BRAKE REPLACEMENT OF THE ROTOR BRAKE PADS | | | | |
| Standard SBs | SB NO. EC120-32-009 | AIRBUS HELICOPTERS - EC120B SERVICE BULLETIN LANDING | - | - | -/RECOMMENDED | REFER TIC-EC120B-22-0001 |
| | | GEAR- NEW BINDING CLAMPS OF THE LANDING GEAR FAIRINGS | | | | |
| Standard SBs | SB NO. 319 77 4097, VERSION B | PYROMETRIC HARNESS - CHANGE IN THE MATERIAL OF THE | - | - | -/ON CONDITION | TO APPLY SB IF THE PYROMETRIC |
| | | THERMOCOUPLE PROBES AND ROUTING MODIFICATION. | | | | HARNESS IS REPLACED (DISCARDED) |
| | | MODIFICATION TF 97 | | | | |
| | | | | | | REFER TIC-EC120B-22-0003 |
| Standard SBs | SB NO. EC120-00-002, REV. 2 | INTRODUCTION TO ALERT SERVICE BULLETINS, SERVICE | - | - | -/NOT APPLICABLE | TIC-EC120B-22-0007 |
| | | BULLETIN AND TECHNICAL DIRECTIVES UPDATED FOR | | | | |
| | | HARMONIZATION | | | | |
| Standard SBs | EC120-32A014 (EASA AD 2022-0053) | LANDING GEAR INSPECTION FOR CORROSION ON THE LANDING | - | 28/04/2024 | -/TO BE COMPLIED | TO BE COMPLY. REFER TIC-EC120B-22- |
| | | GEAR | | | | 0037 |
| Standard SBs | SB 319 71 4089 VER.A | AIR INTAKE GRIDS. ELIMII\ATION OF BRAZING AND | - | - | -/OPTIONAL | APPLICATION UPON CUSTOMER |
| | | SIMPLIFICATION OF HE DESIGN. APPLICATION OF MODIFICATION | | | | REQUEST OR N/A YES FOLLOWING |
| | | TF 89 | | | | DEPLETION OF EXISTING STOCK |
| | | | | | | |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 00-001 | Presentation of the subject, content and use of ALERT SERVICE | - | - | -/OPTIONAL | NOT APPLICABLE |
| | | BULLETINS, SERVICE BULLETINS and TECHNICAL DIRECTIVES | | | | |
| Standard SBs | 00-002 | Introduction to ALERT SERVICE BULLETINS, Service Bulletins and | - | - | -/OPTIONAL | NOT APPLICABLE |
| | | Technical Directives updated for harmonization | | | | |
| Standard SBs | 01-001 | Check of the tail rotor pitch change control rod inside the tail rotor | - | - | -/FOR INFO ONLY | FOR INFO ONLY |
| | | gearbox for binding points | | | | |
| Standard SBs | 01-002 | Flight Restriction for Engine-to-MGB Coupling Tube Assembly and | - | - | -/SUPERSEDED | SUPERSEEDED BY ASB 04A002 |
| | | Engine Support Fitting | | | | |
| Standard SBs | 04-003 | Flight Envelope Extension to Minus 40 Degrees Celsius | - | - | -/NOT APPLICABLE | N/A. HELICOPTER OPERATING IN |
| | | | | | | TROPICAL AND DAMP ATMOSPHERE. |
| | | | | | | REFER EUROCOPTER AIRFRAME |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| | | | | | | 014100. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 5 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|-----------|----------|------------------|--|
| Standard SBs | 04A001 | Check of the Tail Rotor Pitch Change Control Rod for Binding Points Inside the Tail Rotor Gearbox | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO TGB INSTALLED PART NUMBER NOT AFFECTED. PN C652A0101055 SN M192 INSTALLED. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 04A002 | Flight Restriction for Engine-to-MGB Coupling Tube Assembly and Engine Support Fitting | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO COUPLING PART NUMBER NOT AFFECTED. INSTALLED ON A/C PN C631A1101101. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 04A004 | SIREN Load Release Units: Load jammed on the cargo hook in the open position | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO CARGO HOOK NOT INSTALLED. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 04A005 | Engine Mount | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO COMPLIED WITH SB 71-003 ON 24/02/2003 AT A/C 988.50 FH. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 04A006 | Non-Airworthiness Declaration for Spherical Thrust Bearings,P/No. 7050A3622036 | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO PART NOT AFFECTED. PN 7050A3622022 SN 0235, 0255 & 0284 INSTALLED. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 04A007R1 | Limitations - Emergency floatation gear control on the lighting and ancillary control unit | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO PART NOT FITTED. REF. MYCAS JC 1409. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 05-002 | Monitoring of fuel system contamination | - | - | -/FOR INFO ONLY | N/A. AIRCRAFT SERIAL NUMBER 1089 REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 6 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|-----------|----------|-----------------|---|
| Standard SBs | 05-004 | Check of Horizontal Stabilizer Drain Holes | - | - | -/COMPLIED WITH | COMPLIED WITH. REF.: VH-TRW NON RECURRING AD, SPECIAL INSPECTION AND MODIFICATION CERTIFICATION LOG BOOK ONE |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 05-007 | Calendar Check for Corrosion on Main Rotor Head Attach Beams | - | - | -/FOR INFO ONLY | |
| Standard SBs | 05-009 | Lubrication of the couplings of the non-rotating and rotating scissors | - | - | -/FOR INFO ONLY | |
| Standard SBs | 05-010R1 | Emergency floatation gear float cover | - | - | -/FOR INFO ONLY | |
| Standard SBs | 05-013 | SKURKA (ex APC) starter-generators (MP/N) 160SG140Q1 and 160SG140Q1XL | - | - | -/COMPLIED WITH | STARTER GENERATOR LOGGED MORE 1000H. INITIAL 150H COMPLIED BY ECM ON 08 OCT 2013 AT 2370.6HRS. REFER WIO# 2013-494-001. SUBSEQUENTLY BRUSH CONDITION CHECK AT 300H AND OVERHAUL AT 900H. REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 05A001 | Check of the engine-to-MGB coupling tube assembly | - | - | -/FOR INFO ONLY | |
| Standard SBs | 05A005R1 | Cabin Sliding Door Adjustment | - | - | -/COMPLIED WITH | COMPLIED WITH ON 19/07/2001 AT A/C 485.00FH. REFER AUSTRALIAN MODIFICATION BOOK REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 05A006 | Tail Rotor Drive Shaft: Damper Friction Ring on the Rear Drive Shaft | - | - | -/COMPLIED WITH | COMPLIED WITH ON 25/03/2014 AT A/C 2396.80 FH. REFER ECM WO# 2014 025 001 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 05A008R2 | Crack in the Belt Buckle | - | - | -/COMPLIED WITH | RI: COMPLIED WITH ON 15/11/2007 AT A/C 1897.60 FH. REFER ECM WO# 2007-533. BUCKLES REPLACED. REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 7 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|-----------|----------|------------------|--|
| Standard SBs | 05A011 | Emergency floatation gears: periodic check of the floats with intervals in hours | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO PART NOT INSTALLED |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 07-001 | Safety improvement to TIRFOR locking unit on portable crane | - | - | -/NOT APPLICABLE | N/A, PORTABLE CRANE NOT FITTED |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 21-001 | Installation of the Air-Conditioning Unit Optional Equipment | - | - | -/OPTIONAL | |
| Standard SBs | 21-002 | Improvement of cabin ventilation sealing | - | - | -/OPTIONAL | |
| Standard SBs | 21-003 | Interference Suppression of the SIB 120 Intercommunication System | - | - | -/OPTIONAL | |
| | | Audio Channels by Replacing the Cabin Fan With an Interference- Suppressed Fan | | | | |
| Standard SBs | 21-004 | Preventing Damage to the Ventilation Duct due to Overheating Should the Air Conditioning Fan Fail | - | - | -/OPTIONAL | |
| Standard SBs | 53-001 | Provisions for Installation of Ballast in the Fenestron | - | - | -/OPTIONAL | |
| Standard SBs | 21-005 | Reduction of the Noise Level of the Cabin Heating | - | - | -/OPTIONAL | |
| Standard SBs | 21-006 | Ventilation duct insulation | - | - | -/COMPLIED WITH | COMPLIED WITH. REF.: VH-TRW NON- RECURRING AD, SPECIAL INSPECTION AND MODIFICATION CERTIFICATION LOG BOOK ONE |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 21-008 | Heating System For Very Cold Weather | - | - | -/OPTIONAL | |
| Standard SBs | 21-009 | Elimination of the Outside Air Intakes at the Console | - | - | -/OPTIONAL | |
| Standard SBs | 21-010 | Improved Draining of the Air Conditioning System | - | - | -/COMPLIED WITH | COMPLIED WITH ON 30 SEP 2003 AT A/F TT 1132.5 HRS. REFER TO AUSTRALIAN MODIFICATION BOOK. REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 21-011 | Extreme cold weather heating option | - | - | -/OPTIONAL | |
| Standard SBs | 21-012 | Reserved | - | - | -/OPTIONAL | |
| Standard SBs | | Rear/tail boom structure | - | - | -/FOR INFO ONLY | |
| Standard SBs | 21-013 | Adding a water trap to the air conditioning system | - | - | -/OPTIONAL | |
| Standard SBs | 21-014 | Modification of P2 valve control pin | - | - | -/FOR INFO ONLY | |



SERVICE BULLETIN (SB'S) STATUS LIST

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 8 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|-----------|----------|------------------|---------------------------------|
| Standard SBs | 21C007 | Modification of the Heating System Called Silencer System | - | - | -/OPTIONAL | |
| Standard SBs | 23-001 | Replacement of the SIB 120 intercommunication system with the new | - | - | -/OPTIONAL | |
| | | model intercommunication system to prevent the risk of radio | | | | |
| | | interference | | | | |
| Standard SBs | 23-002 | External Connector for the ICS | - | - | -/OPTIONAL | |
| Standard SBs | 23C003 | VHF installation KY196B for 8.33 kHz capability | - | - | -/OPTIONAL | |
| Standard SBs | 24-001 | Relocating the battery aft | - | - | -/OPTIONAL | |
| Standard SBs | 24-002 | Installation of the Ground Power Socket as Optional Equipment | - | - | -/OPTIONAL | |
| Standard SBs | 24-003 | To eliminate generation system breaking problem (following engine start | - | - | -/OPTIONAL | |
| | | -up with generator switch set to OFF) with a new electronic card Z100 | | | | |
| | | replacing the former card inside the electrical master box | | | | |
| Standard SBs | 24-004 | Installation of the Battery Heater Optional Equipment | - | - | -/OPTIONAL | |
| Standard SBs | 24-005 | Replacement of the Electrical Connector of the Tail Boom Position Light | - | - | -/OPTIONAL | |
| | | with a Connector Requiring no Tool for its Disconnection | | | | |
| Standard SBs | 24-006 | SUBJECT: ELECTRICAL POWER THALES Starter Generator | - | - | -/OPTIONAL | |
| | | Installation | | | | |
| Standard SBs | 24-007 | Electrical master box and SEFEE breaker panel installation | - | - | -/OPTIONAL | |
| Standard SBs | 24-008 | Modification to Electrical Master Box | - | - | -/OPTIONAL | |
| Standard SBs | 24-009 | Inhibition of the Flight/Ground Signal | - | - | -/OPTIONAL | |
| Standard SBs | 24-010 | APC Starter-generator: Fan Attachment Nut | - | - | -/FOR INFO ONLY | |
| Standard SBs | 24-011 | Replacement of SEFEE SE07111 Electrical Master Box to Provide | - | - | -/FOR INFO ONLY | |
| | | Power to the Map Readers When the BAT Switch is Set to OFF | | | | |
| Standard SBs | 24-013 | Possible short-circuit | - | - | -/OPTIONAL | |
| Standard SBs | 24-014 | Modification of the SEFEE electrical master box (P/N) SE07113 | - | - | -/FOR INFO ONLY | |
| Standard SBs | 24-015 | Separation of the Direct Battery distribution from the electrical master | - | - | -/FOR INFO ONLY | |
| | | box | | | | |
| Standard SBs | 24-016R1 | Electrical Power - Starter-generator Improved SKURKA starter- | - | - | -/FOR INFO ONLY | |
| | | generator | | | | |
| Standard SBs | 24A012 | EMERgency SWitch (EMER SW) wiring | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO SERIAL |
| | | | | | | NUMBER NOT AFFECTED |
| | | | | | | |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 25-001 | Equipping The Helicopter with the Optional Emergency Flotation Gear | - | - | -/OPTIONAL | |
| | | (Fixed parts) | | | | |
| Standard SBs | 25-002 | Cargo sling fixed part installation | - | - | -/OPTIONAL | |
| Standard SBs | 25-003 | Installation of an electric rear-view mirror | - | - | -/OPTIONAL | |

SBS



SBS

| Aircra | aft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/ | /05/2023 | Page No: | 9 |
|--------|-------------------|---------|------------|---------|-----------|----------|-----------|------|
| Aircra | aft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: | 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | |
|--------------|-----------|---|-----------|----------|------------------|---|
| Standard SBs | 25-004 | Emergency Flotation Gear Đ Reinforcement of Drag Patch Attachment | - | - | -/NOT APPLICABLE | N/A, EMERGENCY FLOTATION NOT INSTALLED |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 25-005 | Installation of the Optional "SOCATA" Emergency Locator Transmitter | - | - | -/OPTIONAL | |
| Standard SBs | 25-006 | Installation of the optional SKI assembly | - | - | -/OPTIONAL | |
| Standard SBs | 25-007 | Enhanced Sound-Proofing | - | - | -/OPTIONAL | |
| Standard SBs | 25-008 | Installation of the Cabin Access Handles | - | - | -/OPTIONAL | |
| Standard SBs | 25-009 | Installation of a filter on SOCATA emergency beacon | - | - | -/OPTIONAL | |
| Standard SBs | 25-012 | Routing of the Removable Part of the Cargo Sling Installation | - | - | -/NOT APPLICABLE | N/A, CARGO SLING NOT INSTALLED |
| | | Mechanical Emergency Load Release Unit Control | | | | |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 25-013 | Installation of the Wire Strike Protection System | - | - | -/OPTIONAL | |
| Standard SBs | 25-014 | Rear Passenger Seat Bench: Corrosion-Preventive Treatment | - | - | -/OPTIONAL | |
| Standard SBs | 25-015 | Passenger seat: Longer Harness Strap | - | - | -/OPTIONAL | |
| Standard SBs | 25-016 | Folding Stretcher Option | - | - | -/OPTIONAL | |
| Standard SBs | 25-017 | KANNAD 406 AF-H Emergency Location Transmitter (ELT) installation | - | - | -/OPTIONAL | |
| Standard SBs | 25-018R1 | Checking the rear LH cable of the sling support | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25-019 | Optional KANNAD 121AF-H E.L.T. installation | - | - | -/OPTIONAL | |
| Standard SBs | 25-020 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25-021 | First-Aid Kit | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25-022 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25-024 | Emergency Floatation Gear - Floatation gear cylinder identification label | - | - | -/OPTIONAL | |
| | | on the rear RH bottom fairing | | | | |
| Standard SBs | 25-025 | Sling: Under-estimation of the weight of the carried load | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25-028 | Protection of tri-band antenna MP/N 21-41 | - | - | -/FOR INFO ONLY | |
| Standard SBs | 25A023 | Electrical bonding of energy- absorbing seats | - | - | -/COMPLIED WITH | COMPLIED WITH ON 24/01/2008 AT A/C |
| | | | | | | 1911.90 FH. REFER ECM WO# 2008-006 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 25A026 | Protector installation on the rear bracket and the supply couplings | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO PART NOT |
| | | | | | | INSTALLED |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |



GalaxyAerospace

maintenance.repair.overhaul

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 10 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|------------------|--|
| Standard SBs | 25C010 | Cabin Comfort Interior | - | - | -/OPTIONAL | |
| Standard SBs | 25C011 | Retrofitting S/N 1115, 1140, 1150 Aircraft | - | - | -/OPTIONAL | |
| Standard SBs | 25C027 | Installation of three-frequency Emergency Locator Transmitter (ELT) (JAR OPS 3) | - | - | -/FOR INFO ONLY | |
| Standard SBs | 26-001 | Fire Protection Replacement of fire extinguisher further to obsolescence | 02/09/2020 | - | -/COMPLIED WITH | COMPLIED WITH PARA 4.A. & 4.B. ON 02/09/2020 AT A/C 3439.500 FH. REF.: HRSB JC# 0319 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 28-001 | Installation of New Fuel Quantity Probes | - | - | -/OPTIONAL | |
| Standard SBs | 28-006 | Optional fuel flowmeter | - | - | -/OPTIONAL | |
| Standard SBs | 28-007 | Use of Replacement Fuel Types (JP4 - JET B -TS1 - RT) | - | - | -/NOT APPLICABLE | N/A DUE POST MOD TF 17 AND TF 39. FUEL TYPES NOT AVAILABLE IN MALAYSIA. REFER W/O 2011 078 002 REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 28-008 | Electrical bonding of upper fuel tank plate | - | - | -/RECOMMENDED | NOT CARRIED OUT. RECOMMENDED SB REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 28-009 | Protection of engine fuel system without antifreeze additive down to - 15 _i C | - | - | -/OPTIONAL | |
| Standard SBs | 28-010 | Check of the integrity of the lower fuel tank (P/No. 501101-X) retaining studs | 24/02/2008 | - | -/COMPLIED WITH | COMPLIED WITH ON 04/02/2008 AT A/C 1911.90FH. REF.: ECM W0#2008-0060 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 28-011 | Fuel system modification further to engine fuel control unit evolution (FCU) | - | - | -/OPTIONAL | |
| Standard SBs | 28-012 | Integration of a relay in the fuel pump control circuit | - | - | -/FOR INFO ONLY | |
| Standard SBs | 28C002 | Fuel Tank Cleaning Procedure | - | - | -/OPTIONAL | |
| Standard SBs | 28C003 | Reserved | _ | - | -/FOR INFO ONLY | |



SBS

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 11 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|---|------------|----------|------------------|--|
| Standard SBs | 28C004 | Modification of the Fuel System to Protect the Engine From Contamination | 12/03/2001 | - | -/COMPLIED WITH | COMPLIED ON 12/03/2001 AT A/C 296.1OH . REF.: AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 28C005 | Reserved | | | -/FOR INFO ONLY | BOLLETIN COMPLIANCE STATUS. |
| Standard SBs | 29-001 | Improvement of the Electrovalve on the Hydraulic Power Pack | - | - | -/OPTIONAL | |
| Standard SBs | 29-002 | New Hydraulic Power Pack Pre-Clogging Indicator | - | - | -/OPTIONAL | |
| Standard SBs | 29-002 | GHC100 Compact Hydraulic Power Unit | - | - | -/OPTIONAL | |
| Standard SBs | 30-001 | Optional windscreen wiper installation | - | - | -/OPTIONAL | |
| | 30-001 | • | - | - | -/OPTIONAL | |
| Standard SBs | | Deflectors for optional windshield wiper | - | - | | |
| Standard SBs | 31-001 | Reserved | - | - | -/OPTIONAL | |
| Standard SBs | 31-002 | Reserved | - | - | -/OPTIONAL | |
| Standard SBs | 31-003 | VEMD New version | - | - | -/OPTIONAL | |
| Standard SBs | 31-004 | New design LACU | - | - | -/OPTIONAL | |
| Standard SBs | 31-005 | LACU's SELA power supply unit retrofit | - | - | -/OPTIONAL | |
| Standard SBs | 31-006R1 | Check of the warning panel | - | - | -/FOR INFO ONLY | |
| Standard SBs | 76A006 | Check of the Twist Grip Drive Tube and Control Pinion Attachment | | | | CARRIED OUT IAW PARA 2.B.4 ON 08/05/2012 AT A/C 2133.10 FH. REFER ECM WO #2011 485 007 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 31-007 | Check of Control warning panel | - | - | -/FOR INFO ONLY | |
| Standard SBs | 31-009 | Replacement of the ASU card No. 1 | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52-019 | Doors -Reinforcement of the control rods of the standard cabin doors | - | - | -/FOR INFO ONLY | |
| Standard SBs | 31A008 | Indicating and Recording Systems Replacement of push-button FLOAT ARM of SMS unit | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO PART NOT FITIED. REF. MYCAS JC 1409 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 32-001 | Installation of end plates on the landing gear skids | - | - | -/OPTIONAL | |
| Standard SBs | 32-002 | Preventing or Repairing Loose Rivets in the Landing Gear Forward Cross-Tube / Skid Attachments | 30/07/2002 | - | -/COMPLIED WITH | COMPLIED ON 30/07/2002. REF.: VH-TRW NON-RECURRING AD, SPECIAL INSPECTION AND MODIFICATION CERTIFICATION LOG BOOK ONE PG.02 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| | | | | | | |



SBS

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 12 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|------------------|--------------------------------------|
| Standard SBs | 32-004 | Improvement of the Skid-Type Landing Gear / Access Footstep | - | - | -/OPTIONAL | |
| | | Connection | | | | |
| Standard SBs | 32-005 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 32-006R1 | Replacement of the landing gear rear attachment clamp | - | - | -/FOR INFO ONLY | |
| Standard SBs | 32-007 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 32C008 | Not translated | - | - | -/FOR INFO ONLY | |
| Standard SBs | 33-001 | Installation of the optional swiveling landing light | - | - | -/OPTIONAL | |
| Standard SBs | 33-002 | Check of the Position Light and Anti-Collision Light Electrical Harness | - | - | -/FOR INFO ONLY | |
| | | Routing on the Fin Top Fairing | | | | |
| Standard SBs | 33-003 | Installation of fixed landing light indicator light | - | - | -/OPTIONAL | |
| Standard SBs | 33-004 | Position and anticollision LED lights | - | - | -/OPTIONAL | |
| Standard SBs | 34-001 | Cabin adaptation for night VF | - | - | -/OPTIONAL | NOT COMPLIED. REFER W/O 2011 078 002 |
| | | | | | | |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 34-002 | OAT Measurement Calibration | - | - | -/OPTIONAL | |
| Standard SBs | 34-003 | To Eliminate the Continuous Vibrations Affecting the Airspeed Indicator | - | - | -/OPTIONAL | |
| | | Pointer | | | | |
| Standard SBs | 34-004 | Replacement of the Connector on the Pitot Tube | - | - | -/OPTIONAL | |
| Standard SBs | 34-005 | GPS Labels With or Without Navigation Coupling | 15/12/2008 | - | -/COMPLIED WITH | COMPLIED WITH ON 15/12/2008 AT A/C |
| | | | | | | 2019.60FH. REF.: ECM WO 2008-183-005 |
| | | | | | | |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 34-007 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 34-008 | Radio Altimeter: AHV 16 (ERT160) Transceiver; improved reliability of | - | - | -/OPTIONAL | |
| | | the radio altimeter height signal transmitted for autopilot coupling and | | | | |
| | | display of the radio altimeter indication | | | | |
| Standard SBs | 34A006 | Horizontal Situation Indicator KI 525A | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO KI 525A NOT |
| | | | | | | INSTALLED |
| | | | | | | |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 34C009 | Not translated | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52-001 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52-002 | To Allow Key Locking of Cargo Doors | - | - | -/OPTIONAL | |
| Standard SBs | 52-003 | To prevent or repair loose attachment rivets of lower fitting of sliding | - | - | -/OPTIONAL | |
| | | door | | | | |
| Standard SBs | 52-005 | Improvement of the Door working | | | -/OPTIONAL | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 13 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|------------------|---|
| Standard SBs | 52-006 | Improvement of the Cabin Door Ergonomics | - | - | -/OPTIONAL | |
| Standard SBs | 52-007 | New Door Seals | 08/10/2013 | - | -/COMPLIED WITH | COMPLIED ON 08/10/2013 BY ECM AT A/C 2370.60FH. REF.: WO 2013 494 001 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 52-008 | Modification to the Lower Receptacle of the Left Forward Cabin Door | - | - | -/OPTIONAL | |
| Standard SBs | 52-009 | RH Fixed Panel Adjustment | - | - | -/OPTIONAL | |
| Standard SBs | 52-010 | New Sliding Door Fittings | - | - | -/OPTIONAL | |
| Standard SBs | 52-011 | New Cabin Door Handles | - | - | -/OPTIONAL | |
| Standard SBs | 52-012 | Improvement of Cabin Sliding Door | - | - | -/OPTIONAL | |
| Standard SBs | 52-013 | Doors protection | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52-016 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52-019 R1 | Reinforcement of the control rods of the standard cabin doors | - | - | -/FOR INFO ONLY | |
| Standard SBs | 52A004R1 | Installation of a Stop on the Upper Front Rail of the Cabin Sliding Door | - | - | -/COMPLIED WITH | COMPLIED WITH ON 19/07/2001 AT A/C 485.00FH. REFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 52A014R2 | Attachment of the sliding door star support | - | - | -/COMPLIED WITH | COMPLIED WITH AD 2013-0093 ON 14/03/2014 BY AHM. REF. WO 2014 025 001. REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 52A017 | Check of the installation of the crew door actuators | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH FLOATATION GEAR REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 52A018R1 | Doors -Reinforcement of the door locking/unlocking mechanism | - | - | -/COMPLIED WITH | COMPLIED WITH ON 22/06/2018 AT A/C 3163.70 FH. REFER MYCAS JC# 4255 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 52C015 | Cabin doors standard upgrade | | | -/OPTIONAL | BULL THE COWF LIANCE STATUS. |
| Standard SBs | 53-002 | Protection of the Battery and the Rear Compartment Area Against | - | - | -/OPTIONAL | |
| Stanuaru SBS | | Grease Expelled From the Tail Rotor Drive Shaft Bearing | - | - | | |
| Standard SBs | 53-003 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 53-004 | Reduced Instrument Panel Vibrations | - | - | -/OPTIONAL | |



| Aircraft Registr | ation: 9M-GAS | Serial No: | 1089 | Date: | 03/05/2023 | Page No: | 14 |
|------------------|---------------|------------|---------|-----------|------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: | : 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|-----------------|--|
| Standard SBs | 53-005 | Increased possibilities for adjusting the center-of-gravity | - | - | -/OPTIONAL | |
| Standard SBs | 53-007 | Improved Tuning of Z- and Y-Axis Anti-Vibration Units | - | - | -/OPTIONAL | |
| Standard SBs | 53-008 | Easy-to-Adjust Cabin Antivibrators With Calibrated Blades | - | - | -/OPTIONAL | |
| Standard SBs | 53-009 | Fenestron Ballast Increased to 19Êkg | - | - | -/OPTIONAL | |
| Standard SBs | 53-010R1 | Reinforcement of X1710 frame for lateral Y vibration damper support fitting attachment | 20/09/2006 | - | -/COMPLIED WITH | RO: COMPLIED WITH ON 20/09/2006 AT A/C 1709.00FH. REF.: ECM WO 2006-173 REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 53-011 | Trimmed Fenestron Keel | - | - | -/OPTIONAL | |
| Standard SBs | 53-012 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 53-013 | Cable anti-retention device on the canopy center post | - | - | -/FOR INFO ONLY | |
| Standard SBs | 53-014 | Modification of the bolt length on the junction frame | - | - | -/FOR INFO ONLY | |
| Standard SBs | 53-016 | Repair of the tail boom at the VOR antenna attachments | - | - | -/CANCELLED | |
| Standard SBs | 53A015R1 | Corrosion on the tail boom | - | , | /NOT APPLICABLE | NOT APPLICABLE. REF. : ECM WO# 2014 449 00 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 53C006 | Evaluation of Self-Adjusting Antivibrators in Op?rational Environment | - | - | -/OPTIONAL | |
| Standard SBs | 55-001 | Repair and/or Reinforcement of the Horizontal Stabilizer Attachment | - | - | -/OPTIONAL | |
| Standard SBs | 56-002 | Protection of Transparent Panel Bonding Areas Against UV Radiation | - | - | -/OPTIONAL | |
| Standard SBs | 56-003 | Strengthening RH and LH side windshield panels | - | - | -/OPTIONAL | |
| Standard SBs | 56-004 | RH and LH side new windshields panels | 14/03/2014 | - | -/COMPLIED WITH | COMPLIED WITH ON 14/03/2014 AT A/C 2396.80 FH. REFER ECM WO# 2014 025 002 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 56C001 | Reinforcement of the Pilot's and Copilot's Sliding Windows | - | - | -/OPTIONAL | |
| Standard SBs | 62-001 | Visualization of the Rotor Disk | | _ | -/OPTIONAL | |
| Standard SBs | 62-002 | To Prevent Incorrect Greasing of Anti-vibrator Bearings | | - | -/OPTIONAL | |
| Standard SBs | 62-003 | To Ease Installation of Stationary and Rotating Scissors Assemblies | - | - | -/OPTIONAL | |
| Standard SBs | 62-004 | Improvement of the balance weight attachment fittings on the MRH | 26/01/2010 | - | | COMPLIED WITH ON 26/01/2010 AT A/C 2121.00FH. REF.: ECM WO 2011 485 002 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 62-005 | Improvement of the MRH Electrical Bonding | | | -/OPTIONAL | |
| Stanuaru SDS | 02-000 | improvement of the writer Electrical Boliding | | - | -/FOR INFO ONLY | |



SBS

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 15 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|-----------------|--------------------------------------|
| Standard SBs | 62-007 | New Swashplate Adjustement Shim | 24/02/2003 | - | -/COMPLIED WITH | COMPLIED ON 24/02/2003. REF.: VH-TRW |
| | | | | | | NON-RECURRING AD, SPECIAL |
| | | | | | | INSPECTION AND MODIFICATION |
| | | | | | | CERTIFICATION LOG BOOK ONE PG.2 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 62-008 | Check of the Scissors Drive Adapter Attachment | - | - | -/FOR INFO ONLY | |
| Standard SBs | 62-009 | Increased Clearance Between the Main Rotor Blades and the Tail Boom | - | - | -/OPTIONAL | |
| Standard SBs | 62-010 | Increasing the blade clearance from tail boom | - | - | -/OPTIONAL | |
| Standard SBs | 62-011 | Improved sealing of main blade balancing weight support | - | - | -/OPTIONAL | |
| Standard SBs | 62-012 | New protection baffle plates for swashplate bearing | - | - | -/OPTIONAL | |
| Standard SBs | 62-013 | Main blade sand protection | - | - | -/OPTIONAL | |
| Standard SBs | 62-014 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 62-015 | Improved wear resistance of the stationary and rotary scissors hinge | - | - | -/OPTIONAL | |
| | | bushes | | | | |
| Standard SBs | 62-016 | Modification of swashplate baffle plates | - | - | -/FOR INFO ONLY | |
| Standard SBs | 62C017 | Not translated | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63-001 | Installation of a Reinforced Engine-to-MGB Coupling Tube P/No. | - | - | -/FOR INFO ONLY | |
| | | C631A1101101 and a New Engine Mount Fitting Assembly | | | | |
| Standard SBs | 63-002 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63-003 | MGB Input Flange Blanking Plug | 24/02/2003 | - | -/COMPLIED WITH | COMPLIED ON 24/02/2003. REF.: VH-TRW |
| | | | | | | NON-RECURRING AD, SPECIAL |
| | | | | | | INSPECTION AND MODIFICATION |
| | | | | | | CERTIFICATION LOG BOOK ONE PG .2 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-004 | Improving the Rotor Brake Handle Unit | 15/12/2008 | - | -/COMPLIED WITH | COMPLIED WITH ON 15/12/2008 AT A/C |
| | | | | | | 2019.60FH. REF.: ECM WO 2008 183 005 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-005R2 | Improved Operation of The Rotor Brake Unit | - | - | -/FOR INFO ONLY | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 16 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|---|------------|----------|-----------------|--|
| Standard SBs | 63-006R1 | Corrosion on Main Rotor Shaft | - | - | -/COMPLIED WITH | R1: COMPLIED WITH ON 05 FEB 08 AT AIRFRAME TT 1911.9 HRS. REFER ECM W/O # 2008-006 |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-007R1 | New MGB Input Spiroid Worm Gear | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63-009 | Replacement of a Resistor in the NR Indicating System | - | - | -/OPTIONAL | |
| Standard SBs | 63-010 | Installation of the New MGB Input Flange Plug | 13/12/2005 | - | -/COMPLIED WITH | COMPLIED WITH ON 13/12/2005 AT A/C 1470.00FH. REF.: ECM WO 2005-026 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-011 | Rotor brake disk spline wear suppression | 28/01/2006 | - | -/COMPLIED WITH | COMPLIED WITH ON 28/01/2006 AT A/C 1525.20FH. REF.: ECM WO 2006-024. ROTOR BRAKE DISK PN-C635A1103201 & TORLON SPLIT RING PN-C365A1111201 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-012 | Check of MGB Main Module Tapered Pin Attaching Cones | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63-013 | Check for Absence of Corrosion Inside the Rotor Shaft | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63-014 | MGB housing corrosion protection improvement | - | - | -/OPTIONAL | |
| Standard SBs | 63-015 | Follow-up of the Main Gear Box Input Housing | 15/11/2017 | - | -/COMPLIED WITH | COMPLIED WITH ON 15/11/2007 A/C 1897.60FH. REF.: ECM WO 2007-533. PN- C632A2181102 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-016 | Replacement of a BJE (leak-tight connector terminal) module in the NR indicator circuit | 21/01/2011 | - | -/COMPLIED WITH | COMPLIED WITH ON 21/01/2011 AT A/C 2062 .10FH. REF.: ECM WO 2007 183 038 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 63-019 | Change in NR/NF indicator | - | - | -/OPTIONAL | |
| Standard SBs | 63C008 | Monitoring of Oil Filter Differential Pressure | - | - | -/OPTIONAL | |
| Standard SBs | 63C017 | Not translated | - | - | -/FOR INFO ONLY | |
| Standard SBs | 63C018 | Adaptation of N Rotor line | - | - | -/OPTIONAL | |
| Standard SBs | 63C020 | Not translated | - | - | -/FOR INFO ONLY | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 17 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|-----------|----------|------------------|---|
| Standard SBs | 64-001 | Longer rings on TRH | - | - | -/OPTIONAL | |
| Standard SBs | 64-002 | Tail rotor hub (TRH) behavior monitoring in operation | - | - | -/OPTIONAL | |
| Standard SBs | 65-001 | Replacement of the Existing Tail Gear Box Friction Bushes With Torlon Bushes | - | - | -/COMPLIED WITH | FACTORY COMPLIED |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 65-002 | Checking Two Tail Gearbox Casing Attachment Lugs | - | - | -/NOT APPLICABLE | N/A, TGB S/N M192 INSTALLED. |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 65-003 | Increase of the Centering Length on the Output Gear of the Tail Rotor Gear Box | - | - | -/NOT APPLICABLE | N/A BY TGB P/N C652A0101055 INSTALLED |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 65-005 | Installation of new TGB pitch control rod lubrification cap | - | - | -/OPTIONAL | |
| Standard SBs | 65-006 | TAIL ROTOR DRIVE - Tail rotor drive shaft. Installation of a blanking plate on the drive tube on the TGB side | - | - | -/OPTIONAL | |
| Standard SBs | 65A004 | Tail Rotor Drive Shaft Damper | - | - | -/COMPLIED WITH | COMPLIED WITH ON 13/01/2004 AT A/C 1182.70 FH. REFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67-001 | Replacement of Pilot and Copilot Pedal Unit Links (RH Side) | - | - | -/OPTIONAL | |
| Standard SBs | 67-002 | Improved Resistance of the Pedal Torque Tube to Hammering | - | - | -/OPTIONAL | |
| Standard SBs | 67-004 | Provision for Quick Removal of LH Controls | - | - | -/OPTIONAL | |
| Standard SBs | 67-006 | Increased Stability of Pedal Unit Adjustment | - | - | -/OPTIONAL | |
| Standard SBs | 67-012 | Replacing the Rivets on the Hinge Housing of the LH Cyclic Stick | - | - | -/NOT APPLICABLE | N/A BY AIRCRAFT S/N. |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67-015 | Catching up play in collective levers, proposal for rework | - | - | -/OPTIONAL | |
| Standard SBs | 67-016 | Reserved | - | - | -/FOR INFO ONLY | |



SBS

| Aircr | raft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05 | 5/2023 | Page No: | 18 |
|-------|--------------------|---------|------------|---------|--------------|--------|-----------|------|
| Aircr | raft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 46 | 621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|------------------|--|
| Standard SBs | 67-017 | Replacement of the RH Collective Lever End on the Collective Torque | 05/05/2017 | - | -/COMPLIED WITH | COMPLIED ON 05/05/2017 BY MYCOPTER |
| | | Tube Assembly | | | | AT A/C 2913.60FH. REF.: MYCAS JC#2352 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67-018 | Dual mechanical locking of flying control stops | - | - | -/OPTIONAL | |
| Standard SBs | 67-019 | Nose-up stop modification after incorporation of a ring into the droop | - | - | -/OPTIONAL | |
| | | restrainer ring | | | | |
| Standard SBs | 67-020 | Fixed length anticipator link | - | - | -/OPTIONAL | |
| Standard SBs | 67-021 | Collective Levers: Collective Lever Balancing | - | - | -/OPTIONAL | |
| Standard SBs | 67-022 | RH pedal unit: Play in the torque tube-to-yaw ball-type control lever | 18/01/2020 | - | -/COMPLIED WITH | COMPLIED ON 18/01/2020 AT A/C |
| | | assembly | | | | 2042.40FH. REF.: ECM WO 2008 183 023 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67-023 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 67-024 | Check for free movement and lubrication of the swivel bearing of the aft | - | - | -/NOT APPLICABLE | N/A BY AFT YAW MP/N: 76CF8921 (P/N: |
| | | yaw ball-type control | | | | 7050A3672002.) REFER W/O 2011 485 007 |
| | | | | | | FOR DETAILS. |
| | | | | | | REFER AIRBUS HELICOPTER AIRFRAME |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 67-025R2 | Check the yaw ball-type control | 20/03/2012 | - | -/COMPLIED WITH | R2: COMPLIED WITH ON 20/03/2012 AT A/C |
| | | | | | | 2121.00FH. REAR PART SN-129, SN-119 |
| | | | | | | FITTED. REF.: ECM WO 2011 485 002 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67-026 | Yaw control - Improvement of the flexball control sealing | - | - | -/FOR INFO ONLY | |
| Standard SBs | 67A003 | To Provide Double Locking for the Attachment Pins of the Cyclic Pitch | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO SERIAL |
| | | Stick Yokes on the Torque Tube | | | | NUMBER GREATER THAN SN 1029 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 19 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|---------------|-----------|--|-----------|----------|-----------------|---|
| Standard SBs | 67A005 | Yaw Control Protection | - | - | -/COMPLIED WITH | COMPLIED WITH ON 24/01/2002 AT A/C 639.20FH. REFER AUSTRALIAN MODIFICATION BOOK. |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67A007 | Rotor Flight Control: Yaw Control Protection | - | - | -/COMPLIED WITH | COMPLIED WITH ON 24/01/2002 AT A/C 639.20FH. REFER AUSTRALIAN MODIFICATION BOOK. |
| Oten dead OD- | 674.000 | Listing Costin District Origin Transf | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67A008 | Limited Cyclic Pitch Control Stick Travel | - | - | -/COMPLIED WITH | COMPLIED WITH ON 25/07/2002 AT A/C 797.60 FH. REFER TO AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67A009 | Stiffening of Collective Pitch Lever Control | - | - | -/COMPLIED WITH | COMPLIED WITH ON 24/02/2003 AT A/C 988.50 FH. REFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67A010R3 | Introduction of Double Locking of Flight Control Stop Screws by Sealing the Screws | - | - | -/COMPLIED WITH | COMPLIED WITH ON 30/09/2003 AT A/C 1132.50 FH. REFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67A011R1 | New Thrust Washers for Cyclic Stick Friction | - | - | -/COMPLIED WITH | COMPLIED WITH ON 13/10/2004 AT A/C 1282.50 FH. RFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 20 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-----------|--|------------|----------|-----------------|--|
| Standard SBs | 67A014 | Collective Torque Tube Assembly | - | - | -/COMPLIED WITH | COMPLIED WITH ON 02/03/2004 AT A/C 1203.80 FH. REFER AUSTRALIAN MODIFICATION BOOK |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 67C013 | Replacement of Collective Lever Coupling Tube Assembly | - | - | -/OPTIONAL | |
| Standard SBs | 71-001 | Installation of the optional sand filter | - | - | -/OPTIONAL | |
| Standard SBs | 71-002 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 71-003 | Improvement of the Engine Mount | 24/02/2003 | - | -/COMPLIED WITH | COMPLIED ON 24/02/2003. REF.: VH-TRW NON-RECURRING AD, SPECIAL INSPECTION AND MODIFICATION CERTIFICATION LOG BOOK ONE PG.02 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 71-004 | Reserved | - | - | -/FOR INFO ONLY | |
| Standard SBs | 71-005 | Spring-type engine suspension system | - | - | -/OPTIONAL | |
| Standard SBs | 76-001 | Removal of the anticipator control regulating cam under the cargo compartment, following its integration in the governor by TURBOMECA, and replacement of the fuel flow flexible control sheath stop support | - | - | -/OPTIONAL | |
| Standard SBs | 76-002 | Marking of "ENGINE START" Position on Twist Grips | - | - | -/OPTIONAL | |
| Standard SBs | 76-003 | Modification of the Pilot's and Copilot's Twist Grip Centering Bush and Lubrication | - | - | -/OPTIONAL | |
| Standard SBs | 76-004 | Increased Rotor Speed Setting Range | 10/02/2007 | - | -/COMPLIED WITH | COMPLIED WITH ON 10/02/2207 AT A/C 1821.00FH. REF.: ECM WO 2007-060 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 76-007 | Modification to the setting of the twist grip locking pin | - | - | -/FOR INFO ONLY | |
| Standard SBs | 76-008 | Travel of the anticipator ball-type control | 07/04/2014 | - | -/COMPLIED WITH | COMPLIED ON 07/04/2014 AT A.C 2396.8FH. REF.: ECM WO# 2014 081 001 REFER HELISTAR AIRFRAME SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 76-009 | New anticipator ball-type control | | - | -/FOR INFO ONLY | |
| | 10 000 | | _ | | | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 21 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | | |
|--------------|--------------|--|------------|----------|------------------|--|
| Standard SBs | 76A005R1 | Replacement of the Twist Grip Drive Tube | - | - | -/NOT APPLICABLE | VERIFIED ON 08/05/2012 AT A/C 2133.10 FH |
| | | | | | | AND FOUND NOT APPLICABLE. RH TWIST |
| | | | | | | GRIP PN C761A2024102 SN 090, LH TWIST |
| | | | | | | GRIP PN C761A2025104 SN ILLIGIBLE |
| | | | | | | FITTED ON A/C. LH FOUND N/A TO |
| | | | | | | CONTROL BOX S/N AS PER APPENDIX 1 |
| | | | | | | OF ASB. CONTROL BOX SN 911 FITTED. |
| | | | | | | REF.: ECM W0#2011 485 007 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 76A006R2 | Check of the Twist Grip Drive Tube and Control Pinion Attachment | - | - | -/COMPLIED WITH | CARRIED OUT IAW PARA 2.B.4 ON |
| | | | | | | 08/05/2012 AT A/C 2133.10 FH. REFER ECM |
| | | | | | | WO #2011 485 007 |
| | | | | | | REFER HELISTAR AIRFRAME SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Engine SBs | | | | | | 1 |
| Standard SBs | A319 73 4001 | Periodic replacement, check or cleaning of privilege injector pipe | 05/04/2013 | - | -/COMPLIED WITH | COMPLIED WITH ON 05/04/2013 AT ENG. |
| | | | | | | 2277.80 H. REFER. ECM WO# 2013 182 001. |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4002 | Reduction of the check valve spring stiffness and min. Fuel Control Unit | - | - | -/FOR INFO ONLY | |
| | | adjusted at 29 l/h | | | | |
| Standard SBs | 319 72 4003 | Turbine casing. Inspection of the two P3 bleed air tapping bosses (for | | - | -/COMPLIED WITH | COMPLIED WITH BY TURBOMECA ON 30 |
| | | aircraft manufacturer's use) and of the FCU supply boss. | | | | MAR 2007 AT ENGINE TT 1828 HRS. |
| | | | | | | REFER TURBOMECA ENGINE LOG BOOK, |
| | | | | | | SECTION E, W/O MD61800 |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 319 73 4004 | Fuel Control Unit (FCU) Tf 4 :Modification of the anticipator cam | - | - | -/FOR INFO ONLY | |
| | | profile Tf 5 : Deletion of the stealth stop interface spacer of helicopter | | | | |
| | | flow control lever | | | | |
| Standard SBs | 319 72 4005 | Flame tube. Increased covering of the tab of the chamber bottom | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 73 4006 | Fuel Control Unit (FCU). Fireproof plates made of stainless steel | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4007 | Flame tube. Reduction of the injector guiding plate clearance | - | - | -/FOR INFO ONLY | |



SBS

| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 22 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due Interval/Status | Limitation Notes |
|--------------|--------------|--|-----------|--------------------------|-------------------------------------|
| Standard SBs | 319 72 4008 | Turbine casing. P3 boss for aircraft manufacturer's purpose provided | - | /FOR INFO ONLY | |
| | | with a blank and screws made of titanium. | | | |
| Standard SBs | 319 72 4009 | Reductor gearbox module. Assembly of "Magnetic Seal" joint on the the | - | /FOR INFO ONLY | · |
| | | starter-generator drive | | | |
| Standard SBs | 319 72 4010 | Reduction gear module. Installation of a "Magnetic Seal" type seal on | - | /FOR INFO ONLY | · |
| | | the main drive | | | |
| Standard SBs | 319 72 4011 | Module M01 (reduction gearbox). Torquemeter stop bearing with double | - | /FOR INFO ONLY | · |
| | | angular-contact | | | |
| Standard SBs | 319 72 4012 | Module M02 (gas generator). Gas generator stop SNFA bearing | - | /NOT APPLICABLE | NOT APPLICABLE DUE TO ENGINE POST |
| | | | | | TF 12. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | |
| | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4013 | Reserved | - | /FOR INFO ONLY | · |
| Standard SBs | 319 72 4014 | Module M01 (reduction gearbox). Installation of a magnetic seal on the | - | /FOR INFO ONLY | · |
| | | breather outlet | | | |
| Standard SBs | 319 75 4015 | Control P3 air pipe flanged to turbine casing | - | /FOR INFO ONLY | |
| Standard SBs | A319 75 4016 | Clamp securing the first section of the P3 pipe | - | /NOT APPLICABLE | NOT APPLICABLE DUE TO ENGINE POST |
| | | | | | TF16. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | |
| | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4017 | Fuel Control Unit (FCU). Limitation of axial clearance of slope stop | - | /FOR INFO ONLY | · |
| | | assembly. | | | |
| Standard SBs | 319 77 4018 | Pyrometric harness. Increased outer diameter of double | - | /FOR INFO ONLY | · |
| | | thermocouplestealth. | | | |
| Standard SBs | 319 72 4019 | Reduction gearbox module. Balancing of breather | - | /FOR INFO ONLY | · |
| Standard SBs | 319 72 4020 | Generator module. P3 air tapping jet for aircraft manufacturer's | - | /FOR INFO ONLY | · |
| | | purposes with a 8,5 mm diameter. | | | |
| Standard SBs | 319 72 4022 | M02. Increase of power turbine radial clearance | - | /FOR INFO ONLY | · |
| Standard SBs | 319 72 4023 | Air intake casing. Addition of 7 oil discharge holes on the gas generator | - | /FOR INFO ONLY | · |
| | | front bearing. | | | |
| Standard SBs | 319 73 4024 | Fuel Control Unit. Increase of the length of the threads of the slope stop | - | /FOR INFO ONLY | · |
| | | clevis / nut assembly. | | | |
| Standard SBs | 319 71 4025 | Separation of the rear wall and air intake grid. | - | /FOR INFO ONLY | · |
| Standard SBs | 319 72 4026 | M01 module (reductor gearbox).Addition of a sealing ensured by | - | /FOR INFO ONLY | , |
| | | preformed packing on the output gear. | | | |
| Standard SBs | 319 72 4027 | Gas generator module. Gas generator rear bearing with increasing min. | - | /FOR INFO ONLY | |
| | | axial clearance. | | | |
| Standard SBs | 319 73 4028 | FCU assembly. Preformed packings made of 61D6.29 Apr 2020 | - | /FOR INFO ONLY | , |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 23 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|-------------|---|-----------|----------|-----------------|--------------------------------|
| Standard SBs | 319 72 4029 | M02 module (gas generator). Air intake casing with built-in attachement | - | - | -/FOR INFO ONLY | · |
| | | flange for Tf 25A air intake grids. | | | | |
| Standard SBs | 319 72 4030 | M02 module (gas generator).Borescope port blanking with renforced | - | - | -/FOR INFO ONLY | , |
| | | flange. | | | | |
| Standard SBs | 319 72 4031 | Module M01 (reduction gearbox).Reduction gear front casing with large | - | - | -/OPTIONAL | TF31A TO BE EMBODIED UPON |
| | | link radius at the mating face of the torquemeter box cover. | | | | CUSTOMER REQUEST. |
| | | | | | | |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE |
| | | | | | | SERVICE BULLETIN COMPLIANCE |
| | | | | | | STATUS. |
| Standard SBs | 319 72 4032 | M01. Reduction gear front casing with large radius pitting at the bending | - | - | -/FOR INFO ONLY | |
| | | radius of the torquemeter box cover mating face | | | | |
| Standard SBs | 319 26 4033 | Extension of fire detection harness | - | | -/FOR INFO ONLY | |
| Standard SBs | 319 79 4034 | Oil system. BM 1030 electrical magnetic plug for the drain unit. | - | | -/FOR INFO ONLY | |
| Standard SBs | 319 79 4035 | Oil system. BR1091 oil drain pump. | - | | -/FOR INFO ONLY | |
| Standard SBs | 319 79 4036 | Oil system. BM 1030 rear bearing electrical magnetic plug. | - | - | -/FOR INFO ONLY | · |
| Standard SBs | 319 73 4037 | Check valve seat assembly attached by bondings and with screws. | - | - | -/CANCELLED | |
| Standard SBs | 319 72 4038 | Fuel Control Unit (FCU). Improved HP pump drain sealing ring. | - | - | -/FOR INFO ONLY | · |
| Standard SBs | 319 73 4039 | Fuel control unit (FCU). Adjustment of maximum flow for JP4 fuel. | - | - | -/FOR INFO ONLY | · |
| Standard SBs | 319 72 4040 | M02 module (gas generateor).Linkage between the rear bearing / | - | - | -/FOR INFO ONLY | · |
| | | bearing support / power turbine (PT) flange using underheard free-cut | | | | |
| | | screws. | | | | |
| Standard SBs | 319 72 4041 | M02 module (gas generator).Linkage between rear bearing/bearing | - | - | -/FOR INFO ONLY | , |
| | | support/power turbine (PT) flange using underhead free-cut screws and | | | | |
| | | crimped nuts. | | | | |
| Standard SBs | 319 72 4043 | M02 module (gas generator). Rear bear oil ducts with toleranced ends. | - | - | -/FOR INFO ONLY | · |
| Standard SBs | 319 72 4044 | M02 module (gas generator). Rear bearing C with increased diameter | - | - | -/FOR INFO ONLY | , |
| Standard SBs | 319 72 4045 | M02. Non-silver-plated mating face of power turbine nuts | - | - | -/FOR INFO ONLY | , |
| Standard SBs | 319 72 4046 | M02. Simplified turbine casing | - | - | -/FOR INFO ONLY | , |
| Standard SBs | 319 73 4050 | Fuel Control Unit (FCU). NTL flyweight shaft with "plasma coating". | - | - | -/FOR INFO ONLY | , |
| Standard SBs | 319 73 4051 | Fuel Control Unit (FCU). Acceleration slope adjustment support held in | - | - | -/FOR INFO ONLY | · |
| | | place by a cover. | | | | |
| Standard SBs | 319 72 4052 | M02. Laser drilled flame tube | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4053 | M02. Flame tube with prevaporizing tubes protected by | - | - | -/FOR INFO ONLY | |
| | | chromium/aluminium-plating and HP turbine cooling air scallops | | | | |
| Standard SBs | 319 73 4054 | Adjusted valve assembly. Start electro-valve with improved internal | - | - | -/FOR INFO ONLY | · |
| | | sealing. | | | | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 24 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | |
|--------------|-------------|---|-----------|----------|------------------|---|
| Standard SBs | 319 73 4055 | Fuel Control Unit (FCU). To ensure proper installation of constant delta P valve diaphragm. | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO FCU INSTALLED POST TF55. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4056 | Installation of a load bearing magnetic seal on the starter drive. | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4057 | Module M02 (gas generator).Centrifugal diffuser assembled by brazing on half-through valves. | - | - | -/COMPLIED WITH | COMPLIED WITH BY TURBOMECA ON 30 MAR 2007 AT ENGINE TT 1828 HRS. REFER TURBOMECA ENGINE LOG BOOK, SECTION E, W/O MD61800 |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4058 | Module M01 (reduction gearbox).Installation of a magnetic seal with a lift face on the breather outlet. | - | - | -/OPTIONAL | TF58 TO BE EMBODIED UPON CUSTOMER'S REQUEST REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 71 4059 | Air system. Air intake, half grids with opening to allow entry of borescope duct. | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4060 | Module M01 (reduction gearbox)Attaching screw of the fuel control unit adaptor. | - | - | -/COMPLIED WITH | COMPLIED WITH BY TURBOMECA ON 30 MAR 2007 AT ENGINE TT 1828 HRS. REFER TURBOMECA ENGINE LOG BOOK, SECTION E, W/O MD61800 REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4061 | Module M01 (reduction gearbox).Addition of a steel torquemeter stop. | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4062 | M02. Flame tube with prevaporizing tubes made of HS31 (KC25NW) and HP turbine cooling air scallops | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 73 4066 | Changes to the pressure-reducing valve cover attachment of the adjusted FCU. | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4069 | M02. Flame tube with prevaporizing tubes made of NC22FED, protected by chromium/aluminium-plating | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4070 | M02. Flame tube with prevaporizing tubes made of KC25NW | - | - | -/FOR INFO ONLY | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 25 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due Interval/Status | Limitation Notes |
|--------------|-------------|---|-----------|--------------------------|--|
| Standard SBs | 319 72 4071 | Module M02 (gas generator).Reinforced rings to hold turbine casing/rear bearing support/High Pressure Turbine (HPT) ring.Stopping of incorporation / Elimination of modification Tf 71A | - | /FOR INFO ONLY | |
| Standard SBs | 319 79 4075 | Lubrication unit. Check valve with seal-free piston. | - | /NOT APPLICABLE | NOT APPLICABLE DUE TO ENGINE POST TF75. REFER SAFRAN ENGINE LOG BOOK REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4076 | Module M02 (gas generator).Centrifugal diffuser assembled by brazing on through double vanes. | - | /OPTIONAI | TF76A TO BE EMBODIED WHEN REPLACEMENT OF M02 OR CENTRIFUGAL DIFFUSER IS CARRY OUT. REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4077 | Adjusted FCU assembly. Addition of an auxiliary delta P valve. | - | /NOT APPLICABLE | NOT APPLICABLE DUE TO FCU POST TF77 INSTALLED. REFER SAFRAN ENGINE LOG BOOK REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4078 | Module M01 (reduction gearbox).Output gear without damping ring. | - | /OPTIONAL | TF78 TO BE EMBODIED WHEN REPLACEMENT OF M01 IS CARRY OUT. REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4079 | Module M01 (reduction gearbox).Intermediate gear without damping ring. | - | /OPTIONAL | TF 79 TO BE EMBODIED WHEN REPLACEMENT OF M01 IS CARRIED OUT. REFER EUROCOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS |
| Standard SBs | 319 71 4080 | General system. Elimination of a possible interference between the right rear half-wall and the P3 pipe (first section). If post TF25 | - | /OPTIONAL | |
| Standard SBs | 319 71 4081 | Adjusted valve assembly cover.Interference between the adjusted valve assembly cover and the fuel pipes. | - | /CANCELLED | 5 |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 26 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|--------------|---|-----------|----------|------------------|--|
| Standard SBs | 319 72 4082 | Flame tube with change of material and addition of a ceramic coating at the bottom of the chamber | - | - | -/OPTIONAL | TO BE CALL OUT AT NEXT INSPECTION |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4083 | Fuel system. Part Numbers created for the right-hand and left-hand | | | -/OPTIONAL | |
| Stanuaru SDS | 51972 4005 | injector half-manifolds and the privilege injector pipe, which are specific | - | - | -/OF HONAL | |
| | | to the ARRIUS 2F variant. | | | | |
| Standard SBs | 319 72 4084 | Gas generator module. Improved squeeze film for the gas generator | | | | NOT APPLICABLE DUE TO ENGINE POST |
| Standard SBS | 319724084 | | - | - | -/NOT APPLICABLE | |
| | | front bearing.Application of modification Tf84 | | | | TF 12. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4085 | Introduction of insulating seals below the injector flange of both the | | - | -/CANCELLED | |
| otandara obs | 010 10 4000 | lefthand and righthand injector halfmanifold assemblies and the privilege | | | /O/WOLLED | |
| | | injector pipe assembly.Incorporation of modification Tf85. | | | | |
| Standard SBs | 319 26 4801 | To improve attachement of fire detection harness to fire detectors. | | | | COMPLIED WITH BY TURBOMECA ON 30 |
| Standard SDS | 010 20 4001 | Addition of RHODORSIL CAF 730 sealant | | | | MOR 2007 AT ENGINE TT 1828 HRS. |
| | | | | | | REFER TURBOMECA ENGINE LOG BOOK, |
| | | | | | | SECTION E, W/O# MD61800. |
| | | | | | | REFER EUROCOPTER ENGINE SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS |
| Standard SBs | A319 79 4802 | Lubrication unit. Replacement of check valve piston preformed | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO ENGINE POST |
| | | packing.Comments: If pre Tf 75 | | | | TF75. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4803 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4804 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4805 | Replacement procedure of the cooling ring | - | - | -/OPTIONAL | |
| Standard SBs | 319 72 4806 | Superseded by SB No. 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4807 | Procedure to replace the power turbine ring | - | - | -/OPTIONAL | |
| Standard SBs | A319 73 4808 | Fuel Control Unit. Increase of the max fuel flow "on site". | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO FCU PN |
| | | | | | | 0319878010 SN 47010 INSTALLED |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4809 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| | | | | | | 1 |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 27 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|--------------|---|-----------|----------|------------------|--|
| Standard SBs | 319 75 4810 | Inspection of clearance between the P3 air pipe (first section) and the | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO ENGINE POST |
| | | RH rear halfwall | | | | TF80. REFER SAFRAN ENG INE LOG BOOK |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE |
| | | | | | | BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4811 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4812 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4813 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4814 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4815 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4816 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4817 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4818 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4819 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4820 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4821 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | 319 72 4822 | Centrifugal diffuser vane check. | - | - | -/NOT APPLICABLE | N/A. MO2 S/N: 322 POST TF57A |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | A319 73 4823 | Check of correct position of adjusted FCU fuel filter. | - | - | -/COMPLIED WITH | COMPLIED WITH ENGINE 1470.0 FH . REFER ECM WO # 2005-026 |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4824 | Superseded by SB No. 319 72 4826 | - | - | -/RECOMMENDED | |
| Standard SBs | A319 73 4825 | Fuel control unit. Check and replacement of the constant delta P device diaphragm. | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO FCU PN 0319878010 SN 47010 INSTALLED |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 72 4826 | Deep Maintenance technical Instructions organized Into 2 (two) books. Comments:Book X 319 L6 351 2 Book X 319 L6 352 2 | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 73 4829 | Check of flow rate from fuel injection manifolds at a Service Station. Comments: Expired | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 72 4830 | Module M02 (gas generator).Inspection of the oil jet support of the | | | -/CANCELLED | |
| Stanuaru SBS | 319724030 | power turbine rear bearing assembly | - | - | -/CANGELLED | |



| Aircraft Registration: | 9M-GAS | Serial No: | 1089 | Date: 03/05/2023 | Page No: | 28 |
|------------------------|---------|------------|---------|-------------------|-----------|------|
| Aircraft Hours: | 3858:16 | Landings: | 5169.00 | Engine 1: 4621:54 | Engine 2: | 0:00 |

| Types | SB Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|--------------|--------------|---|-----------|----------|------------------|---|
| Standard SBs | 319 79 4831 | Lubrication unit. Inspection of jet bonding on ejector assembly | - | - | -/COMPLIED WITH | COMPLIED WITH ON 06 AUG 10 AT ENGINE TT 2054.2 HRS BY TURBOMECA PERSONNEL. REFER ENG LOG BOOK PG. E23. |
| | | | | | | REFER AIRBUS HELICOPTER ENGINE SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4832 | Replacement of post TF 77 regulator. Comments:SB expired after end of replacement and/or control of FCU. Restricted | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 79 4834 | Visual inspection of the drive-link splines of the lubricating device | - | - | -/COMPLIED WITH | COMPLIED DURING ENGINE RETURN TO REPAIR CENTRE ON 08/05/2015. REFER SAFRAN ENGINE LOG BOOK |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 79 4835 | Lubrication device. Check of the nozzle bonding on the ejector assembly. | - | - | -/NOT APPLICABLE | NOT APPLICABLE DUE TO COMPLIED WITH MSB 319 79 4831 VER.A ON 06/ 08/2010. REFER MYCAS-SBK-15-004 |
| | | | | | | REFER HELISTAR ENGINE#1 SERVICE BULLETIN COMPLIANCE STATUS. |
| Standard SBs | 319 73 4837 | Updating of the engine log book to extend the TBO of the ARRIUS 2F Pump and Metering Valve Assembly,Adjusted | - | - | -/OPTIONAL | |
| Standard SBs | 319 72 4838 | Updating of the engine log book to extend the TBO of the ARRIUS 2F Pump and Metering Valve Assembly, Adjusted | - | - | -/FOR INFO ONLY | |
| Standard SBs | 319 73 4839 | Return to service for civil operation of an ARRIUS 2 F or ARRIUS 2 R engine originating from an operator not controlled by a Civil Authority military, paramilitary, etc.) | - | - | -/OPTIONAL | |
| Standard SBs | 319 73 4846 | Creation of a configuration applicable to ARRIUS 2B1, 2B1A, 2B2, 2F, 2K1 and 2K2 turboshaft engines during overhaul | - | - | -/FOR INFO ONLY | |
| Standard SBs | MSB No. 1559 | GTN 650 and GTN 750 Notification of Mod Level 5. This service bulletin provides instructions to inspect and return affected GTN 650/750 units to Garmin for a Mod Level change. This service bulletin also provides optional instructions for marking Mod Level 5 on the nameplate (serial tag) of unaffected GTN 650/750 units. Mandatory for units listed in Table 2. This Service Bulletin must be accomplished by October 31st, 2016 | - | - | -/FOR INFO ONLY | |