

		_			-	
AIRCRAFT TYPE: 40		REG. NO: 9M-		DR. NO:	13	862/48
SOURCE REFERENCE	E: PRINC =	SB. No. 283	72R4 DT	011.12.17		
DATE RAISED: 0.	4.18	CHECK TYPE:		WORK ORDER	(JCN):L	856866
A/F HRS 345-16	O NO.1 ENG	3145-10	(TSN/ TSO)	NO.2 ENG 23	48.60	(TSN /TSO)
DISCREPANCY - P	PINC 38 N	2837284	DTD II. I	2.17 (CA	(E 1)	Paul Moo
SELECT SOLE	ENDID CMS	5)-SEALIN	G MSS	CAVITY W	ITH R	N(ATUCHE
				050	N	
RAISED BYMOHD	SHAZALIE R	AMLI SIGN & STA	MP: Pali	e PTRE	DATE	60.18
				CAM		
DISPOSITION	2011	16 NO 082	12VIL /	aubuan	医 N	ITH
10 CARRY O	an fincs	NO 202	1m (Cicipon		
SIGN:	etj	STAMP:	OAP 949 ASB		DATE:	18.10.01
MHP: N	1HA:	CUST. APP. SIGNATURE:	MATERIAL COST:			
CORRECTIVE ACTION				MECH	LA	AE/AH & DATE
PUCSBNO 28372R4 DTD 11.12.17					dr	000
					CH	elely
(CAT3) C/C	MI ANY C	owif Chery C	N POLA	AIC		QAP
FIMM NO11	MD NO. Z	ENGS AND		AJC 873 ASB		949 ASB
FONNY					h.	01.2018
FOUND: SANS	PACTORY!					01 2010
COMPONENT/ PAR	RT CHANGE					
PART NO.	DESCRI		S/NO. ON	S/NO. OFF	QTY.	BATCH NO.
3045896-05		GENENT MODIL		796 - (No.1		RE-BCC359
8063-863-01	FM M		13284627	- (NO.2	EXE)	RE-RO3CS
	,					.,
DUPLICATE / RII /	CRITICAL TASK					
N/A				NA		
First Insp. Sign / St	amp / Date		Second In	sp. Sign / Stam	p / Date	
		arried out in accor	lance with the	requirements of	the <	A 16
The work recorded						The second secon

Pratt & Whitney Canada Corp. 1000, Marie-Victorin Longueuil, Québec, Canada J4G 1A1 Tél. 450-677-9411



11 December 2017

P&WC S.B. No. 28372R4

REVISION TRANSMITTAL SHEET TURBOSHAFT ENGINE MODEL PW200

SUBJECT: Pratt & Whitney Canada Service Bulletin No. PW200-72-28372, Rev. No. 4, dated Dec 11/2017 (P&WC S.B. No. 28372R4) FUEL MANAGEMENT MODULE, MODE SELECT SOLENOID (MSS) - SEALING MSS CAVITY WITH RTV

Replace your existing copy of this service bulletin with the attached revised bulletin. Destroy the superseded copy.

Please retain this Revision Transmittal Sheet with the revised bulletin.

SUMMARY: This service bulletin is revised to correct the effectivity statement to add P/N 8063-856 and P/N 8063-1020 for PW206B3 engine in Para. 1.A., Effectivity.

EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT:

None.

NOTE: A black bar in the left margin indicates a change in that line of text or figure.

REVISION HISTORY:

Original Issue: Feb 09/2016 Revision No. 1: Apr 14/2016 Revision No. 2: Sep 09/2016 Revision No. 3: Oct 05/2017 Revision No. 4: Dec 11/2017

SERVICE BULLETIN

P&WC S.B. No. 28372R4

BULLETIN INDEX LOCATOR

TURBOSHAFT ENGINE

FUEL MANAGEMENT MODULE, MODE SELECT SOLENOID (MSS) - SEALING MSS CAVITY

WITH RTV

MODEL APPLICATION

PW206B, PW206B2, PW206B3, PW206C, PW207C, PW207D, PW207D1, PW207D2, PW207K

Compliance: CATEGORY 3

Summary: Field experience has shown that corrosion can occur in the Mode Select Solenoid

(MSS) because there is a path for fluids to reach the internal MSS electrical

compartment. Apply RTV sealant to seal the path to the MSS.

Feb 09/2016 Revision No. 4: Dec 11/2017

PW200-72-28372 Cover Sheet

24-Hour Global Service
CFIRST CENTRE
Toll free where available (SIL GEN-027)

 Other
 1-450-647-8000

 Fax
 1-450-647-2888

 Web Site
 www.pwc.ca

PRATT & WHITNEY CANADA SERVICE BULLETIN

P&WC S.B. No. 28372R4

TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE, MODE SELECT SOLENOID (MSS) - SEALING MSS CAVITY WITH RTV

Planning Information

Effectivity

Engines PW206B with Fuel Management Module (FMM) 8063-136, 8063-162, 8063-166, 8063-169, 8063-176, 8063-177, 8063-860, 8063-861, 8063-862 and 8063-865.

Engines PW206B2 with Fuel Management Module (FMM) 8063-853, 8063-856 and 8063-1020.

Engines PW206B3 with Fuel Management Module (FMM) 8063-856, 8063-1020.

Engines PW206C with Fuel Management Module (FMM) 8063-167, 8063-182, 8063-189, 8063-190, 8063-191, 8063-192, 8063-863, 8063-866 and 8063-1024.

Engines PW207C with Fuel Management Module (FMM) 8063-857 and 8063-1029.

Engines PW207D with Fuel Management Module (FMM) 8063-194, 8063-851 and 8063-1034.

Engines PW207D1 with Fuel Management Module (FMM) 8063-867 and 8063-1035.

Engines PW207D2 with Fuel Management Module (FMM) 8063-1035.

Engines PW207K with Fuel Management Module (FMM) 8063-858 and 8063-1037.

The above effectivity list does not identify engines that have been converted from one engine model to another via an engine conversion service bulletin. To clarify the effectivity of converted engines, refer to the original engine effectivity above. For the parts embodied during the engine conversion, refer to conversion service bulletin.

B. Concurrent Requirements

P&WC S.B. No. 28372 is superseded by P&WC S.B. No. 70019 for engine model PW207D2M.

C. Reason

(1) Problem

Field experience has shown that corrosion can occur in the Mode Select Solenoid (MSS). The reason is because there is a path for fluids to reach the internal MSS electrical compartment.

Cause (2)

The current MSS gasket is not optimized leaving a path for external fluids to reach the internal MSS electrical components.

(3) Solution

Apply RTV sealant to seal the path to the MSS.

D. Description

Clean and degrease the cavity under the Fuel Management Module (FMM) nameplate, apply RTV sealant to MSS cavity to seal the leakage path and re-identify the FMM.

P&WC No. DCR33856, DCR35487, EC-0003332

P&WC Proprietary Information. Subject to the restrictions on the back of the locator

PRINTED IN CANADA

The export control classification with respect to this document is contained on the back of the locator Feb 09/2016

Revision No. 4: Dec 11/2017 © 2016 Pratt & Whitney Canada Corp. PW200-72-28372 Page 1 of 8

SERVICE BULLETIN

P&WC S.B. No. 28372R4

TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE, MODE SELECT SOLENOID (MSS) - SEALING MSS CAVITY WITH RTV

1. Planning Information (Cont'd)

E. Compliance

- CATEGORY 3 For operators flying regularly over salt water or in a very humid environment (Tropical Climate), it is recommended to complete this SB within 150 flight hours from receipt of revision 3 of this service bulletin.
- CATEGORY 3 For all other operators, it is recommended to complete this SB within 600 flight hours from receipt of revision 3 of this service bulletin.

F. Approval

D.A.A. approved

G. Manpower

Once you have access to the part, an estimate of 1.0 man-hours is required to include this service bulletin at maintenance.

No more man-hours are necessary to include this service bulletin at overhaul.

H. Weight and Balance

None.

I. Electrical Load Data

Not changed.

J. Software Accomplishment Summary

Not applicable.

K. References

Woodward, Inc. Component Maintenance Manual 73-20-14 (WG 60090), 73-20-15 (WG 60093), 73-20-21 (WG 60103), 73-20-33 (WG 60194), 73-20-34 (WG 60195) and 73-20-35 (WG 60197)

Woodward SB 83092-73-016

L. Publications Affected

None.

M. Interchangeability and Intermixability of Parts

Not applicable.

P&WC Proprietary information. Subject to the restrictions on the back of the locator

Feb 09/2016

The export control classification with respect to this document is contained on the back of the local Revision No. 4: Dec 11/2017

Pw200-72-28372 Page 2 of 8