


EASA	AIRWORTHINESS DIRECTIVE					
	<p>AD No.: 2011-0127</p> <p>Date: 01 July 2011</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>					
<p>This AD is issued in accordance with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>						
<p>Type Approval Holder's Name :</p> <p>EUROCOPTER</p>		<p>Type/Model designation(s) :</p> <p>AS 365, EC 155, SA 365 and SA 366 helicopters</p>				
<p>TCDS Number: France No. 159</p>						
<p>Foreign AD: Not applicable</p>						
<p>Supersedure: This AD supersedes DGAC France AD F-2008-004 dated 04 June 2008.</p>						
ATA 63	Main Rotor Drive - Main Gearbox Casing – Inspection / Repair					
<p>Manufacturer(s): Eurocopter (formerly Eurocopter France, Aérospatiale)</p>						
<p>Applicability: EC 155 B, EC 155 B1, SA 365 N, SA 365 N1, AS 365 N2, AS 365 N3, SA 366 G1, SA 365 C, SA 365 C1, SA 365 C2 and SA 365 C3 helicopters, all serial numbers, if equipped with Main Gearboxes (MGB), as defined in table 1 hereunder:</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th style="text-align: center;">Table 1</th> </tr> </thead> <tbody> <tr> <td>MGB, all part numbers (P/N), delivered before 5 December 2007 (inclusive), or</td> </tr> <tr> <td>MGB, all P/N, installed on helicopters delivered before 5 December 2007 (inclusive); and</td> </tr> <tr> <td>MGB, all P/N, overhauled or repaired before 30 September 2008 (inclusive).</td> </tr> </tbody> </table>			Table 1	MGB, all part numbers (P/N), delivered before 5 December 2007 (inclusive), or	MGB, all P/N, installed on helicopters delivered before 5 December 2007 (inclusive); and	MGB, all P/N, overhauled or repaired before 30 September 2008 (inclusive).
Table 1						
MGB, all part numbers (P/N), delivered before 5 December 2007 (inclusive), or						
MGB, all P/N, installed on helicopters delivered before 5 December 2007 (inclusive); and						
MGB, all P/N, overhauled or repaired before 30 September 2008 (inclusive).						
<p>Reason: In 2008, two reports were received of atmospheric corrosion on the MGB casing lower area of two helicopters, between the two servo-control anchoring fitting attachment ribs.</p> <p>The investigation showed that initiation of corrosion in this area is due to a confined area under the anchoring fittings, associated with PR sealing compound on the lower part of the fitting/casing attachment.</p> <p>This PR sealing compound may have been applied on some helicopters due</p>						

	<p>to a misinterpretation of the EUROCOPTER documentation during installation.</p> <p>This condition, if not detected and corrected, could lead to crack initiation and crack growth in the affected area of the casing which could cause this area to fail and consequent loss of control of the helicopter.</p> <p>This unsafe condition, which is unrelated to design approval, was addressed in June 2008 by DGAC France AD F-2008-004.</p> <p>Later, in July 2008, EASA issued the EASA Airworthiness Directive Policy, (referenced C.Y001-01) which allowed the agency to issue Airworthiness Directives to address non-conformities of aircraft with the EASA approved design, due to manufacturing or maintenance deficiencies.</p> <p>For the reasons described above and in the frame of an EASA Airworthiness Directive Policy catch-up process for this type of Airworthiness Directives, this EASA AD supersedes DGAC France AD F-2008-004 retaining all its requirements although it does not introduce any new requirement.</p>
Effective Date:	15 July 2011
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) Within 15 Flight Hours (FH) after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], inspect all the lower parts of the MGB servo-control anchoring fittings to detect the presence of PR sealing compound in accordance with the instructions of paragraph 2.B.2. of EUROCOPTER EC 155 Alert Service Bulletin (ASB) No. 63A011 or AS 365 ASB No. 63.00.17 or SA 360/365 ASB No. 65.47, or SA 366 ASB No. 65.03, as applicable to helicopter type. (2) If, during the inspection required by paragraph (1) of this AD, PR sealing compound is found on any lower part of the MGB servo-control anchoring fittings, before next flight, inspect the affected area for corrosion in accordance with the instructions of paragraph 2.B.3. of EUROCOPTER EC155 ASB No. 63A011 or AS365 ASB No. 63.00.17 or EUROCOPTER SA360/365 ASB No. 65.47, EUROCOPTER SA366 ASB No. 65.03, as applicable to helicopter type. (3) If, during the inspection required by paragraph (2) of this AD, corrosion is found, within the compliance time indicated in Table 1 in Appendix 1 of this AD, as applicable, accomplish corrective actions in accordance with the instructions of paragraph 2.B.3. EUROCOPTER EC155 ASB No. 63A011 or AS365 ASB No. 63.00.17 or EUROCOPTER SA360/365 ASB No. 65.47, EUROCOPTER SA366 ASB No. 65.03, as applicable to helicopter type, and, depending on findings, accomplish a repair in accordance with EUROCOPTER Repair Sheet No. 365-63-36-08. (4) After 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], do not install MGB listed in Table 1 in Appendix 1 of this AD on a helicopter, unless in compliance with the inspections and corrective actions, if any, of paragraphs (1), (2) and (3) of this AD.
Ref. Publications:	<p>EUROCOPTER EC155 ASB No. 63A011 dated 7 May 2008.</p> <p>EUROCOPTER AS365 ASB No. 63.00.17 dated 7 May 2008.</p> <p>EUROCOPTER SA360/365 ASB No. 65.47 dated 5 May 2008.</p> <p>EUROCOPTER SA366 ASB No. 65.03 dated 7 May 2008.</p> <p>EUROCOPTER Repair Sheet No. 365-63-36-08 dated 4 April 2008.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>

Remarks :	<ol style="list-style-type: none">1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.2. This AD was posted on 05 May 2011 as PAD 11-045 for consultation until 02 June 2011. No comments were received during the consultation.3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail ADs@easa.europa.eu.4. For any question concerning the technical content of the requirements in this AD, please contact: EUROCOPTER (STDI) - Aéroport de Marseille Provence 13725 Marignane Cedex, France. Telephone +33 (0) 4 42 85 97 97, Fax +33 (0) 4 42 85 99 66. E-mail: Directive.technical-support@eurocopter.com.
-----------	---

APPENDIX 1

Table 1		
Helicopter operating conditions:	MGB operating time accumulated since new or since last complete overhaul:	Compliance time, in accumulated MGB operating time :
Helicopters that have been operated in one of the following conditions: <ul style="list-style-type: none"> - Helicopters based onboard a ship and operated off-shore, and/or - Helicopters operated less than 1 kilometre from the coast, and/or - Helicopters operated at low altitude (less than 1 000 feet) over the sea. 	Less than 30 months.	33 months.
	Between 30 and 33 months.	33 months, or within 3 months after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], without exceeding 55 FH after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004].
	More than 33 months.	Within 3 months after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], without exceeding 55 FH after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004].
All other helicopters	Less than 54 months.	60 months.
	Between 54 and 60 months.	60 months, or within 6 months after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], without exceeding 110 FH after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004].
	More than 60 months.	Within 6 months after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004], without exceeding 110 FH after 14 May 2008 [the effective date of the French superseded DGAC AD F-2008-004].