



Airworthiness Directive

AD No.: 2021-0027R1

Issued: 22 January 2021

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 355 helicopters

Effective Date: 03 February 2021 (same as original issue)

TCDS Number(s): EASA.R.146

Foreign AD: Not applicable

Revision: This AD revises EASA AD 2021-0027 dated 20 January 2021.

ATA 67 – Rotors Flight Control – Collective Controls / Protective Cover – Modification

Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter

Applicability:

AS 355 NP helicopters, all serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The ASB: AH Alert Service Bulletin (ASB) AS355-67.00.47.

Affected part: Pilot collective stick, having Part Number (P/N) 355A08-5376-00 (equipment manufacturer part number (MP/N) N2000383 or MP/N N2000383 Amd A).

Groups: Group 1 helicopters are those that have an affected part installed. Group 2 helicopters are those that do not have an affected part installed. A helicopter that has embodied AH modification (mod) 074930 in production is a Group 2 helicopter, provided the helicopter remains in that configuration.

Note 1: The affected part is not eligible for installation on other AS 355 helicopter models.



Reason:

Mechanical deformation was found on the protective cover (also referred to as switch guard) of the "SHEAR" control pushbutton installed on a co-pilot collective stick of an EC 225 LP helicopter. Incorrect handling was identified as the root cause for the deformation. Due to having an identical design switch guard installed, AS 355 NP helicopters may also be affected.

This condition, if not corrected, could lead to unintended shearing of the hoist cable, possibly resulting in injury to hoisted person(s).

To address this potential unsafe condition, AH developed mod 074930, introducing an improved protective cover for the "SHEAR" control pushbutton, and issued the ASB to provide modification instructions.

For the reason described above, this AD requires replacement of the protective cover of the "SHEAR" control pushbutton, and re-identification (new AH P/N 704A41110150 (MP/N 00016645AA or 00016645AA Amd A)) of the pilot collective stick. This AD also prohibits (re)installation of an affected part and the old design protective cover.

This AD is revised to correct and reduce the Applicability, and to amend the re-identification P/N in the Reason section.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Modification:

- (1) For Group 1 helicopters: Within the compliance time as specified in Table 1 of this AD, replace the protective cover of the "SHEAR" control pushbutton and re-identify the pilot collective stick in accordance with the instructions of the ASB.

Table 1 – Protective Cover Replacement / Collective Stick Re-identification

Helicopter Configuration	Compliance Time
"SHEAR" control associated with a hoist installation	Within 3 months after the effective date of this AD
"SHEAR" control not associated with a hoist installation	Within 12 months, or upon connecting the "SHEAR" control with a hoist installation, whichever occurs first after the effective date of this AD

Parts Installation:

- (2) Do not install on any helicopter a "SHEAR" control pushbutton protective cover P/N 700070 on the pilot collective stick, and do not install on any helicopter an affected part, as defined in this AD, as required by paragraph (2.1) or (2.2) of this AD, as applicable.

(2.1) For Group 1 helicopters: After modification of the helicopter as required by paragraph (1) of this AD.

(2.2) For Group 2 helicopters: From the effective date of this AD.



Ref. Publications:

AH ASB AS355-67.00.47 original issue dated 12 January 2021.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact Airbus Helicopters Customer Support by raising a Technical Event through the Technical Request Management tool accessible through the [AirbusWorld Portal](#) (Keycopter Technical Request Management); or send by E-mail: TechnicalSupport.Helicopters@airbus.com; Telephone +33 (0)4.42.85.97.89.

