	AIRWORTHINESS DIRECTIVE No F-2000-222-079 R1	Distribution: A	Issue date: September 15, 2004	Page : 1/2
	Direction générale de l'aviation civile France GSAC publication	This Airworthiness Directive is published by the DGAC on behalf of EASA, Airworthiness Authority of the State of Design for the affected product, part or appliance.		<i>Translation of « Consigne de Navigabilité » of same number. In case of difficulty, reference should be made to the French issue.</i>
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.				
Corresponding foreign Airworthiness Directive(s): Not applicable		Airworthiness Directive(s) replaced: 2000-222-079 original issue		
Person in charge of airworthiness: EUROCOPTER		Type(s): AS 350 helicopters		
Type certificate(s) No. 84 TCDS No 157				
ATA chapter: 05, 64	Subject: Tail rotor - Bearing spacer of the tail rotor head pitch change plate			

1. **EFFECTIVITY:**

AS 350 helicopters, versions B, B1, B2, B3, BA, BB and D, fitted with tail rotor pitch change rotating plates all part numbers, on which EUROCOPTER modification (MOD) 07 6554 has not been embodied.

This Airworthiness Directive (AD) does not apply to pitch change plate assembly part number 350A33-2030-00 (MOD 076550).

2. **REASONS:**

This AD is issued to prevent deterioration and loss of the tail rotor head (TRH) pitch change control.

Revision 1 of this AD covers referenced Revision 1 of EUROCOPTER AS 350 Alert Service Bulletin (ASB) No. 05.00.33, with no change to the technical content, but reducing the effectivity defined in paragraph 1 with reference to a modification.

3. **MANDATORY ACTIONS AND COMPLIANCE TIMES:**


The following measures are rendered mandatory as from the effective date of the original issue of this AD:

3.1. At the latest within 10 flying hours, identify the position of the spacer and the tail rotor pitch change rotating plate in compliance with the instructions given in paragraph 2.B.1. of referenced EUROCOPTER AS 350 ASB No. 05.00.33 R1.

3.2. At each check after the last flight of the day, check in compliance with the instructions given in paragraph 2.B.2. of the referenced ASB, that the paint index marks on the tail rotor pitch change rotating plate and on the spacer are aligned.

If the paint index marks are aligned, comply with the instructions described in paragraph 2.B.3. of the referenced ASB (embodiment of MOD 07 6554) at the latest during the next "T" basic inspection.

If the paint index marks are not aligned, comply with the instructions described in paragraph 2.B.4. of the referenced ASB (embodiment of MOD 07 6554) at the latest within 25 flying hours from detection of the misalignment.

	AIRWORTHINESS DIRECTIVE No F-2000-222-079 R1	Distribution: A	Issue date: September 15, 2004	Page: 2/2
---	---	---------------------------	--	---------------------

3.3. Before installing a pitch change plate assembly or a tail gear box assembly, held as spares, on an aircraft, comply with the instructions described in paragraph 2.B.3. of the referenced ASB (embodiment of MOD 07 6554).

4. REFERENCE PUBLICATION:

EUROCOPTER AS 350 Alert Service Bulletin No. 05.00.33 R1
(Any subsequent approved revision to this ASB is acceptable).

5. EFFECTIVE DATES:

Original issue : Upon receipt of telegraphic AD dated June 02, 2000
Revision 1 : September 25, 2004.

6. REMARK:

For any questions concerning the technical content of the requirements in this AD, please contact:

EUROCOPTER (STXI) – Aéroport de Marseille Provence, 13725 Marignane Cedex – France
Phone: +33 (0)4 42 85 97 97 – Fax: +33 (0)4 42 85 99 66
E-mail: Directive.technical-support@eurocopter.com

7. APPROVAL:

This AD Revision is approved under EASA reference No 2004-9369 dated September 07, 2004.