K	AIRWORTHINESS DIRECTIV No F-2002-606 R1			Distribution:	Issue date: March 02, 2005	Page : 1/2	
Direction générale de l'aviation	This Airworthiness Directive is published by the DGAC EASA, Airworthiness Authority of the State of Design for product, part or appliance.				Translation of « Consigne de Navigabilité » of same number. In case of difficulty, reference should be made to the French issue.		
civile France GSAC publication		No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.					
Corresponding foreign Airworthiness Directive(s):			Airwor	Airworthiness Directive(s) replaced:			
Not applicable			2002-	2002-606 original issue			
Person in charge of airworthiness: EUROCOPTER			, , ,	Type(s): EC 120 helicopters			
Type certificate(s) No. 189 TCDS No 189							
ATA chapter:		Subject:	<u> </u>				
67	Rotor flight controls - Collect			ive pitch le	ver		

1. **EFFECTIVITY**:

EC120 B helicopters with serial numbers below 1344.

Note: This Airworthiness Directive (AD) is intended for maintenance personnel and crews.

2. REASONS:

This AD is issued following a case of stiffening of the collective pitch lever control encountered in flight due to an increase of the friction factor of the friction mechanism pads.

The purpose of Revision 1 of this AD is to cover the conversion of EUROCOPTER EC 120 Alert Telex No. 67A009 into an Alert Service Bulletin (ASB) bearing the same reference number, with no change to the technical content. The effectivity according to the serial number of the helicopter is specified.

3. MANDATORY ACTIONS AND COMPLIANCE TIMES:

The following measures are rendered mandatory:

- **3.1.** For crews, as from the next flight following the effective date of the original issue of this AD, and until compliance is ensured with § 3.2. below:
 - Only slightly tighten the collective pitch lever friction,
 - If stiff operation is felt in flight with the collective pitch lever, loosen the collective pitch lever friction immediately.
- **3.2.** No later than within 110 flying hours or 3 months following the effective date of the original issue of this AD (the first limit reached is applicable), secure each pad + spherical bearing element to the lever using adhesive in compliance with the instructions specified in § 2.B.2.a. of referenced EUROCOPTER EC120 Alert Service Bulletin (ASB) No. 67A009.



AIRWORTHINESS DIRECTIVE No F-2002-606 R1

Distribution:

Α

Issue date:

March 02, 2005

Page: **2/2**

3.3. No later than within 110 flying hours or 13 months following compliance with the instructions specified in § 3.2. above (the first limit reached is applicable), check the bonding quality by complying once with the instructions specified in § 2.B.2.b. of the referenced ASB.

- **3.4.** Before installing a replacement friction mechanism on an aircraft, comply with the instructions specified in § 2.B.2.a. of the referenced ASB.
- **3.5.** No later than within 110 flying hours or 13 months following compliance with the instructions specified in § 3.4. above (the first limit reached is applicable), check the bonding quality by complying once with the instructions specified in § 2.B.2.b. of the referenced ASB.

4. REFERENCE PUBLICATION:

EUROCOPTER EC120 Alert Service Bulletin No. 67A009 (Any subsequent approved revision of this ASB is acceptable).

5. EFFECTIVE DATES:

Original issue: Upon receipt as from December 11, 2002

Revision 1 : March 12, 2005.

6. REMARK:

For any questions concerning the technical content of the requirements in this AD, please contact:

EUROCOPTER (STXI) - Aéroport de Marseille Provence, 13725 Marignane Cedex - France

Phone: +33 (0) 4 42 85 97 97 - Fax: +33 (0) 4 42 85 99 66 E-Mail: Directive.technical-support@eurocopter.com

7. APPROVAL:

This AD Revision is approved under EASA reference No 2005-1917 dated February 22, 2005.