

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

SERVICE BULLETIN

_{N°} 139-726

DATE: August 3, 2022

REV.: /

TITLE

ATA 31 - MODULAR AVIONIC UNIT (MAU) MARKING

REVISION LOG

First Issue



1. PLANNING INFORMATION

A. EFFECTIVITY

AW139 helicopters from S/N 41801 to S/N 41806.

B. COMPLIANCE

At Customer's option.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

This Service Bulletin is issued in order to provide the necessary instruction on how to mark the MAU P/N and S/N to be compliant to latest design.

E. DESCRIPTION

This Service Bulletin provides information on how to mark the P/N and S/N of the MAU in order to be compliant with the relative design.

The marking consists in modifying the MAU plates or in replacing them.

F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives. If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

G. MANPOWER

To comply with this Service Bulletin two (2) MMH are deemed necessary.

MMH are based on hands-on time and can change with personnel and facilities available.



H. WEIGHT AND BALANCE

N.A.

I. REFERENCES

1) PUBLICATIONS

Following Data Modules refer to AMP:

DATA MODULE			<u>DESCRIPTION</u>	<u>PART</u>	
	DM01	39-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance.	-	
	DM02	39-A-06-41-00-00A-010A-A	Access doors and panels - General data	-	

2) ACRONYMS & ABBREVIATIONS

AMDI Aircraft Material Data Information

AMP Aircraft Maintenance Publication

DM Data Module

DOA Design Organization Approval

EASA European Aviation Safety Agency

IPD Illustrated Part Data

LH Leonardo Helicopters

LH Leonardo Helicopters

MAU Modular Avionic Unit

MMH Maintenance Man Hours

P/N Part Number

S/N Serial Number

3) ANNEX

N.A.

J. PUBLICATIONS AFFECTED

N.A.

K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.

S.B. N°139-726 DATE: August 3, 2022

REVISION: /



2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

1) PARTS

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL NOTE	LOG P/N
1	3G4600A00622		MAU INSTALLATION	REF		-
2	3G4600A00137		MAU1 ASSY	REF		-
3	A148A001B1		Plate	1		-
4	3G4600A00235		MAU2 ASSY	REF		-
5	A148A001B1		Plate	1		-

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

2) CONSUMABLES

Refer to AMDI for the consumable materials required to comply with the AMP DM referenced in the accomplishment instructions.

3) LOGISTIC MATRIX

N.A.

B. SPECIAL TOOLS

N.A.

C. INDUSTRY SUPPORT INFORMATION

Configuration change.

S.B. N°139-726 DATE: August 3, 2022 REVISION: /

Page 4 of 7



3. ACCOMPLISHMENT INSTRUCTIONS

GENERAL NOTES

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- b) Let adhesive cure at room temperature for at least24 hours unless otherwise specified.
- 1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. In accordance with DM 39-A-06-41-00-00A-010A-A and with reference to Figure 1, remove all external panels, internal panels and internal liners as required to gain access to the area affected by the installation and perform MAU installation P/N 3G4600A00622 as described in the following procedure:
 - 2.1 With reference to Figure 1 perform MAU1 assy P/N 3G4600A00137 installation as described in the following procedure:

NOTE

Perform the following step only if the old plate is NOT to be replaced with the new one.

2.1.1 With reference to Figure 1 View B, mark the new P/N 3G4600A00137 and mark the S/N of the installed MAU followed by "/1" on the existing plate.

NOTE

Perform the following steps from 2.1.2 thru 2.1.4 only if the old plate needs to be replaced with the new one.

- 2.1.2 With reference to Figure 1 View B, remove the existing plate from the MAU cabinet.
- 2.1.3 With reference to Figure 1 View B, install the plate P/N A148A001B1 on the MAU cabinet.
- 2.1.4 With reference to Figure 1 View B, record the P/N 3G4600A00137 and the S/N of the installed MAU followed by "/1" on the new plate P/N A148A001B1.

S.B. N°139-726 DATE: August 3, 2022

REVISION: /



2.2 With reference to Figure 1 perform MAU2 assy P/N 3G4600A00235 installation as described in the following procedure:

NOTE

Perform the following step only if the old plate is NOT to be replaced with the new one.

2.2.1 With reference to Figure 1 View D, mark the new P/N 3G4600A00235 and mark the S/N of the installed MAU followed by "/1" on the existing plate.

NOTE

Perform the following steps from 2.2.2 thru 2.2.4 only if the old plate needs to be replaced with the new one.

- 2.2.2 With reference to Figure 1 View D, remove the existing plate from the MAU cabinet.
- 2.2.3 With reference to Figure 1 View D, install the plate P/N A148A001B1 on the MAU cabinet.
- 2.2.4 With reference to Figure 1 View D, record the P/N 3G4600A00235 and the S/N of the installed MAU followed by "/1" on the new plate P/N A148A001B1.
- 3. In accordance with AMP DM 39-A-06-41-00-00A-010A-A re-install all external panels, internal panels and liners previously removed.
- 4. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
- 5. Send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

As an alternative, gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

S.B. N°139-726 DATE: August 3, 2022 REVISION: /






Figure 1

S.B. N°139-726 DATE: August 3, 2022 REVISION: /



Please send to the followi	SERVICE BULLETIN COMPLIANCE FORM			Date:		
LEONARDO S.p.	A.					
CUSTOMER SUPPORT & SE	Number:					
PRODUCT SUPPORT ENGINEE	RING & LICENSES DEPT.					
Via Giovanni Agusta, 520 21017 Cascina Costa di Samara	Revision:					
Tel.: +39 0331 225036 Fax: +39						
Customer Name and Addre			Telephone:			
		Fax:				
				B.T. Compliance Date:		
Helicopter Model	S/N		Total N	umber	Total Hours	T.S.O.
Remarks:						
Information:						
We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in						

Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.