

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

SERVICE BULLETIN

_{N°} 189-304

DATE: October 25, 2021

REV.: /

TITLE

ATA 46 - CABIN PC APPLICATION SOFTWARE RELEASE 1.6.3 INSTALLATION

REVISION LOG

First Issue



1. PLANNING INFORMATION

A. EFFECTIVITY

All AW189 helicopters equipped with mission console system kit P/N 8G4620F00211 or P/N 8G4620F00411 and Avionic Software Phase 5 or Phase 6.

B. COMPLIANCE

Within 1 year after the issue of this Service Bulletin.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of Cabin PC application software release 1.6.3.

E. DESCRIPTION

This Service Bulletin provides instructions on how to upload the new cabin PC software release 1.6.3 on all helicopters equipped with software release Phase 5.0 or software release Phase 6.0.

The Cabin PC application software 1.6.3 has been released by LHD to fix some bug reported by Customers during the in-service operations.

The new software introduces also the functionality to manage a different optional Direction Finder (DF) P/N 938-00.

F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives. If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

S.B. N°189-304 DATE: October 25, 2021

REVISION: /



G. MANPOWER

To comply with this Service Bulletin two (2) MMH are deemed necessary.

MMH are based on hands-on time and can change with personnel and facilities available.

H. WEIGHT AND BALANCE

N.A

I. REFERENCES

1) PUBLICATIONS

Following Data Modules refer to AMP:

DATA	MODULE	<u>DESCRIPTION</u>	<u>PART</u>	
DM01	89-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance.	-	
DM02	89-B-46-22-06-00A-750A-A	Cabin PC - Load software procedure.	-	
DM03	89-A-46-32-03-00A-750A-B	Cabin PC - Load software procedure.	-	

2) ACRONYMS & ABBREVIATIONS

AMDI	Aircraft Material Data Information
AMP	Aircraft Maintenance Publication
DM	Data Module
DOA	Design Organization Approval
EASA	European Aviation Safety Agency
IPD	Illustrated Part Data
LHD	Leonardo Helicopters Division
MMH	Maintenance Man Hours
P/N	Part Number
S/N	Serial Number

3) ANNEX

N.A.

J. PUBLICATIONS AFFECTED

N.A.

S.B. N°189-304

DATE: October 25, 2021

REVISION: /



K. SOFTWARE ACCOMPLISHMENT SUMMARY

Software to be updated:

Cabin PC application software release 1.6.3 P/N 8G4620FS0106.

S.B. N°189-304 DATE: October 25, 2021 REVISION: /



2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

1) PARTS

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL	NOTE	LOG P/N	
1	8G4620FS0106		Cabin PC application software release 1.6.3	1		(1)	-	_

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

2) CONSUMABLES

N.A.

3) LOGISTIC MATRIX

N.A.

NOTE

(1) This software will not be supplied; it will be available, along with relevant certification document, in "My Software" sub-section of Leonardo AW Customer Portal website https://leonardo.agustawestland.com.

B. SPECIAL TOOLS

Refer to ITEP for the special tools required to comply with the AMP DM referenced in the accomplishment instructions.

C. INDUSTRY SUPPORT INFORMATION

WARRANTY: Owners/Operators who comply with the instructions of this Service Bulletin no later than the applicable date in the "Compliance" section will be eligible to receive necessary replacements on free of charge basis, except for Consumable Materials and Special Tools.

NOTE: Customers who fail to comply with the instructions in this Service Bulletin before the compliance date are not eligible for the aforementioned special policy.

Please Issue relevant MMIR form to your Warranty Administration Dpt.

S.B. N°189-304

DATE: October 25, 2021

REVISION: /



3. ACCOMPLISHMENT INSTRUCTIONS

GENERAL NOTES

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- 1. In accordance with DM 89-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.

NOTE

Perform the following step only if the helicopter is equipped with mission console system kit P/N 8G4620F00211.

2. In accordance with AMP DM 89-A-46-32-03-00A-750A-B perform the Cabin PC application software P/N 8G4620FS0106 installation.

NOTE

Perform the following step only if the helicopter is equipped with mission console system kit P/N 8G4620F00411.

- 3. In accordance with AMP DM 89-B-46-22-06-00A-750A-A perform the Cabin PC application software P/N 8G4620FS0106 installation.
- 4. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
- 5. Send the attached compliance form to the following mail box:

engineering.support.lhd@leonardocompany.com

As an alternative, gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

S.B. N°189-304 DATE: October 25, 2021 REVISION: /

Page 6 of 6



Please send to the followi	SERVICE BULLETIN COMPLIANCE FORM			Date:		
LEONARDO S.p.						
CUSTOMER SUPPORT & SE	Number:					
PRODUCT SUPPORT ENGINEE	RING & LICENSES DEPT.					
Via Giovanni Agusta, 520 21017 Cascina Costa di Samara	ate (VA) - ITALY	Revision:				
Tel.: +39 0331 225036 Fax: +39						
Customer Name and Addre	ess:			Telephone:		
				Fax:		
				B.T. Compliance Date:		
Helicopter Model	S/N		Total Number		Total Hours	T.S.O.
Remarks:						
Information:						
We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in						

Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.