
SERVICE BULLETIN

N° 139-724

ALERT

DATE: July 27, 2022

REV. : A - September 19, 2022

TITLE

ATA 64 – TAIL ROTOR DAMPER BRACKET INSPECTION

REVISION LOG

Rev. A of this Service Bulletin is issued in order to extend its effectivity to every S/N of the P/N 3G6420A06131.

Revision bars identify changes.

An appropriate entry should be made in the aircraft log book upon accomplishment.
If ownership of aircraft has changed, please, forward to new owner.

1. PLANNING INFORMATION

A. EFFECTIVITY

All tail rotor damper bracket assemblies P/N 3G6420A06131.

B. COMPLIANCE

- Within and not later than fifty (50) FH or two (2) months, whichever comes first, after the issue date of this Service Bulletin.
- Every fifty (50) FH or six (6) months, whichever comes first, after first accomplishment.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

This Service Bulletin is issued in order to prescribe a recurrent detailed inspection of the tail rotor damper bracket P/N 3G6420A06131.

E. DESCRIPTION

Due to some events of cracks on the TR damper bracket recorded in service, this Service Bulletin prescribes a recurrent detailed inspection of the TR damper bracket P/N 3G6420A06131 in order to detect potential cracks and corrosion. If cracks are found, it is required the immediate replacement of the component. Then, the recurrent inspection is still required.

F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives. If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

G. MANPOWER

To comply with this Service Bulletin, if bracket replacement is required, approximately eight (8) MMH are deemed necessary; otherwise approximately one (1) MMH is required to perform the inspection.

MMH are based on hands-on time and can change with personnel and facilities available.

H. WEIGHT AND BALANCE

N.A.

I. REFERENCES

1) PUBLICATIONS

Following Data Modules refer to AMP:

| <u>DATA MODULE</u> | <u>DESCRIPTION</u> | <u>PART</u> |
|-------------------------------|--|-------------|
| DM01 39-A-00-20-00-00A-120A-A | Helicopter on ground for a safe maintenance. | - |
| DM02 39-C-64-21-02-00A-520A-A | Lag damper – remove procedure | - |
| DM03 39-A-64-21-01-00A-530A-B | Tail rotor head - Disassemble procedure | - |
| DM04 39-A-64-21-01-00A-710A-B | Tail rotor head - Assemble procedure | - |
| DM05 39-C-64-21-02-00A-720A-A | Lag damper - Install procedure | - |

Following Data Modules refer to CSRP:

| <u>DATA MODULE</u> | <u>DESCRIPTION</u> | <u>PART</u> |
|---------------------------------|---|-------------|
| DM06 CSRP-A-51-21-06-00A-644A-D | Chromate conversion treatments of aluminum alloys - Chromate. | - |

2) ACRONYMS & ABBREVIATIONS

| | |
|------|------------------------------------|
| AMDI | Aircraft Material Data Information |
| AMP | Aircraft Maintenance Publication |
| AR | As Required |
| CSRP | Common Structural Repair Procedure |
| DM | Data Module |
| DOA | Design Organization Approval |
| EASA | European Aviation Safety Agency |
| FH | Flight Hours |
| IPD | Illustrated Part Data |
| LH | Leonardo Helicopters |

| | |
|-----|-----------------------|
| MMH | Maintenance Man Hours |
| P/N | Part Number |
| S/N | Serial Number |
| TR | Tail Rotor |

3) ANNEX

N.A.

J. PUBLICATIONS AFFECTED

AW139 AMP.

K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.

2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

1) PARTS

| # | P/N | ALTERNATIVE P/N | DESCRIPTION | Q.TY | LVL | NOTE | LOG P/N |
|---|--------------|-----------------|-----------------------------------|------|-----|------|---------|
| 1 | 3G6420A06131 | | Tail Rotor damper bracket assy | AR | . | (1) | - |

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

2) CONSUMABLES

The following consumable materials, or equivalent, are necessary to accomplish this Service Bulletin:

| # | SPEC./LHD CODE NUMBER | DESCRIPTION | Q.TY | NOTE | PART |
|---|--|--------------------------|------|------|------|
| 2 | Commercial | Scotch Brite (C015) | AR | (2) | |
| 3 | MIL-DTL-81706, Class 1A & 3, Form II | Alodine 1200 (C237) | AR | (2) | |
| 4 | CCC-C-440, Class I | Cheesecloth (C028) | AR | (2) | |
| 5 | P-D-680, Type II or MIL-PRF-680B, Type II | Cleaning solvent (C010) | AR | (2) | |
| 6 | TT-N-95-B Code No. 531055030 | Aliphatic Naphtha (C059) | AR | (2) | |

Refer also to AMDI for the consumable materials required to comply with the AMP DM referenced in the accomplishment instructions.

3) LOGISTIC MATRIX

N.A.

NOTES

- (1) The quantity of TR damper brackets to be ordered depends on the results of the inspection.
- (2) Item to be procured as local supply.

B. SPECIAL TOOLS

The following special tools, or equivalent, are necessary to accomplish this Service Bulletin:

| # | P/N | DESCRIPTION | Q.TY | NOTE | PART |
|----|---|---------------------------------------|------|------|------|
| 7 | RMGE-SL-06-2010-RH or approved alternative | Platform right (GG-02-00) | 1 | (B1) | |
| 8 | Commercial | Magnifying glass (10 power) | 1 | (B1) | |
| 9 | Commercial | Light source (fluorescent)/Flashlight | 1 | (B1) | |
| 10 | Commercial | Mirror | 1 | (B1) | |

Refer also to ITEP for the special tools required to comply with the AMP DM referenced in the accomplishment instructions.

SPECIAL TOOLS NOTE

(B1) Item to be procured as a local supply.

C. INDUSTRY SUPPORT INFORMATION

As reported in step 9, only if Product Support Engineering confirms the replacement, please Issue relevant MMIR form to your Warranty Administration Dpt.

Please note that “Product Support Engineering’s approvals” is mandatory to evaluate your request, otherwise MMIR could be rejected.

Owners/Operators who comply with the instructions of this Service Bulletin no later than the applicable date in the “Compliance” section will be eligible to receive required materials on free of charge basis, except for Consumable Materials and Special Tools.

NOTE: Customers who fail to comply with the instructions in this Service Bulletin before the compliance date are not eligible for the aforementioned special policy.

Please Issue relevant MMIR form to your Warranty Administration Dpt.

3. ACCOMPLISHMENT INSTRUCTIONS

GENERAL NOTES

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later re-use.
 - b) Exposed thread surface and nut must be protected using a layer of tectyl according to MIL-C-16173 grade I.
 - c) All lengths are in mm.
1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
 2. Put the platform (GG-02-00), or an approved alternative, adjacent to the right side of the fuselage.

NOTE

The procedure described in steps 3 thru 8 has to be performed on all the TR damper brackets P/N 3G6420A06131.

3. With reference to Figure 1, gain access to the component P/N 3G6420A06131 object of the inspection.
4. With reference to Figure 1 (View A) perform a detailed inspection for cracks and for corrosion of the TR damper bracket P/N 3G6420A06131 in accordance with the following procedure:
 - 4.1 Properly illuminate the area to be inspected (using a flash light, a mirror and a magnifying glass 10 power).
 - 4.2 Clean the area to be inspected with the Cheesecloth (C028) and the Aliphatic naphtha (C059) or Cleaning solvent (C010).

NOTE

Refer to Figure 2 for an example of the cracks that might be found during the inspection.

- 4.3 With reference to Figures 1 and 2, accurately examine the surface of the bracket, paying particular attention to the area around the four holes.

NOTE

Before issuing any request, in case of findings, contact
Product Support Engineering
(engineering.support.lhd@leonardo.com) to report
about the results of the inspections required and send
photos of the cracks.

NOTE

It is NOT needed to remove the Tail Rotor Head in order
to replace the TR damper bracket.

5. In case of cracks replace the TR damper bracket P/N 3G6420A06131 according to the following procedure:
 - 5.1 In accordance with the applicable steps of AMP DM 39-A-64-11-02-00A-520A-A disconnect the blade damper attachment assy P/N 3G6410A00831 from the blade assy (without removing the lag damper from the damper attachment assy).
 - 5.2 In accordance with applicable steps of AMP DM 39-A-64-21-01-00A-530A-B disconnect the damaged TR damper bracket assy from the tail rotor head (without removing the lag damper from the damper bracket).
 - 5.3 Place the removed assy (made of lag damper, damper bracket and damper attachment) on a proper work table and, in accordance with the applicable steps of AMP DM 39-C-64-21-02-00A-520A-A, disconnect the elastomeric damper from the TR damper bracket to be replaced.
 - 5.4 Replace the damper bracket P/N 3G6420A06131 with a new one and discard the damaged one.
 - 5.5 In accordance with the applicable steps of AMP DM 39-C-64-21-02-00A-720A-A, reconnect the new TR damper bracket to the elastomeric damper previously disconnected.
 - 5.6 In accordance with the applicable steps of AMP DM 39-A-64-21-01-00A-710A-B (hub side) and with the applicable steps of AMP DM 39-A-64-11-02-00A-720A-A (blade side) reconnect the damper bracket to the rotor hub and the damper attachment to the blade assy.

CAUTION

During polish operation with the Scotch Brite (C015) on the area to be examined, make sure that you follow the subsequent precautions:

- The Scotch Brite must be used only in the direction of the circumference of each bracket eyelet (ref. to Fig. 2 “polishing direction”);
 - The Scotch Brite must be used only with your hands.
6. If no cracks are found, but suspected evidences of corrosion signs are found, gently polish the interested area with a very light Scotch Brite (C015).
 7. After polishing, examine the bracket:
 - 7.1 If, after polishing, the suspected signs of corrosion are no longer evident, treat the component with alodine or equivalent in accordance with CSRP DM CSRP-A-51-21-06-00A-644A-D.

NOTE

Before issuing any request, in case of findings, contact Product Support Engineering (engineering.support.lhd@leonardo.com) to report about the results of the inspections required and send photos of the corrosion.

NOTE


It is NOT needed to remove the Tail Rotor Head in order to replace the TR damper bracket.

- 7.2 If the signs of corrosion are confirmed, replace the TR damper bracket P/N 3G6420A06131 according to the following procedure:
 - 7.2.1 In accordance with the applicable steps of AMP DM 39-A-64-11-02-00A-520A-A disconnect the blade damper attachment assy P/N 3G6410A00831 from the blade assy (without removing the lag damper from the damper attachment assy).
 - 7.2.2 In accordance with applicable steps of AMP DM 39-A-64-21-01-00A-530A-B disconnect the damaged TR damper bracket assy from the tail rotor head (without removing the lag damper from the damper bracket).
 - 7.2.3 Place the removed assy (made of lag damper, damper bracket and damper attachment) on a proper work table and in accordance with the applicable steps of AMP DM 39-C-64-21-02-00A-520A-A, disconnect the elastomeric damper from the TR damper bracket to be replaced.

- 7.2.4 Replace the damper bracket P/N 3G6420A06131 with a new one and discard the damaged one.
 - 7.2.5 In accordance with the applicable steps of AMP DM 39-C-64-21-02-00A-720A-A, reconnect the new TR damper bracket to the elastomeric damper previously disconnected.
 - 7.2.6 In accordance with the applicable steps of AMP DM 39-A-64-21-01-00A-710A-B (hub side) and with the applicable steps of AMP DM 39-A-64-11-02-00A-720A-A (blade side) reconnect the damper bracket to the rotor hub and the damper attachment to the blade assy.
8. Repeat the steps from 4 thru 7 for the other TR damper brackets P/N 3G6420A06131.
 9. In case of findings, contact Product Support Engineering (engineering.support.lhd@leonardo.com) to report about the results of the inspections required and send photos of the cracks and/or corrosion.
 10. Remove the platform from the right fuselage side.
 11. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
 12. Send the attached compliance form to the following mail box:


engineering.support.lhd@leonardo.com

As an alternative, gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".



VIEW A

Figure 1



POLISHING DIRECTION

Figure 2

S.B. N°139-724 ALERT
DATE: July 27, 2022
REVISION: A - September 19, 2022

| | | | | |
|---|-----|---|-------------|--------|
| Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988 | | SERVICE BULLETIN COMPLIANCE FORM | | Date: |
| | | Number: | | |
| | | Revision: | | |
| Customer Name and Address: | | Telephone: | | |
| | | Fax: | | |
| | | B.T. Compliance Date: | | |
| Helicopter Model | S/N | Total Number | Total Hours | T.S.O. |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Remarks: | | | | |
| Information: We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given. | | | | |