

HELICOPTERS



No. EC155-00-002

Civil version(s): B, B1

# Introduction - SERVICE BULLETIN

### **Reason for last Revision:**

The purpose of revision 3 of this document is to add the information about the new format of the Service Bulletin introduced in 2023.

Export Control: US Export Control - No US content. This Item does not contain any U.S. origin ITAR or EAR content. FR Export Control - Not Listed. This Item is not listed against the EC regulations in the EU/FR. Revision 0 2010-06-07 Page 1/28 Revision 3 2023-12-12 This document is available on the Internet: www.airbushelicopters.com/techpub/

Export Control: US\_EC\_NoUScontent - FR\_EC\_NotListed

### 1. AIM OF THIS DOCUMENT

The aim of document No. 00-002 is to improve understanding and to explain the rules governing ALERT SERVICE BULLETINS (ASBs), Service Bulletins (SBs) and Temporary Technical Instruction (TTI).

The document No. 00-002 give information about the new layout of the document not describe in the document No. 00-001.

The aims of this document are:

- To define the purpose of these three types of documents and their methods of issue.
- To detail their structure paragraph by paragraph and specify the information specific to each of them.
- To introduce the modifications implemented for harmonization.

### 1.1. **DEFINITIONS**

L

I

ASBs, SBs are technical notices drafted by the helicopter manufacturer, aimed at ensuring of continued airworthiness of helicopters, optimizing their operational availability, improving their mission capabilities and reducing their operating costs.

To that effect, they provide instructions about:

- New one-time.
- Operating limits.
- Helicopter modifications.

- Etc.

ASBs and SBs are intended both for civil operators and military operators.

In the past, TDs were intended only for instructions to be applied by some military operators. They were also used to define instructions to be applied only by Airbus Helicopters technicians.

### 1.2. SERVICE BULLETIN MANUAL

There is a Service Bulletin manual for each type of helicopter. It contains:

- An index: that lists all the Service Bulletins (ASBs, SBs and TTIs)
- All the Service Bulletins (ASBs, SBs and TTIs) that are published by Airbus Helicopters. Note : Some documents are not published in the Service Bulletin manual for confidential reason.

### 1.3. PURPOSE

Service Bulletins provide a unique source to inform customers of new instructions, notably in the following cases:

- Checks/inspections to ensure the fail-safety of a helicopter and its equipment:
  - Periodic checks/inspections required to detect an incipient malfunction.
  - One-time checks/inspections to detect a manufacturing non-conformity or deterioration in service.
  - Checks/inspections to be carried out pending implementation of a possible corrective action (modification) via a new Service Bulletin which will give the instructions enabling this modification to be embodied.
- Addition of limitations or restrictions on existing limitations.



- Replacement of one part with another, when the replacement is considered sufficiently urgent or critical that a special implementation schedule is required.
- Modifications made to the helicopter or to the equipment, including integrated software, affecting the performance, improving reliability, increasing fail-safety, increasing cost savings or facilitating maintenance or use.
- Modifications affecting the interchangeability or mixability of parts.
- Installation of optional equipment or a customized installation.
- End of manufacture or finalization of an installation directly on the helicopter.
- Version transformation.
- Helicopter completions.
- Behavior follow-up of new definitions on specific helicopters.



### 2. TYPES OF SERVICE BULLETINS

There are several types of Service Bulletins as described below.

### 2.1. ALERT SERVICE BULLETINS (ASB)

ALERT SERVICE BULLETINS provide instructions linked to continued Airworthiness/Helicopter Safety. Compliance with these ALERT SERVICE BULLETINS is:

- MANDATORY, when covered by an "European Union Aviation Safety Agency (EASA)" Airworthiness Directive. In that case, it means that the introduced measures relate to an unsafe condition.
- REQUIRED, when the safety concern described is not expected to be mandated by any Airworthiness Directive but AIRBUS HELICOPTERS requires implementation of the defined measures.

### <u>NOTE</u>

Since revision 3 of this document, ESSENTIAL" compliance is replaced with "REQUIRED" compliance..

The "Compliance" paragraph always specifies a deadline.

Mandatory ALERT SERVICE BULLETINS are usually covered by an "EASA" Airworthiness Directive. They can also be covered by the aviation authorities in charge of airworthiness of other countries.

#### a) Introduction of mandatory protective measures

An ALERT SERVICE BULLETIN is issued:

- When a technical event occurs which is likely to lead to an "unsafe condition" (an incident classified as an airworthiness incident in accordance with the Part 21 definition).
- When a non-conformity is discovered with respect to the certification regulations which could lead to an "unsafe condition".
- When a technical event occurs which does not lead to an "unsafe condition" but which could force the pilot(s) to apply an emergency procedure that is difficult to perform.

These ALERT SERVICE BULLETINS must be complied at once or periodically, in accordance with the specified compliance limits, or until a modification is embodied. These ALERT SERVICE BULLETINS must also be complied to the Master Servicing Manual (MSM).

#### "EMERGENCY" classification:

When the compliance limit is at short notice following receipt of the document (usually less than 50 hours or 1 month), the ASB includes the "EMERGENCY" classification and is subject to a rapid issuing procedure.

b) Introduction of mandatory corrective measures

A corrective measure usually corresponds to the embodiment of a modification to the definition. It is introduced by an ALERT SERVICE BULLETIN following a technical event that can, or cannot, lead to an "unsafe condition" for which the protective measures are complex and difficult to apply, or when only the embodiment of a modification can restore the required safety level.

It can also concern a return to conformity with respect to the certification regulations when the non-conformity can lead to an "unsafe condition" or to forced application of an emergency procedure that is difficult to perform.

c) Introduction of required corrective measures

A required corrective measure usually corresponds to the embodiment of a modification to the definition. It is introduced by an ALERT SERVICE BULLETIN following a technical event that does not lead to an "unsafe condition.

### 2.2. SERVICE BULLETINS (SBs)

Service Bulletins introduce:

- Protective measures following an incident that does not lead to an "unsafe condition".
- Modifications (corrective measures or improvement of the product).
- Installation of optional equipment.
- Conversions.
- Contract.
- a) Introducing non-mandatory protective measures

When a technical event that does not lead to the issue of an ALERT SERVICE BULLETIN occurs or when a non-conformity with respect to the certification regulation, which does not lead to an unsafe condition, is discovered, a Service Bulletin is issued.

These Service Bulletins are mainly used to modify the applicable maintenance procedure, and usually include an indication about recommended compliance. This compliance recommendation is documented in the "COMPLIANCE" paragraph.

If they cover checks and verifications, compliance with these Service Bulletins must be ensured once or periodically as per the specified limit(s) for compliance or until a modification is embodied. These Service Bulletins are issued as a supplement to the Master Servicing Manual.

b) Introducing non-mandatory corrective measures

A corrective measure usually corresponds to a modification to the design. When a non-mandatory corrective measure is introduced, Airbus Helicopters can propose a compliance limit. Three cases can arise:

• Case No. 1:

Corrective measure following a technical event that can lead to an "unsafe condition" for which the precautionary measures are specified in an ALERT SERVICE BULLETIN.

Taking corrective measures makes it possible to streamline maintenance or restore the initial operating conditions by performing a definition (modification) not affected by the ASB. This corrective measure exempts you from complying with a protective measure introduced previously through an ALERT SERVICE BULLETIN.

This Service Bulletin can propose an application limit or range to help you comply with the instructions that it introduces:

- The "Reason" paragraph documents the compliance proposal to help you decide under your full responsibility whether to comply with the Service Bulletin or not.
- The "Compliance" paragraph contains a compliance limit or application range in accordance with the other maintenance tasks (intervals/inspections defined in the Master Servicing Manual), if possible.

To encourage compliance with the Service Bulletin, special commercial conditions can be proposed until the compliance date proposed and mentioned in the Service Bulletin.

Case No. 2:

Corrective measure following a technical event that does not lead to an "unsafe condition" and for which no other measures exist.

As described previously, the Service Bulletin can propose a suitable range in accordance with the other maintenance tasks to facilitate compliance with the instructions that it introduces:

- The "Reason" paragraph will document the compliance proposal to help you decide under your full responsibility whether to comply with the Service Bulletin or not.
- Usually, the compliance range is independent of the other maintenance tasks.



• Case No. 3:

Corrective measure resulting from a technical event that does not lead to an "unsafe condition" for which the protective measures have been specified in a Service Bulletin.

This Service Bulletin does not include any recommendation for compliance and does not propose a compliance limit or range. Compliance is left to the operator's initiative. However, these corrective measures make it possible to no longer apply the protective measures introduced previously through a Service Bulletin.

c) Introducing a measure that does not relate to an incident and including a design modification

The modification is introduced by a Service Bulletin as part of product improvement to reduce the maintenance and operating costs, or to propose new optional or mission-specific equipment.

### 2.3. TEMPORARY TECHNICAL INSTRUCTION (TTIs)

A Temporary Technical Instruction (TTI) is a document requested by Airbus Helicopters within the scope of a test campaign before the certification of a modification.

The TTI is dedicated to a specific helicopter serial number and does not allow customer to resume flight unless other authorization are provided by Airbus Helicopters Airworthiness Department or authorities. Once the modification is certified, the TTI is replaced by a SB.

#### MANAGEMENT AND ISSUE OF SERVICE BULLETINS 3.

### 3.1. NUMBERING

I

### 3.1.1. Numbering for ATA100 format

Service Bulletins are identified by a number that includes several digits in accordance with the following rules, which result from the successive changes in the ATA (Air Transport of America) regulations.



In addition, to facilitate your search for documents in chapters 01 and 04 (Limitations) or 05 (Time limits maintenance checks), where the number does not indicate the ATA chapter which is actually concerned by the document, the ATA chapter is specified on the cover page of the Service Bulletin.

### 3.1.2. Numbering for S1000D format

Service Bulletins are identified by a number that includes several digits in accordance with the following rule which result from the ASD S1000D standard.

- Service Bulletins number consists of eight digits:
  - . The two first digits identify the ATA chapter concerned
  - . The two middle digits identify the sub-chapter
  - . The four last digits identify the sequence number of the SB in the sub sub chapter.



### 3.2. SERVICE BULLETIN REVISIONS

#### 3.2.1. Service Bulletin revisions in ATA100 format

In the case of a revision of a Service Bulletin:

- The revision number given on the first page changes and increases in chronological order:
- "0" = original issue, "1" = first update, "2" = second update, etc
- The date of the original issue and the latest revision is indicated in the footer of the Service Bulletin,
- A table on the cover page summarizes all the revision numbers, approval dates (where applicable) and associated issue dates.

The changes introduced by the latest revision of the document are indicated by revision marks in the margin.

#### 3.2.2. Service Bulletin revisions in S1000D format

The first release of a Service Bulletin is issue 001

In the case of a revision of a Service Bulletin:

- The issue number given on the first page changes and increases in chronological order:
- "001" = original issue, "002" = first update, "003" = second update, etc.
- The date of the original issue and the latest revision is indicated at the header of the Service Bulletin.

The changes introduced by the latest revision of the document are indicated by revision marks in the margin.



### 3.3. SERVICE BULLETIN INDEX

The numerical indexes provide the references of all Service Bulletins.

### 3.4. ISSUING OF SERVICE BULLETINS

Airbus Helicopters proposes the electronic publication of its operational technical documentation. Given its advantages (rapidity and reliability of distribution, access to the latest revision, paper savings and protection of the environment), Airbus Helicopters favors this type of distribution. All of Airbus Helicopters operators and customers can opt for the free-of-charge electronic issue of ASBs and SBs only. The paper issue is optional but still possible. The paper issue must be specifically requested for new contracts.

ASBs and SBs are available on the Airbus Helicopters Technical Information Publication on Internet (T.I.P.I.) website, at the following address: <u>www.airbushelicopters.com/techpub/</u>.

### 4. CONTENT DESCRIPTION OF SERVICE BULLETINS

### 4.1. SB IN ATA 100 FORMAT

As specified in ATA Specification 2200, Service Bulletins include a cover page and four main chapters:

- Planning information.
- Material information.
- Accomplishment instructions.
- Appendix.

The content description of Service Bulletins is detailed below in accordance with the numbering of the Service Bulletin paragraphs:

- The sections shown in green font appear only if these sections are completed.
- The sections shown in orange font appear if one of them is completed (in the paragraph concerned).

(When an SB/ASB/TTI is issued, all the paragraphs and sections are in black font; the colors in this document are only used to improve understanding.

### • COVER PAGE

This page includes the following information:

- Type of helicopter and SB/ASB number.
- List of the helicopter versions concerned.
- Type of document (Service Bulletin).
- Type of measure (corrective or protective measure).
- Title corresponding to the ATA chapter number of the SB.
- Key words/short sentence summarizing the SB.
- Documentation source: MOD, DESC, etc.
- Staff or person concerned (flight crews, maintenance staff).
- Area affected by the change.
- A table listing revision numbers and issue dates.
- Summary of the SB.
- Level of compliance of the document (optional, recommended, required, mandatory).
- Reason for the latest revision (in case of revision).
- S/N of helicopters for customized issue.
- Date of issue of the first and latest revision.
- T.I.P.I website address.

Three examples of cover pages are detailed in the appendices.

### • STRUCTURE

### 1. PLANNING INFORMATION

This section includes several paragraphs:

### 1.A. EFFECTIVITY

#### 1.A.1. Helicopters/installed equipment or parts

Specifies the criteria about the validity of the document with respect to the helicopters and/or equipment installed: modification numbers, Service Bulletins, systems and installations necessary for compliance with the document. Indicates any incompatibilities with respect to compliance with the document.



#### 1.A.2. Non-installed equipment or parts

Specifies the criteria about the validity of the document with respect to equipment which is not installed on a helicopter: modification numbers, Service Bulletins, systems and installations necessary for compliance with the document.

#### 1.B. ASSOCIATED REQUIREMENTS

Modifications and Service Bulletins which must be embodied or complied with before, during or after compliance with the document.

#### 1.C. REASON

Summarizes the aim, context and associated advantages of the Service Bulletin.

1.D. DESCRIPTION

Describes the procedure to be carried out.

- 1.E. COMPLIANCE
- 1.E.1. Compliance at H/C manufacturer level

Helicopters/installed equipment or parts:

Indicates the conditions for complying with the SB/ASB/TTI or for embodying the corresponding modification at the manufacturer level.

#### Non-installed equipment or parts:

Indicates the conditions for complying with the SB/ASB/TTI or for embodying the corresponding modification on the equipment held as spares at the manufacturer level.

1.E.2. Compliance in service

#### Helicopters/installed equipment or parts:

Indicates the compliance/embodiment conditions for the check, modification or maintenance action to be performed on the helicopters or on installed equipment.

#### Non-installed equipment or parts:

Indicates the compliance/embodiment conditions for the check, modification or maintenance action to be performed on non-installed equipment.

1.F. APPROVAL

<u>The chapter "Approval</u>" contains the approval identifier given by Airbus Helicopter approval authorities.

### 1.G. MANPOWER

Indicates the number of person, their qualification, the time necessary to perform the operation and, if possible, the estimated helicopter downtime.

### 1.H. WEIGHT AND BALANCE

Indicates the difference in weight and moment following compliance with the instructions of the document.

### 1.I. POWER CONSUMPTION

Specifies the impact on electrical power consumption.

### 1.J. SOFTWARE UPGRADES/UPDATES

Substantiates the approval of the modification to the software.

### 1.K. REFERENCES

Lists the technical publications necessary for compliance with the instructions of this document (e.g. PRE/MSM, ICO, etc.).

### 1.L. OTHER AFFECTED PUBLICATIONS

Lists the manuals (as part of Instructions for Continued Airworthiness (ICA)) that have been updated to take into account the modification of the helicopter configuration.

### 1.M. PART INTERCHANGEABILITY OR MIXABILITY

#### Interchangeability:

Indicates the possibility of a full or conditional replacement of components before and after modification.

Mixability:

Indicates the possibility of mixing the parts or equipment before or after modification.



### 2. EQUIPMENT OR PARTS INFORMATION

### 2.A. EQUIPMENT OR PARTS: PRICE - AVAILABILITY - PROCUREMENT

This paragraph:

- Describes the special price conditions, warranty conditions and periods of validity of these conditions.
- Gives information on the availability of the material or on the procurement cycles.
- Gives the procurement addresses for the material necessary for compliance with the Service Bulletin.

#### 2.B. LOGISTIC INFORMATION

Describes the possibilities of trade-in of assemblies or equipment or provides information on specific services.

#### 2.C. EQUIPMENT OR PARTS REQUIRED PER HELICOPTER/COMPONENT

This paragraph gives the following information, where applicable:

<u>Kits to be ordered for one helicopter or one assembly:</u> Summary table of the material necessary for one helicopter or one assembly.

Equipment or parts to be ordered separately:

Table giving the quantity of consumables and components not supplied in the kits.

Consumables to be ordered separately:

Table giving the quantities of chemical products, liquids, solvents, greases, fluids and adhesives.

Equipment or parts supplied by the user:

Lists the materials supplied by the operator (B or 800G material/consumables, hardware, etc.).

#### Equipment or parts required for non-installed components:

This paragraph is used if the material for non-installed components is different from the material necessary for installed components.

#### Special tools:

Specifies the tooling and other specific tools (excluding standard tools) necessary for compliance with the Service Bulletin.

The tables are shown as follows:

General format for kits:

Key word	Qty	New Reference	ltem	Former Reference	$\rightarrow$	Instruction	
1	2	3	4	5		6	

General format for consumables:

Key word	Qty	Product Reference	СМ	Item
1	2	3	7	4

General format for special tools:

Key word	Qty	Tool Reference or equivalent	Item
1	2	3	4

1 Designation of the part, component, consumable, special tool, etc...

- 2 Quantities of parts required for with the ASB/SB/TTI.
- 3 Reference (P/N Part Number) of the part, component, consumable, special tool, etc...
- 4 Item corresponding to the part used in the procedure:
  - Number for parts or assemblies.
  - Number + letter alphabet for parts of an assembly component.
- 5 Reference (P/N Part Number) of removed parts,
- 6 Special instructions for the part (discard, put in storage, or send back) or reference to a note.

7 Material code.

<u>NOTE:</u> "For ref." can be used for Qty (2) or (New) P/N (3) to reference a sub-component used in the procedure.

### 2.D. EQUIPMENT OR PARTS TO BE RETURNED

Lists the materials to be returned to the equipment manufacturer or to Airbus Helicopters to be modified, repaired, or replaced, and the applicable conditions for return.

### 3. ACCOMPLISHMENT INSTRUCTIONS

This section details the work to be performed in chronological order.

### 3.A. GENERAL

Lists the general instructions for compliance with the Service Bulletin.

#### 3.B. WORK STEPS

This paragraph gives a detailed description of the operations to be performed on the helicopter or in the workshop. It can include illustrations or photos and gives the following information where applicable.

Besides, this section between 3.B. and 3.B.1. may contain instructions that apply to the entire procedure.

#### 3.B.1. Preliminary steps

Describes the operations before starting the work, such as removing items for access, installing access equipment, preparatory work, etc.

#### 3.B.2. Procedure

Describes the operations to be performed on the helicopter or in the workshop.

#### 3.B.3. <u>Tests</u>

Indicates the checks and functional tests to ensure the correct operation of the modified installations.

#### 3.B.4. Final steps

Indicates the operations necessary to return the helicopter to flight configuration.

#### 3.B.5. Ground run-up/flight test

Asks for a ground run-up or a flight test.

#### 3.B.6. Removal after tests (specific for TTI)

Removal of the test installations to keep the new installation after the tests.

#### 3.B.7. Feedback of information (specific for TTI)

Description of the reports, reporting frequencies and transmission modes to be used to send information to Airbus Helicopters about the various tests carried out for a new modification.

#### 3.B.8. Final steps after removal (specific for TTI)

Indicates the items to be installed again and the final steps necessary to return the helicopter to its original condition (e.g. before installation of the modification), (TTI, etc.).

#### 3.B.9. Work steps for non-installed equipment

Describes the operations to be performed on non-installed equipment (discard, modify, replace).

### 3.C. RECORD OF COMPLIANCE

#### Compliance with this document:

Gives the instructions to ensure the traceability of compliance with the SB/ASB/TTI (and the revisions) in the helicopter documentation.

#### QR code and hyperlink:

A QR code and a hyperlink have been added since January 2020 to each SB/ASB/EASB/TTI to enable feedback on SB/ASB/EASB/TTI compliance of a helicopter identified by its serial number.

#### Tracking of modifications in the documentation:

Gives the instructions to ensure the traceability of the modifications in the helicopter documentation.

#### Identification of modifications on the equipment or parts: Defines the parts and/or assemblies to be identified or re-identified and the methods of

identification.

#### 3.D. OPERATING AND MAINTENANCE INSTRUCTIONS

#### **Operating instructions:**

Gives the instructions for use by flight crews and specifies the Flight Manual supplements and sections, following compliance with the SB/ASB/TTI.

#### Maintenance instructions:

Indicates the maintenance to be performed following compliance with the SB/ASB/TTI. (*The illustrations or photos can also be inserted here at the end of chapter 3*).

#### 4. APPENDIX

The appendices can include the following documents:

- "Equipment-manufacturer's SB".
- "Completion-work table".
- "Extract from Test Technical Notes".
- "Extract from a Flight Manual" given for information purposes.
- "Un-issued Work Cards (for options and baseline)".
- "Installation or manufacturing technical sheets".

# AIRBUS

## No. EC155-00-002

### 4.2. INTRODUCTION TO THE NEW FORMAT S1000D

A new Service Bulletin format is introduced in accordance with standard ASD S1000D. The purpose of this chapter is to give the definition of information contains in the new format.

### 4.2.1. CONTENT DESCRIPTION OF SERVICE BULLETINS

### • TYPES OF MEASURES

The first page indicates one of the following categories, which enables the Service Bulletin type to be defined at first sight:

- <u>Protective measure</u>: following an in-service technical event (incident), it allows resuming normal operation or safety of the helicopter by prescribing / mandating inspections, limitations.
- <u>Corrective measure:</u> generally serves to cancel the protective measure by implementing a modification.
- <u>Product improvement</u>: serves to implement a modification on the fleet in service, to improve helicopter performance, reliability, etc.
- <u>Obsolescence management</u>: used to ensure the fitting of new equipment when the previous one is no longer available.
- <u>Maintenance improvement:</u> used to reduce scheduled maintenance tasks, periods or downtime of the helicopter, reduce DMC.
- Optional equipment / Installation: allows installing additional equipment following a customer request.

### APPLICABILITY

This paragraph indicates the applicability of the document according to the model and the version of the helicopter.

The applicability of the document may be specified by several configuration criteria:

- <u>Helicopters affected:</u> the document is applicable only to the aircraft serial number listed
- <u>Component affected</u>: the document is applicable only to aircraft that are equipped with the reference listed
- <u>Helicopters PREMOD & Helicopters POSTMOD:</u> the document is applicable only to the listed helicopter configuration

#### Exemple:

Model:	EC155
Version:	B1
Helicopters affected:	6837
Component affected:	365P61-5615-00
Helicopters PREMOD:	MC24C52
Helicopters POSTMOD:	MC39D02

The document is applicable to EC155 version B1 :

- For helicopter S/N 6837
- The helicopter must be equipped with component 365P61-5615-00 and be in
- PRE MOD MC24C52
- and be in
- POST MOD MC39D02

Note: The applicability is defined based on the original helicopter configuration (as defined in the individual inspection log book). It also takes into account all Airbus Helicopters approved configuration changes made after delivery, if Airbus Helicopters was informed of them. It is the responsibility of the operator to check the compatibility of any modifications with the current helicopter configuration. If modifications are not compatible, it is the responsibility of the operator to define the necessary adaptation work and have them approved by the air transport authorities in the country concerned, and to make sure that their airworthiness is followed up.

### COMPLIANCE

This paragraph shows:

- the compliance category,
- if applicable, the timeline recommendations to apply the instructions,
- if applicable, specific conditions to comply the instructions.

### • SUMMARY

This paragraph presents the subject of the Service Bulletin.

### • GENERAL ILLUSTRATION

The general illustration provides an overview of the impacted area and/or of the modification introduced by the Service Bulletin.

### • PLANNING INFORMATION

### 1. REASON

Summarizes the purpose, the context and the associated benefits of the Service Bulletin.

### 2. DESCRIPTION

Describes an overview of the procedure to be carried out.

### 3. CONCURRENT REQUIREMENTS

This paragraph indicates:

- The modifications that must be complied with beforehand or jointly
- The modifications that are not compatible with the current document.

### 4. APPROVAL

The chapter "Approval" contains the approval identifier given by Airbus Helicopter approval authorities.

### 5. MANPOWER

This paragraph gives the estimated Main Man Hours (MMH) required for compliance with the Service Bulletin. It is only an indication, non-contractual and can in no way be qualified as binding. The MMH to apply the procedure and the MMH relative to the set-up and the close-up operations are separate.

### 6. WEIGHT AND BALANCE

Indicates the difference in weight and moment following compliance with the instructions of the document.

### 7. ELECTRICAL LOAD DATA

Specifies the impact on electrical power consumption.

### 8. DOCUMENTATION AFFECTED

Lists the manuals (as part of Instructions for Continued Airworthiness (ICA)) that have been updated to take into account the modification of the helicopter configuration.

### 9. MATERIAL INFORMATION

#### 9.1. Price

This paragraph provides information on the sales terms.

#### 9.2. Availability

This paragraph provides information on the availability terms.

#### 9.3. Procurement

This paragraph provides information on the procurement terms.

#### 9.4. Mixability

This paragraph provides information on the mixability conditions. If mixability between the pre-modification component and post-modification component is authorized, the part will be identified.

### 9.5. LIST OF NEW MATERIALS

### - SPARE SETS LIST

Summary table of the material necessary for one helicopter or one assembly. This table is introduced by the designation and the reference of the kit and contains a list of components.

	Spare Sets List					
	Set Designation	Set Re	ference			
De	esignation of the kit	Referenc	e of the kit			
	9	Set Content				
ltem	Designation	Reference	MFC	QTY		
Number of the part called in the procedure	Designation of the part	Reference of the part	Manufacturer Code	Quantities of parts required		

### - INDIVIDUAL SPARES LIST

This table gives a list of components.

Individual Spares List						
ltem	Designation	Reference	MFC	QTY		
Number of the part called in the procedure	Designation of the part	Reference of the part	Manufacturer Code	Quantities of parts required		

### CONSUMABLES, MATERIALS AND EXPENDABLES

This table gives the chemical products, liquids, solvents, lubricants, fluids and adhesives required to perform the procedure.

Consumables, Materials and Expendables						
Designation	Reference	MFC	QTY			
Designation of the consumable	Material Code	Manufacturer code	Quantities of parts required			

### - LIST OF SUPPORT EQUIPMENT

This table gives the specific tools required to do the procedure.

	Special Tools						
ltem	Designation	Reference	MFC	QTY			
Number of the part called in the procedure	Designation of the tool	Reference of the tool	Manufacturer code	Quantities of parts required			

### 9.6. LIST OF EXISTING PARTS

### - INTERCHANGEABLE PARTS

This paragraph gives the list of before modification part numbers that are interchangeable with after modification part numbers.

The interchangeability values are: one way or two way.

For the definition of interchangeability, refer to Illustrated Parts Catalog (IPC).

INTERCHANGEABLE PARTS				
Old Reference	Designation	New Reference	Interch	
Old reference of the part	Designation of the part	New reference of the part	Type of interchangeability	

#### - RE-IDENTIFIED PARTS

This table gives the part numbers that are re-identified through compliance with the Service Bulletin.

### - REMOVED PARTS

This chapter provides the list of removed or modified parts (former Part Numbers) which are no longer considered as a spare for aircraft that have accomplished the Service Bulletin.

### **10. ACCOMPLISHMENT INSTRUCTION**

It generally contain links to one or several accomplishment procedures. If applicable, this paragraph gives directly the instruction procedure.

### **11. ADDITIONAL INFORMATION**

This part is used to include any information that may be useful.

### ACCOMPLISHMENT PROCEDURE

#### 1. APPLICABILITY

Refer to the previous explain.

#### 2. GENERAL INFOS

This section lists the accronyms and abbreviations.

### 3. PRELIMINARY REQUIREMENTS

This section gives:

- . Conditions that the helicopter or equipment must be fulfil before the procedural steps can be carried out (i.e. safe for maintenance, in a hangar or removed from the helicopter).
- . The list of materials, tools, spares or customized kits
- . General safety requirements that must be obeyed while the procedure is being done.

### 4. PROCEDURE

Describes the operations to be performed.

### 5. CLOSE-UP

This section gives:

- . The required procedural steps to be done after the procedure is completed
- . Instructions for recording compliance with the Service Bulletin in the aircraft documentation.

### 5. APPENDICES

### 5.1. EXAMPLE OF A SB ATA 100 COVER PAGE



L

## No. EC155-00-002

### 5.2. EXAMPLE OF AN ASB ATA 100 COVER PAGE

-/11/000	HELICOPTERS
a.,	No. EC155-00-002
	Civil version(s): B, B1
ALERT SEF	<b>RVICE BULLETIN</b>
PROTECTIVE MEASURE	
EQUIPMENT AND FURNISHINGS - E Check of the front emergency floata	mergency Floatation tion hoses
For the attention of	The second se
	A A A A A A A A A A A A A A A A A A A
Revision number	Date of issue
Revision 0	2020-01-07
<u>Summary</u> .	
The purpose of this ALERT SERVICE BULLET floatation balloons are not clogged. Compliance: Compliance with this ALERT SERVICE BULLE	TIN is to make sure that the inflation hoses of the front emergency

L

## No. EC155-00-002

5.3. EXAMPLE OF AN EASB ATA 100 "EMERGENCY" COVER PAGE

EMERGENCY         ALECTONE SECURIC EDULLETIN is mandatory         ACTION PROVE - Tail Gear Box (TGB)         Content on Content on Content on the recess of the TGB housing         Image: Content on Content on Content on the recess of the TGB housing         Image: Content on Con	EMERGENCY         ALECTOR SECTION CLEADURE         AND ALEXA SECTION AND	EM ALERT SEF ALERT SEF ALERT SEF OTECTIVE MEASURE IL ROTOR DRIVE – Tail Gear Box ( hecking there is no oil retention in t or the attention of CONCERNED AS365 65.00.19 AS365 65.00.9 SA366 65.06 EC155 65A008	ERGENC EVICE I TGB) he recess of the TG	(resion(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
ALCONTRACTOR SECURIC BULLETIN is mandatory.	ALECT SERVICE BULLETIN is mandatory.         ALENT SERVICE BULLETIN is mandatory.	ALERT SEF COTECTIVE MEASURE ALL ROTOR DRIVE – Tail Gear Box ( tecking there is no oil retention in t or the attention of CONCERNED AS365 65.00.19 AS365 65.00.9 SA366 EC155 65A008	TGB) the recess of the TG <u>Civil</u> N1, N2, N3	GB housing	
A COTECTIVE MEASURE ALE COTECTIVE ALEXANT SERVICE BULLETIN is mandatory. A Safe of the ALERT SERVICE BULLETIN is mandatory.	PROTECTIVE MEASURE         AL ROTOR DRIVE - Tail Gear Box (TGB)         Checking there is no oil retention in the recess of the TGB housing         Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Image: Civil         MUMBER       Civil       Military         AS65       65.00.19       N1, N2, N3       F, Fi, K, K2         AS65       65.00.19       N1, N2, N3       F, Fi, K, K2         AS65       65.00.09       MA, MB, MBe, SA, SB, SA366       65.06         Ec165       65A008       B, B1       GA         Revision No.       Date of issue       2019-07-10         Immary:       Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Image: Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2"         Mexision No.       Date of issue       Colspan="2">Colspan="2"         Immary:       Image: Colspan="2">Image: Colspan="2"         Image: Colspan= Co	ROTECTIVE MEASURE ALL ROTOR DRIVE – Tail Gear Box ( hecking there is no oil retention in t for the attention of all concerned AS365 65.00.19 AS365 65.00.09 SA366 65.06 EC155 65A008	TGB) the recess of the TG Ve Civil N1, N2, N3	GB housing /ersion(s) 	
ALROTOR DRIVE - Tail Gear Box (TGB) tecking there is no oil retention in the recess of the TGB housing tecking there is no oil retention in the recess of the TGB housing technology and the recess of the TGB housing and the technology and the recession of the recess of the recession of the recent here and the recess of the recent here and there and the recent here and the recent here and the rec	ROTECTIVE MEASURE         AL ROTOR DRIVE - Tail Gear Box (TGB)         checking there is no oil retention in the recess of the TGB housing         For the attention of         Image: Concerned of Concerned of Concerned of State         AS365       65.00.19         NUMBER       Civil Military         AS365       65.00.19         N1, N2, N3       F, Fi, K, K2         AS366       65.06         B, SA366       65.06         Revision No.       Date of issue         Revision 0       2019-07-10         ummary:       he purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in to not obstructed by a foreign object.         ompliance:       ompliance with this ALERT SERVICE BULLETIN is mandatory.	ROTECTIVE MEASURE IL ROTOR DRIVE – Tail Gear Box ( lecking there is no oil retention in t for the attention of AS365 65.00.19 AS365 65.00.19 AS366 65.06 EC155 65A008	TGB) the recess of the TG Ve Civil N1, N2, N3	GB housing /ersion(s) 	
AL ROTOR DRIVE - Tail Gear Box (TGB) hecking there is no oil retention in the recess of the TGB housing for the attention of Corderned Cord	AL ROTOR DRIVE – Tail Gear Box (TGB) thecking there is no oil retention in the recess of the TGB housing For the attention of Version(s)         MUMBER       Civil       Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS366       65.00.9       MA, MB, MBe, SA, SB, SA366       65.06       GA         EC155       65A008       B, B1       Ga       Ga         Revision No.       Date of issue       2019-07-10         ummary:       he purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in to not obstructed by a foreign object.       ompliance:         ompliance with this ALERT SERVICE BULLETIN is mandatory.       Service BULLETIN is mandatory.	ALL ROTOR DRIVE – Tail Gear Box ( hecking there is no oil retention in t for the attention of fellicopter(s) CONCERNED AS365 AS365 AS365 AS366 EC155 AS308 AS30	TGB) he recess of the TG Ve Civil N1, N2, N3	GB housing /ersion(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
AL ROTOR DRIVE - Tail Gear Box (TGB) hecking there is no oil retention in the recess of the TGB housing For the attention of Cordenate TELICOPTER(S) CONCERNED UMBER Civil Version(S) CONCERNED Version(S) CONCERNED Version(S) Civil AS365 65.00.19 N1, N2, N3 F, Fi, K, K2 AS365 65.00.09 NA, MB, MBe, SA, SB, UB SA366 65.06 B, B1 Revision No. Date of issue Revision 0 2019-07-10 mmary: the purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE of obstructed by a foreign object. mpliance: mpliance with this ALERT SERVICE BULLETIN is mandatory.	AIL ROTOR DRIVE - Tail Gear Box (TGB) thecking there is no oil retention in the recess of the TGB housing For the attention of Provided State	ALL ROTOR DRIVE – Tail Gear Box ( hecking there is no oil retention in t for the attention of ALLICOPTER(S) CONCERNED AS365 AS365 AS365 AS366 EC155 AS308 AS AS AS AS AS AS AS AS AS AS AS AS AS A	TGB) the recess of the TG Ve Civil N1, N2, N3	GB housing /ersion(s) 	
Recking there is no oil retention in the recess of the TGB housing         For the attention of         Image: Concerned Concerne	Recking there is no oil retention in the recess of the TGB housing         For the attention of         Image: Second S	For the attention of         For the attention of         Image: Concerned         AS365         AS365         65.00.19         AS366         65.006         EC155	the recess of the TG Ve Civil N1, N2, N3	JB housing /ersion(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
For the attention of         Image: Concerned concerned by a foreign object.       NUMBER Civil Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS365       65.00.09       MA, MB, MBe, SA, SB, UB       SA366       65.00         SA366       65.00.09       MA, MB, MBe, SA, SB, UB       SA366       65.00       MA, MB, MBe, SA, SB, UB         SA366       65.00       B, B1       GA       GA       GA         Revision No.       Date of issue       Curve of issue       Curve of issue       Curve of issue         Revision 0       2019-07-10       Mmary:       Curve of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGB of obstructed by a foreign object.       Mpliance:         mpliance:       mpliance with this ALERT SERVICE BULLETIN is mandatory.       Mandatory.	For the attention of       Version(s)         Version(s)       MUMBER         CONCERNED       NUMBER         AS365       65.00.19         N1, N2, N3       F, Fi, K, K2         AS365       65.00.9         MA, MB, MBe, SA, SB,         SA366       65.06         EC155       65A008         Revision No.       Date of issue         Revision 0       2019-07-10         ummary:       Nummary:         The purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the oil obstructed by a foreign object.         ompliance:       ompliance with this ALERT SERVICE BULLETIN is mandatory.	For the attention of HELICOPTER(S) CONCERNED AS365 AS365 AS365 AS365 AS366 EC155 AS308 AS3	Ve Civil N1, N2, N3	Version(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
For the attention of         Image: Concerned Civil       NUMBER       Civil       Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS565       65.00.09       MA, MB, MBe, SA, SB, UB       SA366         SA366       65.06       GA         EC155       65A008       B, B1       GA         Revision No.       Date of issue       Revision 0       2019-07-10         mmary:       E purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGB of obstructed by a foreign object.       mpliance:         mpliance with this ALERT SERVICE BULLETIN is mandatory.       Service BULLETIN is mandatory.	For the attention of Concerned       Version(s)         HELICOPTER(\$) CONCERNED       NUMBER       Civil       Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS365       65.00.09       MA, MB, MBe, SA, SB, SA366       65.06       GA         EC155       65A008       B, B1       GA         Revision No.       Date of issue       2019-07-10         ummary:       not obstructed by a foreign object.       2019-07-10         ompliance:       ompliance with this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the other co	For the attention of         IELICOPTER(S)         CONCERNED         AS365         65.00.19         AS565         65.00.09         SA366         65.00         EC155	Ve Civil N1, N2, N3	Version(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
Image: Number of the second	MUMBER       Version(s)         CONCERNED       NUMBER       Civil       Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS565       65.00.09       MA, MB, MBe, SA, SB,       SA366       65.06         SA366       65.06       GA       GA         EC155       65A008       B, B1       GA         Revision No.       Date of issue       2019-07-10         ummary:       Revision 0       2019-07-10         ummary:       not obstructed by a foreign object.       ompliance:         ompliance       With this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the not obstructed by a foreign object.	IELICOPTER(S) CONCERNED         NUMBER           AS365         65.00.19           AS565         65.00.09           SA366         65.06           EC155         65A008	Ve Civil N1, N2, N3	Version(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
HELICOPTER(S) CONCERNED       NUMBER       Civil       Military         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS565       65.00.09       MA, MB, MBe, SA, SB, UB         SA366       65.06       GA         EC155       65A008       B, B1         Revision No.       Date of issue         Revision 0       2019-07-10         mmary:       Purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE of obstructed by a foreign object.         mpliance:       mpliance with this ALERT SERVICE BULLETIN is mandatory.	HELICOPTER(S) CONCERNED       NUMBER       Version(s)         AS365       65.00.19       N1, N2, N3       F, Fi, K, K2         AS365       65.00.09       MA, MB, MBe, SA, SB,         SA366       65.06       GA         EC155       65A008       B, B1         Revision No.         Date of issue         Revision 0       2019-07-10         ummary:         ne purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object.         ompliance:         ompliance with this ALERT SERVICE BULLETIN is mandatory.	IELICOPTER(S) CONCERNED         NUMBER           AS365         65.00.19           AS565         65.00.09           SA366         65.06           EC155         65A008	Ve Civil N1, N2, N3	/ersion(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
HELICOPTER(\$) CONCERNED         NUMBER         Version(s)           A\$365         65.00.19         N1, N2, N3         F, Fi, K, K2           A\$366         65.00.09         MA, MB, MBe, SA, SB, UB         SA366           \$A\$366         65.06         GA         GA           EC155         65A008         B, B1         GA           Revision No.         Date of issue         Constructed of issue           Revision 0         2019-07-10	HELICOPTER(\$) CONCERNED         NUMBER         Version(s)           AS365         65.00.19         N1, N2, N3         F, Fi, K, K2           AS365         65.00.09         MA, MB, MBe, SA, SB,         SA366           SA366         65.06         GA           EC155         65A008         B, B1         GA           Revision No.         Date of issue         2019-07-10           Immary:         Revision 0         2019-07-10	HELICOPTER(S) CONCERNED         NUMBER           AS365         65.00.19           AS565         65.00.09           SA366         65.06           EC155         65A008	Ve Civil N1, N2, N3	/ersion(s) Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
Itelactor lengs         NUMBER         Version(s)           CONCERNED         NUMBER         Civil         Military           A3365         65.00.19         N1, N2, N3         F, Fi, K, K2           AS366         65.00.09         MA, MB, MBe, SA, SB, UB         SA366           SA366         65.06         GA         GA           EC155         65A008         B, B1         GA           Revision No.         Date of issue         2019-07-10           mmary:         a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE of obstructed by a foreign object.           mpliance:         mpliance with this ALERT SERVICE BULLETIN is mandatory.	HELICOPTER(s) CONCERNED         NUMBER         Version(s)           A\$365         65.00.19         N1, N2, N3         F, Fi, K, K2           A\$365         65.00.09         MA, MB, MBe, SA, SB,         SA366           \$\$A366         65.06         GA         GA           EC155         65A008         B, B1         GA           Revision No.           Revision 0         2019-07-10           Immary:         Date of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the not obstructed by a foreign object.           ompliance:         Dompliance with this ALERT SERVICE BULLETIN is mandatory.	NUMBER           AS365         65.00.19           AS565         65.00.09           SA366         65.06           EC155         65A008	Civil N1, N2, N3	Military F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
Concentration         Civil         Military           A\$365         65.00.19         N1, N2, N3         F, Fi, K, K2           A\$565         65.00.09         MA, MB, MBe, SA, SB, UB         SA366           SA366         65.00         GA         GA           EC155         65A008         B, B1         GA           Revision No.         Date of issue         Constructed by a foreign object.           mmary:         e purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE of obstructed by a foreign object.         mpliance:           mpliance with this ALERT SERVICE BULLETIN is mandatory.         Service BULLETIN is mandatory.	Civil         Military           A\$365         65.00.19         N1, N2, N3         F, Fi, K, K2           A\$565         65.00.9         MA, MB, MBe, SA, SB,         SA366         65.06         GA           EC155         65A008         B, B1         GA         GA         GA           Revision No.         Date of issue         2019-07-10         2019-07-10           Immary:         net purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object.         ompliance:           ompliance         :         is and atory.         Immary:	A\$365 65.00.19 A\$565 65.00.09 \$A366 65.06 EC155 65A008	N1, N2, N3	F, Fi, K, K2 MA, MB, MBe, SA, SB, UB	
ASSOC       03.00.10       IT, HZ, HS       T, HZ, HZ         AS565       65.00.09       MA, MB, MBe, SA, SB, UB       SA366       66.06       GA         EC155       65A008       B, B1       GA       GA       GA         Revision No.       Date of issue         Revision 0       2019-07-10         mmary:       e purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE of obstructed by a foreign object.         mpliance:       mpliance with this ALERT SERVICE BULLETIN is mandatory.	ASSOC       000013       FL, RZ, RS         AS565       65.00.09       MA, MB, MBe, SA, SB,         SA366       65.06       GA         EC155       65A008       B, B1         Revision No.         Revision 0       2019-07-10         Immary:       Prevision 0         Revision 0       2019-07-10         Immary:       Prevision 0         Revision 0       2019-07-10	A\$565         65.00.19           A\$565         65.00           SA366         65.06           EC155         65A008	n I, NZ, NJ	MA, MB, MBe, SA, SB, UB	
No.         Date of issue           Revision No.         Date of issue           Revision 0         2019-07-10	Associ       Ostor.03       MA, MB, MBE, SA, SB,         SA366       65.06       GA         EC155       65A008       B, B1         Revision No.         Revision 0       2019-07-10         Immary:         ne purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object.         ompliance:         ompliance with this ALERT SERVICE BULLETIN is mandatory.	SA366 65.06 EC155 65A008		MA, MD, MDE, 3A, 3D, UB	
BASSO       00.00       04         EC155       65A008       B, B1         Revision No.         Revision 0       2019-07-10         mmary:       2019-07-10         e purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE to to obstructed by a foreign object.         mpliance:         mpliance with this ALERT SERVICE BULLETIN is mandatory.	BROOD       BROOD       BROOD         EC155       65A008       B, B1         Revision No.       Date of issue         Revision 0       2019-07-10         Immary:       Description         not obstructed by a foreign object.       Description         ompliance:       Description         ompliance with this ALERT SERVICE BULLETIN is mandatory.	EC155 65A008		CA	
Revision No.         Date of issue           Revision 0         2019-07-10             mmary:         2019-07-10             a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE to to obstructed by a foreign object.           mpliance:         mpliance with this ALERT SERVICE BULLETIN is mandatory.	Revision No.         Date of issue           Revision 0         2019-07-10	20100	B B1	GA	
Revision No.       Date of issue         Revision 0       2019-07-10         mmary:       a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE not obstructed by a foreign object.         mpliance:       mpliance with this ALERT SERVICE BULLETIN is mandatory.	Revision No.       Date of issue         Revision 0       2019-07-10         ummary:		0,01		
Revision No.         Date of issue           Revision 0         2019-07-10             mmary:         a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE not obstructed by a foreign object.           mpliance:         mpliance with this ALERT SERVICE BULLETIN is mandatory.	Revision No.         Date of issue           Revision 0         2019-07-10		1	Data af is sure	
Revision 0       2019-07-10         mmary:       a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE to obstructed by a foreign object.         mpliance:       mpliance with this ALERT SERVICE BULLETIN is mandatory.	Revision 0       2019-07-10         ummary:	Revision No. Date of issue			
mmary: • purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGE iot obstructed by a foreign object. mpliance: mpliance with this ALERT SERVICE BULLETIN is mandatory.	ummary: ne purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object. ompliance: ompliance with this ALERT SERVICE BULLETIN is mandatory.	Revision 0		2019-07-10	
mmary: a purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGB iot obstructed by a foreign object. mpliance: mpliance with this ALERT SERVICE BULLETIN is mandatory.	ummary: ne purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object. ompliance: ompliance with this ALERT SERVICE BULLETIN is mandatory.				
e purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGP not obstructed by a foreign object. mpliance: mpliance with this ALERT SERVICE BULLETIN is mandatory.	he purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object. ompliance: ompliance with this ALERT SERVICE BULLETIN is mandatory.	mmary'			
e purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in the TGI not obstructed by a foreign object. mpliance: mpliance with this ALERT SERVICE BULLETIN is mandatory.	he purpose of this ALERT SERVICE BULLETIN is to make sure that the oil duct of the control bearing in t not obstructed by a foreign object. ompliance: ompliance with this ALERT SERVICE BULLETIN is mandatory.	<u>Innary</u> .			
not opstructed by a foreign object.	not opstructed by a foreign object.	purpose of this ALERT SERVICE BULLETIN	N is to make sure that the	e oil duct of the control bearing in the TGB	
mpliance with this ALERT SERVICE BULLETIN is mandatory.	ompliance:	ot obstructed by a foreign object.			
mpliance with this ALERT SERVICE BULLETIN is mandatory.	ompliance with this ALERT SERVICE BULLETIN is mandatory.	mpliance:			
mpliance with this ALERT SERVICE BULLETIN is mandatory.	ompliance with this ALERT SERVICE BULLETIN is mandatory.				
		npliance with this ALERT SERVICE BULLET	IN is mandatory.		

### 5.4. EXAMPLE OF A S1000D FORMAT SB COVER PAGE

	AIRBUS	HELICOPTERS		New SB coding: - EC155 : H/C Model - 34 : Chapter - 11 : Subchapter - 0001 : SB sequence
		SBI	EC155-34-11-000 Issue 001 2023-03-(	1 38
	SER	VICE BULLE	TIN	Number and date of issue of the last
	TITLE: Flight enviro	nment data - Single pilot IFR kit		revision
	SB Type: Product imp	rovement		
	Maria	50455		
	Model:	EC155		
	Heliconters affected:	6837		Standardized
	Component affected:	365P61-5615-00		applicability
	Helicopters PREMOD:	MC24C52		
	Helicopters POSTMOD:	MC39D02		
	COMPLIANCE: OPTIO At customer's option.	NAL		
	The purpose of this Servi flight in IFR conditions by	ce Bulletin is to make the aircraft mentioned installing an SPIFR kit (Single Pilot Instrume	capable for Single Pilot nt Flight Rules).	
	GENERAL EVALUATIO	DN		
	Dorform on co	Evaluation table	NO	
Information the recurrence of the SB	Perform once	YES Accomplish recurring	NO	
	SB EC155-34-11-0001		Page 1/1	ī

### 5.5. EXAMPLE OF AN ASB S1000D FORMAT COVER PAGE

	HELICOPTERS		
	ASB EC15	5-32-00-00 001 2023-0	<b>01</b> 3-08
ALERT	SERVICE BULL	ETIN	
TITLE: Landing gea gear selecto CVFDR SB Type: Protective n	ar - Installation of a set of wires to transfer or position signal to the MFDAU for record neasure	the landing ing on the	
APPLICABILITY			S/N of helicopters
Model:	EC155		
Version:	B1		
Helicopters affected:	6784		
Component affected:	365A08-4728-0299		
Helicopters PREMOD:	0731B96		
Helicopters POSTMOD:	0731B89		
COMPLIANCE: MAND	)ATORY	lichever comes	
Comply with this Alert Se first. SUMMARY The purpose of this Alert the landing gear selector standard ED112 and after	t Service Buletin is to add wires that transfer the por r (UP/DOWN) to the MFDAU for recording on the r embodiment of modification 0731B89.	isition signal of CVFDR as per	
Comply with this Alert Se first. SUMMARY The purpose of this Alert the landing gear selector standard ED112 and after GENERAL EVALUATION	t Service Buletin is to add wires that transfer the por r (UP/DOWN) to the MFDAU for recording on the r embodiment of modification 0731B89.	isition signal of CVFDR as per	
Comply with this Alert Se first. SUMMARY The purpose of this Alert the landing gear selector standard ED112 and after GENERAL EVALUATION	t Service Buletin within 50 hight hours of 1 months, with the service Buletin is to add wires that transfer the port (UP/DOWN) to the MFDAU for recording on the or rembodiment of modification 0731B89.	visition signal of CVFDR as per	

### 5.6. EXEMPLE OF AN EASB S1000D FORMAT SB COVER PAGE

	HELICOPTERS
	EASB EC155-32-00-0001 Issue 001 2023-03-04
EME SER	RGENCY ALERT
TITLE: Landing gea gear selecto CVFDR	r - Installation of a set of wires to transfer the landing r position signal to the MFDAU for recording on the
SB Type: Protective m	neasure
A D D L LC A D II J T V	
APPLICABILITY	
Model:	EC155
Model: Version:	EC155 B1
Model: Version: Helicopters affected:	EC155 B1 6784
Model: Version: Helicopters affected: Component affected:	EC155 B1 6784 365A08-4728-0299
Model: Version: Helicopters affected: Component affected: Helicopters PREMOD:	EC155 B1 6784 365A08-4728-0299 0731B96
APPLICABILITY Model: Version: Helicopters affected: Component affected: Helicopters PREMOD: Helicopters POSTMOD:	EC155 B1 6784 365A08-4728-0299 0731B96 0731B89
APPLICABILITY Model: Version: Helicopters affected: Component affected: Helicopters PREMOD: Helicopters POSTMOD: COMPLIANCE: MAND	EC155 B1 6784 365A08-4728-0299 0731B96 0731B89 ATORY
APPLICABILITY Model: Version: Helicopters affected: Component affected: Helicopters PREMOD: Helicopters POSTMOD: COMPLIANCE: MAND Comply with this Emerge comes first.	EC155         B1         6784         365A08-4728-0299         0731B96         0731B89    ATORY ancy Alert Service Bulletin within 2 flight hours or 1 day, whichever
APPLICABILITY Model: Version: Helicopters affected: Component affected: Helicopters PREMOD: Helicopters POSTMOD: COMPLIANCE: MAND Comply with this Emerge comes first. SUMMARY	EC155 B1 6784 365A08-4728-0299 0731B96 0731B89 ATORY ency Alert Service Bulletin within 2 flight hours or 1 day, whichever
Model: Version: Helicopters affected: Component affected: Helicopters PREMOD: Helicopters POSTMOD: COMPLIANCE: MAND Comply with this Emerge comes first. SUMMARY The purpose of this Emer signal of the landing geal as per standard ED112 ar	EC155         B1         6784         365A08-4728-0299         0731B96         0731B89    ATORY  Arrory Alert Service Bulletin within 2 flight hours or 1 day, whichever  rgency Alert Service Bulletin is to add wires that transfer the position r selector (UP/DOWN) to the MFDAU for recording on the CVFDR and after embodiment of modification 0731B89.