

SERVICE BULLETIN

TITLE: Service and miscellaneous - New battery door compensator rod

SB Type: Product improvement

APPLICABILITY

Model:	EC155
Version:	B, B1
Helicopters PRE MOD:	0752C81

COMPLIANCE: OPTIONAL

At customer's option.

SUMMARY

The purpose of this Service Bulletin is to replace the compensator rod.

GENERAL EVALUATION

Evaluation table			
Perform once	YES	Accomplish recurring	NO


Export Control: US Export Control - No US content. This Item does not contain any U.S. origin ITAR or EAR content. FR Export Control - Not Listed. This Item is not listed against the EC regulations in the EU/FR.




Issue 001 2024-07-25


GENERAL ILLUSTRATION

BEFORE MODIFICATION





AFTER MODIFICATION





PLANNING INFORMATION

1. REASON

The purpose of this Service Bulletin is to replace the compensator rod which is no longer supplied, with a new compensator rod.

The mounting orientation of the new compensator rod is changed to allow for better lubrication and performance.

Therefore, the connecting rod is installed with the connecting rod body up and the connecting rod down.

The technical data and instructions contained in this Service Bulletin refer to the modification 0752C81.

2. DESCRIPTION

The Service Bulletin provides instructions to:

- Remove the old compensator rod from the battery door
- Counter-drill the corner
- Install the new compensator rod.

3. CONFIGURATION DEFINITION

Not applicable.

4. CONCURRENT REQUIREMENTS

Not applicable.

5. APPROVAL

The technical content of this document is approved under the authority of the Design Organization Approval ref. EASA. 21J.700.

For helicopters operated outside the terrain regulated by the EASA, the application of this document is subject to validation provided by the responsible aviation authority of the state of registry.

Issue 001 2024-07-25

6. MANPOWER

NOTE

The Purpose of Man Hours is to give Airbus Helicopters customers a guideline for maintenance scheduling. It is not a contractual information.

6.1. Manpower for procedure

Number of Persons	Qualification Estimated Man Ho	
1	Mechanical technician	2h

7. WEIGHT AND BALANCE

There is no change in weight and moment.

8. ELECTRICAL LOAD DATA

Not applicable.

9. DOCUMENTATION AFFECTED

- Illustrated Parts Catalog (IPC)
- Aircraft Maintenance Manual (AMM)
- The changes to Instructions for Continued Airworthiness (ICA) which are required as a result of this Service Bulletin will be incorporated in the next Normal Revision. Refer to DN.105.0034 until the information is available in the published technical documentation.

10.MATERIAL INFORMATION

10.1. Price

For information about the price of the modification kits and/or components, or for aid, contact the Airbus Helicopters Network Sales and Customer Relations Department.

Issue 001 2024-07-25

10.2. Availability

Contact the Sales and Customer Relations Department to know the delivery lead times.

10.3. Procurement

Send an order for the necessary quantities to the Airbus Helicopters Network Sales. You can send an order for the consumables from the AirbusWorld Marketplace through e-ordering. If you cannot get access to e-ordering, please contact your Logistic Focal Point.

10.4. Mixability

This Service Bulletin has no effect on the mixability.

10.5. LIST OF NEW MATERIALS

Individual Spares List					
Item	Designation	Reference	MFC	QTY	
1	COMPENSATOR ROD	IG6004-40052	F0210	1	
2	SELF-LOCKING HEX NUT	ASN52320BH060N	F5442	2	
3	SHOULDER PIN	365A61671120	F0210	2	
4	FLAT WASHER	23111AG040LE	F0111	3	
5	SPLIT PIN	23310CA015012	F0111	2	

Consumables, Materials and Expendables				
Designation	Reference	MFC	QTY	
None				

	Special Tools					
ltem	Designation	Reference	MFC	QTY		
None						



Issue 001 2024-07-25

10.6. LIST OF EXISTING PARTS

REMOVED SPARE PARTS		
Old Reference	Designation	
23111AG040LE	Flat washer	
23310CA015012	Split pin	
23310CA015015	Split pin	
ASN52320BH060N	Self-locking hex nut	
IG6004-40050	Compensator rod	
0721330304060N	Compensator rod	
365A61671120	Shoulder pin	
22719BC040011L	Shoulder pin	

11. ACCOMPLISHMENT INSTRUCTION

Comply with the ACCOMPLISHMENT PROCEDURE <u>52-41-0001, 933</u>

12.ADDITIONAL INFORMATION

Not applicable.

End of section

ACCOMPLISHMENT PROCEDURE 52-41-0001, 933

1. APPLICABILITY

Model:	EC155
Version:	B, B1
Helicopters PRE MOD:	0752C81

2. GENERAL INFORMATION

Acronym/Abbreviation List FOD - Foreign Object Debris

3. PRELIMINARY REQUIREMENTS

3.1. Applicable Documents

- Assembly by screws and nuts Joining <u>MTC 20-02-05-404</u>
- Cleaning of mechanical parts Cleaning MTC 20-04-01-401
- Handling of helicopters in a hangar and in a prepared area Handling <u>MTC</u> <u>20-07-01-201</u>
- Helicopter parked in a repair shop Safety instructions MTC 20-07-02-201

3.2. Set up

- Handling of helicopters in a hangar and in a prepared area Handling <u>MTC</u> <u>20-07-01-201</u>
- Helicopter parked in a repair shop Safety instructions <u>MTC 20-07-02-201</u>
- Remove and/or open all applicable cowlings, panels, doors and other items of equipment to get access to the different work areas.
- 3.3. Special Tools

None

3.4. Consumables, Materials and Expendables

Issue 001 2024-07-25

None

3.5. Spares

Designation	Reference	MFC	QTY
COMPENSATOR ROD	IG6004-40052	F0210	1
SELF-LOCKING HEX NUT	ASN52320BH060N	F5442	2
SHOULDER PIN	365A61671120	F0210	2
FLAT WASHER	23111AG040LE	F0111	3
SPLIT PIN	23310CA015012	F0111	2



3.6. Safety conditions



4. PROCEDURE

- 4.1. Removal of the compensator rod
- 4.1.1. Remove and discard pins, self-locking nuts and flat washers from the compensator rod on both sides according to (Figure 1).
- 4.1.2. Remove the compensator rod according to (Figure 1).




Figure 1



Issue 001 2024-07-25

4.2. Modification of the door corner if necessary

NOTE

Counter-drill the corner at diameter D1 = 6,2 mm according to (Figure 2). For touch-up after drilling, refer to $\underline{MTC \ 20-04-01-401}$.




Figure 2



Issue 001 2024-07-25

4.3. Installation of the compensator rod

NOTE

The connecting rod should be installed with the connecting rod body up (battery door side) and the connecting rod down (structure side).

- 4.3.1. Install on the door side (top in (Figure 3)):
 - The SHOULDER PIN 365A61671120 (3)
 - The SELF-LOCKING HEX NUT ASN52320BH060N (2), dry tightening torque refer to <u>MTC 20-02-05-404</u>
 - The COMPENSATOR ROD IG6004-40052 (1)
 - The FLAT WASHER 23111AG040LE (4)
 - The SPLIT PIN 23310CA015012 (5).
- 4.3.2. Install on the structure side (bottom in (Figure 3)):
 - The SHOULDER PIN 365A61671120 (3)
 - The SELF-LOCKING HEX NUT ASN52320BH060N (2), dry tightening torque refer to <u>MTC 20-02-05-404</u>
 - The COMPENSATOR ROD IG6004-40052 (1)
 - The two FLAT WASHER 23111AG040LE (4)
 - The SPLIT PIN 23310CA015012 (5).




Figure 3

Issue 001 2024-07-25

5. CLOSE UP

- 5.1. Remove all the tools, the materials and the equipment from your work area.
- 5.2. Record the full compliance with this Service Bulletin, with its issue number, in the helicopter documents and, if applicable, in the log card of the equipment or its next higher assembly.
- 5.3. Record the modification 0752C81 in the helicopter documents and if applicable, in the log card of the equipment or its next higher assembly.
- 5.4. Record compliance with this Service Bulletin (see IN 3785-I-00 for instructions):



SB EC155-52-41-0001

End of Service Bulletin