

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

SERVICE BULLETIN

_{N°} 139-757

OPTIONAL

DATE: June 21, 2023

REV.: /

TITLE

ATA 62 - MAIN ROTOR RETROMOD P/N 3G6200P00111 INSTALLATION

REVISION LOG

First Issue



1. PLANNING INFORMATION

A. EFFECTIVITY

AB/AW139 helicopters equipped with Main Rotor Installation P/N 3G6200A00111, P/N 3G6200A00112, P/N 3G6200A00114, P/N 4G6200A00111, P/N 4G6200A00112 or P/N 4G6200A00113.

B. COMPLIANCE

At Customer's option.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

Leonardo developed the retromod P/N 3G6200P00111 in order to reduce the installation and maintenance effort of the Main Rotor Head. Indeed, the new configuration ensures a greater stability of the MR bolts torque and a greater stiffness of the whole assembly.

LH issued this SB for the following reason:

Helicopter Reliability/Maintainability		
Product Improvement	✓	
Obsolescence		
Customization		
Product/Capability Enhancement		

E. DESCRIPTION

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of retromod P/N 3G6200P00111, related to a new Main Rotor Head configuration, consisting in the replacement of washer, nuts, bolts and retaining element assy.

F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

S.B. N°139-757 OPTIONAL DATE: June 21, 2023



EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives.

If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

G. MANPOWER

To comply with this Service Bulletin 4 (four) MMH are deemed necessary.

MMH are based on hands-on time and can change with helicopter configuration, personnel and facilities available. MMH are not comprehensive of the overall hours necessary to get access to work areas and to remove all the equipment that interferes with the application of the prescribed instructions.

H. WEIGHT AND BALANCE

N.A

I. REFERENCES

I.1 PUBLICATIONS

Following Data Modules refer to AMP:

DATA	<u>MODULE</u>	<u>DESCRIPTION</u>	<u>PART</u>
DM01	39-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance.	-
DM02	39-A-62-21-05-00A-520A-A	Top conical ring - Remove procedure	-
DM03	39-A-62-21-05-00A-720A-A	Top conical ring - Install procedure	-

I.2 ACRONYMS & ABBREVIATIONS

AMDI	Aircraft Material Data Information
AMP	Aircraft Maintenance Publication
AR	As Required
DM	Data Module
DOA	Design Organization Approval
EASA	European Aviation Safety Agency
FIPS	Full Ice Protection System

S.B. N°139-757 OPTIONAL DATE: June 21, 2023



IPD Illustrated Part Data

ITEP Illustrated tool and equipment publication

LH Leonardo Helicopters Division

MMH Maintenance Man Hours

N.A. Not ApplicableP/N Part NumberSB Service Bulletin

I.3 ANNEX

N.A.

J. PUBLICATIONS AFFECTED

N.A.

K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.



2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

A.1 PARTS

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL NOTE	LOG P/N
1	3G6200P00111		MAIN ROTOR INSTALLATION RETRO MOD	REF		-
2	3G6220A02152		Washer	1		139-757L1
3	3G6220A02252		Nut	1		139-757L1
4	3G6220A02334		Retaining element assy	1		139-757L1
5	3G6220A11751		Nut	12	••	139-757L1
6	3G6220L00851		Bolt	12		139-757L1

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

A.2 CONSUMABLES

The following consumable materials, or equivalent, are necessary to accomplish this Service Bulletin:

#	SPEC./LHD CODE NUMBER	DESCRIPTION	Q.TY	NOTE	PART
7	MS20995C32	Lock wire	AR	(1)	-

Refer also to AMDI for the consumable materials required to comply with the AMP DM referenced in the accomplishment instructions.

A.3 LOGISTIC MATRIX

In order to apply this Service Bulletin, the following Logistic P/N can be ordered in accordance with the applicable notes:

LOGISTIC P/N	Q.TY (PER HELO)	R HELO) NOTE PA		
139-757L1	1	-	-	

NOTE

(1) Item to procured as local supply.

B. SPECIAL TOOLS

Refer to ITEP for the special tools required to comply with the AMP DM referenced in the accomplishment instructions.

C. INDUSTRY SUPPORT INFORMATION

Product improvement.

S.B. N°139-757 OPTIONAL DATE: June 21, 2023

REVISION: / Page 5 of 11



3. ACCOMPLISHMENT INSTRUCTIONS

GENERAL NOTES

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- b) Exposed thread surface and nut must be protected using a layer of tectyl according to MIL-C-16173 grade I.
- c) All lengths are in mm.
- 1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.

NOTE

The following Step 2 is applicable ONLY to helicopters equipped with main rotor installation P/N 3G6200A00111 or P/N 3G6200A00112 or P/N 3G6200A00114.

- 2. In accordance with applicable steps of AMP DM 39-A-62-21-05-00A-520A-A (Configuration A) and with reference to Figures 1 and 2, remove from the main rotor head the following components:
 - washer P/N 3G6220A02151;
 - nut P/N 3G6220A02251;
 - retaining element assy P/N 3G6220A02333;
 - n°12 bolt P/N 3G6220A02451;
 - n°12 nut P/N NAS509-8.

S.B. N°139-757 OPTIONAL DATE: June 21, 2023



NOTE

The following Step 3 is applicable ONLY to helicopters equipped with main rotor head installation P/N 4G6200A00111 or P/N 4G6200A00112 or P/N 4G6200A00113.

- 3. In accordance with applicable steps of AMP DM 39-A-62-21-05-00A-520A-A (Configuration A) and with reference to Figures 1 and 2, remove from the main rotor head the following components:
 - washer P/N 3G6220A02151;
 - nut P/N 3G6220A02251;
 - retaining element assy P/N 4G6220A01631;
 - n°12 bolt P/N 3G6220A02451;
 - n°12 nut P/N NAS509-8.

NOTE

Check the tightening torque and the correct installation of the bolt P/N 3G6220L00851 and the nuts P/N 3G6220A11751.

- 4. In accordance with applicable steps of AMP DM 39-A-62-21-05-00A-720A-A (Configuration B) and with reference to Figures 3 and 4, install on the main rotor head the following components:
 - washer P/N 3G6220A02152;
 - nut P/N 3G6220A02252;
 - retaining element assy P/N 3G6220A02334;
 - n°12 bolt P/N 3G6220L00851;
 - n°12 nut P/N 3G6220A11751.
- 5. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
- 6. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

As an alternative, send the attached compliance form to the following mail box:


engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:


AWPC.Engineering.Support@leonardocompany.us

S.B. N°139-757 OPTIONAL DATE: June 21, 2023





3G6200P00111 MAIN ROTOR INSTALLATION RETRO MOD



VIEW A
(FOR REMOVAL)
STRUCTURES AND SYSTEMS ARE PARTIALLY
OMITTED FOR BETTER CLARITY PURPOSE

Figure 1

S.B. N°139-757 OPTIONAL DATE: June 21, 2023 REVISION: /







Figure 2

S.B. N°139-757 OPTIONAL DATE: June 21, 2023

REVISION: /


NOTE:






VIEW D
(FOR INSTALLATION)
STRUCTURES AND SYSTEMS ARE PARTIALLY
OMITTED FOR BETTER CLARITY PURPOSE





STRUCTURES AND SYSTEMS ARE PARTIALLY OMITTED FOR BETTER CLARITY PURPOSE



SECTION F-F
STRUCTURES AND SYSTEMS ARE PARTIALLY
OMITTED FOR BETTER CLARITY PURPOSE

Figure 4

S.B. N°139-757 OPTIONAL DATE: June 21, 2023



Please send to the following address:		SERVICE BULLETIN COMPLIANCE FORM Date:			Date:	
LEONARDO S.p.A.						
	CUSTOMER SUPPORT & SERVICES - ITALY					
PRODUCT SUPPORT ENGINEE	RING & LICENSES DEPT.					
Via Giovanni Agusta, 520 21017 Cascina Costa di Samara	ate (VA) - ITALY	Revision:				
Tel.: +39 0331 225036 Fax: +39	0331 225988					
Customer Name and Addre	ess:	Telephone:				
				Fax:		
				B.T. Compliance Date:		
Helicopter Model	S/N		Total N	umber	Total Hours	T.S.O.
Remarks:						
Information:						
We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in						

Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.