

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

SERVICE BULLETIN

RECOMMENDED

№ 109EP-182

DATE: October 10, 2023 REV.: /

TITLE

ATA 05 – MPM UPDATED

REVISION LOG

First Issue

An appropriate entry should be made in the aircraft log book upon accomplishment. If ownership of aircraft has changed, please, forward to new owner.



1. PLANNING INFORMATION

A. EFFECTIVITY

Part I, Part II, Part III and Part IV

All the A109E helicopters

B. COMPLIANCE

NOTE

The compliance time is subject to the same tolerances as per MPM Chap. 05 Para. 05-00-4. Permissible inspection interval tolerances, except differently indicated.

<u>Part I</u>

Within and not later than reaching the next scheduled inspection at 200 FH/12 months, after the issue of this Service Bulletin, and subsequently refer to MPM scheduling.

Part II

- Helicopter that has accumulated less than 1000 FH:
 - Within and not later than reaching the 1000 FH or within and not later than 200 FH or 1 year after the issue of this Service Bulletin, whichever occurs later, and subsequently refer to MPM scheduling.
- Helicopter that has accumulated more than 1000 FH:
 - Within and not later than 200 FH or 1 year, whichever occurs later after the issue of this Service Bulletin (no tolerance allowed), and subsequently refer to MPM scheduling.

Part III

- Helicopter that has accumulated less than 2000 FH:
 - Within and not later than reaching the 2000 FH or within and not later than 200 FH or 1 year after the issue of this Service Bulletin, whichever occurs later, and subsequently refer to MPM scheduling.
- Helicopter that has accumulated more than 2000 FH:
 - Within and not later than 200 FH or 1 year, whichever occurs later after the issue of this Service Bulletin (no tolerance allowed), and subsequently refer to MPM scheduling.

Part IV

• Helicopter that has less than 6 years:



- Within and not later than reaching the 6 years or within and not later 2 years after the issue of this Service Bulletin, whichever occurs later, and subsequently refer to MPM scheduling.
- Helicopter that has more than 6 years:
 - Within and not later 2 years after the issue of this Service Bulletin (no tolerance allowed), and subsequently refer to MPM scheduling.

LH recommends the implementation of this SB in accordance with the indicated compliance time, with related tolerances as applicable. It is Operator's responsibility to properly plan and execute the SB application i.a.w. LH recommendations. The Operator remains liable for any deviation.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

This SB is issued in order to give a grace period for the application of the new inspection tasks included in MPM Chapter 05 - Inspection requirements and component overhaul schedule.

LH issued this SB for the following reason:

Helicopter Reliability/Maintainability	
Product Improvement	
Obsolescence	
Customization	
Product/Capability Enhancement	

E. DESCRIPTION

LH has introduced a set of modifications within MPM Chapter 05 Scheduled/unscheduled maintenance with the scope to harmonize the publications and/or include improvements taking benefit from changes already implemented on other AW109/AW119 lines or derived from latest applicable design information and in service recommendations.

This SB is therefore issued to give a grace period for the application of the new inspection tasks included in MPM Chapter 05 – Inspection requirements and component overhaul schedule.



F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked with Local Aviation Authority.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives. If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

G. MANPOWER

N.A.

H. WEIGHT AND BALANCE

N.A

I. REFERENCES

I.1 PUBLICATIONS

Following Section/Paragraph refer to MM:

SECTION/PARAGRAPH	ARAGRAPH DESCRIPTION					
DM01 00-20-01	Helicopter safety	All				
Following Section/Paragraph refer to MPM:						
SECTION/PARAGRAPH	DESCRIPTION	<u>PART</u>				
DM02 05-50-1	Special inspections	All				

I.2 ACRONYMS & ABBREVIATIONS

- AMDI Aircraft Material Data Information
- DOA Design Organization Approval
- EASA European Union Aviation Safety Agency
- LH Leonardo Helicopters
- MM Maintenance Manual
- MMH Maintenance Man Hours
- MPM Maintenance Planning Manual
- N.A. Not Applicable



SB Service Bulletin

I.3 ANNEX

N.A.

J. PUBLICATIONS AFFECTED

N.A.

K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.



2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

A.1 PARTS

N.A.

- A.2 CONSUMABLES
- N.A.
- A.3 LOGISTIC MATRIX

N.A.

B. SPECIAL TOOLS

N.A.

C. INDUSTRY SUPPORT INFORMATION

N.A.



3. ACCOMPLISHMENT INSTRUCTIONS

<u>PART I</u>

- 1. In accordance with MM Paragraph 00-20-01, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. In accordance with MPM Paragraph 05-50-1, apply the maintenance task 18. item c "Examine all tail rotor drive shaft supports for condition and corrosion including adjacent fuselage/tail area for cracks".
- 3. Return the helicopter to flight configuration and record for compliance with Part I of this Service Bulletin on the helicopter logbook.
- 4. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

As an alternative, send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to: <u>AWPC.Engineering.Support@leonardocompany.us</u>



<u>PART II</u>

- 1. In accordance with MM Paragraph 00-20-01, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. In accordance with MPM Paragraph 05-50-1, apply the maintenance task 21 "Perform a detail inspection of the upper deck area and panels for cracks, corrosion debonding and damage".
- 3. Return the helicopter to flight configuration and record for compliance with Part II of this Service Bulletin on the helicopter logbook.
- 4. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

As an alternative, send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:

AWPC.Engineering.Support@leonardocompany.us



<u>PART III</u>

- 1. In accordance with MM Paragraph 00-20-01, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- In accordance with MPM Paragraph 05-50-1, apply the maintenance task 23 "Perform a detail inspection for cracks to the cargo bay frame in the rear fuselage at STA 4710 (ref. to Para 53-21-19) and STA 4960 (ref. to Para 53-21-20)".
- 3. Return the helicopter to flight configuration and record for compliance with Part III of this Service Bulletin on the helicopter logbook.
- 4. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

As an alternative, send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:

AWPC.Engineering.Support@leonardocompany.us



<u>PART IV</u>

- 1. In accordance with MM Paragraph 00-20-01, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. In accordance with MPM Paragraph 05-50-1, apply the maintenance task 25 "Perform a detail inspection of internal and external visible parts of the fuel tanks for debris, cleanliness, contamination and presence of fungus. Ref to para 28-11-8".
- 3. Return the helicopter to flight configuration and record for compliance with Part IV of this Service Bulletin on the helicopter logbook.
- 4. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".

As an alternative, send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:

AWPC.Engineering.Support@leonardocompany.us





Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY		SERVICE BULLETIN COMPLIANCE FORM			Date:	
		Number:				
PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988						
		Revision:				
Customer Name and Address:		Telephone:				
				Fax:		
			B.T. Compliance Date:			
Helicopter Model S/N			Total Number		Total Hours	T.S.O.
Remarks:						
Information:						

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.