

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

SERVICE BULLETIN

RECOMMENDED

_{N°} 139-778

DATE: June 12, 2024

REV.: /

TITLE

ATA 55 - TAIL PLANE ROD ASSY INSTALLATION INSPECTION

REVISION LOG

First Issue



1. PLANNING INFORMATION

A. EFFECTIVITY

All the tail plane rod assy P/N 3G5510A08931 with S/N reported in Annex A and NOT compliant with this Service Bulletin, installed on AB/AW139 helicopters and/or kept in stock.

B. COMPLIANCE

NOTE

The compliance time is subject to the same tolerances as per AMPI Chap. 05 DM 39-A-05-11-00-00A-028E-P Permitted inspection/check interval tolerances - General.

NOTE

The following compliance applies to the tail plane rod assy P/N 3G5510A08931 installed on AB/AW139 helicopters.

Within and not later than 300 flight hours after the issue of this Service Bulletin.

NOTE

The following compliance applies to the tail plane rod assy P/N 3G5510A08931 kept in stock.

Before the installation on the helicopter.

Leonardo Helicopters recommends the implementation of this SB in accordance with the indicated compliance time, with related tolerances as applicable. It is Operator's responsibility to properly plan and execute the SB application in accordance with Leonardo Helicopters recommendations. The Operator remains liable for any deviation.

C. CONCURRENT REQUIREMENTS

N.A.

D. REASON

Leonardo Helicopters issued this Service Bulletin as consequence of some in-service reports and a Quality Alert from MAG: it has been identified a batch of potentially non-conformant tail plane rod assy P/N 3G5510A08931 because of the incorrect placement of the "INBOARD" decal P/N 3G1120A13951.

This Service Bulletin is issued in order to identify and correct the affected components.



Leonardo Helicopters issued this SB for the following reason:

Helicopter Reliability/Maintainability			
Product Improvement			
Obsolescence			
Customization			
Product/Capability Enhancement			

E. DESCRIPTION

This Service Bulletin provides the necessary instructions to:

- identify the affected tail plane rod assy P/N 3G5510A08931 from a list of potentially affected component S/Ns, inspecting the item(s) installation on the helicopter or the item(s) kept in stock;
- fix the issue on the affected components, replacing the "INBOARD" decal P/N 3G1120A13951, as applicable;
- restore the correct tail plane rod assy P/N 3G5510A08931 installation for the affected item(s) installed on the helicopter.

F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives.

If an aircraft listed in the effectivity embodies a modification or repair not Leonardo Helicopters certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

G. MANPOWER

To comply with this Service Bulletin, approximately six (6) MMH are deemed necessary.

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024

REVISION: / Page 3 of 17



MMH are based on hands-on time and can change with helicopter configuration, personnel and facilities available. MMH are not comprehensive of the overall hours necessary to get access to work areas and to remove all the equipment that interferes with the application of the prescribed instructions.

H. WEIGHT AND BALANCE

N.A.

I. REFERENCES

I.1 PUBLICATIONS

Following Data Modules refer to AMPI:

DATA	<u>MODULE</u>	<u>DESCRIPTION</u>	<u>PART</u>
DM01	39-A-05-11-00-00A-028E-P	Permitted inspection/check interval tolerances – General	-

Following Data Modules refer to AMP:

DATA MODULE		MODULE	DESCRIPTION	<u>PART</u>
	DM02	39-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance	-
	DM03	39-A-06-41-00-00A-010A-A	Access doors and panels – General data	-
	DM04	39-A-11-00-01-00A-520A-A	Decal (polyester film) – Remove procedure.	-
	DM05	39-A-11-00-01-00A-720A-A	Decal – Install procedure	-
	DM06	39-C-55-11-02-00A-520A-A	Left rod – Remove procedure	-
	DM07	39-C-55-11-02-00A-720A-A	Left rod – Install procedure	-
	DM08	39-C-55-11-03-00A-520A-A	Right rod – Remove procedure	-
	DM09	39-C-55-11-03-00A-720A-A	Right rod – Install procedure	-

I.2 ACRONYMS & ABBREVIATIONS

AMDI	Aircraft Material Data Information
AMP	Aircraft Maintenance Publication
AMPI	Aircraft Maintenance Planning Information
AR	As Required
DM	Data Module
DOA	Design Organization Approval
EASA	European Union Aviation Safety Agency
IPD	Illustrated Parts Data Publication



ITEP Illustrated Tools and Equipment Publication

LH Left Hand

MAG Mecaer Aviation Group

MMH Maintenance Man Hours

N.A. Not Applicable

P/N Part Number

RH Right Hand

SB Service Bulletin

S/N Serial Number

I.3 ANNEX

AFFECTED TAIL PLANE ROD ASSY P/N 3G5510A08931 S/NS Annex A LIST

J. PUBLICATIONS AFFECTED

N.A.

K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.

S.B. N°139-778 RECOMMENDED

REVISION: / Page 5 of 17

DATE: June 12, 2024



2. MATERIAL INFORMATION

A. REQUIRED MATERIALS

A.1 PARTS

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL	NOTE	LOG P/N
1	3G1120A13951		Decal "INBOARD"	AR		(1)	-

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

A.2 CONSUMABLES

Refer to AMDI for the consumable materials required to comply with the AMP DMs referenced in the accomplishment instructions.

A.3 LOGISTIC MATRIX

N.A.

NOTES

(1) Item to be ordered in q.ty 1 only if the installed one is not compliant.

B. SPECIAL TOOLS

The following special tools, or equivalent, are necessary to accomplish this Service Bulletin:

#	P/N	DESCRIPTION	Q.TY	NOTE	PART
2	Commercial	Caliper gauge	1	(B1)	-

Refer also to ITEP for the special tools required to comply with the AMP DMs referenced in the accomplishment instructions.

SPECIAL TOOLS NOTES

(B1) Item to be procured as local supply.

S.B. N°139-778 RECOMMENDED DATE: June 12, 2024



C. INDUSTRY SUPPORT INFORMATION

Owners/operators who comply with the instructions of this Service Bulletin no later than the applicable date in the "Compliance" section will be eligible to receive required materials on free of charge basis, except for Consumable Materials and Special Tools. NOTE: Customers who fail to comply with the instructions in this Service Bulletin before the compliance date are not eligible for the aforementioned special policy.

Please Issue relevant MMIR form to your Warranty Administration Dpt. including the Inspection Report Form in Figure 4 completed in every part and the Log Card of the affected S/N.

If the required documentation is not be provided, the relevant MMIR will be rejected.

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024



3. ACCOMPLISHMENT INSTRUCTIONS

GENERAL NOTES

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- b) Let adhesive cure at room temperature for at least 24 hours unless otherwise specified.
- c) Exposed thread surface and nut must be protected using a layer of tectyl according to MIL-C-16173 grade I.
- d) All lengths are in mm.

NOTE

The following steps 1, 2, 3, 4, 6, 10 and 13 are not applicable to the tail plane rod assy P/N 3G5510A08931 kept in stock.

- 1. In accordance with AMP DM 39-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. In accordance with AMP DM 39-A-06-41-00-00A-010A-A and with reference to Figure 1 View A, remove the access panels 360DL and 360CL to gain access to the area affected by the inspection.
- 3. With reference to Figure 1 View B, Figure 2 and Figure 3, check if the tail plane rod assy P/N 3G5510A08931 is installed in the correct position, as described in the following procedure:



NOTE

As shown in Figure 3, the correct installation of the tail plane rod assy P/N 3G5510A08931 has:

- the longer highlighted side of the fork end (blue)
 on the OUTBOARD side of the installation;
- the shorter highlighted side of the fork end (green) on the INBOARD side of the installation.
- 3.1 Using a caliper gauge, take the dimension "A" and "B" on the fork lug of the tail plane rod assy P/N 3G5510A08931 and verify that the larger dimension is on the inboard side of the tail plane rod assy installation.
- 3.2 In case of findings, compile and send the Inspection Report Form in Figure 4 and proceed with step 6; otherwise proceed with the following step.
- 4. In accordance with Figure 1 View B, check if the decal "INBOARD" P/N 3G1120A13951 facing the inboard side of the helicopter.
 - In case of not compliant decal installation, compile and send the Inspection Report Form in Figure 4 and proceed with step 6; otherwise proceed with step 11.

NOTE

The following step 5 is applicable ONLY to the tail plane rod assy P/N 3G5510A08931 kept in stock.

NOTE

The decal "INBOARD" P/N 3G1120A13951 must be installed on the same side where fork lug is located 11.7 mm from rod axis (Ref. Figure 2 Detail C).

- 5. In accordance with Figure 2, check if the decal "INBOARD" P/N 3G1120A13951 is installed in the correct position.
 - In case of not compliant installation, compile and send the Inspection Report Form in Figure 4 and proceed with step 7, otherwise proceed with step 11.
- 6. In accordance with AMP DM 39-C-55-11-02-00A-520A-A (LH side) or DM 39-C-55-11-03-00A-520A-A (RH side) and with reference to Figure 1, remove the left or right tail plane rod assy P/N 3G5510A08931 from the helicopter, as necessary.

NOTE

The following steps 7 thru 9 are applicable to the tail plane rod assy P/N 3G5510A08931 both removed from the helicopter and kept in stock.

7. Put the tail plane rod assy on an applicable work table.

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024

REVISION: / Page 9 of 17



8. In accordance with AMP DM 39-A-11-00-01-00A-520A-A and with reference to Figure 2 View D, remove the existing decal from the wrong position on the tail plane rod assy P/N 3G5510A08931.

NOTE

Install the decal "INBOARD" P/N 3G1120A13951 taking care to bond it on the same side where fork lug is located 11.7 mm from rod axis (Ref. Figure 2 Detail C).

- 9. In accordance with AMP DM 39-A-11-00-01-00A-720A-A and with reference to Figure 2, install the new decal "INBOARD" P/N 3G1120A13951 to the indicated position on the tail plane rod assy P/N 3G5510A08931.
- 10. In accordance with AMP DM 39-C-55-11-02-00A-720A-A (LH side) or DM 39-C-55-11-03-00A-720A-A (RH side) and with reference to Figure 1, install the left or right tail plane rod assy P/N 3G5510A08931 on the helicopter, as necessary.

NOTE

The following step is applicable to the tail plane rod assy P/N 3G5510A08931 both removed from the helicopter and kept in stock.

- 11. Record for compliance with this Service Bulletin on the Log Card of the tail plane rod assy P/N 3G5510A08931.
- 12. In accordance with AMP DM 39-A-06-41-00-00A-010A-A and with reference to Figure 1 View A re-install the access panels 360DL and 360CL previously removed.
- 13. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
- 14. Gain access to My Communications section on <u>Leonardo Customer Portal</u> and compile the "Service Technical Bulletin Application".


As an alternative, send the attached compliance form to the following mail box:


engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:

AWPC.Engineering.Support@leonardocompany.us







VIEW B STRUCTURES AND SYSTEMS ARE PARTIALLY OMITTED FOR BETTER CLARITY PURPOSE

Figure 1

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024



NOTE:
INSTALL DECAL INBOARD TAKING CARE TO BOND IT ON THE SAME SIDE WHERE FORK LUG IS LOCATED 11.7 MM FROM ROD AXIS.





Figure 2





The correct installation of tail plane rod assy P/N 3G5510A08931 has:

- the longer highlighted side of the fork end (blue) on the **OUTBOARD** side of the installation;
- the shorter highlighted side of the fork end (green) on the INBOARD side of the installation.

LH tail pane rod assy shown. RH tail plane rod assy is opposite.

Figure 3

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024



SB 139-778 Rev. / – Inspection Report Form							
DATE							
Customer							
	S/I	N					
Affected							
Tail plane rod assy P/N 3G5510A08931	☐ INSTALLED ON THE HELICOPTER	☐ KEPT IN STOCK					
Note:							



ANNEX A

AFFECTED TAIL PLANE ROD ASSY P/N 3G5510A08931 S/NS LIST

DATE: June 12, 2024 REVISION: /

ANNEX A



MCR02148	MCR02178	MCR02211	MCR02244	MCR02281	MCR02347	MCR02380
MCR02149	MCR02181	MCR02212	MCR02247	MCR02282	MCR02348	MCR02381
MCR02150	MCR02182	MCR02213	MCR02250	MCR02283	MCR02349	MCR02382
MCR02151	MCR02183	MCR02214	MCR02251	MCR02284	MCR02350	MCR02383
MCR02152	MCR02184	MCR02215	MCR02252	MCR02285	MCR02351	MCR02387
MCR02153	MCR02185	MCR02216	MCR02253	MCR02286	MCR02354	MCR02388
MCR02154	MCR02186	MCR02217	MCR02254	MCR02287	MCR02355	MCR02390
MCR02155	MCR02187	MCR02218	MCR02256	MCR02288	MCR02356	MCR02391
MCR02156	MCR02188	MCR02219	MCR02257	MCR02289	MCR02357	MCR02392
MCR02157	MCR02189	MCR02220	MCR02258	MCR02290	MCR02358	MCR02393
MCR02158	MCR02190	MCR02221	MCR02259	MCR02291	MCR02359	MCR02394
MCR02159	MCR02191	MCR02222	MCR02260	MCR02292	MCR02360	MCR02395
MCR02160	MCR02192	MCR02223	MCR02261	MCR02293	MCR02361	MCR02396
MCR02161	MCR02194	MCR02224	MCR02262	MCR02294	MCR02362	MCR02405
MCR02162	MCR02195	MCR02225	MCR02263	MCR02295	MCR02363	MCR02408
MCR02163	MCR02196	MCR02227	MCR02264	MCR02296	MCR02364	MCR02409
MCR02164	MCR02197	MCR02228	MCR02265	MCR02297	MCR02365	MCR02410
MCR02165	MCR02198	MCR02229	MCR02267	MCR02298	MCR02366	MCR02412
MCR02166	MCR02199	MCR02231	MCR02268	MCR02299	MCR02367	MCR02413
MCR02167	MCR02200	MCR02232	MCR02270	MCR02300	MCR02368	MCR02414
MCR02168	MCR02201	MCR02233	MCR02271	MCR02301	MCR02369	MCR02416
MCR02169	MCR02202	MCR02234	MCR02272	MCR02302	MCR02371	MCR02417
MCR02170	MCR02203	MCR02235	MCR02273	MCR02303	MCR02372	MCR02419
MCR02171	MCR02204	MCR02236	MCR02274	MCR02304	MCR02373	MCR02420
MCR02172	MCR02205	MCR02237	MCR02275	MCR02305	MCR02374	MCR02421
MCR02173	MCR02206	MCR02239	MCR02276	MCR02306	MCR02375	MCR02422
MCR02174	MCR02207	MCR02240	MCR02277	MCR02329	MCR02376	MCR02424
MCR02175	MCR02208	MCR02241	MCR02278	MCR02343	MCR02377	MCR02425
MCR02176	MCR02209	MCR02242	MCR02279	MCR02344	MCR02378	MCR02427
MCR02177	MCR02210	MCR02243	MCR02280	MCR02345	MCR02379	MCR02428

ANNEX A



MCR02429	MCR02435	MCR02447	MCR02453	MCR02464	MCR02470	MCR02484
MCR02430 MCR02436 MCR0		MCR02448	MCR02454	MCR02465	MCR02471	MCR02485
MCR02431	MCR02443	MCR02449	MCR02455	MCR02466	MCR02472	MCR02486
MCR02432	MCR02444	MCR02450	MCR02456	MCR02467	MCR02473	MCR02487
MCR02433	MCR02445	MCR02451	MCR02457	MCR02468	MCR02474	MCR02488
MCR02434	MCR02446	MCR02452	MCR02463	MCR02469	MCR02483	MCR02490

S.B. N°139-778 RECOMMENDED

DATE: June 12, 2024 REVISION: /



Please send to the following address:		SERVICE BULLETIN COMPLIANCE FORM Date:					
LEONARDO S.p.							
CUSTOMER SUPPORT & SE	Number:						
PRODUCT SUPPORT ENGINEE	RING & LICENSES DEPT.						
Via Giovanni Agusta, 520 21017 Cascina Costa di Samara	ate (VA) - ITALY	Revision:					
Tel.: +39 0331 225036 Fax: +39	0331 225988						
Customer Name and Addre	ess:			Telephone:			
				·			
				Fax:			
				B.T. Compli	iance Date:		
Helicopter Model	S/N		Total N	umber	Total Hours	T.S.O.	
Remarks:							
Information:							
We request your cooperation in its parts and sent to the above	n filling this form, in order to address or you can commu	keep out sta	atistical data rel oplication also v	evant to aircrai ia Technical Bi	ft configuration up-to-date. Thulletin Application Communic	ne form should be filled in all ation Section placed in	

Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.