

PRATT & WHITNEY CANADA  
**SERVICE BULLETIN**

P&WC S.B. No. 41119R4

**BULLETIN INDEX LOCATOR**  
**74-10-00**


TURBOSHAFT ENGINE  
IGNITION EXCITER - REPLACEMENT OF

MODEL APPLICATION

PT6C-67C, PT6C-67C1

Compliance: CATEGORY 7

Summary: The ignition exciter spider switch is no longer available due to obsolescence. Replace the ignition exciter with one that has an available spider switch.



Feb 11/2021  
Revision No. 4: Jun 25/2021

**PT6C-74-41119**  
Cover Sheet

24-Hour Global Service <b>CFIRST CENTRE</b> Toll free where available (SIL GEN-027)	USA & CANADA..... 1-800-268-8000 International ..... (IAC*)+8000-268-8000 * International Access Code	Other ..... 1-450-647-8000 Fax ..... 1-450-647-2888 Web Site ..... <a href="http://www.pwc.ca">www.pwc.ca</a>
---	---	---

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:

VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.



Jun 25/2021

P&WC S.B. No. 41119R4

REVISION TRANSMITTAL SHEET  
TURBOSHAFT ENGINE MODEL PT6C

SUBJECT: Pratt & Whitney Canada Service Bulletin No. PT6C-74-41119, Rev. No. 4 dated Jun 25/2021 (P&WC S.B. No. 41119R4) IGNITION EXCITER - REPLACEMENT OF

Replace your existing copy of this service bulletin with the attached revised bulletin. Destroy the superseded copy.

Please retain this Revision Transmittal Sheet with the revised bulletin.

SUMMARY:

This revision is issued to:

- modify the PT6C-67C engine effectivity,

EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT:

None.

REVISION HISTORY:

Original Issue: Feb 11/2021

Revision No. 1: Apr 27/2021

Revision No. 2: May 18/2021

Revision No. 3: May 26/2021

Revision No. 4: Jun 25/2021



PRATT & WHITNEY CANADA  
**SERVICE BULLETIN**

P&WC S.B. No. 41119R4

TURBOSHAFT ENGINE  
IGNITION EXCITER - REPLACEMENT OF

1. Planning Information

A. Effectivity

PT6C-67C (BS963, BS1019) Engines which are before and include Serial No.  
PCE-KB2540 including KB2549 to KB2552, KB2553, KB2561, KB2562, KB2564,  
KB2566, KB2568, KB2570, KB2571, KB2572 and KB2575.  
PT6C-67C1 (BS1447, BS1448) Engines.

NOTE: The above effectivity list does not identify engines that have been converted from one engine model to another via an engine conversion service bulletin. To clarify the effectivity of converted engines, refer to the original engine effectivity above. For the parts embodied during the engine conversion, refer to conversion service bulletin.

B. Concurrent Requirements

None.

C. Reason

(1) Problem

The ignition exciter spider switch is no longer available.

(2) Cause

The ignition exciter spider switch has been obsoleted.

(3) Solution

Replace the ignition exciter with one that has an available spider switch.

D. Description

Replace the ignition exciter with a new one.

E. Compliance

CATEGORY 7 - You can do this service bulletin when the supply of superseded parts is fully used.

F. Approval

D.O.T./D.A.A. approved.

G. Manpower

Once you have access to the part, an estimate of 1.0 man-hours is required to include this service bulletin at repair.

P&WC No. CO-0010439, CO-0010811

Feb 11/2021

Revision No. 4: Jun 25/2021

P&WC Proprietary Information. Subject to the restrictions on the back of the locator

© 2021 Pratt & Whitney Canada Corp.

PRINTED IN CANADA

**PT6C-74-41119**

Page 1 of 5

PRATT & WHITNEY CANADA  
**SERVICE BULLETIN**

P&WC S.B. No. 41119R4

TURBOSHAFT ENGINE  
IGNITION EXCITER - REPLACEMENT OF

1. Planning Information (Cont'd)

No more man-hours are necessary to include this service bulletin at overhaul.

H. Weight and Balance

None.

I. Electrical Load Data

Not applicable.

J. Software Accomplishment Summary

Not applicable.

K. References

Illustrated Parts Catalog P/N [3045334](#) (PT6C-67C/C1)

Maintenance Manual P/N [3045332](#) (PT6C-67C/C1)

Overhaul Manual P/N [3045333](#) (PT6C-67C/C1)

Champion SBCH92106-74-003

L. Publications Affected

Illustrated Parts Catalog P/N [3045334](#) (PT6C-67C/C1)

Champion CMM 74-11-05

M. Interchangeability and Intermixability of Parts

Interchangeability - Refer to Para. 2.C.

Intermixability - Not changed.

2. Material Information

A. Industry Support Information

Not applicable.

B. Material - Price and Availability

You can get the procurable parts listed in Para. 2.C. from any Pratt & Whitney Canada Parts Distribution Center.

# PRATT & WHITNEY CANADA SERVICE BULLETIN

P&WC S.B. No. 41119R4

## TURBOSHAFT ENGINE IGNITION EXCITER - REPLACEMENT OF

### 2. Material Information (Cont'd)

The estimated total cost of new parts needed to replace old parts is \$Quote (US, 2021).

The new parts will be available March 1st.

### C. Material Necessary for Each Engine

The quantity of materials listed in this section is on a per engine basis.

<u>New P/N</u>	<u>Keyword</u>	<u>Old P/N</u>	<u>Qty</u>	<u>Est. Unit List Price (\$US, 2021)</u>	<u>Instructions Dispositions</u>
	Ignition Exciter (0AFL4) P&WC P/N 3043937-07	CH92106-2	1		(A)(B)
<a href="#">CH92106-4</a>	Ignition Exciter (0AFL4) P&WC P/N 3043937-09		1	Quote	(A)

(A) TWO WAY INTERCHANGEABLE (ATA200 Explanation Code 02): The old or the new parts can replace the old or the new part.

(B) Discard the part if it is unserviceable. Return a serviceable part to stock.

### D. Reidentified Parts

None.

### E. Tooling - Price and Availability

Not Applicable

### 3. Accomplishment Instructions

A. Remove the parts in the Old P/N list in Para. 2.C., Material Information, in accordance with the maintenance or overhaul manual instructions as follows:

Ref. MM 74-10-00.

Ref. OHM 74-10-00.

B. Install the parts in the New P/N list in Para. 2.C., Material Information, in accordance with the maintenance or overhaul manual instructions as follows:

Ref. MM 74-10-00.

Ref. OHM 74-10-00.


C. Write the accomplishment of P&WC SB41119 in the engine module log book.

### 4. Appendix

PRATT & WHITNEY CANADA  
**SERVICE BULLETIN**

P&WC S.B. No. 41119R4

TURBOSHAFT ENGINE  
IGNITION EXCITER - REPLACEMENT OF



ICN-00198-G000042847-001-01

Ignition Exciter - Part Progression  
Figure 1



PRATT & WHITNEY CANADA  
**SERVICE BULLETIN**

P&WC S.B. No. 41119R4

TURBOSHAFT ENGINE  
IGNITION EXCITER - REPLACEMENT OF

4. Appendix (Cont'd)

None.