

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2021-10

4/26/2021 - 5/9/2021



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-01

2020-26-10		Leonardo S.p.a.	A119 and AW119 MKII
2020-26-13		Sikorsky Aircraft Corporation	S-92A
2020-26-14	R 75-16-20	Mitsubishi Heavy Industries, Ltd.	MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, MU-2B-26, MU-2B-26A, MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, MU-2B-40, and MU-2B-60

Biweekly 2021-02

2020-26-16		Piper Aircraft, Inc.	PA-28-151, PA-28-161, PA-28-181, PA-28-235, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-32-260, PA-32-300, PA-32R-300, PA-32RT-300, and PA-32RT-300T
------------	--	----------------------	---

Biweekly 2021-03

2021-01-02		M7 Aerospace LLC	SA26-AT and SA26-T
------------	--	------------------	--------------------

Biweekly 2021-04

2021-02-20		Hélicoptères Guimbal	Cabri G2
2021-04-04	R 2020-19-02	Airbus Helicopters	SA330J
2021-04-06		Pilatus Aircraft Ltd.	PC-7

Biweekly 2021-05

2020-26-19		Pilatus Aircraft Ltd.	PC-7
2021-01-05		Pilatus Aircraft Ltd.	PC-24
2021-02-03		Leonardo S.p.a.	AW189
2021-02-04		Pilatus Aircraft Ltd.	PC-12/47E
2021-03-01	R 2018-05-09	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, and SA330J
2021-03-04		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-03-06		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1
2021-03-07		Leonardo S.p.a.	AB139 and AW139
2021-03-13		Bell Textron Canada Limited	429
2021-03-15	R 2020-13-02	Leonardo S.p.a.	A119 and AW119 MKII
2021-03-16		Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-04-03		Pilatus Aircraft Ltd.	PC-24
2021-04-07		Piper Aircraft, Inc.	PA-46-350P; PA-46-500TP; PA-46R-350T
2021-04-08		Airbus Helicopters	AS350B3
2021-05-52	E	Bell Textron Canada Limited	505

Biweekly 2021-06

2021-02-01	R 2015-26-01	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC225LP, AS-365N2, AS 365 N3, EC 155B and EC155B1
2021-02-08	R 2018-19-01	Airbus Helicopters	AS-365N2, AS 365 N3, EC 155B, EC155B1, SA-365N, SA-365N1, and SA-366G1
2021-02-09		Airbus Helicopters	EC 155B and EC155B1
2021-02-11		Airbus Helicopters Deutschland GmbH	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, and MBB-BK117 C-2
2021-04-01		Leonardo S.p.a.	AB139 and AW139
2021-04-10		Textron Aviation, Inc.	208 and 208B
2021-04-12		Robinson Helicopter Company	R66
2021-04-13		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130 B4 and EC130 T2
2021-04-15		Airbus Helicopters	AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; AS350B3
2021-04-16		Sikorsky Aircraft Corporation	S-92A
2021-04-17		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, AS355F2, and AS355N
2021-04-18	R 2020-23-02	Airbus Helicopters	EC225LP

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-04-19		Bell Textron Inc.	205B
2021-05-01		Airbus Helicopters	SA330J
2021-05-02		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130B4 and EC130T2
2021-05-04		Leonardo S.p.a.	A109S and AW109SP
2021-05-05	R 2016-23-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2021-05-07		Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, and BO-105S; MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-05-08		Safran Helicopter Engines, S.A.	Arriel 2C, 2C1, 2S1, and 2S2
2021-05-09	R 2018-15-02	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-05-22		Safran Helicopter Engines, S.A.	Arriel 1B, Arriel 1C, Arriel 1C2, and Arriel 1D1; Astazou XIV B and Astazou XIV H
Biweekly 2021-07			
2021-05-06		Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC 155B, EC155B1, EC225LP, and SA330J
2021-05-13		Leonardo S.p.a.	AW189
2021-05-14		Air Tractor, Inc.	AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-401B, AT402, AT-402A, AT-402B, AT-501, AT-502, AT-502A, AT-502B, AT-503, AT-503A, AT-504, AT-602, AT-802, and AT-802A
2021-05-17	R 2019-12-09	Rockwell Collins, Inc.	Flight Display System Application FDSA-6500
2021-06-02		Airbus Helicopters	AS332L, AS332L1, AS332C, and AS332C1
2021-06-06	R 2021-05-52	Bell Textron Canada Limited	505
2021-07-05	R 2007-26-52	Leonardo S.p.a.	A109C, A109E, and A109K2
2021-07-08	R 97-26-02	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3
Biweekly 2021-08			
2021-04-21		Airbus Helicopters	EC120B
2021-05-15	A 2019-09-03	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2021-05-19		Sikorsky Aircraft and Sikorsky Aircraft Corporation	S-61L, S-61N, S-61NM, and S-61R; S-61A, S-61D, S-61E, and S-61V
2021-05-21	R 2017-23-08	Leonardo S.p.a.	AB139 and AW139
2021-06-01		Pilatus Aircraft Ltd.	PC-24
2021-06-05	R 2017-07-08	Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-07-07		Airbus Helicopters	EC 155B and EC155B1
2021-07-12		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-07-13		Pacific Scientific Company	rotary buckle assembly
2021-07-15	R 82-20-05	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-08-07		Rockwell Collins, Inc.	GPS-4000S
Biweekly 2021-09			
2021-07-16		Leonardo S.p.a.	AB412
2021-08-06	R 97-06-10	Textron Aviation Inc.	76
2021-08-15		Garmin International	GMN-00962 GTS
2021-08-18	R 2021-04-16	Sikorsky Aircraft Corporation	S-92A
2021-09-02	R 2021-04-07	Piper Aircraft, Inc.	PA-46-350P (Malibu Mirage), PA-46R-350T (Malibu Matrix), and PA-46-500TP (Malibu Meridian)
2021-09-04		Austro Engine GmbH	E4 and E4P
2021-09-07	R 2019-17-02	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-09-09		Uninsured United Parachute Technologies, LLC	Vector 3 SE

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-10

2021-08-05		Airbus Helicopters	SA341G and SA342J
2021-08-16		PZL Swidnik S.A.	W-3A
2021-08-17		Airbus Helicopters	AS332L2
2021-09-05	R 2016-08-20	Airbus Helicopters	EC130B4 and EC130T2
2021-10-08		Bell Textron Canada Limited	206L, 206L-1, 206L-3, and 206L-4



2021-08-05 Airbus Helicopters: Amendment 39-21499; Docket No. FAA-2020-1165; Project Identifier 2019-SW-027-AD.

(a) Effective Date

This airworthiness directive (AD) is effective June 1, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model SA341G and SA342J helicopters, certificated in any category, equipped with any tail rotor blade (TRB) specified in paragraph (c)(1) or (2) of this AD.

(1) An affected part as defined in European Union Aviation Safety Agency (EASA) AD 2019-0034, dated February 14, 2019 (EASA AD 2019-0034).

(2) A TRB having part number (P/N) 341A335101.01, P/N 341A335130.05, or P/N 341A335130.06.

(d) Subject

Joint Aircraft System Component (JASC) Code 6410, Tail Rotor Blades.

(e) Reason

This AD was prompted by the determination that a new life limit was necessary for TRBs that were manufactured without a new process that affects the structural characteristics. The FAA is issuing this AD to address TRBs that might break, resulting in loss of tail rotor control and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0034.

(h) Exceptions to EASA AD 2019-0034

(1) Where EASA AD 2019-0034 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0034 does not apply to this AD.

(3) Where EASA AD 2019-0034 refers to flight hours (FH), this AD requires using hours time-in-service.

(4) Where paragraph (4) of EASA AD 2019-0034 specifies to contact the manufacturer, for this AD, repair using a method approved by the Manager, Strategic Policy Rotorcraft Section, FAA. For a repair method to be approved by the Manager, Strategic Policy Rotorcraft Section, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

(5) Where paragraph (5) of EASA AD 2019-0034 specifies it must be determined that the rework/repair/modification is valid for part number 341A335130.06, for this AD, rework/repair/modification of an affected part is prohibited.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Blaine Williams, Aerospace Engineer, Los Angeles ACO Branch, 3960 Paramount Blvd., Lakewood, California, 90712; telephone (562) 627-5371; email blaine.williams@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0034, dated February 14, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0034, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the

AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1165.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 30, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-08564 Filed 4-23-21; 8:45 am]



2021-08-16 PZL Swidnik S.A.: Amendment 39-21510; Docket No. FAA-2021-0299; Project Identifier MCAI-2020-00253-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 11, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to PZL Swidnik S.A. (PZL) Model W-3A helicopters, certificated in any category, with a Collins Aerospace (formerly Goodrich) electric hoist (hoist) part number (P/N) 76378-500 with a stainless steel cable (cable) P/N 712952 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2597, Equip/Furnishing System Wiring.

(e) Unsafe Condition

This AD defines the unsafe condition as wear and reduction of the cable diameter near the swaged terminal due to movement of the hook assembly. This condition could result in reduced strength of the cable, potentially resulting in an in-flight loss of the hoist load, injury to persons, and reduced control of or damage to the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless accomplished previously.

(g) Required Actions

(1) Within 25 hours time-in service on the hoist (hoist hours) after the effective date of this AD, and thereafter at intervals not to exceed 25 hoist hours:

(2) Remove the bottom part of the hook assembly, disengage and lift the hook assembly, clean the cable near the swaged terminal, and visually inspect for wear and damage. For the purposes of this AD, damage may be indicated by broken wires, kinks, bird cages, flattened areas, abrasion, necking, corrosion, or fretting. Visually inspect the area at no less than 12 cm of the cable between the cable swaged terminal and the hook assembly, as depicted in Figures 2 and 3 of Goodrich Actuation Systems Alert Service Bulletin 76378-500-25-P01, Revision 0, dated December 3, 2019 (ASB 76378-500-25-P01).

(i) If the cable is worn or damaged, before the next hoist operation, remove the cable from service and replace with an airworthy part. Within 30 calendar days, email the non-compliant information in accordance with paragraph 3.A.(4)(a) of ASB 76378-500-25-P01 to PL-CustomerSupport.AW@leonardocompany.com.

(ii) If there is no damage, before the next hoist operation, inspect the cable diameter restriction on the 12 cm length ensuring the cable diameter is ≥ 4.60 mm (0.181 in) paying particular attention to the cable diameter which is approximately 1 cm from the cable swaged terminal.

(iii) If the cable diameter is less than 4.60 mm (0.181 in), before the next hoist operation, replace the cable with an airworthy part. Within 30 calendar days, email the non-complaint information in accordance with paragraph 3.B.(1)(f) of ASB 76378-500-25-P01 to PL-CustomerSupport.AW@leonardocompany.com.

(iv) If the cable diameter is ≥ 4.60 mm (0.181 in), lubricate the cable with oil MIL-L-23699 or MIL-L-7808, or equivalent, reassemble bottom part of the hook assembly on the upper part, and bring the hook assembly back to the stowage position.

(3) As of the effective date of this AD, do not install a hoist or cable with a P/N identified in paragraph (c) of this AD unless they meet the conditions as required by paragraph (g) of this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Kristi Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email kristin.bradley@faa.gov.

(2) WYTWÓRNA SPRZETU KOMUNIKACYJNEGO “PZL-Świdnik” Spółka Akcyjna Mandatory Alert Service Bulletin No. BO-37-19-309, dated January 28, 2020, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact WSK “PZL-Świdnik” S.A., Al. Lotników Polskich 1, 21-045 Świdnik, Poland; telephone +48-664 424 798; fax (+48) 817 225 710; or at www.pzl.swidnik.pl. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2020-0017, dated January 30, 2020. You may view the EASA AD on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2021-0299.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Goodrich Actuation Systems Alert Service Bulletin 76378-500-25-P01, Revision 0, dated December 3, 2019 (ASB 76378-500-25-P01).

Note 1 to paragraph (j)(2)(i): ASB 76378-500-25-P01 is attached to WYTWÓRNIA SPRZETU KOMUNIKACYJNEGO “PZL-Świdnik” Spółka Akcyjna Alert Service Bulletin No. ASB-37-19-309, dated January 28, 2020, which is not incorporated by reference in this AD.

(ii) [Reserved]

(3) As the design approval holder for the product identified in paragraph (c) of this AD, contact PZL Swidnik S.A. for the Goodrich Actuation Systems service information identified in this AD, at WSK “PZL-Świdnik” S.A., Al. Lotników Polskich 1, 21-045 Świdnik, Poland; telephone +48-664 424 798; fax (+48) 817 225 710; or at www.pzl.swidnik.pl.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 7, 2021.

Lance T. Gant,
Director, Compliance & Airworthiness Division, Aircraft Certification Service.
[FR Doc. 2021-08567 Filed 4-23-21; 8:45 am]



2021-08-17 Airbus Helicopters: Amendment 39-21511; Docket No. FAA-2021-0300; Project Identifier MCAI-2020-01077-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 12, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model AS332L2 helicopters with main gearbox (MGB) part number (P/N) 332A323001.XX with a main reduction gear module (module) P/N 332A323011.XX that has free wheel shaft P/N 332A322191.20 installed, where “XX” stands for any two digit dash number, certificated in any category.

Note 1 to paragraph (c): Free wheel shaft P/N 332A322191.20 is also referred to as modification 07-53016.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

(e) Unsafe Condition

This AD defines the unsafe condition as wear on the ramps and roller cages of the MGB free wheel shaft. This condition could result in reduced one engine inoperative (OEI) power from by the right engine following an in-flight shut-down of the left engine, resulting in reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless accomplished previously.

(g) Required Actions

(1) Within 50 hours time-in-service (TIS) after the effective date of this AD, install a placard on the instrument panel prohibiting use of the ENG1 “TRAINING IDLE” switch in accordance with Figure 3 of Airbus Helicopters Alert Service Bulletin AS332-01.00.95, Revision 1, dated July 29, 2020.

(2) Replace the MGB with an airworthy MGB at the following compliance time:

(i) If the free wheel shaft has accumulated less than 950 total hours TIS, before the free wheel shaft accumulates 1,000 total hours TIS; or

(ii) If the free wheel shaft has accumulated 950 or more total hours TIS, within 50 hours TIS after the effective date of this AD.

(3) As of the effective date of this AD, do not install a right free wheel shaft P/N 332A322191.20 on any helicopter unless the free wheel shaft has accumulated less than 1,000 total hours TIS.

(4) If you replace the MGB with a MGB that does not have free wheel shaft P/N 332A322191.20 installed, you may remove the placard required by paragraph (g)(1) of this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Rao Edupuganti, Aviation Safety Engineer, Dynamic Systems Section, Technical Innovation Policy Branch, Policy & Innovation Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email rao.edupuganti@faa.gov.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2020-0141R1, dated July 30, 2020. You may view the EASA AD on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2021-0300.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin AS332-01.00.95, Revision 1, dated July 29, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 8, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft
Certification Service.

[FR Doc. 2021-08568 Filed 4-26-21; 8:45 am]



AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-09-05 Airbus Helicopters: Amendment 39-21518; Docket No. FAA-2020-1182; Product Identifier 2018-SW-036-AD.

(a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Model EC130B4 and EC130T2 helicopters, certificated in any category, with a tail boom to Fenestron junction frame (junction frame).

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in the junction frame. This condition could result in failure of the junction frame, which could result in loss of the Fenestron and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD replaces AD 2016-08-20, Amendment 39-18497 (81 FR 26103, May 2, 2016).

(d) Effective Date

This AD becomes effective June 2, 2021.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) For helicopters without modification (MOD) 074775, or MOD AH 350A087421 or SB EC130-53-029 installed, at the compliance time specified by the hours time-in-service (TIS) accumulated on the junction frame in Figure 1 to this paragraph, do the following:
Figure 1 to Paragraph (f)(1)

Junction Frame Accumulated Hours TIS	Compliance Time
Less than 325 hours TIS	Before accumulating 350 hours TIS, or within 25 hours TIS, whichever occurs later.
325 or more hours TIS, but less than 675 hours TIS	Within 25 hours TIS.
675 or more hours TIS	Before accumulating 700 hours TIS, or within 10 hours TIS, whichever occurs later.

(i) Remove the horizontal stabilizer; using a clean, lint-free, white cloth soaked with liquid Methyl Ethyl Ketone (MEK), clean the inside of the junction frame (a) as shown in Figure 1 of Airbus Helicopters Emergency Alert Service Bulletin No. 05A017, Revision 7, dated March 21, 2018 (EASB 05A017, Rev 7); and visually inspect for cracking around the circumference of the junction frame, in the web of the junction frame (a) and in the radius between the web and the flange of the tail boom side as shown in Figure 1 EASB 05A017, Rev 7. Pay particular attention to the area around the 4 spars (b) as shown in Figure 1 of EASB 05A017, Rev 7. Examples of cracks are shown in Figure 3 of EASB 05A017, Rev 7. If there is a crack, before further flight, replace or repair the junction frame in accordance with an FAA approved repair procedure. Repairing or replacing the junction frame does not constitute terminating action for the requirements of this AD.

(ii) Thereafter following paragraph (f)(1)(i) of this AD, within 25 hours TIS or 390 sling cycles for helicopters that perform external load carrying operations, whichever occurs first, and thereafter at intervals not exceeding 25 hours TIS or 390 sling cycles, whichever occurs first, either perform the actions of paragraph (f)(1)(i) of this AD or, if the surface of the junction frame area is clean, use a borescope through the horizontal stabilizer opening to borescope inspect for a crack around the circumference of the junction frame, and in the web of the junction frame (a) and in the radius between the web and the flange on the tail boom side as shown in Figure 2 EASB 05A017, Rev 7. Pay particular attention to the area around the 4 spars (b) of Figure 2 of EASB 05A017, Rev 7. Examples of cracks are shown in Figure 3 of EASB 05A017, Rev 7. For purposes of this AD, a sling cycle is defined as one landing with or without stopping the rotor or one external load-carrying operation; an external load-carrying operation occurs each time a helicopter picks up an external load and drops it off. If there is a crack, before further flight, replace or repair the junction frame in accordance with an FAA approved repair procedure. Repairing or replacing the junction frame does not constitute terminating action for the requirements of this AD.

(iii) Thereafter following paragraph (f)(1)(i) of this AD, within 150 hours TIS and thereafter at intervals not to exceed 150 hours TIS, accomplish the actions required by paragraph (f)(1)(i) of this AD. Accomplishment of this paragraph constitutes compliance for an instance of paragraph (f)(1)(ii) of this AD.

(2) For helicopters without MOD 074775 installed, but with MOD AH 350A087421 or SB EC130-53-029 installed, before the junction frame accumulates 350 hours TIS or within 10 hours TIS, whichever occurs later:

(i) Visually inspect for cracking on the junction frame (a) in the upper and lower right-hand side and upper and lower left-hand side areas of the skin cut-out as shown in Detail A, Figure 4 of EASB 05A017, Rev 7. If there is a crack, before further flight, replace or repair the junction frame in accordance with an FAA approved repair procedure. Repairing or replacing the junction frame does not constitute terminating action for the requirements of this AD.

(ii) Thereafter following paragraph (f)(2)(i) of this AD, within 10 hours TIS or 250 sling cycles for helicopters that perform external load carrying operations, whichever occurs first, and thereafter at intervals not exceeding 10 hours TIS or 250 sling cycles, whichever occurs first, accomplish the actions required by paragraph (f)(2)(i) of this AD.

(iii) Thereafter following paragraph (f)(2)(i) of this AD, within 660 hours TIS and thereafter at intervals not to exceed 660 hours TIS, accomplish the actions required by paragraph (f)(1)(i) of this AD. Accomplishment of this paragraph constitutes compliance for an instance of paragraph (f)(2)(ii) of this AD.

(3) For helicopters without MOD 074775 installed, with or without MOD AH 350A087421 or SB EC130-53-029 installed, without MOD 074609 or SB 53-024 installed, and on which the skin of the junction frame area has never been repaired, within 24 months as of the effective date of this AD, install MOD 074775 by following the Accomplishment Instructions, paragraphs 3.B.2.a. through g., of Airbus Helicopters Service Bulletin No. EC130-53-036, Revision 4, dated April, 28, 2020 (ASB EC130-53-036, Rev 4), except where ASB EC130-53-036, Rev. 4 specifies to certain discard parts, you are required to remove those parts from service instead and where ASB EC130-53-036, Rev 4.

specifies contacting Airbus Helicopters for corrective action, the corrective action must be accomplished using a method approved by the FAA. Where ASB EC130-53-036, Rev 4, specifies completing the table in Appendix 4.H. under paragraph 3.B.2.g., complete and return the table to Airbus Helicopters within 30 days after installing MOD 074775. Installation of MOD 074775 constitutes terminating action for the inspections required by paragraphs (f)(1) and (2) of this AD.

(4) For helicopters without MOD 074775 installed, with MOD 074609 or SB 53-024 installed, or on which the skin of the junction frame area has been previously repaired at any time, within 24 months as of the effective date of this AD, reinforce the junction frame by replacing the two lateral splices which join the skins with four carbon patches (left-hand side, right-hand side, and lower sides) in accordance with an FAA approved corrective procedure. Installation of this reinforcement constitutes terminating action for the inspections required by paragraphs (f)(1) and (2) of this AD.

(5) For Model EC130B4 helicopters with MOD 074775 installed or with the reinforcement that is required by paragraph (f)(4) of this AD; and for Model EC130T2 helicopters with MOD 074775 installed or with the reinforcement that is required by paragraph (f)(4) of this AD, but without MOD 074581 installed:

(i) Within 600 hours TIS after the installation of MOD 074775 or the reinforcement that is required by paragraph (f)(4) of this AD, and thereafter at intervals not exceeding 600 hours TIS, perform the actions of paragraph (f)(1)(i) of this AD.

(ii) If there is a crack, before further flight, replace or repair the junction frame in accordance with an FAA approved repair procedure. Repairing the junction frame does not constitute terminating action for the requirements of this AD.

(g) Special Flight Permits

Special flight permits are prohibited.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Kristi Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

(2) Airbus Helicopters Service Bulletin No. EC130-53-029, Revision 1, dated January 27, 2016, Airbus EC 130 B4 Chapter 4, Airworthiness Limitations Section, Revision 11, dated January 19, 2019, Airbus EC 130 T2 Chapter 4, Airworthiness Limitations Section, Revision 9, dated September 9, 2019, and Section 55-11-00, 6-4–Horizontal Stabilizer–Inspection/Check, of Aircraft Maintenance Manual EC130, dated November 9, 2017, which are not incorporated by reference, contain additional information about the subject of this AD. This service information is available at the contact information specified in paragraphs (k)(3) and (4) of this AD.

(3) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) 2018-0104, dated May 4, 2018. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2020-1182.

(j) Subject

Joint Aircraft Service Component (JASC) Code: 5302, Rotorcraft Tail Boom.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin No. 05A017, Revision 7, dated March 21, 2018.

(ii) Airbus Helicopters Service Bulletin No. EC130-53-036, Revision 4, dated April, 28, 2020.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 14, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-08781 Filed 4-27-21; 8:45 am]



2021-10-08 Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited): Amendment 39-21541 Docket No. FAA-2006-25084; Project Identifier 2005-SW-38-AD.

(a) Effective Date

This airworthiness directive (AD) is effective June 11, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited (type certificate previously held by Bell Helicopter Textron Canada Limited) Model 206L, 206L-1, 206L-3, and 206L-4 helicopters, certificated in any category, with a low fuel level detector switch unit (switch unit) part number (P/N) 206-063-613-003:

- (1) With a switch unit serial number (S/N) 1413, 1414, 1415, 1424, 1428, 1430, 1432, or 1433 installed, or
- (2) With a missing or illegible switch unit S/N or if the S/N cannot be determined, installed.

Note 1 to paragraph (c): Helicopters with a 206L-1+ designation are Model 206L-1 helicopters. Helicopters with a 206L-3+ designation are Model 206L-3 helicopters.

Note 2 to paragraph (c): The switch unit is located on the aft fuel boost pump assembly. The P/N and S/N for the switch unit could be on the outside face of the attachment flange, in the cross hatched area of the switch unit.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2842, Fuel Quantity Sensor.

(e) Unsafe Condition

This AD was prompted by a manufacturing flaw that could cause a switch unit to hang in the high position and fail to indicate a low fuel condition. The FAA is issuing this AD to prevent failure of the switch unit to indicate a low fuel condition that could lead to fuel exhaustion and which if not addressed, could result in a subsequent forced landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For a switch unit identified in paragraph (c)(1) of this AD, on or before the next 100-hour time-in-service inspection after the effective date of this AD, remove the switch unit from service.

(2) For a switch unit identified in paragraph (c)(2) of this AD, on or before the next 100-hour time-in-service inspection after the effective date of this AD:

(i) Determine the color of the switch unit mounting flange. If the mounting flange color is any color other than red, determine the purchase date. If the purchase date of the switch unit is between April 19 and July 26, 2004, or cannot be determined, do an operational test.

(ii) If the switch unit fails the operational test, before further flight, remove the switch unit from service.

(3) As of the effective date of this AD, do not install a switch unit identified in paragraph (c)(1) of this AD on any helicopter.

(4) As of the effective date of this AD, do not install a switch unit identified in paragraph (c)(2) of this AD on any helicopter unless the actions in paragraphs (g)(2)(i) and (ii) of this AD have been accomplished.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(2) Bell Helicopter Textron Alert Service Bulletin No. 206L-04-132, Revision A, dated October 4, 2004, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone (450) 437-2862 or (800) 363-8023; fax (450) 433-0272; or at <https://www.bellcustomer.com>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this AD is addressed in Transport Canada AD CF-2004-24, dated November 24, 2004. You may view the Transport Canada AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2006-25084.

(j) Material Incorporated by Reference

None.

Issued on April 28, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-09278 Filed 5-6-21; 8:45 am]