

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,  
BALLOONS, & AIRSHIPS**

**BIWEEKLY 2021-16**

*7/19/2021 - 8/1/2021*



Federal Aviation Administration  
Continued Operational Safety Policy Section, AIR-141  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

### Biweekly 2021-01

2020-26-10		Leonardo S.p.a.	A119 and AW119 MKII
2020-26-13		Sikorsky Aircraft Corporation	S-92A
2020-26-14	R 75-16-20	Mitsubishi Heavy Industries, Ltd.	MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, MU-2B-26, MU-2B-26A, MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, MU-2B-40, and MU-2B-60

### Biweekly 2021-02

2020-26-16		Piper Aircraft, Inc.	PA-28-151, PA-28-161, PA-28-181, PA-28-235, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-32-260, PA-32-300, PA-32R-300, PA-32RT-300, and PA-32RT-300T
------------	--	----------------------	---

### Biweekly 2021-03

2021-01-02		M7 Aerospace LLC	SA26-AT and SA26-T
------------	--	------------------	--------------------

### Biweekly 2021-04

2021-02-20		Hélicoptères Guimbal	Cabri G2
2021-04-04	R 2020-19-02	Airbus Helicopters	SA330J
2021-04-06		Pilatus Aircraft Ltd.	PC-7

### Biweekly 2021-05

2020-26-19		Pilatus Aircraft Ltd.	PC-7
2021-01-05		Pilatus Aircraft Ltd.	PC-24
2021-02-03		Leonardo S.p.a.	AW189
2021-02-04		Pilatus Aircraft Ltd.	PC-12/47E
2021-03-01	R 2018-05-09	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, and SA330J
2021-03-04		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-03-06		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1
2021-03-07		Leonardo S.p.a.	AB139 and AW139
2021-03-13		Bell Textron Canada Limited	429
2021-03-15	R 2020-13-02	Leonardo S.p.a.	A119 and AW119 MKII
2021-03-16		Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-04-03		Pilatus Aircraft Ltd.	PC-24
2021-04-07		Piper Aircraft, Inc.	PA-46-350P; PA-46-500TP; PA-46R-350T
2021-04-08		Airbus Helicopters	AS350B3
2021-05-52	E	Bell Textron Canada Limited	505

### Biweekly 2021-06

2021-02-01	R 2015-26-01	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC225LP, AS-365N2, AS 365 N3, EC 155B and EC155B1
2021-02-08	R 2018-19-01	Airbus Helicopters	AS-365N2, AS 365 N3, EC 155B, EC155B1, SA-365N, SA-365N1, and SA-366G1
2021-02-09		Airbus Helicopters	EC 155B and EC155B1
2021-02-11		Airbus Helicopters Deutschland GmbH	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, and MBB-BK117 C-2
2021-04-01		Leonardo S.p.a.	AB139 and AW139
2021-04-10		Textron Aviation, Inc.	208 and 208B
2021-04-12		Robinson Helicopter Company	R66
2021-04-13		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130 B4 and EC130 T2
2021-04-15		Airbus Helicopters	AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; AS350B3
2021-04-16		Sikorsky Aircraft Corporation	S-92A
2021-04-17		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, AS355F2, and AS355N
2021-04-18	R 2020-23-02	Airbus Helicopters	EC225LP

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-04-19		Bell Textron Inc.	205B
2021-05-01		Airbus Helicopters	SA330J
2021-05-02		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130B4 and EC130T2
2021-05-04		Leonardo S.p.a.	A109S and AW109SP
2021-05-05	R 2016-23-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2021-05-07		Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, and BO-105S; MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-05-08		Safran Helicopter Engines, S.A.	Arriel 2C, 2C1, 2S1, and 2S2
2021-05-09	R 2018-15-02	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-05-22		Safran Helicopter Engines, S.A.	Arriel 1B, Arriel 1C, Arriel 1C2, and Arriel 1D1; Astazou XIV B and Astazou XIV H
<b>Biweekly 2021-07</b>			
2021-05-06		Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC 155B, EC155B1, EC225LP, and SA330J
2021-05-13		Leonardo S.p.a.	AW189
2021-05-14		Air Tractor, Inc.	AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-401B, AT402, AT-402A, AT-402B, AT-501, AT-502, AT-502A, AT-502B, AT-503, AT-503A, AT-504, AT-602, AT-802, and AT-802A
2021-05-17	R 2019-12-09	Rockwell Collins, Inc.	Flight Display System Application FDSA-6500
2021-06-02		Airbus Helicopters	AS332L, AS332L1, AS332C, and AS332C1
2021-06-06	R 2021-05-52	Bell Textron Canada Limited	505
2021-07-05	R 2007-26-52	Leonardo S.p.a.	A109C, A109E, and A109K2
2021-07-08	R 97-26-02	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3
<b>Biweekly 2021-08</b>			
2021-04-21		Airbus Helicopters	EC120B
2021-05-15	A 2019-09-03	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2021-05-19		Sikorsky Aircraft and Sikorsky Aircraft Corporation	S-61L, S-61N, S-61NM, and S-61R; S-61A, S-61D, S-61E, and S-61V
2021-05-21	R 2017-23-08	Leonardo S.p.a.	AB139 and AW139
2021-06-01		Pilatus Aircraft Ltd.	PC-24
2021-06-05	R 2017-07-08	Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-07-07		Airbus Helicopters	EC 155B and EC155B1
2021-07-12		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-07-13		Pacific Scientific Company	rotary buckle assembly
2021-07-15	R 82-20-05	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-08-07		Rockwell Collins, Inc.	GPS-4000S
<b>Biweekly 2021-09</b>			
2021-07-16		Leonardo S.p.a.	AB412
2021-08-06	R 97-06-10	Textron Aviation Inc.	76
2021-08-15		Garmin International	GMN-00962 GTS
2021-08-18	R 2021-04-16	Sikorsky Aircraft Corporation	S-92A
2021-09-02	R 2021-04-07	Piper Aircraft, Inc.	PA-46-350P (Malibu Mirage), PA-46R-350T (Malibu Matrix), and PA-46-500TP (Malibu Meridian)
2021-09-04		Austro Engine GmbH	E4 and E4P
2021-09-07	R 2019-17-02	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-09-09		Uninsured United Parachute Technologies, LLC	Vector 3 SE

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

### Biweekly 2021-10

2021-08-05		Airbus Helicopters	SA341G and SA342J
2021-08-16		PZL Swidnik S.A.	W-3A
2021-08-17		Airbus Helicopters	AS332L2
2021-09-05	R 2016-08-20	Airbus Helicopters	EC130B4 and EC130T2
2021-10-08		Bell Textron Canada Limited	206L, 206L-1, 206L-3, and 206L-4

### Biweekly 2021-11

2021-08-02		Safran Helicopter Engines, S.A.	Arriel 2D and Arriel 2E
2021-09-14	R 2010-16-51	Airbus Helicopters	SA330J
2021-10-01		Leonardo S.p.a.	AW169
2021-10-03	R 2019-03-12	Airbus Helicopters	EC225LP
2021-10-10		Airbus Helicopters	SA330J
2021-10-14	A 2016-25-14	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, and BO-105LS A-3
2021-10-24	R 2015-25-04	Leonardo S.p.a.	A109A and A109A II

### Biweekly 2021-12

2021-10-15		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2; MBB-BK 117 D-2
2021-10-16		Carson Helicopters, Inc. Croman Corporation Sikorsky Aircraft Corporation Siller Helicopters	S-61L; SH-3H; S-61A, S-61D, S-61E, and S-61V; CH-3E; SH-3A
2021-10-17		Mooney International Corporation	M20V
2021-10-18		Airbus Helicopters Deutschland GmbH	MBB-BK117 D-2
2021-10-21	R 2019-07-07	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO105LS A-3, MBB-BK 117A-1, MBB-BK 117A-3, MBB-BK 117A-4, MBB-BK 117B-1, MBB-BK 117B-2, MBB-BK 117C-1, MBB-BK 117C-2, and MBB-BK 117D-2
2021-10-23		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-10-25		Airbus Helicopters	EC130B4 and EC130T2

### Biweekly 2021-13

2021-10-28		Pilatus Aircraft Ltd.	PC-24
2021-11-01	R 2013-20-13	Bell Textron Canada Limited	206B and 206L
2021-11-03		Airbus Helicopters	EC 155B, EC155B1, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-11-05		Airbus Helicopters	EC225LP
2021-11-08	R 2014-25-04	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-11-09		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-11-12		Pilatus Aircraft Ltd.	PC-24
2021-11-13		Bell Textron Canada Limited	429
2021-11-14		Leonardo S.p.a.	AW169
2021-11-16	R 79-01-03 R 83-20-03	Piper Aircraft, Inc.	PA-36-285, PA-36-300, and PA-36-375
2021-11-17		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-11-19		Bell Textron Canada Limited	505
2021-11-22	R 2016-11-21	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-12-03		Leonardo S.p.a.	AW189
2021-12-05		Airbus Helicopters	EC155B1
2021-12-06		Airbus Helicopters	AS-365N2, AS 365 N3, SA-365N, and SA-365N1
2021-12-10		Leonardo S.p.a.	AB139 and AW139

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-13-07		GE Aviation Czech s.r.o	M601D-11, M601E-11, M601E-11A, M601E-11AS, M601E-11S, and M601F
<b>Biweekly 2021-14</b>			
2021-11-25		Airbus Helicopters	AS350B3 and EC130T2
2021-12-08		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-12-09		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-12-16		Airbus Helicopters Deutschland GmbH	MBB-BK117 C-2 and MBB-BK117 D-2
2021-13-01		Leonardo S.p.a.	AB139 and AW139; AW189
2021-13-15		Bell Textron Canada Limited	429
2021-13-21		Leonardo S.p.a.	AB139, AW139, and AW189
<b>Biweekly 2021-15</b>			
2021-13-03		Safran Helicopter Engines, S.A.	Arriel 2B, 2B1, 2C, 2C1, 2C2, 2S1 and 2S2
2021-13-04		Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2021-13-05		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-13-08		Safran Helicopter Engines, S.A.	Arriel 2C and Arriel 2S1g
2021-13-09		Airbus Helicopters	SA330J
2021-13-14		Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, and BO-105LS A-3
2021-13-17	R 2017-17-01	Airbus Helicopters	AS332L2 and EC225LP
2021-13-19	R 2014-11-02	Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-14-02		Aircraft Industries a.s.	L-420, L 410 UVP-E20, and L 410 UVP-E20 CARGO
2021-14-05		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-14-07	R 2003-25-01	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1; AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, and AS355N
2021-14-12		True Flight Holdings LLC	AA-1, AA-1A, AA-1B, AA-1C, and AA-5
2021-14-14		Leonardo S.p.a.	AW119 MKII
2021-14-15	R 2002-08-16	Airbus Helicopters, Eurocopter France	SA341G and SA342J; SA-360C
2021-15-51	E	Bell Textron Inc.	204B, 205A, 205A-1, 205B, and 212
2021-15-52	E	Various Manufactures	HH-1K; TH-1F; TH-1L; UH-1A; UH-1B; UH-1E; UH-1F; UH-1H; UH-1H; UH-1H; UH-1L; UH-1P
<b>Biweekly 2021-16</b>			
2021-11-10		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-13-13		Leonardo S.p.a.	AW189
2021-14-16		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1
2021-14-18	R 2011-18-52	Leonardo S.p.a.	AB139 and AW139
2021-15-06		Bell Textron Canada Limited	206A, 206B, 206L, 206L-1, 206L-3, 206L-4
2021-15-09		Leonardo S.p.a.	AB139 and AW139
2021-15-14		Various Restricted Category Helicopters	TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, UH-1P
2021-15-52		Various Restricted Category Helicopters	TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, UH-1P



**2021-11-10 Airbus Helicopters:** Amendment 39-21572; Docket No. FAA-2021-0188; Project Identifier MCAI-2020-00642-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 27, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Airbus Helicopters Model SA-365N, SA-365N1, AS-365N2, and AS 365 N3 helicopters, certificated in any category, as identified in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2016-0028, dated February 15, 2016 (EASA AD 2016-0028).

**(d) Subject**

Joint Aircraft System Component (JASC) Code 2564, Life Raft.

**(e) Reason**

This AD was prompted by a report that damage (scorch marks) was found on an internal life raft installation that contained a half rescue kit. Investigation revealed that the damage was caused by an unsuitable folding process for the life raft, which led to compression of the flashlight battery in the half rescue kit. The FAA is issuing this AD to address leakage of the flashlight battery in a half rescue kit, which could result in damage to the internal life raft, and subsequent failure of the internal life raft to deploy (for example after a ditching), which could impede or prevent safe evacuation of the occupants from the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2016-0028.

### **(h) Exceptions to EASA AD 2016-0028**

(1) Where EASA AD 2016-0028 refers to its effective date or to January 7, 2016 (the effective date of EASA AD 2015-0242), this AD requires compliance within 3 months after the effective date of this AD.

(2) The “Remarks” section of EASA AD 2016-0028 does not apply to this AD.

(3) Where paragraph (2) of EASA AD 2016-0028 specifies accomplishing corrective actions in accordance with the instructions of Zodiac Aerospace SB No. 025-64-13 referred to in paragraph 3.B of Airbus Helicopters ASB AS365-25.01.63, this AD requires using Zodiac Aerospace Service Bulletin SB 025-64-13, Revision 0, dated November 23, 2015 or Revision 1, dated January 19, 2016.

(4) Although the service information referenced in EASA AD 2016-0028 specifies to return certain parts, this AD does not include that requirement.

(5) Although the service information referenced in EASA AD 2016-0028 specifies that trained and authorized Zodiac Aerospace personnel must do the inspection of the half rescue kit, this AD does not require that Zodiac Aerospace personnel do the inspection.

### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### **(j) Related Information**

For more information about this AD, contact Kathleen Arrigotti, Program Manager, Large Aircraft Section, International Validation Branch, Compliance & Airworthiness Division, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax (206) 231-3218; email kathleen.arrigotti@faa.gov.

### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2016-0028, dated February 15, 2016.

(ii) Zodiac Aerospace Service Bulletin SB 025-64-13, Revision 0, dated November 23, 2015.

(iii) Zodiac Aerospace Service Bulletin SB 025-64-13, Revision 1, dated January 19, 2016.

(3) For EASA AD 2016-0028, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. For Zodiac Aerospace service information, contact Safran Aerosystems–Plaisir, 61 rue Pierre Curie CS20001, 78373 Plaisir Cedex, France; telephone (33) 1 61 34 23 23; fax (33) 1 61 34 24 41; or at <https://www.safran-aerosystems.com>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information



on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0188.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 10, 2021.

Ross Landes,  
Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft  
Certification Service.

[FR Doc. 2021-15480 Filed 7-22-21; 8:45 am]



---

**2021-13-13 Leonardo S.p.a.:** Amendment 39-21618; Docket No. FAA-2021-0302; Project Identifier MCAI-2020-01596-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 24, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Leonardo S.p.a. Model AW189 helicopters, certificated in any category.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 7300, Engine fuel and control.

**(e) Unsafe Condition**

This AD was prompted by the identification of misleading information in the emergency procedure for the “1(2) FUEL LOW” caution message. The FAA is issuing this AD to prevent the wrong estimation of the remaining flight time in a low fuel condition. The unsafe condition, if not addressed, could result in an uncommanded engine in-flight shut-down and forced landing, with subsequent damage to the helicopter or injury to the occupants.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Within 14 hours time-in-service after the effective date of this AD, revise page 3-118 of Section 3, Emergency and Malfunction Procedures, of the existing Rotorcraft Flight Manual for your helicopter by adding page 3-118, Temporary Revision 3-1 Rev. A, of AW189–RFM, Document No. 189G0290X002, Record of Temporary Revisions, dated May 24, 2019, as contained in Annex A of Leonardo Helicopters Document No. 189G0257A061, “AW189–MAF for EASA RFM Issue 2 TR 3-1, Low Fuel Caution Procedure,” Issue B, dated May 22, 2019 (TR 3-1 Rev A). Using a different document with information identical to the information in page 3-118 of TR 3-1 Rev A is acceptable for compliance with the requirement of this paragraph. This action may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with § 43.9(a)(1) through (4) and § 91.417(a)(2)(v). The record must be maintained as required by § 91.417, § 121.380, or § 135.439.

### **(h) Special Flight Permits**

Special flight permits are prohibited.

### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### **(j) Related Information**

(1) For more information about this AD, contact Mitch Soth, Flight Test Engineer, Southwest Section, Flight Test Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email mitch.soth@faa.gov.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2019-0136, dated June 11, 2019. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0302.

### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) AW189–RFM, Document No. 189G0290X002, Record of Temporary Revisions, dated May 24, 2019, as contained in Annex A of Leonardo Helicopters Document No. 189G0257A061, “AW189–MAF for EASA RFM Issue 2 TR 3-1, Low Fuel Caution Procedure,” Issue B, dated May 22, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G.Agusta 520, 21017 C.Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://customerportal.leonardocompany.com/en-US/>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 9, 2021.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft  
Certification Service.

[FR Doc. 2021-15300 Filed 7-19-21; 8:45 am]



---

**2021-14-16 Airbus Helicopters (Type Certificate Previously Held by Eurocopter France):**  
Amendment 39-21643; Docket No. FAA-2021-0175; Project Identifier 2001-SW-33-AD.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 24, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Airbus Helicopters (type certificate previously held by Eurocopter France) Model SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1 helicopters, certificated in any category.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code 5311, Fuselage Main, Frame.

**(e) Reason**

This AD was prompted by a quality control check that revealed some stretcher attachment holes were improperly located on the frame where there was insufficient edge distance. The FAA is issuing this AD to address failure of the 9-degree frame flange (frame) due to a crack at the stretcher support attachment holes, which could result in loss of a passenger door, damage to the rotor system, and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with the applicable Direction Générale de l'Aviation Civile (DGAC) ADs specified in paragraphs (g)(1) and (2) of this AD.

(1) For Model SA-365N, SA-365N1, AS-365N2, and AS 365 N3 helicopters: DGAC AD 2001-061-053(A), dated February 21, 2001, (DGAC AD 2001-061-053(A)).

(2) For Model SA-366G1 helicopters: DGAC AD 2001-283-025(A), dated July 11, 2001 (DGAC AD 2001-283-025(A)).

**(h) Exceptions to DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A)**

(1) Where paragraph 3.1 of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies an initial compliance time to do the measurement, for this AD, do the measurement within 50 hours time-in-service (TIS) after the effective date of this AD.

(2) Where paragraph 3.1. of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies to do a measurement, for this AD, do an inspection of the area around the attachment holes for cracks concurrently with the measurement.

(3) Where paragraph 3.2.1.a) of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies “every 550 flight hours, check that there is no crack in the flange,” for this AD, inspect (check) the area around the attachment holes for cracks at intervals not to exceed 550 hours TIS.

(4) Where paragraph 3.2.1.b) of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) requires installation of a reinforcement plate (reinforcing angle) on the flange for certain helicopters, do the installation within 550 hours TIS after accomplishment of the measurement specified in paragraph 3.1. of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A).

(5) Where the service information referred to in DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies to perform a dye penetrant crack inspection “if in doubt,” this AD requires performing a dye penetrant inspection.

(6) Where paragraph 3.2.2. of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies to do various actions specified in paragraphs 3.2.2.a), b), and c) of those ADs, for this AD, if any frame is cracked, before further flight, repair the frame. Acceptable U.S. alternatives to the fasteners and materials needed to perform repairs or modifications are listed in American Eurocopter Engineering Report No. AEC/03R-E-005, “Addendum ASB 53.00.42 and 53.00.43 AS365”, dated January 29, 2003.

(7) Where the Note in paragraph 3.2.2. of DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A) specifies the instructions are no longer applicable after a customized repair has been carried out, for this AD, modifying or repairing the frame constitutes terminating action for the requirements of this AD.

**(i) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are prohibited.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(k) Related Information**

For more information about this AD, contact Blaine Williams, Aerospace Engineer, Cabin Safety & Environmental Systems Section, Los Angeles ACO Branch, Compliance & Airworthiness Division, 3960 Paramount Blvd., Lakewood, CA 90712; telephone 562-627-5371; email blaine.williams@faa.gov.

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Direction Générale de l'Aviation Civile (DGAC) AD 2001-061-053(A), dated February 21, 2001.

(ii) DGAC AD 2001-283-025(A), dated July 11, 2001.

(iii) American Eurocopter Engineering Report No. AEC/03R-E-005, "Addendum ASB 53.00.42 and 53.00.43 AS365", dated January 29, 2003.

(3) For DGAC AD 2001-061-053(A) and DGAC AD 2001-283-025(A), contact the European Union Aviation Safety Agency (EASA), Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find these DGAC ADs on the EASA website at <https://ad.easa.europa.eu>.

(4) For American Eurocopter material identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(5) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 2, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-15302 Filed 7-19-21; 8:45 am]



**2021-14-18 Leonardo S.p.a. (Type Certificate Previously Held by Agusta S.p.A.):** Amendment 39-21645; Docket No. FAA-2021-0348; Project Identifier 2018-SW-076-AD.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 24, 2021.

**(b) Affected ADs**

This AD replaces AD 2011-18-52, Amendment 39-17020 (77 FR 23109, April 18, 2012) (AD 2011-18-52).

**(c) Applicability**

This AD applies to Leonardo S.p.a. (type certificate previously held by Agusta S.p.A.) Model AB139 and AW139 helicopters, certificated in any category, with tail rotor (T/R) blade, part number (P/N) 3G6410A00131, 3G6410A00132, 3G6410A00133, 4G6410A00131, 4G6410A00132, or 4G6410A00133, installed.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 6410, Tail Rotor Blades.

**(e) Unsafe Condition**

This AD defines the unsafe condition as a crack in a T/R blade. This condition could result in failure of a T/R blade and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) For T/R blade P/Ns 3G6410A00131 and 4G6410A00131, within 5 hours time-in-service (TIS) after May 3, 2012 (the effective date of AD 2011-18-52), establish a life limit of 600 hours TIS or 1,500 takeoff and landing cycles (cycles), whichever occurs first, on the affected T/R blades and update the helicopter's historical records. If a T/R blade's total number of cycles is unknown, determine the T/R blade cycles by multiplying the T/R blade's hours TIS by 4.

(2) For T/R blade P/Ns 3G6410A00131 and 4G6410A00131, thereafter following paragraph (g)(1) of this AD, remove any T/R blade from service before accumulating 600 total hours TIS or 1,500 total cycles, whichever occurs first.

(3) For T/R blade P/Ns 3G6410A00132, 3G6410A00133, 4G6410A00132, and 4G6410A00133, within 5 hours TIS after the effective date of this AD, determine the total number of cycles. If a T/R



blade's total number of cycles is unknown, determine the T/R blade cycles by multiplying the blade's hours TIS by 4. Before further flight, remove any T/R blade from service that has accumulated or exceeded its life limit as follows. Thereafter, remove any T/R blade from service before accumulating its life limit as follows:

(i) T/R blade P/Ns 3G6410A00132 and 4G6410A00132: 1,200 total hours TIS or 3,200 total cycles, whichever occurs first.

(ii) T/R blade P/N 3G6410A00133: 40,000 total cycles.

(iii) T/R blade P/N 4G6410A00133: 4,033 total hours TIS or 40,000 cycles, whichever occurs first.

Note 1 to paragraph (g)(3): A combination of T/R blades having different P/Ns can be installed on the same helicopter. The eligible combinations of T/R blades P/N are listed in AgustaWestland Mandatory Bollettino Tecnico No. 139-265, Revision B, dated February 18, 2014 (BT No. 139-265).

(4) For T/R blade P/Ns 3G6410A00131 and P/N 4G6410A00131, within 25 hours TIS after the effective date of this AD, and thereafter at intervals not to exceed 25 hours TIS, visually inspect the T/R blade for a crack and damage that exceeds allowable limits. Inspect in the area depicted in Figure 1 of BT No. 139-265 using a mirror, a 5X or higher power magnifying glass, and a flashlight, or borescope. If there is a crack or damage that exceeds allowable limits, before further flight, remove the T/R blade from service.

(5) As of the effective date of this AD, do not install on any helicopter any T/R blade P/N 3G6410A00131 or P/N 4G6410A00131, unless the actions required by paragraphs (g)(1), (2), and (4) of this AD have been accomplished.

#### **(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(i) Related Information**

(1) For more information about this AD, contact Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2012-0076R2, dated February 20, 2014. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0348.

#### **(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) AgustaWestland Mandatory Bollettino Tecnico No. 139-265, Revision B, dated February 18, 2014.

(ii) [Reserved]

(3) For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G.Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 2, 2021.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-15303 Filed 7-19-21; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2021-15-06 Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited):** Amendment 39-21653; Docket No. FAA-2010-0865; Project Identifier 2010-SW-061-AD.

### **(a) Effective Date**

This airworthiness directive (AD) is effective August 27, 2021.

### **(b) Affected ADs**

None.

### **(c) Applicability**

This AD applies to the following Bell Textron Canada Limited (type certificate previously held by Bell Helicopter Textron Canada Limited) helicopters, certificated in any category:

- (1) Model 206A, serial numbers 004 through 660 inclusive, and 672 through 715 inclusive;
- (2) Model 206B, all serial numbers, including those converted from Model 206A;
- (3) Model 206L, serial numbers 45004 through 45153 inclusive, and 46601 through 46617 inclusive;
- (4) Model 206L-1, serial numbers 45154 through 45790 inclusive;
- (5) Model 206L-3, serial numbers 51001 through 51612 inclusive; and
- (6) Model 206L-4, all serial numbers.

### **(d) Subject**

Joint Aircraft Service Component (JASC) Code: 65, Tail Rotor Drive.

### **(e) Unsafe Condition**

This AD was prompted by a report that a certain tail rotor disc assembly, sold as an alternate part, does not conform to the approved configuration. The FAA is issuing this AD to address helicopters operating with a certain tail rotor disc assembly, sold as an alternate part, that does not conform to the approved configuration, which could result in loss of control of the helicopter.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Required Actions**

Do the actions specified in paragraphs (g)(1) through (4) of this AD, in accordance with Bell Helicopter Alert Service Bulletin 206-09-123, Revision A, dated June 10, 2009; or Bell Helicopter Alert Service Bulletin 206L-09-157, Revision A, dated June 10, 2009, as applicable.

(1) Within 30 days or 100 hours time-in-service (TIS) after the effective date of this AD, whichever occurs first, review the helicopter maintenance records to determine if a disc assembly, part number (P/N) 101584-1 or -2, is installed.

(2) If, during the maintenance records review required by paragraph (g)(1) of this AD, you cannot positively determine that disc assembly P/N 101584-1 or -2 is not installed, within 30 days or 100 hours TIS after the effective date of this AD, whichever occurs first, inspect the tail rotor driveshaft system to determine if disc assembly P/N 101584-1 or -2 is installed.

(3) If, during the maintenance records review required by paragraph (g)(1) of the this AD or during the inspection required by paragraph (g)(2) of this AD, you can positively determine that a disc assembly P/N 101584-1 or -2 is not installed, before further flight, make an entry in the log book showing compliance with this AD.

(4) If, during the maintenance records review required by paragraph (g)(1) of this AD or during the inspection required by paragraph (g)(2) of this AD, you can positively determine that a disc assembly P/N 101584-1 or -2 is installed, within 30 days or 100 hours TIS after the effective date of this AD, whichever occurs first, replace disc assembly P/N 101584-1 or -2 with disc assembly P/N 32721-1.

#### **(h) Parts Installation Prohibition**

As of the effective date of this AD, do not install disc assembly P/N 101584-1 or -2.

#### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(j) Related Information**

(1) For more information about this AD, contact Kathleen Arrigotti, Program Manager, Large Aircraft Section, International Validation Branch, Compliance & Airworthiness Division, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: (206) 231-3218; email: kathleen.arrigotti@faa.gov.

(2) The subject of this AD is addressed in Transport Canada Civil Aviation (TCCA) Canadian AD CF-2010-07, dated February 24, 2010. You may view the TCCA AD at <https://www.regulations.gov> in Docket No. FAA-2010-0865.

#### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Helicopter Alert Service Bulletin 206-09-123, Revision A, dated June 10, 2009.

(ii) Bell Helicopter Alert Service Bulletin 206L-09-157, Revision A, dated June 10, 2009.

(3) For service information identified in this AD, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; phone: 450-437-2862 or 800-363-8023; fax: (450) 433-0272; internet: <https://www.bellcustomer.com>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 9, 2021.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft  
Certification Service.

[FR Doc. 2021-15478 Filed 7-22-21; 8:45 am]



---

**2021-15-09 Leonardo S.p.a.:** Amendment 39-21656; Docket No. FAA-2021-0375; Project Identifier MCAI-2020-01245-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 27, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category, with an emergency flotation system (EFS) control panel part number (P/N) 3G9560V00556 (for use with night vision goggle) or 3G9560V00557 (standard) installed.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 3212, Emergency Flotation Section.

**(e) Unsafe Condition**

This AD was prompted by two events of uncommanded EFS deployment during flight. The FAA is issuing this AD to address improper design of certain EFS control panels. The unsafe condition, if not addressed, could result in reduced control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) At the following compliance time, replace EFS control panel P/N 3G9560V00556 or 3G9560V00557 with EFS control panel P/N 3G9560V00559 or 3G9560V00558, respectively:

(i) For helicopters with EFS P/N 3G9560F00111 or 3G9560F00113, with Aerosekur floats with “pyrotechnical” inflation system P/N 3G9560V01051 installed, within 94 hours time-in-service (TIS) or 3 months after the effective date of this AD, whichever occurs first.

(ii) For helicopters with EFS P/N 3G9560F00111 or 3G9560F00113, with Aerosekur floats with “SMA” inflation system P/N 3G9560V01052 installed, within 377 hours TIS or 12 months after the effective date of this AD, whichever occurs first.

(iii) For helicopters with EFS P/N 3G9560F00212 with Aerosekur floats with “fuse disk” inflation system P/N 3G9560V02051 installed, within 565 hours TIS or 18 months after the effective date of this AD, whichever occurs first.

(2) As of the effective date of this AD, do not install EFS control panel P/N 3G9560V00556 or 3G9560V00557 on any helicopter.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

(1) For more information about this AD, contact Ronnea Derby, Aerospace Engineer, Denver ACO Branch, Compliance & Airworthiness Division, FAA, 26805 E 68th Ave., Mail Stop: Room 214; Denver, CO 80249; telephone (303) 342-1093; email Ronnea.L.Derby@faa.gov.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2015-0172, dated August 21, 2015. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0375.

Issued on July 15, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-15481 Filed 7-22-21; 8:45 am]



**2021-15-14 Various Restricted Category Helicopters:** Amendment 39-21661; Docket No. FAA-2019-0759; Product Identifier 2018-SW-075-AD.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 30, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to various restricted category helicopters originally manufactured by Bell Textron Inc., (Bell) certificated in any category, including but not limited to:

- (1) Rotorcraft Development Corporation Model HH-1K helicopters;
- (2) Robinson Air Crane Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model TH-1F helicopters;
- (3) Bell; Overseas Aircraft Support, Inc. (type certificate previously held by JTBAM, Inc.); and Rotorcraft Development Corporation Model TH-1L helicopters;
- (4) Richards Heavylift Helo, Inc., Model UH-1A helicopters;
- (5) International Helicopters, Inc.; Overseas Aircraft Support, Inc.; Red Tail Flying Services, LLC; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and WSH, LLC (type certificate previously held by San Joaquin Helicopters), Model UH-1B helicopters without Supplemental Type Certificate (STC) No. SR00026DE installed;

Note 1 to paragraph (c)(5): Helicopters with an SW204 or SW204HP designation are Southwest Florida Aviation International, Inc., Model UH-1B helicopters.

- (6) Bell; Overseas Aircraft Support, Inc.; Rotorcraft Development Corporation; Smith Helicopters; and West Coast Fabrications Model UH-1E helicopters;
- (7) AST, Inc.; California Department of Forestry; Robinson Air Crane, Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model UH-1F helicopters;
- (8) Arrow Falcon Exporters Inc.; Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC; JJASPP Engineering Services, LLC; Northwest Rotorcraft, LLC; Overseas Aircraft Support, Inc.; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and Tamarack Helicopters, Inc., Model UH-1H helicopters;

Note 2 to paragraph (c)(8): Helicopters with an SW205 designation are Southwest Florida Aviation International, Inc., Model UH-1H helicopters.

- (9) Bell; Overseas Aircraft Support, Inc.; and Rotorcraft Development Corporation Model UH-1L helicopters; and
- (10) Robinson Air Crane, Inc.; and Rotorcraft Development Corporation Model UH-1P helicopters.



**(d) Subject**

Joint Aircraft System Component (JASC): 5302, Rotorcraft Tail Boom.

**(e) Unsafe Condition**

This AD was prompted by multiple events involving failure of the tail boom attach structure, including the bolts. The FAA is issuing this AD to address fatigue cracking of tail boom attach fittings, cap angles, longerons, and bolts. The unsafe condition, if not addressed, could result in separation of the tail boom from the helicopter and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Before further flight, revise the limitations section of the existing Rotorcraft Flight Manual (RFM) for your helicopter by adding the information in Figure 1 to paragraph (g)(1) of this AD or by inserting a copy of this AD. The action required by this paragraph and the checks required by Figure 1 to paragraph (g)(1) of this AD may be done by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD by following 14 CFR 43.9 (a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

### PRE-FLIGHT TAIL BOOM ATTACHMENT CHECK

(1) Before each flight, use two hands to push on the tail boom at the third vertical rivet line aft of the trailing edge of the elevator to check for looseness of the tail boom. Gradually apply and relieve pressure using body weight a minimum of three times in each of the following directions: inboard pushing from the left; inboard pushing from the right; and upward pushing from the bottom. If there is any looseness, further flight is prohibited until looseness is repaired and the helicopter is approved for return to service.

Note 1 to paragraph (1) of this check: This check is not required if the tail boom cannot be reached from ground level.

(2) Before the first flight of each day: with the oil cooler/baggage compartment door on the right hand side of the helicopter open to gain access to the interior of the tail boom, and with an additional person applying and relieving pressure as detailed in paragraph (1) and using a flashlight, first, check for upper left hand attach bolt movement by observing the torque stripe if present and attempting to rotate the bolt by hand, and second, check the upper left hand tail boom attach structure for any loose and missing rivets, and any cracks in the following areas: on the fuselage side, check the fitting and the cap angle running forward from the fitting for any cracks, paying particular attention to the fitting section near the rivets closest to the attach bolt and the cap angle rivets next to the fitting; and on the tail boom side, check the fitting and the longeron running aft from the fitting for any cracks, paying particular attention to the fitting section near the rivets closest to the attach bolt. If the attach bolt torque stripe is no longer aligned or the bolt rotates by hand, further flight is prohibited until the attach bolt and self-locking nut are removed from service, replaced with a new bolt and new self-locking nut, and the helicopter is approved for return to service. If there are any loose or missing rivets, or cracks, further flight is prohibited until loose and missing rivets, and cracked components are removed from service and the helicopter is approved for return to service.

Note 2 to paragraph (2) of this check: It is not required to push on the tail boom if it cannot be reached from ground level while checking for attach bolt movement, loose and missing rivets, and cracks.

Figure 1 to Paragraph (g)(1)

(2) Within 25 hours time-in-service (TIS):

(i) Open the oil cooler/baggage compartment door on the right hand side of the helicopter to gain access to the interior of the tail boom.

(ii) Remove paint and stray sealant and clean the eight attach fittings (four on the tail boom side and four on the fuselage side). Remove paint and stray sealant and clean the four cap angles, forward of the fuselage fittings, for at least 12 inches from the end of the fittings. Remove paint and stray sealant and clean the four longerons, aft of the tail boom fittings, for at least 12 inches from the end of the fittings. It is only necessary to remove the topcoat. Primer may be left in place and edge and fillet sealant may be left in place. If any primer or edge or fillet sealant is removed, before further flight, reapply the removed primer and sealant.

Note 3 to paragraph (g)(2)(ii): On some models, the baggage compartment floor and net must be removed to gain access to the lower fuselage attach fittings and cap angles.

(iii) With an additional person pushing on the tail boom at the third vertical rivet line aft of the trailing edge of the elevator with both hands and gradually applying and relieving pressure using body weight a minimum of three times in each of the following directions: Inboard pushing from the left; inboard pushing from the right; and upward pushing from the bottom; and using a bright light and borescope, inspect each of the four tail boom attach structures for cracks, bond separation, and loose rivets. On the fuselage side, inspect the fittings and the cap angles running forward from the fittings, paying particular attention to the fitting sections near the rivets closest to the attach bolts and the cap angle rivets next to the fittings. On the tail boom side, inspect the fittings and the longerons running aft from the fittings, paying particular attention to the fitting sections near the rivets closest to the attach bolts. Without pushing on the tail boom, and using a bright light and borescope, inspect each of the four tail boom attach structures for scratches, nicks, gouges, tears, corrosion, buckling, and distortion, and for loose, missing, and smoking rivets. If there are any scratches, nicks, gouges, tears, or corrosion within allowable limits, before further flight, repair the affected components. If there are any scratches, nicks, gouges, tears, or corrosion that exceed allowable limits, or any cracks, buckling or distortion, or loose, missing, or smoking rivets, before further flight, remove the affected components from service. If there is any bond separation, before further flight, re-bond the affected components.

Note 4 to paragraph (g)(2)(iii): It is not required to push on the tail boom if it cannot be reached from ground level while inspecting for cracks, bond separation, and loose rivets.

(iv) Inspect each of the four tail boom attach bolts for exposed threads. If there is less than one full thread or more than three threads exposed, before further flight, remove the bolt and self-locking nut from service and replace with a new bolt and new self-locking nut. Self-locking nuts on Model HH-1K, SW204, SW204HP, TH-1F, TH-1L, UH-1A, UH-1B without STC No. SR00026DE installed, and Model UH-1E, UH-1F, UH-1L, and UH-1P helicopters must be replaced with self-locking nut part number (P/N) NAS9926-7L at the upper left-hand (LH) attach point and self-locking nut P/N NAS9926-6L at the other three attach points.

(v) Inspect each of the four tail boom attach bolts for movement by either applying the required installation torque in the tightening direction only, or by inspecting for torque stripe misalignment if present and attempting to rotate the bolt by hand. If a bolt is under-torqued, a torque stripe is misaligned, or a bolt moves, before further flight, remove the bolt and self-locking nut from service and replace with a new bolt and new self-locking nut. Self-locking nuts on Model HH-1K, SW204, SW204HP, TH-1F, TH-1L, UH-1A, UH-1B without STC No. SR00026DE installed, UH-1E, UH-1F, UH-1L, and UH-1P helicopters must be replaced with self-locking nut P/N NAS9926-7L at the upper LH attach point and self-locking nut P/N NAS9926-6L at the other three attach points.

(vi) After the first flight following any bolt replacement as required by paragraph (g)(iv) or (v) of this AD, retorque any replaced bolt by applying torque in accordance with the existing maintenance instructions for your helicopter in the tightening direction only and then apply a torque stripe on the bolt head.

(3) For Model HH-1K, TH-1F, TH-1L, UH-1A, UH-1B without STC No. SR00026DE installed, UH-1E, UH-1F, UH-1L, and UH-1P helicopters and Southwest Florida Aviation International, Inc. Model SW204 and SW204HP helicopters, at intervals not to exceed 25 hours TIS, perform the

actions required by paragraphs (g)(2)(i) through (vi) of this AD, except you are only required to perform the actions on the upper LH tail boom attach structure including the bolt.

(4) For Model HH-1K, TH-1F, TH-1L, UH-1A, UH-1B without STC No. SR00026DE installed, UH-1E, UH-1F, UH-1L, and UH-1P helicopters and Southwest Florida Aviation International, Inc. Model SW204 and SW204HP helicopters, at intervals not to exceed 100 hours TIS, perform the actions required by paragraphs (g)(2)(i) through (vi) of this AD at all four tail boom attach points.

(5) For Model UH-1H helicopters and Southwest Florida Aviation International, Inc. Model SW205 helicopters, at intervals not to exceed 150 hours TIS, perform the actions required by paragraphs (g)(2)(i) through (vi) of this AD on all four tail boom attach points.

#### **(h) Special Flight Permit**

Special flight permits are prohibited.

#### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Denver ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(j) Related Information**

For more information about this AD, contact Richard R. Thomas, Aerospace Engineer, Denver ACO Branch, Compliance & Airworthiness Division, FAA, 26805 East 68th Ave., Room 214, Denver, CO 80249; phone: (303) 342-1080; fax: (303) 342-1088; email: 9-Denver-Aircraft-Cert@faa.gov.

Issued on July 18, 2021.

Ross Landes,  
Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-15721 Filed 7-23-21; 8:45 am]



**2021-15-52 Various Restricted Category Helicopters:** Amendment 39-21664; Docket No. FAA-2021-0605; Project Identifier AD-2021-00805-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective without actual notice on August 13, 2021. Emergency AD 2021-15-52, issued on July 8, 2021, which contained the requirements of this amendment, was effective with actual notice.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to various restricted category helicopters originally manufactured by Bell Textron Inc. (Bell), certificated in any category, with an outboard main rotor hub strap pin (pin) part number 204-012-104-005 with a serial number prefix “FNFS” installed. These helicopters include but are not limited to:

- (1) Rotorcraft Development Corporation Model HH-1K helicopters;
- (2) Robinson Air Crane Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model TH-1F helicopters;
- (3) Bell; Overseas Aircraft Support, Inc. (type certificate previously held by JTBAM, Inc.); and Rotorcraft Development Corporation Model TH-1L helicopters;
- (4) Richards Heavylift Helo, Inc., Model UH-1A helicopters;
- (5) International Helicopters, Inc.; Overseas Aircraft Support, Inc.; Red Tail Flying Services, LLC; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and WSH, LLC (type certificate previously held by San Joaquin Helicopters), Model UH-1B helicopters;

Note 1 to paragraph (c)(5): Helicopters with an SW204 or SW204HP designation are Southwest Florida Aviation International, Inc., Model UH-1B helicopters.

- (6) Bell; Overseas Aircraft Support, Inc.; Rotorcraft Development Corporation; Smith Helicopters; and West Coast Fabrications Model UH-1E helicopters;
- (7) AST, Inc.; California Department of Forestry; Robinson Air Crane, Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model UH-1F helicopters;
- (8) Arrow Falcon Exporters Inc.; Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC; JJASPP Engineering Services, LLC; Northwest Rotorcraft, LLC; Overseas Aircraft Support, Inc.; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and Tamarack Helicopters, Inc., Model UH-1H helicopters;

Note 2 to paragraph (c)(8): Helicopters with an SW205 designation are Southwest Florida Aviation International, Inc. Model UH-1H helicopters.

- (9) Bell; Overseas Aircraft Support, Inc.; and Rotorcraft Development Corporation Model UH-1L helicopters; and

(10) Robinson Air Crane, Inc.; and Rotorcraft Development Corporation Model UH-1P helicopters.

**(d) Subject**

Joint Aircraft System Component (JASC) Code: 6200, Main Rotor System.

**(e) Unsafe Condition**

This AD was prompted by a fatal accident in which a pin sheared off during flight, which resulted in the main rotor blade and the main rotor head detaching from the helicopter. The FAA is issuing this AD to address this unsafe condition and prevent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Before further flight, remove from service any pin that is identified in the introductory text of paragraph (c) of this AD.

(2) As of the effective date of this AD, do not install any pin that is identified in the introductory text of paragraph (c) of this AD on any helicopter.

**(h) Special Flight Permits**

Special flight permits are prohibited.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, DSCO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the DSCO Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ASW-190-COS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

(1) For more information about this AD, contact David Wilson, Aerospace Engineer, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5786; email david.wilson@faa.gov.

(2) The subject of this AD is addressed in Transport Canada Emergency AD CF-2021-23, dated July 5, 2021 and FAA Emergency AD 2021-15-51, dated July 6, 2021. You may view those ADs at <https://www.regulations.gov> in Docket No. FAA-2021-0605.

Issued on July 21, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft  
Certification Service.

[FR Doc. 2021-16222 Filed 7-27-21; 11:15 am]