

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2021-25

11/22/2021 - 12/5/2021



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-01

2020-26-10		Leonardo S.p.a.	A119 and AW119 MKII
2020-26-13		Sikorsky Aircraft Corporation	S-92A
2020-26-14	R 75-16-20	Mitsubishi Heavy Industries, Ltd.	MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, MU-2B-26, MU-2B-26A, MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, MU-2B-40, and MU-2B-60

Biweekly 2021-02

2020-26-16		Piper Aircraft, Inc.	PA-28-151, PA-28-161, PA-28-181, PA-28-235, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-32-260, PA-32-300, PA-32R-300, PA-32RT-300, and PA-32RT-300T
------------	--	----------------------	---

Biweekly 2021-03

2021-01-02		M7 Aerospace LLC	SA26-AT and SA26-T
------------	--	------------------	--------------------

Biweekly 2021-04

2021-02-20		Hélicoptères Guimbal	Cabri G2
2021-04-04	R 2020-19-02	Airbus Helicopters	SA330J
2021-04-06		Pilatus Aircraft Ltd.	PC-7

Biweekly 2021-05

2020-26-19		Pilatus Aircraft Ltd.	PC-7
2021-01-05		Pilatus Aircraft Ltd.	PC-24
2021-02-03		Leonardo S.p.a.	AW189
2021-02-04		Pilatus Aircraft Ltd.	PC-12/47E
2021-03-01	R 2018-05-09	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, and SA330J
2021-03-04		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-03-06		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1
2021-03-07		Leonardo S.p.a.	AB139 and AW139
2021-03-13		Bell Textron Canada Limited	429
2021-03-15	R 2020-13-02	Leonardo S.p.a.	A119 and AW119 MKII
2021-03-16		Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-04-03		Pilatus Aircraft Ltd.	PC-24
2021-04-07		Piper Aircraft, Inc.	PA-46-350P; PA-46-500TP; PA-46R-350T
2021-04-08		Airbus Helicopters	AS350B3
2021-05-52	E	Bell Textron Canada Limited	505

Biweekly 2021-06

2021-02-01	R 2015-26-01	Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC225LP, AS-365N2, AS 365 N3, EC 155B and EC155B1
2021-02-08	R 2018-19-01	Airbus Helicopters	AS-365N2, AS 365 N3, EC 155B, EC155B1, SA-365N, SA-365N1, and SA-366G1
2021-02-09		Airbus Helicopters	EC 155B and EC155B1
2021-02-11		Airbus Helicopters Deutschland GmbH	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, and MBB-BK117 C-2
2021-04-01		Leonardo S.p.a.	AB139 and AW139
2021-04-10		Textron Aviation, Inc.	208 and 208B
2021-04-12		Robinson Helicopter Company	R66
2021-04-13		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130 B4 and EC130 T2
2021-04-15		Airbus Helicopters	AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; AS350B3
2021-04-16		Sikorsky Aircraft Corporation	S-92A
2021-04-17		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, AS355F2, and AS355N
2021-04-18	R 2020-23-02	Airbus Helicopters	EC225LP

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-04-19		Bell Textron Inc.	205B
2021-05-01		Airbus Helicopters	SA330J
2021-05-02		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130B4 and EC130T2
2021-05-04		Leonardo S.p.a.	A109S and AW109SP
2021-05-05	R 2016-23-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2021-05-07		Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, and BO-105S; MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-05-08		Safran Helicopter Engines, S.A.	Arriel 2C, 2C1, 2S1, and 2S2
2021-05-09	R 2018-15-02	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-05-22		Safran Helicopter Engines, S.A.	Arriel 1B, Arriel 1C, Arriel 1C2, and Arriel 1D1; Astazou XIV B and Astazou XIV H
Biweekly 2021-07			
2021-05-06		Airbus Helicopters	AS332C, AS332C1, AS332L, AS332L1, AS332L2, EC 155B, EC155B1, EC225LP, and SA330J
2021-05-13		Leonardo S.p.a.	AW189
2021-05-14		Air Tractor, Inc.	AT-250, AT-300, AT-301, AT-302, AT-400, AT-400A, AT-401, AT-401A, AT-401B, AT402, AT-402A, AT-402B, AT-501, AT-502, AT-502A, AT-502B, AT-503, AT-503A, AT-504, AT-602, AT-802, and AT-802A
2021-05-17	R 2019-12-09	Rockwell Collins, Inc.	Flight Display System Application FDSA-6500
2021-06-02		Airbus Helicopters	AS332L, AS332L1, AS332C, and AS332C1
2021-06-06	R 2021-05-52	Bell Textron Canada Limited	505
2021-07-05	R 2007-26-52	Leonardo S.p.a.	A109C, A109E, and A109K2
2021-07-08	R 97-26-02	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3
Biweekly 2021-08			
2021-04-21		Airbus Helicopters	EC120B
2021-05-15	A 2019-09-03	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2021-05-19		Sikorsky Aircraft and Sikorsky Aircraft Corporation	S-61L, S-61N, S-61NM, and S-61R; S-61A, S-61D, S-61E, and S-61V
2021-05-21	R 2017-23-08	Leonardo S.p.a.	AB139 and AW139
2021-06-01		Pilatus Aircraft Ltd.	PC-24
2021-06-05	R 2017-07-08	Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-07-07		Airbus Helicopters	EC 155B and EC155B1
2021-07-12		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-07-13		Pacific Scientific Company	rotary buckle assembly
2021-07-15	R 82-20-05	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-08-07		Rockwell Collins, Inc.	GPS-4000S
Biweekly 2021-09			
2021-07-16		Leonardo S.p.a.	AB412
2021-08-06	R 97-06-10	Textron Aviation Inc.	76
2021-08-15		Garmin International	GMN-00962 GTS
2021-08-18	R 2021-04-16	Sikorsky Aircraft Corporation	S-92A
2021-09-02	R 2021-04-07	Piper Aircraft, Inc.	PA-46-350P (Malibu Mirage), PA-46R-350T (Malibu Matrix), and PA-46-500TP (Malibu Meridian)
2021-09-04		Austro Engine GmbH	E4 and E4P
2021-09-07	R 2019-17-02	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-09-09		Uninsured United Parachute Technologies, LLC	Vector 3 SE

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-10

2021-08-05		Airbus Helicopters	SA341G and SA342J
2021-08-16		PZL Swidnik S.A.	W-3A
2021-08-17		Airbus Helicopters	AS332L2
2021-09-05	R 2016-08-20	Airbus Helicopters	EC130B4 and EC130T2
2021-10-08		Bell Textron Canada Limited	206L, 206L-1, 206L-3, and 206L-4

Biweekly 2021-11

2021-08-02		Safran Helicopter Engines, S.A.	Arriel 2D and Arriel 2E
2021-09-14	R 2010-16-51	Airbus Helicopters	SA330J
2021-10-01		Leonardo S.p.a.	AW169
2021-10-03	R 2019-03-12	Airbus Helicopters	EC225LP
2021-10-10		Airbus Helicopters	SA330J
2021-10-14	A 2016-25-14	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, and BO-105LS A-3
2021-10-24	R 2015-25-04	Leonardo S.p.a.	A109A and A109A II

Biweekly 2021-12

2021-10-15		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2; MBB-BK 117 D-2
2021-10-16		Carson Helicopters, Inc. Croman Corporation Sikorsky Aircraft Corporation Siller Helicopters	S-61L; SH-3H; S-61A, S-61D, S-61E, and S-61V; CH-3E; SH-3A
2021-10-17		Mooney International Corporation	M20V
2021-10-18		Airbus Helicopters Deutschland GmbH	MBB-BK117 D-2
2021-10-21	R 2019-07-07	Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO105LS A-3, MBB-BK 117A-1, MBB-BK 117A-3, MBB-BK 117A-4, MBB-BK 117B-1, MBB-BK 117B-2, MBB-BK 117C-1, MBB-BK 117C-2, and MBB-BK 117D-2
2021-10-23		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-10-25		Airbus Helicopters	EC130B4 and EC130T2

Biweekly 2021-13

2021-10-28		Pilatus Aircraft Ltd.	PC-24
2021-11-01	R 2013-20-13	Bell Textron Canada Limited	206B and 206L
2021-11-03		Airbus Helicopters	EC 155B, EC155B1, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-11-05		Airbus Helicopters	EC225LP
2021-11-08	R 2014-25-04	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-11-09		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-11-12		Pilatus Aircraft Ltd.	PC-24
2021-11-13		Bell Textron Canada Limited	429
2021-11-14		Leonardo S.p.a.	AW169
2021-11-16	R 79-01-03 R 83-20-03	Piper Aircraft, Inc.	PA-36-285, PA-36-300, and PA-36-375
2021-11-17		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-11-19		Bell Textron Canada Limited	505
2021-11-22	R 2016-11-21	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-12-03		Leonardo S.p.a.	AW189
2021-12-05		Airbus Helicopters	EC155B1
2021-12-06		Airbus Helicopters	AS-365N2, AS 365 N3, SA-365N, and SA-365N1
2021-12-10		Leonardo S.p.a.	AB139 and AW139

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-13-07		GE Aviation Czech s.r.o	M601D-11, M601E-11, M601E-11A, M601E-11AS, M601E-11S, and M601F
Biweekly 2021-14			
2021-11-25		Airbus Helicopters	AS350B3 and EC130T2
2021-12-08		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-12-09		Airbus Helicopters Deutschland GmbH	MBB-BK 117 D-2
2021-12-16		Airbus Helicopters Deutschland GmbH	MBB-BK117 C-2 and MBB-BK117 D-2
2021-13-01		Leonardo S.p.a.	AB139 and AW139; AW189
2021-13-15		Bell Textron Canada Limited	429
2021-13-21		Leonardo S.p.a.	AB139, AW139, and AW189
Biweekly 2021-15			
2021-13-03		Safran Helicopter Engines, S.A.	Arriel 2B, 2B1, 2C, 2C1, 2C2, 2S1 and 2S2
2021-13-04		Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2021-13-05		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-13-08		Safran Helicopter Engines, S.A.	Arriel 2C and Arriel 2S1g
2021-13-09		Airbus Helicopters	SA330J
2021-13-14		Airbus Helicopters Deutschland GmbH	BO-105A, BO-105C, BO-105S, and BO-105LS A-3
2021-13-17	R 2017-17-01	Airbus Helicopters	AS332L2 and EC225LP
2021-13-19	R 2014-11-02	Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-14-02		Aircraft Industries a.s.	L-420, L 410 UVP-E20, and L 410 UVP-E20 CARGO
2021-14-05		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1
2021-14-07	R 2003-25-01	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1; AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, and AS355N
2021-14-12		True Flight Holdings LLC	AA-1, AA-1A, AA-1B, AA-1C, and AA-5
2021-14-14		Leonardo S.p.a.	AW119 MKII
2021-14-15	R 2002-08-16	Airbus Helicopters, Eurocopter France	SA341G and SA342J; SA-360C
2021-15-51	E	Bell Textron Inc.	204B, 205A, 205A-1, 205B, and 212
2021-15-52	E	Various Manufactures	HH-1K; TH-1F; TH-1L; UH-1A; UH-1B; UH-1E; UH-1F; UH-1H; UH-1I; UH-1L; UH-1P
Biweekly 2021-16			
2021-11-10		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2021-13-13		Leonardo S.p.a.	AW189
2021-14-16		Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1
2021-14-18	R 2011-18-52	Leonardo S.p.a.	AB139 and AW139
2021-15-06		Bell Textron Canada Limited	206A, 206B, 206L, 206L-1, 206L-3, 206L-4
2021-15-09		Leonardo S.p.a.	AB139 and AW139
2021-15-14		Various Restricted Category Helicopters	TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, UH-1P
2021-15-52		Various Restricted Category Helicopters	TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, UH-1P
Biweekly 2021-17			
2021-15-12		Pratt & Whitney Canada Corp.	PW210A and PW210S
2021-15-51		Bell Textron Inc.	204B, 205A, 205A-1, 205B, and 212
2021-16-20		PZL Swidnik S.A.	PZL W-3A
2021-17-01		Austro Engine GmbH	E4 and E4P
Biweekly 2021-18			
2021-15-10		GE Aviation Czech s.r.o.	H75-200, H80-100, and H80-200

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2021-16-02		Airbus Helicopters	SA330J, AS332C, AS332L, AS332L1, AS332L2, and EC225LP
2021-16-06	R 2020-19-11	Leonardo S.p.a.	A119 and AW119 MKII
2021-16-13		Leonardo S.p.a.	A109S; AW109SP
2021-16-14		BALÓNY KUBÍČEK spol. s r.o.	BB78Z; BB85Z; BB92Z; BB130P
2021-17-10		Leonardo S.p.a.	A109A, A109A II, A109C, A109E, A109K2, A109S, and AW109SP
2021-17-13		PZL Swidnik S.A.	PZL W-3A
2021-17-16		Leonardo S.p.a.	AW189
2021-17-18		Leonardo S.p.a.	A109C, A109K2, A109E, A109S, and AW109SP
2021-18-06	R 2021-11-03	Airbus Helicopters	EC 155B, EC155B1, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
Biweekly 2021-19			
2021-16-04		Leonardo S.p.a.	AB412 and AB412 EP
2021-16-05	R 2016-12-51	Airbus Helicopters	AS332L2 and EC225LP
2021-16-09		Leonardo S.p.a.	AW189
2021-16-10		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-16-11		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-16-12		Bell Textron Canada Limited	505
2021-16-16		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2021-16-17		Airbus Helicopters Deutschland GmbH (AHD)	MBB-BK 117 D-2
2021-17-05	R 2014-04-06	Safran Helicopter Engines, S.A.	Arrius 2B1, 2B1A, 2B2, and 2K1
2021-17-15		Leonardo S.p.a.	AB139 and AW139
2021-18-01		B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, and BN-2T-4R
2021-18-07		Leonardo S.p.a.	AB412 and AB412 EP
2021-18-10		Bell Textron Canada Limited	429
2021-19-01		Bell Textron Canada Limited	206, 206A, 206A-1 (OH-58A), 206B, 206B-1, 206L, 206L-1, 206L-3, 206L-4, 222, 222B, 222U, 230, 407, 427, 429, and 430
2021-19-04		Hélicoptères Guimbal	Cabri G2
2021-19-08		Robinson Helicopter Company	R44 and R44 II
Biweekly 2021-20			
2021-20-02		Bell Textron Inc.	205B
Biweekly 2021-21			
2021-18-11		Leonardo S.p.a.	AB139 and AW139
2021-18-12		PZL Swidnik S.A.	PZL W-3A
2021-18-14		DG Flugzeugbau GmbH	DG-808C and DG-1000T
2021-18-15		PZL Swidnik S.A.	PZL W-3A
2021-18-16		Bell Textron Canada Limited	429
2021-19-02		Airbus Helicopters	EC130B4 and EC130T2
2021-19-03		Leonardo S.p.a.	AB139 and AW139
2021-19-05		Leonardo S.p.a.	AB412 and AB412 EP
2021-19-06	R 2007-02-13	UAG Aerospace Services GmbH	Dornier 228-212
2021-19-07		Hélicoptères Guimbal	CABRI G2
2021-19-09	R 2020-24-03	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350D, AS355E, AS355F, AS355F1, and AS355F2
2021-19-14		AERO Sp. z o.o.	AT-3R100
2021-19-16	R 2021-16-02	Airbus Helicopters	SA330J, AS332C, AS332L, AS332L1, AS332L2, and EC225LP

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2021-22

2021-17-17		Airbus Helicopters and Airbus Helicopters Deutschland GmbH	AS332C, AS332C1, AS332L, AS332L1, AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, AS-365N2, AS 365 N3, EC120B, EC130B4, EC130T2, EC 155B, EC155B1, SA-365N, and SA-365N1; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK117 C-2, and MBB-BK117 D-2
2021-19-17		Sikorsky Aircraft Corporation	S-92A
2021-20-03		Leonardo S.p.a.	AW169
2021-20-05		Leonardo S.p.a.	AW189
2021-20-06		Airbus Helicopters	AS355E, AS355F, AS355F1, and AS355F2
2021-20-10		Leonardo S.p.a.	AB139 and AW139
2021-20-11		Bell Textron Canada Limited	429
2021-20-12		Leonardo S.p.a.	AB139, AW139, AB412, and AB412 EP
2021-20-16	R 2021-04-15	Airbus Helicopters	AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; AS350B3
2021-20-17	R 2018-23-52	Leonardo S.p.a.	AW169 and AW189
2021-20-20		Pacific Aerospace Limited	750XL

Biweekly 2021-23

2021-20-21	R 2018-16-10	GE Aviation Czech s.r.o.	H80-200; H85-200
2021-21-01	R 2019-05-06	Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2021-21-03		Leonardo S.p.a.	A109A, A109A II, A109C, A109E, A109K2, A109S, AW109SP, A119, and AW119 MKII
2021-21-08		Leonardo S.p.a.	AB139 and AW139
2021-21-10		Pacific Aerospace Limited	750XL
2021-21-11		Pacific Aerospace Limited	750XL
2021-22-07		Various Manufactures	Various Models
2021-22-12		Honda Aircraft Company LLC	HA-420
2021-22-13		Leonardo S.p.a.	AB139 and AW139
2021-22-20		Austro Engine GmbH Engines	E4 and E4P
2021-22-22		Costruzioni Aeronautiche Tecnam S.P.A.	P2006T

Biweekly 2021-24

2021-05-02R1	A 2021-05-02	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, and AS350D; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; EC130B4 and EC130T2
2021-21-06		Hélicoptères Guimbal	Cabri G2
2021-22-03		Diamond Aircraft Industries GmbH	DA 42, DA 42 NG, and DA 42 M-NG
2021-22-09		Leonardo S.p.a.	AW189
2021-22-10		Leonardo S.p.a.	A109E
2021-24-10	R 2021-09-04	Austro Engine GmbH	E4 and E4P

Biweekly 2021-25

2021-22-02		Leonardo S.p.a.	AB139 and AW139
2021-22-05		Leonardo S.p.a.	A119 and AW119 MKII
2021-22-15		Airbus Helicopters	AS332L2 and EC225LP
2021-22-16		Airbus Helicopters	EC 155B and EC155B1
2021-22-21		ASI Aviation	F406
2021-24-06		Airbus Helicopters	EC130T2
2021-24-09		Bell Textron Canada Limited	430



2021-22-02 Leonardo S.p.a.: Amendment 39-21775; Docket No. FAA-2021-0461; Project Identifier MCAI-2021-00156-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2400, Electrical Power System.

(e) Unsafe Condition

This AD was prompted by a report of a short circuit caused by chafing of the electrical wiring in the overhead panel. The FAA is issuing this AD to address a short circuit caused by chafing of the electrical wiring in the overhead panel, which could cause damaged electrical wiring, possible fire in the overhead panel, and loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0044, dated February 5, 2021 (EASA AD 2021-0044).

(h) Exceptions to EASA AD 2021-0044

(1) Where EASA AD 2021-0044 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021-0044 does not apply to this AD.

(3) Where EASA AD 2021-0044 refers to flight hours (FH), this AD requires using hours time-in-service.

(4) Where paragraphs (3) and (5) of EASA AD 2021-0044 refer to “any discrepancy,” for this AD, discrepancies include chafing of the cable harnesses or incorrect clearance between the anchor nuts/screws and the cable harnesses, incorrect length of the screws, inadequately bonded supports, and poor condition of the white protective tape.

(i) No Reporting Requirement

Although EASA AD 2021-0044 and the service information referenced in EASA AD 2021-0044 specify to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided the flight is straight, level, and avoids areas of known turbulence.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Jacob Fitch, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: (817) 222-4130; email: jacob.fitch@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0044, dated February 5, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0044, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0461.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 13, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25691 Filed 11-24-21; 8:45 am]



2021-22-05 Leonardo S.p.a.: Amendment 39-21778; Docket No. FAA-2021-0572; Project Identifier MCAI-2021-00391-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model A119 and AW119 MKII helicopters, certificated in any category, all serial numbers.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6700, Rotorcraft Flight Control.

(e) Unsafe Condition

This AD was prompted by reports of abnormal play on the collective torque tube on two Model AW119 MKII helicopters. The FAA is issuing this AD to address abnormal play on the collective torque tube, which could result in reduced control of the helicopter, resulting in a forced landing and consequent damage to the helicopter and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0096, dated March 31, 2021 (EASA AD 2021-0096).

(h) Exceptions to EASA AD 2021-0096

- (1) Where EASA AD 2021-0096 refers to flight hours (FH), this AD requires using hours time-in-service (TIS).
- (2) Where EASA AD 2021-0096 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraphs (1) and (2) of EASA AD 2021-0096 specify the compliance times for Group 1 helicopters to inspect the affected part, this AD requires an initial inspection within 50 hours TIS after the effective date of this AD, and thereafter at intervals not to exceed 100 hours TIS.

(4) Where paragraph (5) of EASA AD 2021-0096 specifies, for Group 1 helicopters, replacement of an affected part with a serviceable part “within 36 months after April 3, 2019 [the effective date of EASA AD 2019-0057],” for this AD, that replacement must be done within 24 months after the effective date of this AD.

(5) Where the service information referenced in EASA AD 2021-0096 specifies to return a torque tube assembly to the manufacturer, this AD does not include that requirement.

(6) Where the service information referenced in EASA AD 2021-0096 specifies to contact the manufacturer “in case of doubt” regarding the batch number on a torque tube assembly, determining the batch number is required by this AD but contacting the manufacturer is not required.

(7) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0096.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0096 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Mail Stop: Room 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0096, dated March 31, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0096, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N 321, Fort Worth, TX 76177. For information on the availability of the EASA material at the FAA, call (817) 222-5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 13, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25690 Filed 11-24-21; 8:45 am]



2021-22-15 Airbus Helicopters: Amendment 39-21788; Docket No. FAA-2021-0693; Project Identifier MCAI-2020-01666-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model AS332L2 and EC225LP helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020-0281, dated December 16, 2020 (EASA AD 2020-0281).

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2500, Cabin Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a design deficiency. The FAA is issuing this AD to correct the electrical hoist installation wiring routing. The unsafe condition, if not addressed, could result in a short circuit of the hoist control electrical harness and subsequent hoist shear command and hoisted load loss, possibly resulting in injury to a person being lifted or injury to persons on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020-0281.

(h) Exceptions to EASA AD 2020-0281

- (1) Where EASA AD 2020-0281 requires compliance within 30 days after its effective date, this AD requires compliance within 30 hours time-in-service after the effective date of this AD.
- (2) This AD does not require the "Remarks" section of EASA AD 2020-0281.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2020-0281 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Ronnea Derby, Aerospace Engineer, Denver ACO Branch, Compliance & Airworthiness Division, FAA, 26805 E 68th Ave., Mail Stop: Room 214, Denver, CO 80249; telephone (303) 342-1093; email Ronnea.L.Derby@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0281, dated December 16, 2020.

(ii) [Reserved]

(3) For EASA AD 2020-0281, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0693.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 15, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25687 Filed 11-24-21; 8:45 am]



2021-22-16 Airbus Helicopters: Amendment 39-21789; Docket No. FAA-2021-0197; Project Identifier 2018-SW-107-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model EC 155B and EC155B1 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6300, Main Rotor Drive System.

(e) Unsafe Condition

This AD was prompted by the failure of a main gearbox (MGB) second stage planet gear. The FAA is issuing this AD to prevent failure of an MGB planet gear assembly. The unsafe condition, if not addressed, could result in failure of the MGB and subsequent loss of helicopter control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For helicopters with at least one Type Y planet gear assembly with a serial number (S/N) listed in Appendix 4.A. of Airbus Helicopters Alert Service Bulletin ASB No. EC155-05A034, Revision 5, dated December 4, 2018 (ASB EC155-05A034 Rev 5) or with at least one Type Z planet gear assembly with an S/N listed in Appendix 4.B. of ASB EC155-05A034 Rev 5 installed, within 10 hours time-in-service (TIS) after the effective date of this AD, and thereafter at intervals not to exceed 10 hours TIS, inspect the MGB magnetic plugs for particles. If there are any particles that consist of any scale, flake, splinter, or other particle other than cotter pin fragments, pieces of lock wire, swarf, abrasion, or miscellaneous non-metallic waste, and any of the planet gears have accumulated less than 50 total hours TIS, before further flight, inspect the MGB filter for particles. Thereafter, for 25 hours TIS, continue to inspect the MGB plugs for particles before each flight, inspect the MGB filter for particles at intervals not to exceed 25 hours TIS, and inspect the

cumulative surface area of the particles collected from the magnetic plugs, the MGB filter, since last MGB overhaul, or since new if no overhaul has been performed.

Note 1 to the introductory text of paragraph (g)(1): Airbus Helicopters service information refers to an MGB filter as an oil filter.

(i) If the total surface area of the particles is less than 3 mm^2 , examine the particles with the largest surface area (S), greatest length (L), and greatest thickness (e).

(A) If any (S) of all of the particles is less than or equal to 1 mm^2 , the (L) is less than or equal to 1.5 mm, and the (e) is less than or equal to 0.2 mm, inspect the MGB plugs for particles before further flight, and inspect the MGB filter for particles within 25 hours TIS. Thereafter:

(1) For 25 hours TIS, continue to inspect the MGB plugs for particles before each flight and perform the actions required by paragraphs (g)(1)(i) and (ii) of this AD.

(2) Inspect the MGB filter for particles at intervals not to exceed 25 hours TIS and perform the actions required by paragraphs (g)(1)(i) and (ii) of this AD.

(B) If any (S) is greater than 1 mm^2 , (L) is greater than 1.5 mm, or (e) is greater than 0.2 mm, perform a metallurgical analysis for any 16NCD13 particles, using a method in accordance with FAA-approved procedures.

(C) If there are any 16NCD13 particles, before further flight, replace the MGB with an airworthy MGB.

(ii) If the total surface area of collected particles is greater than or equal to 3 mm^2 , before further flight, perform a metallurgical analysis for any 16NCD13 particles using a method in accordance with FAA-approved procedures. If there are any 16NCD13 particles, before further flight, replace the MGB with an airworthy MGB.

(2) For helicopters with at least one Type Y planet gear assembly with an S/N listed in Appendix 4.A. of ASB EC155-05A034 Rev 5 installed, within 25 hours TIS after the effective date of this AD, inspect the MGB filter for particles. If there are any particles that consist of any scale, flake, splinter, or particle other than cotter pin fragments, pieces of lock wire, swarf, abrasion, or miscellaneous non-metallic waste, and any of the planet gears have accumulated more than 50 total hours TIS, before further flight, perform the actions required by paragraphs (g)(1)(i) and (ii) of this AD.

(3) For helicopters with at least one Type Y planet gear assembly with an S/N listed in Appendix 4.A. of ASB EC155-05A034 Rev 5 installed, within 50 hours TIS after the effective date of this AD, replace the MGB or as an alternative to replacing an affected MGB, replace the epicyclic reduction gear module in the affected MGB in accordance with paragraph 3.B.2. of the Accomplishment Instructions of Airbus Helicopters Service Bulletin SB No. EC155-63-016, Revision 5, dated March 6, 2019 (SB EC155-63-016 Rev 5), except you are not required to contact Airbus Helicopters.

(4) For helicopters without any Type Y planet gear assembly installed but with at least one Type Z planet gear assembly with an S/N listed in Appendix 4.B. of ASB EC155-05A034 Rev 5 installed, within 50 hours TIS after the effective date of this AD, or before any gear accumulates 1,800 total hours TIS, whichever occurs later, replace the MGB or as an alternative to replacing an affected MGB, replace the epicyclic reduction gear module in the affected MGB in accordance with paragraph 3.B.2. of the Accomplishment Instructions of SB EC155-63-016 Rev 5, except you are not required to contact Airbus Helicopters.

(5) For helicopters with at least one Type Z planet gear assembly with an S/N listed in Appendix 4.B. of ASB EC155-05A034 Rev 5 installed, inspect the MGB filter for particles within the compliance times specified in Figure 1 to paragraph (g)(5) of this AD and inspect the oil sump for particles within the compliance times specified in Figure 2 to paragraph (g)(5) of this AD, based on the total hours TIS accumulated by the Type Z planet gear with the most total hours TIS accumulated since first installation in an MGB. If there are particles, before further flight, perform the actions required by paragraphs (g)(1)(i) and (ii) of this AD.

Figure 1 to Paragraph (g)(5)

Total hours TIS accumulated	Compliance time for initial inspection	Compliance time for repetitive inspections
Less than 400 total hours TIS	Within 55 hours TIS after the effective date of this AD	Within 55 hours TIS
400 or more total hours TIS	Within 25 hours TIS after the effective date of this AD	Within 25 hours TIS

Figure 2 to Paragraph (g)(5)

Total hours TIS accumulated	Compliance time for initial inspection	Compliance time for repetitive inspections
Less than 400 total hours TIS	Before exceeding 400 hours TIS after the effective date of this AD	Within 55 hours TIS
400 or more total hours TIS	Within 55 hours TIS after the effective date of this AD	Within 55 hours TIS

(6) As of the effective date of this AD, do not install a type Y planet gear assembly with an S/N listed in Appendix 4.A. of ASB EC155-05A034 Rev 5 on any helicopter, and do not install an MGB with a Type Y planet gear assembly with an S/N listed in Appendix 4.A. of ASB EC155-05A034 Rev 5 on any helicopter.

(7) As of the effective date of this AD, do not install a Type Z planet gear assembly with an S/N listed in Appendix 4.B. of ASB EC155-05A034 Rev 5 that has accumulated 1,800 or more total hours TIS on any helicopter, and do not install an MGB with at least one Type Z planet gear assembly with an S/N listed in Appendix 4.B. of ASB EC155-05A034 Rev 5 that has accumulated 1,800 or more total hours TIS on any helicopter.

(8) As of the effective date of this AD, do not install any planet gear on any helicopter if the planet gear assembly type cannot be determined, and do not install any MGB on any helicopter if any of the planet gear assembly types cannot be determined.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Rao Edupuganti, Aerospace Engineer, Dynamic Systems Section, Technical Innovation Policy Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email rao.edupuganti@faa.gov.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2018-0263, dated December 7, 2018. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0197.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin ASB No. EC155-05A034, Revision 5, dated December 4, 2018.

(ii) Airbus Helicopters Service Bulletin SB No. EC155-63-016, Revision 5, dated March 6, 2019.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25703 Filed 11-24-21; 8:45 am]



2021-22-21 ASI Aviation (Type Certificate Previously Held by Reims Aviation S.A.):
Amendment 39-21794; Docket No. FAA-2021-0714; Project Identifier 2019-CE-016-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to ASI Aviation (type certificate previously held by Reims Aviation S.A.) Model F406 airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2400, Electrical Power System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of a circuit breaker (CB) switch. The FAA is issuing this AD to prevent smoke and burning smell in the cockpit caused by failure of CB switches. The unsafe condition, if not addressed, could result in reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Actions

Within 200 hours time-in-service (TIS) or within 12 months, whichever occurs first after the effective date of this AD, prepare the airplane and gain access in accordance with steps 1 through 7 of the Accomplishment Instructions in ASI Aviation Service Bulletin No. F406-62, Revision 01, dated December 14, 2018 (SB F406-62R1), and inspect each avionics bus CB switch part number (P/N) CM3589-50 to identify the date code.

(1) If a CB switch does not have a date code, before further flight, remove the CB switch from service and install CB switch P/N 4061-2400-1 in accordance with steps 9 through 14 of the Accomplishment Instructions in SB F406-62R1.

(2) If a CB switch has a date code earlier than 0434, before the CB switch exceeds 1,000 hours TIS since first installation on an airplane, remove the CB switch from service and install CB switch P/N 4061-2400-1 in accordance with steps 9 through 14 of the Accomplishment Instructions in SB F406-62R1.

(3) If a CB switch has a date code 0434 or later, before the CB switch exceeds 6 years since first installation on an airplane or within 12 months after the effective date of this AD, whichever occurs later, remove the CB switch from service and install CB switch P/N 4061-2400-1 in accordance with steps 9 through 14 of the Accomplishment Instructions in SB F406-62R1.

(h) Replacements

Within 200 hours TIS or within 12 months, whichever occurs first after the effective date of this AD, remove each CB switch P/N CM3589-20 from service, re-identify the CB panel, and install CB switches with P/N 406E2450-00000-100 in accordance with Part 1, steps 1 through 13, of the Accomplishment Instructions in ASI Aviation Service Bulletin No. F406-90, dated December 14, 2018 (SB F406-90).

(i) Life Limit

Before exceeding 6 years since first installation on an airplane and thereafter at intervals not to exceed 6 years, remove each CB switch P/N 4061-2400-1 and P/N 406E2450-00000-100 from service and replace it in accordance with steps 9 through 14 of the Accomplishment Instructions in SB F406-62R1 or Part 1, steps 1 through 13, of the Accomplishment Instructions in SB F406-90, as applicable.

(j) Parts Installation Prohibition

As of the effective date of this AD, do not install a CB switch P/N CM3589-50 or P/N CM3589-20 on any airplane.

(k) Credit for Previous Actions

You may take credit for the actions required by paragraph (g) of this AD if you performed those actions before the effective date of this AD using Reims Aviation Industries Service Bulletin No. F406-62, dated March 8, 2006.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m)(1) of this AD or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(m) Related Information

(1) For more information about this AD, contact Gregory Johnson, Aviation Safety Engineer, International Validation Section, FAA, 901 Locust, Room 301, Kansas City, MO 64106-2641; phone: (720) 626-5462; email: gregory.johnson@faa.gov.

(2) Refer to European Aviation Safety Agency (EASA) AD 2019-0015, dated January 29, 2019, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0714.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) ASI Aviation Service Bulletin No. F406-62, Revision 01, dated December 14, 2018.

(ii) ASI Aviation Service Bulletin No. F406-90, dated December 14, 2018.

(3) For service information identified in this AD, contact ASI Aviation, A rodrome de Reims Prunay, 51360 Prunay, France; telephone: +33 3 26 48 46 84; fax: +33 3 26 49 18 57; email: contact@asi-aviation.fr; website: <https://asi-aviation.fr/page-Accueil.html>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 22, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25688 Filed 11-24-21; 8:45 am]



2021-24-06 Airbus Helicopters: Amendment 39-21827; Docket No. FAA-2021-1009; Project Identifier MCAI-2021-01173-R.

(a) Effective Date

This airworthiness directive (AD) is effective December 9, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model EC130T2 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) Emergency AD 2021-0235-E, dated October 28, 2021 (EASA AD 2021-0235-E).

(d) Subject

Joint Aircraft System Component (JASC) Code: 5300, Fuselage Structure.

(e) Unsafe Condition

This AD was prompted by a report of degradation of the rear transmission shaft bearing support and the determination that all of the attachment rivets of the transmission shaft bearing support were sheared. The FAA is issuing this AD to address sheared attachment rivets of the transmission shaft bearing support. This condition, if not addressed, could lead to failure of the tail rotor drive shaft and subsequent loss of yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0235-E.

(h) Exceptions to EASA AD 2021-0235-E

(1) Where EASA AD 2021-0235-E refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2021-0235-E requires doing an inspection after each last flight of the day or "ALF," this AD requires doing that inspection before each first flight of the day.

(3) Where paragraph (2) of EASA AD 2021-0235-E requires, if any rivet on the rear transmission bearing support is found missing, loose or sheared, or any visible crack is present, contacting Airbus Helicopters to obtain approved repair instructions and accomplishing those instructions, this AD requires doing a repair in accordance with an FAA-approved method.

(4) Where the service information referenced in EASA AD 2021-0235-E specifies that the inspection can be done by a mechanical technician, a pilot with correct training and accreditation, or a pilot-owner, this AD requires that the inspection be done by a qualified mechanic.

(5) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0235-E.

(6) Where paragraph (1) of EASA AD 2021-0235-E requires doing inspections of the rivets for presence of cracks, for this AD, inspect for visible cracks and missing, loose, or sheared rivets.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0235-E specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be permitted provided that there are no passengers on board.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2021-0235-E, dated October 28, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0235-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1009.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 12, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25635 Filed 11-22-21; 11:15 am]



2021-24-09 Bell Textron Canada Limited: Amendment 39-21830; Docket No. FAA-2021-1011; Project Identifier MCAI-2021-00867-R.

(a) Effective Date

This airworthiness directive (AD) is effective December 7, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 430 helicopters, having serial number 49001 through 49129, inclusive, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6220, Main Rotor Head.

(e) Unsafe Condition

This AD was prompted by an in-flight failure of the main rotor (M/R) pitch link clevis (clevis) due to fatigue damage and excessive wear. The FAA is issuing this AD to detect and address any wear and damage of the M/R clevis neck or threaded area. The unsafe condition, if not addressed, could result in crack initiation at the M/R clevis neck and failure of the M/R pitch link, resulting in loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 25 hours time-in-service (TIS) or 30 days, whichever occurs first, after the effective date of this AD:

(i) Remove and disassemble each M/R pitch link assembly part number (P/N) 430-010-411-105, or P/N 430-010-411-107, but do not remove the inserts from the tube. Visually inspect the M/R clevis P/N 430-010-432-101 and rod end for wear, corrosion, and damage, which for the purposes of this inspection may be indicated by distortion, bending, a crack, or damaged M/R clevis threads. If there is any wear, corrosion or damage, before further flight, remove the affected M/R clevis or the affected rod end from service.

(ii) Visually inspect each universal bearing P/N 212-010-412-001 for binding, stiffness, wear, looseness, excess axial and radial play, and damage, which for the purposes of this inspection may be indicated by distortion, bending, or a crack.

(A) If there is any wear, looseness, excess axial and radial play, or damage and the M/R pitch link assembly is P/N 430-010-411-105 or P/N 430-010-411-107 and has accumulated 5,000 or less total hours TIS, before further flight, remove the universal bearing P/N 212-010-412-001 from service and replace with an airworthy part.

(B) If there is any binding or stiffness and the M/R pitch link assembly is P/N 430-010-411-105 or P/N 430-010-411-107 and has accumulated more than 5,000 total hours TIS, before further flight, remove the universal bearing P/N 212-010-412-001 and M/R clevis from service and replace with airworthy parts.

(C) If there is any wear, looseness, excess axial and radial play, or damage and the M/R pitch link assembly is P/N 430-010-411-105 or P/N 430-010-411-107 and has accumulated more than 5,000 total hours TIS, before further flight, remove the universal bearing P/N 212-010-412-001 from service and replace with an airworthy part.

(iii) Purge grease the bearings of each universal bearing.

(iv) Perform a magnetic particle inspection for any crack on each M/R clevis by following the Accomplishment Instructions, Part I, paragraphs 8. through 8.d., of Bell Alert Service Bulletin 430-21-60, dated July 13, 2021 (ASB 430-21-60). If there is any crack, before further flight, remove each affected M/R clevis from service. If there is no crack, before further flight, perform a selective brush cadmium plating to replace any missing cadmium plating and apply a chromate conversion coating.

(2) Within 50 hours TIS after completion of paragraph (g)(1) of this AD, and thereafter at intervals not to exceed 50 hours TIS:

(i) Using a 10X magnifying glass, visually inspect the neck and threaded area of each M/R clevis for wear, corrosion, and damage, which for the purposes of this inspection may be indicated by distortion, bending, a crack, or damaged M/R clevis threads. Refer to Figure 3 of ASB 430-21-60 for a depiction of the area to inspect on each M/R clevis. If there is any wear, corrosion, or damage, before further flight, remove the affected M/R clevis from service and replace with an airworthy part.

(ii) Perform the actions required in paragraph (g)(1)(iv) of this AD for each M/R clevis.

(3) Within 150 hours TIS after the completion of paragraph (g)(1) of this AD, and thereafter at intervals not to exceed 150 hours TIS, visually inspect and purge grease each universal bearing, by performing the actions as required in paragraphs (g)(1)(ii) and (iii) of this AD.

(h) Special Flight Permits

A special flight permit may be permitted provided that there are no passengers onboard.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(2) The subject of this AD is addressed in Transport Canada CF-2021-26 AD, dated July 26, 2021. You may view the Transport Canada AD at <https://www.regulations.gov> in Docket No. FAA-2021-1011.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Alert Service Bulletin 430-21-60, dated July 13, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; telephone 1-450-437-2862 or 1-800-363-8023; fax 1-450-433-0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 16, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-25489 Filed 11-18-21; 11:15 am]