

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2022-01

12/20/2021 - 01/02/2022



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2022-01

2021-05-03		Airbus Helicopters	EC225LP
2021-23-01		Stemme AG	Stemme S 12
2021-23-06		Various Manufactures	234; CH-47D
2021-24-18		Viking Air Limited	DHC-3
2021-24-19		Flugzeugbau GmbH	DG-500MB and DG-1000M
2021-24-21		Embraer S.A.	EMB-500 and EMB-505
2021-24-22	R 2012-06-16	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-25-01		Leonardo S.p.a.	A109S and AW109SP
2021-25-08		Leonardo S.p.a.	AW189
2021-25-10		Daher Aerospace	TBM 700
2021-25-11	R 78-02-03	Piper Aircraft, Inc.	PA-23-250
2021-26-07	R 2020-11-05	Airbus Helicopters	EC120B
2021-26-08		Bell Textron Canada Limited	206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4
2022-01-05	R 2021-24-06	Airbus Helicopters	EC130T2



2021-05-03 Airbus Helicopters: Amendment 39-21864; Docket No. FAA-2020-0904; Product Identifier 2019-SW-041-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model EC225LP helicopters, certificated in any category, with a left-hand side (LH) engine fuel supply (fuel supply) hose part number (P/N) 704A34416087 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2820, Aircraft Fuel Distribution System.

(e) Unsafe Condition

This AD was prompted by a report of an incorrect installation of the LH fuel supply hose P/N 704A34416087. The FAA is issuing this AD to prevent restricted fuel flow to the LH engine. The unsafe condition, if not addressed, could result in a decrease of the LH engine power when accelerating to a power setting corresponding to One Engine Inoperative power and subsequent reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 110 hours time-in-service (TIS) after the effective date of this AD, visually inspect the LH fuel supply hose for twisting as shown in Figures 1 and 2 of Airbus Helicopters Alert Service Bulletin No. EC225-71A019, Revision 2, dated May 21, 2021 (ASB EC225-71A019 Rev 2). If the LH fuel supply hose has any twisting, before further flight, borescope inspect the entire length of the inside of the fuel supply hose for twisting as shown in Figures 3 through 5 of ASB EC225-71A019 Rev 2.

(i) If the inside of the LH fuel supply hose has any twisting, before further flight, remove the LH fuel supply hose from service and install an airworthy LH fuel supply hose by following the Accomplishment Instructions, paragraph 3.B.3.b, of ASB EC225-71A019 Rev 2.

(ii) If the LH fuel supply hose does not have any twisting, reinstall the LH fuel supply hose by following the Accomplishment Instructions, paragraph 3.B.3.b, of ASB EC225-71A019 Rev 2.

(2) Within 1,200 hours TIS after the effective date of this AD, modify your helicopter by removing from service LH fuel supply hose P/N 704A34416087 and installing the improved LH fuel supply hose P/N 704A34416101 in accordance with the Accomplishment Instructions, paragraph 3.B.3.b, of ASB EC225-71A019 Rev 2.

(3) As of the effective date of this AD, do not install a LH fuel supply hose P/N 704A34416087 on any helicopter unless it is installed by following the Accomplishment Instructions, paragraph 3.B.3.b, of ASB EC225-71A019 Rev 2.

(h) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g)(1) of this AD, if those actions were performed before the effective date of this AD using Airbus Helicopters Alert Service Bulletin No. EC225-71A019, Revision 1, dated February 28, 2019.

(i) Special Flight Permits

Special flight permits may be permitted provided that there are no passengers on board.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2021-0156, dated July 2, 2021. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2020-0904.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin No. EC225-71A019, Revision 2, dated May 21, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 8, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27638 Filed 12-22-21; 8:45 am]



2021-23-01 Stemme AG: Amendment 39-21799; Docket No. FAA-2021-0716; Project Identifier 2019-CE-023-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Stemme AG Model Stemme S 12 gliders, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3414, Airspeed/Mach Indicator.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an airspeed indicator (ASI) with speed markings inconsistent with the approved and published values (beginning of the white and green arc). The FAA is issuing this AD to prevent erroneous information being provided to the pilot, particularly at the lower speed operation limits. The unsafe condition, if not addressed, could result in reduced control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 30 days after the effective date of this AD, inspect ASI part number (P/N) IF-W230 or IF-W190 for incorrect markings in accordance with the table in the Appendix, "2.3. Airspeed Indicator Markings," of Stemme Service Bulletin No. P062-980027, Revision 00, dated December 17, 2018 (the SB). If an ASI marking is incorrect, before further flight, perform one of the following:

- (i) Replace the ASI by following the Actions, Action 2, of the SB; or
- (ii) Amend the existing aircraft flight manual (AFM) for your glider by inserting the Appendix, temporary page 2-3 SB, "2.3. Airspeed Indicator Markings," of the SB. Within 3 months after

amending the AFM, replace the ASI by following the Actions, Action 2, of the SB and remove temporary page 2-3 SB, "2.3. Airspeed Indicator Markings," from the AFM.

(2) As of the effective date of this AD, do not install ASI P/N IF-W230 or IF-W190 on any glider unless it has passed the inspection required by this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2019-0082, dated April 12, 2019, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2021-0716.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Stemme Service Bulletin No. P062-980027, Revision 00, dated December 17, 2018.

Note 1 to paragraph (j)(2)(i): This service information has Feb-29 and July 14, 2017, in the footer of every page on the document. Feb-29 refers to the form number and July 14, 2017, is the revision date of the form used to write the service information. The signature block on the bottom of page 1 contains a release date and an approval date. For enforceability purposes, the FAA will cite the Stemme AG service information using the release date of December 17, 2018, that is used in EASA AD 2019-0082, dated April 12, 2019.

Note 2 to paragraph (j)(2)(i): This service information contains German to English translation. EASA used the English translation in referencing the document from Stemme AG. For enforceability purposes, the FAA will cite the Stemme AG service information in English as it appears on the document.

(ii) [Reserved]

(3) For service information identified in this AD, contact STEMME AG, Flugplatzstrasse F2, Nr. 6-7, D-15344 Strausberg, Germany; phone: +49 (0) 3341 3612-0; fax: +49 (0) 3341 3612-30; email: airworthiness@stemme.de; website: <https://www.stemme.com>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 25, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27774 Filed 12-22-21; 8:45 am]



2021-23-06 Various Model 234 and Model CH-47D Helicopters: Amendment 39-21804; Docket No. FAA-2021-0951; Project Identifier AD-2021-01047-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 4, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Model 234 and Model CH-47D helicopters, regardless of type certificate holder, certificated in any category. Type certificate holders include, but are not limited to:

- (1) Columbia Helicopters, Inc.,
- (2) Billings Flying Service, Inc.,
- (3) Tandem Rotor, LLC, and
- (4) Unical Aviation, Inc.

(d) Subject

Joint Aircraft System Component (JASC) Code/Air Transport Association (ATA) of America Code: 6710, Rotor flight controls.

(e) Unsafe Condition

This AD was prompted by inadequate maintenance, which resulted in mechanical failure of the longitudinal cyclic trim actuator (LCTA). The FAA is issuing this AD to correct this unsafe condition, which if not addressed, could result in loss of control of the rotor blades and subsequent loss of control of the helicopter or the rotor blades striking the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 3 calendar days after the effective date of this AD, determine the hours time-in-service (TIS) and lift cycles since last overhaul for each LCTA on your helicopter. If lift cycles cannot be determined, count 6 lift cycles for each hour TIS for each LCTA. For purposes of this AD, a lift cycle is defined as any of the following:

- (i) Takeoff from ground for flight;
- (ii) Lift of a new external load while in flight; or

(iii) Lift of a new internal load while in flight (e.g., fluid drawn into an internal tank).

(2) If the last overhaul of any LCTA was not approved for return to service by a person that meets the requirements of 14 CFR part 43, or, if you are unable to establish hours TIS and lift cycles since last overhaul of an LCTA (e.g., hours TIS and lift cycles for each LCTA were not tracked), within 10 calendar days after the effective date of this AD, and thereafter at intervals not to exceed 3,000 hours TIS or 18,000 lift cycles, whichever occurs first, overhaul that LCTA. For purposes of any overhaul required by this AD, the overhaul must include:

- (i) An inspection of each acme screw for wear and cracking;
- (ii) Lubricating all drive threads and gears; and
- (iii) A test to ensure proper operation of the extend and retract travel limit switches.

(3) If the last overhaul of an LCTA was approved for return to service by a person that meets the requirements of 14 CFR part 43, overhaul the LCTA (to include the overhaul requirements specified in paragraphs (g)(2)(i) through (iii) of this AD) within 500 hours TIS or 3,000 lift cycles since last overhaul, whichever occurs first; or within 90 days after the effective date of this AD, whichever occurs later. Thereafter, overhaul each LCTA at intervals not to exceed 3,000 hours TIS or 18,000 lift cycles, whichever occurs first.

(4) As of the effective date of this AD, do not install any LCTA on any helicopter unless it has been approved for return to service by a person that meets the requirements of 14 CFR part 43 after an overhaul that includes the overhaul requirements specified in paragraphs (g)(2)(i) through (iii) of this AD, and that LCTA has not been in service for more than 3,000 hours TIS or 18,000 lift cycles since that overhaul.

(5) Within 10 days after completing each LCTA overhaul required by this AD, provide the following information by email to vaughn.n.schmitt@faa.gov and ian.a.hansen@faa.gov; or by mail to Vaughn Schmitt and Ian Hansen, Aircraft Evaluation Group, Safety Standards Division, FAA, 10101 Hillwood Parkway, Fort Worth, TX 76177:

- (i) Helicopter Owner/Operator name, email, address, and telephone number,
- (ii) LCTA model, part number and serial number,
- (iii) Months TIS since last LCTA overhaul,
- (iv) Operating hours and lift cycles since last LCTA overhaul,
- (v) Date and location of last LCTA overhaul,
- (vi) LCTA repairs since last LCTA overhaul,
- (vii) LCTA condition when removed,
- (viii) LCTA reports of failures or degraded functions,
- (ix) LCTA part replacements,
- (x) Point of contact information for additional information,
- (xi) Any additional notes or comments, and
- (xii) Pictures, if available.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact David Herron, Aerospace Engineer, Systems & Equipment Section, Seattle ACO Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: (206) 231-3554; email david.herron@faa.gov.

(j) Material Incorporated by Reference

None.

Issued on December 6, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27539 Filed 12-16-21; 11:15 am]



2021-24-18 Viking Air Limited: Amendment 39-21839; Docket No. FAA-2021-0214; Project Identifier 2018-CE-064-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Viking Air Limited Model DHC-3 airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5700, Wing Structure.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as fatigue damage of the wing strut lug fitting components or the fuselage to wing strut attachment (tie-bar). The FAA is issuing this AD to identify and correct potential fatigue damage of the wing strut lug fitting components of the fuselage to wing strut attachment. The unsafe condition, if not addressed, could result in cracking and failure of the structural integrity of the wing or the tie-bar.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) through (3) of this AD:

(1) For all airplanes: Within 3 months after the effective date of this AD, determine and record the number of equivalent air time hours on each wing and tie-bar by doubling the total hours time-in-service (TIS) accumulated on each part. If the total hours TIS of a tie-bar is unknown or cannot be determined, use the total hours TIS of the wing strut lug fitting on the main spar.

(2) For airplanes with a maximum certificated gross weight that has never exceeded 8,000 pounds: Remove from service each left-hand and right-hand wing strut fitting and tie-bar by following the Accomplishment Instructions in Viking DHC-3 Otter SB V3/0008, Revision NC, dated February 9, 2017, and the Replacement section of the Accomplishment instructions in De Havilland Aircraft of Canada, Limited DHC-3 Otter Service Bulletin Number 3/37, Revision B, dated October 8, 1982, at whichever of the following compliance times that occurs later:

(i) Before the part accumulates 40,000 equivalent air time hours, or

(ii) Within 12 months after the effective date of this AD.

(3) For airplanes with a maximum certificated gross weight that has ever exceeded 8,000 pounds: Remove from service each left-hand and right-hand wing strut fitting and tie-bar by following the Accomplishment Instructions in Viking DHC-3 Otter SB V3/0008, Revision NC, dated February 9, 2017, and the Replacement section of the Accomplishment instructions in De Havilland Aircraft of Canada, Limited DHC-3 Otter Service Bulletin Number 3/37, Revision B, dated October 8, 1982, at whichever of the following compliance times that occurs later:

(i) Before the part accumulates 32,200 equivalent air time hours, or

(ii) Within 12 months after the effective date of this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO Branch, send it to the attention of the person identified in paragraph (h)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(h) Related Information

(1) For more information about this AD, contact Aziz Ahmed, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 287-7329; fax: (516) 794-5531; email: aziz.ahmed@faa.gov.

(2) Refer to Transport Canada AD CF-2017-29, dated August 24, 2017, for more information. You may examine the Transport Canada AD at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0214.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-3 Otter Service Bulletin Number V3/0008, Revision NC, dated February 9, 2017.

(ii) De Havilland Aircraft of Canada, Limited DHC-3 Otter Service Bulletin Number 3/37, Revision B, dated October 8, 1982.

Note to paragraph (i)(2)(ii): Although De Havilland Aircraft of Canada Limited DHC-3 Otter Service Bulletin Number 3/37, Revision B, dated October 8, 1982, is at revision B, the footer on pages 3 through 6 shows revision "A," dated May 14, 1982.

(3) For both Viking and De Havilland Aircraft of Canada, Limited service information identified in this AD, contact Viking Air Limited Technical Support, 1959 De Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; phone: (North America) (800) 663-8444; fax: (250) 656-0673; email: technical.support@vikingair.com; website: <https://www.vikingair.com/support/service-bulletins>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at

NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27409 Filed 12-17-21; 8:45 am]



2021-24-19 DG Flugzeugbau GmbH: Amendment 39-21840; Docket No. FAA-2021-0792; Project Identifier AD-2020-00593-G.

(a) Effective Date

This airworthiness directive (AD) is effective January 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to DG Flugzeugbau GmbH Model DG-500MB and DG-1000M gliders, all serial numbers, certificated in any category, with a Solo Kleinmotoren GmbH Solo Model 2625 02i engine installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7300, Engine Fuel and Control.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an error in the engine control unit (ECU) software. The FAA is issuing this AD to prevent an injection of fuel into one cylinder when the ECU is activated. The unsafe condition, if not addressed, could result in difficulty starting the engine and reduced control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 3 months after the effective date of this AD, update the ECU software to software version V517 Revision 8 in accordance with the Actions in Solo Kleinmotoren GmbH Service Bulletin No. 4600-11, Ausgabe 1 (English translation: Issue 1), dated August 19, 2019.

(2) As of the effective date of this AD, do not install ECU software version V517 Revision 7 or earlier on any glider with a Solo Kleinmotoren GmbH Solo Model 2625 02i engine.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2020-0056, dated March 13, 2020, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0792.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Solo Kleinmotoren GmbH Service Bulletin No. 4600-11, Ausgabe 1 (English translation: Issue 1), dated August 19, 2019.

Note 1 to paragraph (j)(2)(i): This service information contains German to English translation. EASA used the English translation in referencing the document from Stemme AG. For enforceability purposes, the FAA will cite the service information in English as it appears on the document.

(ii) [Reserved]

(3) For service information identified in this AD, contact Solo Kleinmotoren GmbH, Postfach 600152, D71050 Sindelfingen, Germany; phone: +49 703 1301-0; fax: +49 703 1301-136; email: aircraft@solo-germany.com; website: <https://aircraft.solo.global/gb/>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 18, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27636 Filed 12-22-21; 8:45 am]



2021-24-21 Embraer S.A.: Amendment 39-21842; Docket No. FAA-2020-1077; Project Identifier MCAI-2020-00819-A.

(a) Effective Date

This airworthiness directive (AD) is effective January 25, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Embraer S.A. Model EMB-500 and EMB-505 airplanes, all serial numbers, certificated in any category, with Model PW617F-E or PW617F1-E engines (for Model EMB-500 airplanes) or Model PW535E engines (for Model EMB-505 airplanes) installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 0200, Operations.

(e) Unsafe Condition

This AD was prompted by a report that the operational envelope does not contain airspeed limitations and procedures for operating the airplane at static air temperatures below -54 °C. The FAA is issuing this AD to prevent inadequate operation below the allowable temperature. The unsafe condition, if not addressed, could result in multiple systems failures and compromise safe flight of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 30 days after the effective date of this AD:

(1) For Model EMB-500 airplanes: Revise Section 2 Limitations and Section 5 Performance of the existing AFM for your airplane by incorporating the information in “V-OPERATING INFORMATION,” of Embraer Phenom Operational Bulletin No. 500-001/20, dated March 9, 2020. You may use a different document provided the language is identical to the language in “V-OPERATING INFORMATION,” of Embraer Phenom Operational Bulletin No. 500-001/20, dated March 9, 2020.

(2) For Model EMB-505 airplanes: Revise Section 2 Limitations, Section 5 Performance, and Supplement 2 of the existing AFM for your airplane by incorporating the information in “V-

OPERATING INFORMATION,” of Embraer Phenom Operational Bulletin No. 505-005/13, Revision 1, dated March 9, 2020. You may use a different document provided the language is identical to the language in V-

OPERATING INFORMATION,” of Embraer Phenom Operational Bulletin No. 505-005/13, Revision 1, dated March 9, 2020.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send your request to the person identified in paragraph (i)(1) of this AD and email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspection, the manager of the local Flight Standards District Office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

(2) Refer to Mandatory Continuing Airworthiness Information (MCAI) Agência Nacional de Aviação Civil AD 2020-05-03, effective June 1, 2020, for related information. This MCAI may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1077.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Embraer Phenom Operational Bulletin No. 500-001/20, dated March 9, 2020.

(ii) Embraer Phenom Operational Bulletin No. 505-005/13, Revision 1, dated March 9, 2020.

(3) For service information identified in this AD, contact Phenom Maintenance Support, Avenida Brigadeiro Faria Lima, 2170, P.O. Box 36/2, São José dos Campos, 12227-901, Brazil; phone: +55 12 3927 1000; email: phenom.reliability@embraer.com.br; website: <https://www.embraer.com.br/en-US/Pages/home.aspx>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27511 Filed 12-20-21; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-24-22 Pilatus Aircraft Ltd.: Amendment 39-21843; Docket No. FAA-2021-0786; Project Identifier MCAI-2021-00429-A.

(a) Effective Date

This AD is effective January 25, 2022.

(b) Affected ADs

This AD replaces AD 2012-06-16, Amendment 39-16997 (77 FR 19061, March 30, 2012).

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 airplanes, all serial numbers, certificated in any category.

Note 1 to paragraph (c): These airplanes may also be identified as Fairchild Republic Company airplanes, Fairchild Industries airplanes, Fairchild Heli Porter airplanes, or Fairchild-Hiller Corporation airplanes.

(d) Subject

Joint Aircraft System Component (JASC) Codes 2700, Flight Control System; 2710, Aileron Control System; 2720, Rudder Control System; and 2730, Elevator Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as detachment or partial detachment of the elevator or rudder in flight. The FAA is issuing this AD to prevent failure of the elevator or rudder attachment. The unsafe condition, if not addressed, could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

The following definitions apply for purposes of this AD.

(1) Group 1 airplanes: Airplanes that have not been modified in accordance with Pilatus PC-6 Service Bulletin (SB) No. 55-003, dated November 29, 2013 (Pilatus SB 55-003); Pilatus PC-6 SB No. 55-003, Revision 1, dated December 9, 2014 (Pilatus SB 55-003R1); Pilatus PC-6 SB No. 55-003, Revision 2, dated January 19, 2017 (Pilatus 55-003R2); Pilatus PC-6 SB No. 55-003, Revision

3, dated November 6, 2017 (Pilatus 55-003R3); or Pilatus PC-6 SB No. 55-005, dated February 25, 2021 (Pilatus SB 55-005).

(2) Group 2 airplanes: Airplanes that have been modified in accordance with Pilatus SB 55-003, SB 55-003R1, SB 55-003R2, Pilatus SB 55-003R3; or Pilatus SB 55-005.

(h) Inspect Elevator, Rudder, and RH Aileron Hinge Bolt Installations

(1) For Group 1 airplanes: Within 14 days after the effective date of this AD, inspect the elevator, rudder, and RH aileron hinge bolt installations and take any corrective actions before further flight by following the Accomplishment Instructions-Part 1-On Aircraft-Inspection in Pilatus SB 55-005.

(2) For Group 1 airplanes: Within 100 hours time-in-service (TIS) after the inspection required by paragraph (h)(1) of this AD and thereafter at intervals not to exceed 100 hours TIS until the modification required by paragraph (i) of this AD is done, inspect the elevator, rudder, and RH aileron hinge bolt installations and take any corrective actions before further flight by following the Accomplishment Instructions-Part 2-On Aircraft-CONFIG 1-Repeat Inspections in Pilatus SB 55-005.

(i) Modify Group 1 Airplanes

Within 11 months after the effective date of this AD, modify the hinge bolt installations on the elevator, rudder, and RH aileron assemblies by following the Accomplishment Instructions-Part 3-On Aircraft-Modification from CONFIG 1 to CONFIG 2 in Pilatus SB 55-005. Modifying the elevator, rudder, and RH aileron hinge bolt installations terminates the repetitive inspections required by paragraph (h)(2) of this AD.

(j) Installation Prohibition

As of the following applicable compliance time, do not install on any airplane an elevator assembly part number (P/N) 113.50.06.011, 113.50.06.012, 6305.0010.00, 6305.0010.52, 6305.0010.53, 6305.0010.54, or 6305.0010.55, or a rudder assembly P/N 113.40.06.018, 6302.0010.51, or 6302.0010.52.

(1) For Group 1 airplanes: As of the modification required by paragraph (i) of this AD.

(2) For Group 2 airplanes: As of the effective date of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD and email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301,

Kansas City, MO 64106; phone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0098, dated April 9, 2021, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2021-0786.

(3) You may obtain information related to Pilatus SB 55-003, SB 55-003R1, SB 55-003R2, Pilatus SB 55-003R3; or Pilatus SB 55-005, which are not incorporated by reference, using the contact information found in paragraph (m)(3) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pilatus PC-6 Service Bulletin (SB) No. 55-005, dated February 25, 2021.

(ii) [Reserved]

(3) Pilatus Aircraft Ltd., Customer Support General Aviation, CH-6371 Stans, Switzerland; phone: +41 848 247 365; email: techsupport.ch@pilatus-aircraft.com; website: <https://www.pilatus-aircraft.com>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27507 Filed 12-20-21; 8:45 am]



2021-25-01 Leonardo S.p.a.: Amendment 39-21844; Docket No. FAA-2021-0834; Project Identifier MCAI-2021-00298-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model A109S and AW109SP helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2021-0065, dated March 8, 2021 (EASA AD 2021-0065).

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2497, Electrical Power System Wiring.

(e) Unsafe Condition

This AD was prompted by the discovery that rubber protection of certain electrical wiring had not been installed in the baggage avionics bay during production. The FAA is issuing this AD to prevent chafing of electrical wiring. The unsafe condition, if not addressed, could result in fire ignition and smoke in the baggage compartment and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0065.

(h) Exceptions to EASA AD 2021-0065

(1) Where EASA AD 2021-0065 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021-0065 refers to its effective date, this AD requires using the effective date of this AD.

(3) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0065.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0065 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0065, dated March 8, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0065, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0834.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 23, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27390 Filed 12-17-21; 8:45 am]



2021-25-08 Leonardo S.p.a.: Amendment 39-21851; Docket No. FAA-2021-1060; Project Identifier MCAI-2021-00340-R.

(a) Effective Date

This airworthiness directive (AD) becomes effective January 4, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model AW189 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency AD 2021-0078, dated March 17, 2021 (EASA AD 2021-0078).

(d) Subject

Joint Aircraft System Component (JASC) Code 3300, Lighting System.

(e) Unsafe Condition

This AD was prompted by the determination that certain part-numbered fairings were never introduced into the main rotor tip lights kit design definition and were not certified for icing conditions. The FAA is issuing this AD to address ice shedding ingestion by the engines, which could lead to a double engine in-flight shut-down and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0078.

(h) Exceptions to EASA AD 2021-0078

(1) Where EASA AD 2021-0078 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0078.

(3) Where EASA AD 2021-0078 refers to flight hours (FH), this AD requires using hours time-in-service (TIS).

(4) This AD does not mandate compliance with paragraph (1) of EASA AD 2021-0078.

(5) Where paragraph (4) of EASA AD 2021-0078 specifies that modification of a helicopter is a terminating action for the requirements of paragraph (1) of EASA AD 2021-0078, this AD does not provide a terminating action for the requirements of paragraph (1) of EASA AD 2021-0078 because this AD does not mandate compliance with paragraph (1) of EASA AD 2021-0078.

(6) Where paragraph (2) of EASA AD 2021-0078 specifies a compliance time of within 400 flight hours or 12 months, whichever occurs first, this AD requires compliance within 400 hours TIS after the effective date of this AD.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0078 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permits

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided it is not flown into known icing conditions.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency AD 2021-0078, dated March 17, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0078, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1060.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 2, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27388 Filed 12-17-21; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-25-10 Daher Aerospace (Type Certificate Previously Held by SOCATA): Amendment 39-21854; Docket No. FAA-2020-1069; Project Identifier 2018-CE-039-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Daher Aerospace (type certificate previously held by SOCATA) Model TBM 700 airplanes, all serial numbers, certificated in any category, with an oil cooler air induction duct part number (P/N) T700A7920040001, T700H792000900000, T700H792001900000, T700H792001900200, T700H792001900400, or T700H792001900600 installed.

Note 1 to paragraph (c) of this AD: The applicable oil cooler air induction duct P/Ns may be installed in accordance with modification 70-0435-79; Daher Aerospace Service Bulletin SB 70-231, Revision 1, dated July 2018; or Daher Aerospace Service Bulletin SB 70-219, Revision 2, dated July 18, 2018.

(d) Subject

Joint Aircraft System Component (JASC) Code 7900, Engine Oil System (Airframe).

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The unsafe condition that is the subject of the MCAI is ice accumulation on the oil cooler air inlet duct fin. The FAA is issuing this AD to prevent ice from accumulating on the oil cooler air induction duct fins, which could lead to an increase in oil temperature, uncommanded engine inflight shutdown, and reduced airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modify the Oil Cooler Air Induction Duct

(1) Within 3 months after the effective date of this AD, remove the four upper fins of the oil cooler air induction duct and re-identify the oil cooler air induction duct in accordance with the

Description of Accomplishment Instructions in Daher Aerospace Service Bulletin SB 70-254, dated April 2018.

(2) As of the effective date of this AD, do not install an oil cooler air induction duct P/N T700A7920040001, T700H792000900000, T700H792001900000, T700H792001900200, T700H792001900400, or T700H792001900600 on any airplane.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Greg Johnson, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (720) 626-5462; fax: (816) 329-4090; email: greg.johnson@faa.gov.

(2) Refer to European Aviation Safety Agency (EASA) AD 2018-0133, dated June 22, 2018, and corrected June 25, 2018, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2020-1069.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Daher Aerospace Service Bulletin SB 70-254, dated April 2018.

(ii) [Reserved]

(3) For Daher Aerospace service information identified in this AD, contact Daher Aerospace Inc., Pompano Beach Airpark, 601 NE 10 Street, Pompano Beach, FL 33060; phone: (954) 893-1400; website: <https://www.tbm.aero>.

(4) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27408 Filed 12-17-21; 8:45 am]



2021-25-11 Piper Aircraft, Inc.: Amendment 39-21855; Docket No. FAA-2020-1006; Project Identifier 2019-CE-047-AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 25, 2022.

(b) Affected ADs

This AD replaces AD 78-02-03 [Reg. Docket No. 77-EA-81, Amendment 39-3128] (43 FR 3079, January 23, 1978) (AD 78-02-03).

(c) Applicability

This AD applies to Piper Aircraft, Inc., Model PA-23-250 airplanes, serial numbers 27-7654001 through 27-7954121, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5510, Horizontal Stabilizer Structure.

(e) Unsafe Condition

This AD was prompted by reports of cracks developing on the stabilator structure. The FAA is issuing this AD to prevent weakening of the stabilator structure and to detect and correct cracks on the stabilator tip tube and weight assembly. The unsafe condition, if not addressed, could cause weakening of the complete structure and lead to loss of the trim tab and counter balance weight, which may result in reduced airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Previously Required Actions Retained From AD 78-02-03

(1) Within 50 hours time-in-service (TIS) after January 26, 1978 (the effective date of AD 78-02-03), do the following inspections and modifications.

(i) For airplanes with serial numbers 27-7654001 through 27-7754054, inspect both stabilator tip ribs for missing rivets and missing tube and weight assembly attachment screws and if necessary alter in accordance with Piper Service Bulletin (SB) 547, dated March 1, 1977.

(ii) For airplanes with serial numbers 27-7654001 through 27-7754127, 27-7754130, 27-7754131, 27-7754133 through 27-7754136, and 27-7754138 through 27-7754144, replace the right and left stabilator tab forward inboard rib/horn assemblies by installing Piper Kit 761 143 or equivalent kit in accordance with Piper SB 569, dated August 24, 1977.

(iii) For airplanes with serial numbers 27-7654001 through 27-7754041 equipped with stabilators Piper part number (P/N) 15658-2, 15658-3, 15658-22 or 15658-23, reinforce the mounting of the stabilator tube and weight assemblies by installing additional nose-ribs with Piper Kit 761 141 or equivalent kit in accordance with Piper Service Letter 807A, dated September 8, 1977.

(2) Before further flight after completing the alterations in paragraphs (g)(1)(ii) and (iii) of this AD, balance the stabilator.

(h) Inspection of Stabilator Tip Tube and Weight Assembly

Within 10 hours TIS after the effective date of this AD or within 100 hours TIS after completing the last inspection required by paragraph (a) of AD 78-02-03, whichever occurs later, and thereafter at intervals not to exceed 100 hours TIS, inspect the left and right stabilator balance weight assemblies for cracks and complete any necessary repairs by following Parts I and II of the Instructions in Piper SB No. 540B, dated February 9, 2021, except you are not required to contact Piper for repair instructions. Instead, repair in accordance with FAA-approved procedures.

(i) Credit for Previous Actions

You may take credit for the initial inspection and corrective actions required by paragraph (h) of this AD if you performed those actions before the effective date of this AD using Piper SB No. 540, dated January 4, 1977, or SB No. 540A, dated October 20, 1980.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the following provisions apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact John Marshall, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5524; fax: (404) 474-5605; email: john.r.marshall@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piper Service Bulletin No. 547, dated March 1, 1977.

(ii) Piper Service Bulletin No. 569, dated August 24, 1977.

(iii) Piper Service Letter No. 807A, dated September 8, 1977.

(iv) Piper Service Bulletin No. 540B, February 9, 2021.

(3) For the service information identified in this AD, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL 32960; phone: (772) 299-2141; website: <https://www.piper.com/>.

(4) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27510 Filed 12-20-21; 8:45 am]



2021-26-07 Airbus Helicopters: Amendment 39-21866; Docket No. FAA-2021-0872; Project Identifier MCAI-2021-00312-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 27, 2022.

(b) Affected ADs

This AD replaces AD 2020-11-05, Amendment 39-21130 (85 FR 31042, May 22, 2020) (AD 2020-11-05).

(c) Applicability

This AD applies to Airbus Helicopters Model EC120B helicopters, certificated in any category, all serial numbers.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6400, Tail rotor system.

(e) Unsafe Condition

This AD was prompted by a report of recurrent loss of tightening torque on several attachment bolts on the tail rotor (TR) hub body. The FAA is issuing this AD to detect cracking and fretting, which if not addressed, could result in potential loss of the TR drive and consequent loss of yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 15 hours time-in-service (TIS) or 7 days, whichever occurs first after the effective date of this AD, and thereafter at intervals not to exceed 15 hours TIS, using a light source and mirror, visually inspect TR hub body part number (P/N) C642A0100103 for a crack in the entire inspection area depicted in Figure 1 of Airbus Helicopters Emergency Alert Service Bulletin 05A020 Revision 2, dated February 8, 2021. If there is a crack, before further flight, perform the actions in paragraphs (g)(1)(i) and (ii) of this AD.

(i) Remove the TR hub body and each bolt, washer, and nut installed on the TR hub body from service and replace with airworthy parts.

(ii) Inspect the TR splined flange for corrosion, impacts, fretting, wear, and a crack in the areas identified in Figure 2 to paragraph (g)(1)(ii) of this AD. If the condition of the part (including

corrosion, impacts, fretting, wear, or cracks) exceeds the criteria as specified in Figure 1 to paragraph (g)(1)(ii) of this AD, before further flight, remove the splined flange from service and replace with an airworthy part.


Note 1 to paragraph (g)(1)(ii): You may refer to “Detailed Check–Splined Flange,” Task 64-21-00, 6-5, Airbus Aircraft Maintenance Manual (AMM), dated October 15, 2020, which pertains to the TR splined flange inspection.

Figure 1 to paragraph (g)(1)(ii) – Inspection Criteria for Tail Rotor Splined

Flange

Location as specified in Figure 2 to paragraph (g)(1)(ii) of this AD	Maximum damage, which causes replacement (E1, Dia. 2, Dia. 3, and Dia. 4 are shown in Figure 2 to paragraph (g)(1)(ii) of this AD)
Zone A	Scratch depth > 0.2 mm (0.008 in.). Crack. E1 < 2.75 mm (0.108 in.). Dia. 3 > 6.02 mm (0.2371 in.). Dia. 2 > 33.03 mm (1.3004 in.).
Zone B	Touch-up depth > 0.1 mm (0.004 in.). Crack.
Zone C	Crack. Scratch depth > 0.2 mm (0.008 in.).
Zone D [Dia. 4 = 14 mm +/- 0.1 mm (0.548; 0.555in.)]	Touch-up depth > 0.1 mm (0.004 in.). Crack. E1 < 2.75 mm (0.108 in.).

Figure 2 to paragraph (g)(1)(ii) – Inspection Areas of Tail Rotor Splined Flange



(2) For helicopters with 9,000 or more total hours TIS, or with unknown total hours TIS, within 15 hours TIS or 7 days, whichever occurs first after the effective date of this AD, and thereafter at intervals not to exceed 1,000 hours TIS, remove each bolt, washer, and nut installed on the TR hub body from service and replace with airworthy parts and perform the actions in paragraph (g)(1)(ii) of this AD.

(3) For helicopters with less than 9,000 total hours TIS, within 1,000 hours TIS or before accumulating 9,000 total hours TIS, whichever occurs first after the effective date of this AD, and thereafter at intervals not to exceed 1,000 hours TIS, remove each bolt, washer, and nut installed on the TR hub body from service and replace with airworthy parts and perform the actions in paragraph (g)(1)(ii) of this AD.

(4) As of the effective date of this AD, do not install TR hub body P/N C642A0100103 on any helicopter, unless the actions of paragraph (g)(1) of this AD have been accomplished.

(h) Special Flight Permits

A special flight permit may be permitted provided that there are no passengers onboard.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(2) Service information identified in this AD, is available at the contact information specified in paragraphs (k)(3) and (4) of this AD.

(3) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2021-0069, dated March 11, 2021. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2021-0872.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin 05A020, Revision 2, dated February 8, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 9, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27625 Filed 12-22-21; 8:45 am]



2021-26-08 Bell Textron Canada Limited: Amendment 39-21867; Docket No. FAA-2021-0728; Project Identifier MCAI-2020-00656-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4 helicopters, certificated in any category, with nut part number (P/N) MS21042L4 or P/N MS21042L5 installed on the tail rotor drive shaft (TRDS) disc pack (Thomas) couplings.

- Note 1 to paragraph (c): Helicopters with an OH-58A designation are Model 206A-1 helicopters.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6510, Tail Rotor Drive Shaft.

(e) Unsafe Condition

This AD was prompted by reports of cracked or missing nuts installed on the TRDS Thomas couplings. The FAA is issuing this AD to prevent failure or loss of a nut on the TRDS Thomas couplings. The unsafe condition, if not addressed, could result in loss of the tail rotor and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 600 hours time-in-service (TIS) after the effective date of this AD:

(i) For helicopters that have not been modified by installing Supplemental Type Certificate (STC) SH2750NM:

(A) Remove each nut P/N MS21042L4 installed on each TRDS Thomas coupling from service, and replace with nut P/N NAS9926-4L. The location of nut P/N NAS9926-4L is depicted in Detail A Figure 1 of Bell Alert Service Bulletin (ASB) 206-19-136, dated August 27, 2019 (ASB 206-19-136)

or Bell ASB 206L-19-181, Revision A, dated August 29, 2019 (ASB 206L-19-181), as applicable to your model helicopter.

(B) Apply a torque of 5.65-7.90 Nm (50-70 in lb) plus tare torque to each nut installed as required by paragraph (g)(1)(i)(A) of this AD, and apply a torque stripe using torque seal lacquer (C-049) or equivalent lacquer, as shown in Figure 2 of ASB 206-19-136 or ASB 206L-19-181, as applicable to your model helicopter.

Note 2 to paragraph (g)(1)(i)(B): Torque stripes are referred to as witness marks in ASB 206-19-136 and ASB 206L-19-181.

(ii) For Bell Textron Canada Limited Model 206, 206A, 206A-1, 206B, 206B-1, and 206L helicopters that have been modified by installing STC SH2750NM and Model 206L-1 and 206L-3 helicopters that have been modified by installing STC SH2750NM but have not been modified by accomplishing Bell Service Instruction BHT-206-SI-2052, Revision 1, dated October 14, 2010 (BHT-206-SI-2052):

(A) Remove each nut P/N MS21042L4 installed on each TRDS Thomas coupling from service, except for nuts P/N MS21042L4 installed on the forward short TRDS Thomas coupling, and replace with nut P/N NAS9926-4L. The location of nut P/N NAS9926-4L is depicted in Detail A Figure 1 of ASB 206-19-136 or ASB 206L-19-181 as applicable to your model helicopter.

(B) Remove each nut P/N MS21042L4 installed on the forward short TRDS Thomas coupling from service and replace with nut P/N 90-132L4.

(C) For each nut installed as required by paragraphs (g)(1)(ii)(A) and (B) of this AD, apply a torque of 5.65-7.90 Nm (50-70 in lb) plus tare torque to each nut and apply a torque stripe using torque seal lacquer (C-049) or equivalent lacquer, as shown in Figure 2 of ASB 206-19-136 or ASB 206L-19-181, as applicable to your model helicopter.

(iii) For Bell Textron Canada Limited Model 206L-1 and 206L-3 helicopters that have been modified by installing STC SH2750NM and have been modified by accomplishing BHT-206-SI-2052:

(A) Remove each nut P/N MS21042L4 installed on each TRDS Thomas coupling from service, except for nuts P/N MS21042L4 installed on the forward short TRDS Thomas coupling, and replace with nut P/N NAS9926-4L. The location of nut P/N NAS9926-4L is depicted in Detail A Figure 1 of ASB 206L-19-181.

(B) Remove each nut P/N MS21042L4 installed on the forward short TRDS Thomas coupling from service and replace with nut P/N 90-132L4.

(C) For each nut installed as required by paragraphs (g)(1)(iii)(A) and (B) of this AD, apply a torque of 5.65-7.90 Nm (50-70 in lb) plus tare torque to each nut, and apply a torque stripe using torque seal lacquer (C-049) or equivalent lacquer, as shown in Figure 2 of ASB 206L-19-181.

(iv) For Bell Textron Canada Limited Model 206L-4 helicopters that have been modified by installing STC SH2750NM:

(A) Remove each nut P/N MS21042L4 installed on each TRDS Thomas coupling from service, except for nuts P/N MS21042L4 installed on the forward short TRDS Thomas coupling, and replace with nut P/N NAS9926-4L. The location of nut P/N NAS9926-4L is depicted in Detail A Figure 1 of ASB 206L-19-181.

(B) Remove from service each nut P/N MS21042L5 installed on the forward short TRDS Thomas coupling and replace with nut P/N 90-132L5.

(C) For each nut installed as required by paragraphs (g)(1)(iv)(A) and (B) of this AD, apply a torque of 5.65-7.90 Nm (50-70 in lb) plus tare torque to each nut, and apply a torque stripe using torque seal lacquer (C-049) or equivalent lacquer, as shown in Figure 2 of ASB 206L-19-181.

(2) Within 25 hours TIS after installation of any nut P/N NAS9926-4L, P/N 90-132L4, or P/N 90-132L5, as required by paragraphs (g)(1)(i)(A), (ii)(A) and (B), (iii)(A) and (B), or (iv)(A) and (B) of this AD, apply a torque of 5.65 Nm (50 in lb) to each nut.

(i) If the nut does not move, apply a torque stripe using torque seal lacquer (C-049) or equivalent lacquer, as shown in Figure 2 of ASB 206-19-136 or ASB 206L-19-181, as applicable to your model helicopter.

(ii) If any nut moves, inspect each TRDS Thomas coupling and each bolt, nut, and washer for elongated holes and fretting on the fasteners. If any TRDS Thomas coupling has an elongated hole, remove the TRDS Thomas coupling from service. If any bolt, nut, or washer has any fretting, remove the affected part from service.

(3) As of the effective date of this AD, do not install nut P/N MS21042L4 or MS21042L5 on any TRDS Thomas coupling.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

(2) Bell Service Instruction BHT-206-SI-2052, Revision 1, dated October 14, 2010, which is not incorporated by reference, contains additional information about the subject of this AD. This service information is available at the contact information specified in paragraphs (j)(3) and (4) of this AD.

(3) The subject of this AD is addressed in Transport Canada AD CF-2020-15, dated May 13, 2020. You may view the Transport Canada AD at <https://www.regulations.gov> in Docket No. FAA-2021-0728.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Alert Service Bulletin 206-19-136, dated August 27, 2019.

(ii) Bell Alert Service Bulletin 206L-19-181, Revision A, dated August 29, 2019.

(3) For Bell service information identified in this AD, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; telephone 1-450-437-2862 or 1-800-363-8023; fax 1-450-433-0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 12, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft
Certification Service.

[FR Doc. 2021-27645 Filed 12-22-21; 8:45 am]



2022-01-05 Airbus Helicopters: Amendment 39-21893; Docket No. FAA-2021-1165; Project Identifier MCAI-2021-01414-R.

(a) Effective Date

This airworthiness directive (AD) is effective January 14, 2022.

(b) Affected ADs

This AD replaces AD 2021-24-06, Amendment 39-21827 (86 FR 66934, November 24, 2021) (AD 2021-24-06).

(c) Applicability

This AD applies to Airbus Helicopters Model EC130T2 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) Emergency AD 2021-0283-E, dated December 17, 2021 (EASA AD 2021-0283-E).

(d) Subject

Joint Aircraft System Component (JASC) Code: 5300, Fuselage Structure.

(e) Unsafe Condition

This AD was prompted by a report of degradation of the rear transmission shaft bearing support and the determination that all of the attachment rivets of the transmission shaft bearing support were sheared. The FAA is issuing this AD to address sheared attachment rivets of the transmission shaft bearing support. This condition, if not addressed, could lead to failure of the tail rotor drive shaft and subsequent loss of yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0283-E.

(h) Exceptions to EASA AD 2021-0283-E

(1) Where EASA AD 2021-0283-E refers to November 1, 2021 (the effective date of EASA Emergency AD 2021-0235-E, dated October 28, 2021), this AD requires using December 9, 2021 (the effective date of AD 2021-24-06).

(2) Where EASA AD 2021-0283-E refers to its effective date, this AD requires using the effective date of this AD.

(3) Where EASA AD 2021-0283-E requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(4) Where paragraphs (1) and (2) of EASA AD 2021-0283-E require accomplishing inspections after each last flight of the day or “ALF,” this AD requires accomplishing those inspections before each first flight of the day.

(5) Where the service information referenced in EASA AD 2021-0283-E specifies that certain inspections can be done by a mechanical technician, a pilot with correct training and accreditation, or a pilot-owner, this AD requires that those inspections be done by a qualified mechanic.

(6) Where paragraphs (3) and (4) of EASA AD 2021-0283-E specify contacting Airbus Helicopters to obtain approved repair instructions and accomplishing those instructions, this AD requires repair done in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters’ EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(7) Where paragraph (6) of EASA AD 2021-0283-E requires reporting inspection results to Airbus Helicopters within 30 days after each rivet replacement, this AD requires reporting inspection results at the applicable time in paragraph (h)(7)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 10 days after each rivet replacement.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

(8) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0283-E.

(i) Special Flight Permit

Special flight permits may be permitted to accomplish the actions required by paragraphs (1) and (2) of EASA AD 2021-0283-E for the before each first flight of the day compliance time only, provided that there are no passengers on board. Special flight permits are prohibited for any other actions required by this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2021-0283-E, dated December 17, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0283-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1165.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 22, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-28340 Filed 12-27-21; 4:15 pm]