

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2022-03

1/17/2022 - 1/30/2022



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2022-01

2021-05-03		Airbus Helicopters	EC225LP
2021-23-01		Stemme AG	Stemme S 12
2021-23-06		Various Manufactures	234; CH-47D
2021-24-18		Viking Air Limited	DHC-3
2021-24-19		Flugzeugbau GmbH	DG-500MB and DG-1000M
2021-24-21		Embraer S.A.	EMB-500 and EMB-505
2021-24-22	R 2012-06-16	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-25-01		Leonardo S.p.a.	A109S and AW109SP
2021-25-08		Leonardo S.p.a.	AW189
2021-25-10		Daher Aerospace	TBM 700
2021-25-11	R 78-02-03	Piper Aircraft, Inc.	PA-23-250
2021-26-07	R 2020-11-05	Airbus Helicopters	EC120B
2021-26-08		Bell Textron Canada Limited	206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4
2022-01-05	R 2021-24-06	Airbus Helicopters	EC130T2

Biweekly 2022-02

2021-26-14	R 2018-11-01	Airbus Helicopters	AS332L2, EC225LP
2021-26-15		Vulcanair S.p.A.	P.68C, P.68C-TC, P.68 "OBSERVER," P.68 OBSERVER 2, P.68R, and P.68TC OBSERVER
2021-26-18	R 2020-21-01	Airbus Helicopters	AS-365N2, AS 365 N3, and SA-365N1; SA-365C1, SA-365C2, and SA-365N; EC 155B and EC155B1
2022-01-06		Cameron Balloons Ltd.	flange adapter
2022-01-09		Stemme AG	Stemme S 10-VT and Stemme S 12
2022-02-01		Sikorsky Aircraft Corporation	S-92A
2022-02-02	R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212

Biweekly 2022-03

2021-26-12		Stemme AG	Stemme S 12
2021-26-16		Various Restricted Category Helicopters	UH-1H
2021-26-21		Pilatus Aircraft Ltd.	PC-24
2021-26-24		Leonardo S.p.a.	A109A and A109A II
2021-26-25		Schempp-Hirth Flugzeugbau GmbH	Duo Discus; Duo Discus T
2021-26-26	R 2005-12-08	Safran Helicopter Engines, S.A.	Arrius 2B1, Arrius 2B1A, and Arrius 2B2
2021-26-29		Leonardo S.p.a.	AW169
2022-02-17		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-03-03	R 2021-22-20	Austro Engine GmbH	E4 and E4P
2022-03-07		Stemme AG	S6 and S6-RT



2021-26-12 Stemme AG: Amendment 39-21871; Docket No. FAA-2021-0842; Project Identifier 2019-CE-032-AD.

(a) Effective Date

This airworthiness directive (AD) is effective February 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Stemme AG Model Stemme S 12 gliders, serial numbers 12-002 through 12-026, inclusive, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3200, Landing Gear System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as incorrect installation of an axle connecting the main landing gear (MLG) to the center steel frame of the glider. The FAA is issuing this AD to prevent failure of the MLG. The unsafe condition, if not addressed, could result in damage to the glider and possible injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before further flight after the effective date of this AD, visually inspect the MLG left-hand and right-hand legs for proper installation as depicted in Figure 3 of Stemme Service Bulletin No. P062-980037, Revision 00, dated June 5, 2019 (SB P062-980037).

(2) If the MLG installation is not as depicted in Figure 3 of SB P062-980037, before further flight, inspect the MLG installation for damage in accordance with the Actions section, Action 2, in SB P062-980037, except you are not required to contact Stemme if there is damage. Instead, repair any damage using a method approved by the FAA or the European Union Aviation Safety Agency (EASA).

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

(2) Refer to EASA AD 2019-0130-E, dated June 7, 2019, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0842.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Stemme Service Bulletin No. P062-980037, Revision 00, dated June 5, 2019.

Note 1 to paragraph (j)(2)(i): This service information has Feb-29 and July 14, 2017, in the footer of the document. Feb-29 refers to the form number and July 14, 2017, is the revision date of the form used to write the service information. For enforceability purposes, the FAA will cite the Stemme AG service information using the release date of June 5, 2019, that is located in the footer on the bottom of page 1 and used in EASA AD 2019-0130-E, dated June 7, 2019.

Note 2 to paragraph (j)(2)(i): This service information contains German to English translation. EASA used the English translation in referencing the document from Stemme AG. For enforceability purposes, the FAA will cite the Stemme AG service information in English as it appears on the document.

(ii) [Reserved]

(3) For service information identified in this AD, contact STEMME AG, Flugplatzstrasse F2, Nr. 6-7, D-15344 Strausberg, Germany; phone: +49 (0) 3341 3612-0; fax: +49 (0) 3341 3612-30; email: airworthiness@stemme.de; website: <https://www.stemme.com>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 9, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00968 Filed 1-19-22; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-26-16 Various Restricted Category Helicopters: Amendment 39-21875; Docket No. FAA-2021-0189; Project Identifier AD-2020-00645-R.

(a) Effective Date

This airworthiness directive (AD) is effective February 25, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to restricted category Model UH-1H helicopters; current type certificate holders include but are not limited to Arrow Falcon Exporters Inc.; Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC; JJASPP Engineering Services, LLC.; Northwest Rotorcraft, LLC; Overseas Aircraft Support, Inc.; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and Tamarack Helicopters, Inc., with KAflex main driveshaft part number (P/N) SKCP2180-1, SKCP2281-1, SKCP2281-1R, or SKCP2281-103 installed.

Note 1 to paragraph (c): Helicopters with an SW205 designation are Southwest Florida Aviation International, Inc., Model UH-1H helicopters.

(d) Subject

Joint Aircraft System Component (JASC) Code: 6310, Engine/Transmission Coupling.

(e) Unsafe Condition

This AD was prompted by multiple reports of failure of the main driveshaft. The unsafe condition, if not addressed, could result in loss of engine power to the transmission and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before further flight after the effective date of this AD, determine the total hours time-in-service (TIS) of the main driveshaft. If the total hours TIS of the main driveshaft cannot be determined, use the helicopter's total hours TIS as the total hours TIS of the main driveshaft for the action required by this paragraph.

(i) If the main driveshaft has accumulated less than 5,000 total hours TIS, before exceeding 5,000 total hours TIS, replace the main driveshaft. The main driveshaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.

Note 2 to paragraph (g)(1)(i): This note applies to paragraphs (g)(1)(i) and (ii), (g)(2), and (g)(3)(i) through (iv) of this AD. U.S. Army Aviation and Missile Command, Depot Maintenance Work Requirement for Main Drive Shaft DMWR 55-1615-278, Original Issuance, dated September 30, 2009, specifies procedures that are not FAA-approved.

(ii) If the main driveshaft has accumulated 5,000 or more total hours TIS, before further flight, replace the main driveshaft. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.

(2) Thereafter following paragraph (g)(1) of this AD, replace the main driveshaft before accumulating 5,000 total hours TIS. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.

(3) Within 25 hours TIS after the effective date of this AD, remove main driveshaft P/N SKCP2180-1, SKCP2281-1, SKCP2281-1R, or SKCP2281-103 by following “6-24.3. Removal–Main Driveshaft P/N SKCP2281-103” on page 6-24, including “4-24. Removal–Air Inlet Filters” on page 4-17 and “Figure 4-9. Engine Air Inlet Filter Installation” on page 4-16, of Headquarters, Department of the Army, Aviation Unit and Intermediate Maintenance Instructions Army Model UH-1H/V/EH-1H/X Helicopters, Technical Manual TM 55-1520-210-23-1, Change No. 42, dated April 14, 2003 (TM 55-1520-210-23-1 C 42), except where instructed to “refer to figure 6-12.2” in TM 55-1520-210-23-1 C 42, refer to Figure 1 to the introductory text of paragraph (g)(3) of this AD, and where instructed to “see figure 6-12.3” in TM 55-1520-210-23-1 C 42, see Figure 2 to the introductory text of paragraph (g)(3) of this AD, and:

Note 3 to the introductory text of paragraph (g)(3): Figures 6-12.2 and 6-12.3 are missing from TM 55-1520-210-23-1 C 42.




Figure 1 to the Introductory Text of Paragraph (g)(3) – Main Driveshaft Installation and Removal Tool





Figure 2 to the Introductory Text of Paragraph (g)(3) – Work Aid Tool Installed on Main Driveshaft

(i) Inspect for any broken, loose, or missing hardware. If there is broken or loose hardware, before further flight, remove the main driveshaft from service. If there is missing hardware, before further flight, replace the main driveshaft. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.





(ii) Visually inspect each flex frame and mount bolt torque stripe (red or yellow) for movement. If there is any torque stripe movement, before further flight, replace the main driveshaft. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.

(iii) Visually inspect each joint for fretting corrosion, which may be indicated by red metallic particles. If there is any grease, oil, or dirt covering a joint, clean the area and visually inspect again. If there is any fretting corrosion, before further flight, replace the main driveshaft. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.

(iv) Inspect the main driveshaft for mechanical damage, corrosion, an edge dent, and nick as shown in Figure 3 to paragraph (g)(3)(iv) of this AD. For the purposes of this inspection, mechanical damage may be indicated by a crack, scratch, or wear; and corrosion may be indicated by corrosion or pitting. If there is a scratch, wear, corrosion, pitting, an edge dent, or a nick within allowable limits, before further flight, repair the main driveshaft in accordance with FAA-approved procedures. If there is a crack, or a scratch, wear, corrosion, pitting, an edge dent, or a nick that exceeds allowable limits, before further flight, replace the main driveshaft. The main drive shaft may be overhauled in accordance with FAA-approved procedures to accomplish the replacement required by this paragraph.



DAMAGE LOCATION SYMBOLS

Type of Damage	Maximum Damage and Repair Depth			
				
MECHANICAL	0.001" before and after repair	0.005" before and after repair	0.005" before and after repair	0.015" before and after repair
CORROSION	Surface, no pits	0.005" before and after repair	0.005" before and after repair	0.010" before and after repair
MAXIMUM AREA PER FULL DEPTH REPAIR	0.05 in ²	0.10 in ²	0.25 in ²	0.25 in ²
NUMBER OF REPAIRS	One per leg			
EDGE DENTS, NICKS	0.001 in	0.010 in	0.010 in	0.025 in

1. No cracks are permitted
2. Repairs must be no less than 1.000 inch apart.
3. Repairs not to be within 0.500 inches of bolt hole.
4. Faying surfaces must be free of any raised metal areas.
5. All repairs to be smooth at maximum depth and smoothly blended with surrounding surface.
6. Exposed bare metal may be touched up with Sermetel Product 1122 or 196. Zinc Chromate, primer color T, even though it does not blend cosmetically with Sermetel coating, can be used if Sermetel touch-up products are unavailable.


7. Sides and corners of flex frames are to be treated as  areas.

Figure 3 to Paragraph (g)(3)(iv) – Damage Limits

(4) Before installing the main driveshaft following paragraph (g)(3) of this AD, and with the engine adapter installed in the end of the engine output shaft, inspect the alignment of the main driveshaft installation between the transmission input drive quill coupling and the engine output shaft adapter by following “6-24. Alignment–Main Driveshaft,” paragraphs c. through g. on pages 6-21

through 6-23, including “Figure 6-7. Transmission Positioning for Driveshaft Alignment” on page 6-2 (Figure 6-7), and “Figure 6-8. Tool Application–Use of Alignment Tool Set (T47)” on page 6-3 (Figure 6-8), of TM 55-1520-210-23-1 C 42. If there is misalignment, before further flight, adjust the alignment by following “6-24. Alignment–Main Driveshaft,” paragraphs h. through j. on page 6-23, including Figure 6-7 and Figure 6-8, of TM 55-1520-210-23-1 C 42.

(5) Within 300 hours TIS after the effective date of this AD, and thereafter within intervals not to exceed 300 hours TIS, with the main driveshaft installed, accomplish the actions in paragraphs (g)(3)(i) through (iv) of this AD.

(6) As an optional terminating action for the requirements of this AD, you may install KAflex main driveshaft P/N SKCP3303-1.

(7) As an option to accomplishing the actions by following the specified portions in TM 55-1520-210-23-1 C 42 in paragraphs (g)(3) and (4) of this AD, you may accomplish the actions by following those specified portions in Headquarters, Department of the Army, Aviation Unit and Intermediate Maintenance Instructions Army Model UH-1H/V/EH-1H/X Helicopters, Technical Manual TM 55-1520-210-23-1, Change No. 47, dated September 20, 2005 (TM 55-1520-210-23-1 C 47), and disregard exceptions to refer to Figure 1 and see Figure 2 to the introductory text of paragraph (g)(3) of this AD, instead refer to “Figure 6-12.2. Main Driveshaft Installation & Removal Tool” and see “Figure 6-12.3. Work Aid Tool Installed on Main Driveshaft,” on page 6-27 of TM 55-1520-210-23-1 C 47 as instructed in TM 55-1520-210-23-1 C 47.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, DSCO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ASW-190-COS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Ameet Shrotriya, Aerospace Engineer, Delegation Oversight Section, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5525; email ameen.shrotriya@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Headquarters, Department of the Army, Aviation Unit and Intermediate Maintenance Instructions Army Model UH-1H/V/EH-1H/X Helicopters, Technical Manual TM 55-1520-210-23-1, Change No. 42, dated April 14, 2003:

(A) “Figure 4-9. Engine Air Inlet Filter Installation,” page 4-16;

(B) Page 4-17;

(C) “Figure 6-7. Transmission Positioning for Driveshaft Alignment,” page 6-2;

(D) “Figure 6-8. Tool Application–Use of Alignment Tool Set (T47),” page 6-3; and

(E) Pages 6-21 through 6-24.

(ii) Headquarters, Department of the Army, Aviation Unit and Intermediate Maintenance Instructions Army Model UH-1H/V/EH-1H/X Helicopters, Technical Manual TM 55-1520-210-23-1, Change No. 47, dated September 20, 2005:

(A) “Figure 4-9. Engine Air Inlet Filter Installation,” page 4-16;

(B) Page 4-17;

(C) “Figure 6-7. Transmission Positioning for Driveshaft Alignment,” page 6-2;

(D) “Figure 6-8. Tool Application–Use of Alignment Tool Set (T47),” page 6-3;

(E) Pages 6-21 through 6-24; and

(F) “Figure 6-12.2. Main Driveshaft Installation & Removal Tool” and “Figure 6-12.3. Work Aid Tool Installed on Main Driveshaft,” page 6-27.

(3) For service information identified in this AD, contact U.S. Army Materiel Command Logistics Data Analysis Center (USAMC LDAC), ATTN: Equipment Publication Control Officers (EPCOs), Building 3305, Redeye Road, Redstone Arsenal, AL 35898-7466; telephone (256) 955-7716 or 1-866-211-3367; email usarmy.redstone.ldac.mbx.logetm@mail.mil; or at <https://enterprise.armyerp.army.mil>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 10, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00991 Filed 1-20-22; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-26-21 Pilatus Aircraft Ltd.: Amendment 39-21880; Docket No. FAA-2021-0218; Project Identifier MCAI-2020-01519-A.

(a) Effective Date

This airworthiness directive (AD) is effective February 25, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC-24 airplanes, serial numbers 101 through 184, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2830, Fuel Dump System.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as insufficient performance of the fuel drain system that could lead to fire and damage of the airplane. The FAA is issuing this AD to prevent fuel contamination of the inboard rear fuselage. If not addressed, this unsafe condition, in combination with an ignition source, could result in fire and loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 5 months after the effective date of this AD, modify the fuel drain pipe routing and install the drain mast by following paragraphs A. and B. of the Accomplishment Instructions in Pilatus PC-24 Service Bulletin No. 28-003, Revision 1, dated January 23, 2020.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as

appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, General Aviation & Rotorcraft Section, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

(2) Refer to European Union Aviation Safety Agency AD 2020-0252, dated November 12, 2020, for related information. You may examine the MCAI at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0218.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pilatus PC-24 Service Bulletin No. 28-003, Revision 1, dated January 23, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Pilatus Aircraft Ltd., Customer Support General Aviation, CH-6371 Stans, Switzerland; phone: +41 848 24 7 365; email: techsupport.ch@pilatus-aircraft.com; website: <https://www.pilatus-aircraft.com>.

(4) You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 16, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-01160 Filed 1-20-22; 8:45 am]



2021-26-24 Leonardo S.p.a. (Type Certificate Previously Held by Agusta S.p.A.): Amendment 39-21883; Docket No. FAA-2021-0948; Project Identifier MCAI-2020-00394-R.

(a) Effective Date

This airworthiness directive (AD) is effective February 22, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. (type certificate previously held by Agusta S.p.A.) Model A109A and A109A II helicopters, certificated in any category, with a main rotor (M/R) blade part number 109-0103-01-115 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6210, Main Rotor Blades.

(e) Unsafe Condition

This AD was prompted by a report of internal corrosion of the spar of an M/R blade. The FAA is issuing this AD to prevent failure of an M/R blade due to corrosion on the internal surface of the spar. The unsafe condition, if not addressed, could result in loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

For each M/R blade identified in paragraph (c) of this AD:

(1) Within 50 hours time-in-service or 3 months after the effective date of this AD, whichever occurs first, unless already done within the last 24 months for the M/R blade, and thereafter, at intervals not to exceed 24 months for the M/R blade, inspect the M/R blade by following the Accomplishment Instructions, paragraphs 1. through 5., of Leonardo Helicopters Alert Service Bulletin No. 109-155, dated March 13, 2020.

(2) Before further flight, send the film for analysis and accomplish repair in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or European Union Aviation Safety Agency (EASA); or Leonardo S.p.a Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

(2) The subject of this AD is addressed in EASA AD 2020-0065, dated March 20, 2020. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0948.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Leonardo Helicopters Alert Service Bulletin No. 109-155, dated March 13, 2020.

(ii) [Reserved]

(3) For Leonardo Helicopters service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://customerportal.leonardocompany.com/en-US/>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 16, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00759 Filed 1-14-22; 8:45 am]



2021-26-25 Schempp-Hirth Flugzeugbau GmbH: Amendment 39-21884; Docket No. FAA-2021-0878; Project Identifier MCAI-2020-01460-G.

(a) Effective Date

This airworthiness directive (AD) is effective February 24, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Schempp-Hirth Flugzeugbau GmbH gliders identified in paragraphs (c)(1) and (2) of this AD, certificated in any category.

- (1) Model Duo Discus gliders, serial number (S/N) 1 through 541 inclusive, except S/N 534.
- (2) Model Duo Discus T gliders, S/N 1 through 174 inclusive.

(d) Subject

Joint Aircraft System Component (JASC) Code 2760, Drag Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as jerky extension of the air brakes at very high air speeds, including cases where the air brake blades interlock. The FAA is issuing this AD to prevent and correct damage of the airbrake end-stops. The unsafe condition, if not addressed, could result in blockage of the air brakes and reduced control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For gliders with air brake end stop plastic bushings (22 mm) installed: Within 3 months after the effective date of this AD, replace each air brake end stop plastic bushing (22 mm) with an air brake end stop plastic bushing (32 mm) in accordance with Schempp-Hirth Flugzeugbau GmbH Working Instructions for Technical Note 890-16 rev1 and Technical Note 396-20 rev1 action 1, dated September 18, 2020.

(2) For gliders with single air brake metal end stops installed: Within 3 months after the effective date of this AD, inspect each single air brake metal end stop for overlap in accordance with

Schempp-Hirth Flugzeugbau GmbH Working Instructions for Technical Note 396-20 rev1 action 2, dated September 18, 2020. If there is insufficient overlap, before further flight, repair using a method approved by the FAA or the European Union Aviation Safety Agency (EASA).

(h) Parts Installation Provision

As of the effective date of this AD, do not install an air brake end stop plastic bushing (22 mm) on any glider.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

(2) Refer to EASA 2020-0233, dated October 27, 2020, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0878.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Schempp-Hirth Flugzeugbau GmbH Working Instructions for Technical Note 396-20 rev1 action 2, dated September 18, 2020.

Note 1 to paragraph (k)(2)(i): The service information listed in paragraphs (k)(2)(i) of this AD contains German to English translation. EASA used the English translation in referencing the document from Schempp-Hirth Flugzeugbau GmbH. For enforceability purposes, the FAA will cite the service information in English as it appears on the document

(ii) Schempp-Hirth Flugzeugbau GmbH Working Instructions for Technical Note 890-16 rev1 and Technical Note 396-20 rev1 action 1, dated September 18, 2020.

(3) For service information identified in this AD, contact Schempp-Hirth Flugzeugbau GmbH, Kребenstrasse 25, 73230 Kirchheim/Teck, Germany; phone: +49 7021 7298-0; fax: +49 7021 7298-199; email: info@schempp-hirth.com; website: <https://www.schempp-hirth.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 16, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00973 Filed 1-19-22; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2021-26-26 Safran Helicopter Engines, S.A. (Type Certificate previously held by Turbomeca S.A.): Amendment 39-21885; Docket No. FAA-2021-0793; Project Identifier MCAI-2021-00372-E.

(a) Effective Date

This airworthiness directive (AD) is effective February 23, 2022.

(b) Affected ADs

This AD replaces AD 2005-12-08, Amendment 39-14124 (70 FR 34334, June 14, 2005).

(c) Applicability

This AD applies to Safran Helicopter Engines, S.A. (Type Certificate previously held by Turbomeca S.A.) Arrius 2B1, Arrius 2B1A, (including those that embody modification (mod) TU45C, identified as Arrius 2B1A_1) and Arrius 2B2 model turboshaft engines with an installed engine electronic control unit (EECU) having part number (P/N) 70EMF01080 or 70EMF01090—for Arrius 2B1 model turboshaft engines without overspeed protection option (TU 19C); P/N 70EMF01100 or P/N 70EMF01120—for Arrius 2B1 model turboshaft engines with overspeed protection option (TU 67C or TU 23C); P/N 70EMH01000 or 70EMH01010—for Arrius 2B1A model turboshaft engines; or P/N 70EMM01000—for Arrius 2B2 model turboshaft engines.

Note 1 to paragraph (c): Turbomeca Mandatory Service Bulletin (MSB) No. 319 73 2082, Version D, dated June 6, 2011, references Arrius 2B1A_1 model turboshaft engines. Arrius 2B1A model turboshaft engines with mod TU 45C applied are identified as Arrius 2B1A_1 on the engine identification plate.

(d) Subject

Joint Aircraft System Component (JASC) Code 7600, Engine Controls.

(e) Unsafe Condition

This AD was prompted by a report of simultaneous loss of automatic control on both engines installed on an Airbus Helicopters Deutschland (formerly Eurocopter Deutschland) EC135 helicopter during flight. The FAA is issuing this AD to prevent simultaneous loss of automatic control of both engines. The unsafe condition, if not addressed, could result in failure of the engines and loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For engines with an EECU having P/N 70EMF01090, 70EMF01100, 70EMF01120, 70EMH01010, or 70EMM01000, within 90 days after June 29, 2005 (the effective date of AD 2005-12-08), or before further flight, whichever occurs later, upload the EECU software on both engines of the helicopter simultaneously using paragraph 2, Instructions to be incorporated, of the applicable Turbomeca MSB listed in Table 1 to paragraph (g) of this AD, or replace the affected EECU with a part eligible for installation.

(2) For engines with an EECU having P/N 70EMF01080 or 70EMH01000, within 90 days after June 29, 2005 (the effective date of AD 2005-12-08), or before further flight, whichever occurs later, replace the affected EECU with a part eligible for installation.

Table 1 to paragraph (g) – Applicable MSBs

For—	Use—
Arrius 2B1 engines with EECUs that have incorporated Modification TU 19C	Turbomeca MSB No. 319 73 2080, Revision 1, dated February 13, 2004
Arrius 2B1 engines with EECUs that have incorporated Modification TU 67C or TU 23C	Turbomeca MSB No. 319 73 2081, Revision 1, dated February 13, 2004
Arrius 2B1A and 2B1A1_1 engines	Turbomeca MSB No. 319 73 2082, Revision 1, dated February 13, 2004, Version C, dated July 31, 2008, or Version D, dated June 6, 2011
Arrius 2B2 engines	Turbomeca MSB No. 319 73 2090, Original Issue, dated February 13, 2004

(h) Installation Prohibition

After the effective date of this AD, do not install onto any engine any EECU having a P/N identified in paragraph (c) of this AD.

(i) Definition

For the purpose of this AD, a “part eligible for installation” is an EECU having a P/N that is not identified in paragraph (c) of this AD.

(j) No Reporting Requirements

The reporting requirements specified in Turbomeca MSB No. 319 73 2080, Revision 1, dated February 13, 2004; Turbomeca MSB No. 319 73 2081, Revision 1, dated February 13, 2004; Turbomeca MSB No. 319 73 2082, Revision 1, dated February 13, 2004, Version C, dated July 31, 2008, and Version D, dated June 6, 2011; and Turbomeca MSB No. 319 73 2090, Original Issue, dated February 13, 2004, are not required by this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending

information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7134; fax: (781) 238-7199; email: wego.wang@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0088R1, dated July 26, 2021, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0793.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on February 23, 2022.

(i) Turbomeca Mandatory Service Bulletin (MSB) No. 319 73 2082, Version C, dated July 31, 2008.

(ii) Turbomeca MSB No. 319 73 2082, Version D, dated June 6, 2011.

(4) The following service information was approved for IBR on June 29, 2005 (70 FR 34334, June 14, 2005).

(i) Turbomeca MSB No. 319 73 2080, Revision 1, dated February 13, 2004.

(ii) Turbomeca MSB No. 319 73 2081, Revision 1, dated February 13, 2004.

(iii) Turbomeca MSB No. 319 73 2082, Revision 1, dated February 13, 2004.

(iv) Turbomeca MSB No. 319 73 2090, Original Issue, dated February 13, 2004.

(5) For Turbomeca service information identified in this AD, contact Safran Helicopter Engines, S.A., Avenue du 1er Mai, 40220 Tarnos, France; phone: +33 (0) 5 59 74 45 00.

(6) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(7) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 17, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00891 Filed 1-18-22; 8:45 am]



2021-26-29 Leonardo S.p.a.: Amendment 39-21888; Docket No. FAA-2021-0570; Project Identifier 2019-SW-091-AD.

(a) Effective Date

This airworthiness directive (AD) is effective February 22, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Leonardo S.p.a. Model AW169 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6700, Rotorcraft Flight Control.

(e) Unsafe Condition

This AD was prompted by a report of a broken adjustable device that is part of the pilot and co-pilot yaw pedal assemblies. The FAA is issuing this AD to address failure of a yaw pedal adjuster, which could result in reduced yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0199, dated August 27, 2021 (EASA AD 2021-0199).

(h) Exceptions to EASA AD 2021-0199

(1) Where EASA AD 2021-0199 refers to flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021-0199 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where the service information referenced in EASA AD 2021-0199 specifies discarding certain parts, this AD requires removing those parts from service.

(4) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0199.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0199 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5485; email kristin.bradley@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0199, dated August 27, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0199, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222- 5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0570.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 17, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-00757 Filed 1-14-22; 8:45 am]



2022-02-17 Airbus Helicopters Deutschland GmbH (AHD): Amendment 39-21914; Docket No. FAA-2022-0009; Project Identifier MCAI-2021-01459-R.

(a) Effective Date

This airworthiness directive (AD) is effective February 10, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH (AHD) Model MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code: 7160, Engine Air Intake System.

(e) Unsafe Condition

This AD was prompted by reports of engine flame out following prolonged operations in falling snow with the inlet barrier filter (IBF) system installed. The FAA is issuing this AD to prevent partial icing of an IBF engine intake and engine flame out. The unsafe condition, if not addressed, could result in engine failure and reduced control of the helicopter, possibly resulting in damage to the helicopter or injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) Emergency AD 2021-0289-E, dated December 23, 2021 (EASA AD 2021-0289-E).

(h) Exceptions to EASA AD 2021-0289-E

(1) Where EASA AD 2021-0289-E defines Retrofit SB, replace the text “AH Service Bulletin (SB) MBB-BK117 C-2-71-005, SB MBB-BK117 D-2-71-001 and SB MBB-BK117 D-3-71-001, as applicable, installing the IBF system,” with “AH Service Bulletin (SB) MBB-BK117 C-2-71-005 and SB MBB-BK117 D-2-71-001, as applicable, installing the IBF system; and for Model MBB-BK 117

D-3 helicopters, in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.”

(2) Where EASA AD 2021-0289-E requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(3) Where EASA AD 2021-0289-E refers to its effective date, this AD requires using the effective date of this AD.

(4) Where paragraph (1) of EASA AD 2021-0289-E specifies to “inform all flight crews, and, thereafter, operate the helicopter accordingly,” this AD does not require those actions.

(5) The action required by paragraphs (1) and (2) of EASA AD 2021-0289-E may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417 or 135.439.

(6) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0289-E.

(i) Special Flight Permit

Special flight permits may be permitted provided that there are no passengers on board.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2021-0289-E, dated December 23, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0289-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0009.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 13, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-01540 Filed 1-24-22; 11:15 am]



2022-03-03 Austro Engine GmbH: Amendment 39-21920; Docket No. FAA-2022-0013; Project Identifier MCAI-2021-01371-E.

(a) Effective Date

This airworthiness directive (AD) is effective February 14, 2022.

(b) Affected ADs

This AD replaces AD 2021-22-20, Amendment 39-21793 (86 FR 60159, November 1, 2021).

(c) Applicability

This AD applies to Austro Engine GmbH E4 and E4P model diesel piston engines equipped with either:

(1) A cylinder head having part number (P/N) E4A-12-500-000, installed in combination with high-pressure pump (HPP) driving gear P/N E4A-30-000-601 (any revision), P/N E4A-30-000-201 rev. AB.1, or P/N E4A-30-000-201 with a serial number (S/N) listed in Chapter 1.4, Table 1 of Austro Engine Mandatory Service Bulletin No. MSB-E4-036/1, Revision No. 1, dated December 14, 2021 (MSB-E4-036/1); or

(2) An HPP driving gear, having P/N E4A-30-000-201, with an S/N listed in Chapter 1.4, Table 1 of Austro Engine MSB-E4-036/1.

(d) Subject

Joint Aircraft System Component (JASC) Code 8520, Reciprocating Engine Power Section.

(e) Unsafe Condition

This AD was prompted by reports of failure of the HPP driving gear and a subsequent investigation by the manufacturer, which determined that a certain batch of HPP driving gears may have been damaged during assembly. The investigation also determined that the combination of a certain affected cylinder head installed on an engine with a certain affected HPP driving gear installed on the same engine may cause damage to the HPP driving gear. The FAA is issuing this AD to prevent the failure of the HPP driving gear. The unsafe condition, if not addressed, could result in in-flight engine shut-down, forced landing, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For engines equipped with a cylinder head and HPP driving gear combination identified in paragraph (c)(1) of this AD, before further flight after the effective date of this AD, remove the HPP driving gear and replace it with an HPP driving gear eligible for installation using paragraphs 2.1.1 through 2.1.4., Removal and inspection of the HPP driving gear, of Austro Engine MSB-E4-036/1.

(2) Before further flight after performing the required actions in paragraph (g)(1) of this AD, visually inspect the removed HPP driving gear using the criteria in paragraph 7. Appendix II, Table 6, of Austro Engine MSB-E4-036/1.

(3) If, based on the visual inspection required by paragraph (g)(2) of this AD, the HPP driving gear does not meet the acceptable condition criteria in paragraph 7. Appendix II, Table 6, of Austro Engine MSB-E4-036/1, before further flight, visually inspect the HPP shaft, cylinder head, camshaft gear, and inlet/outlet camshaft bushing using the criteria in paragraph 7. Appendix II, Table 7, of Austro Engine MSB-E4-036/1.

(4) If, based on the visual inspection required by paragraph (g)(3) of this AD, the HPP shaft, cylinder head, camshaft gear, or inlet/outlet camshaft bushing do not meet the acceptable condition criteria in paragraph 7. Appendix II, Table 7, of Austro Engine MSB-E4-036/1, before further flight, remove any part not meeting the acceptable condition criteria and replace with a part eligible for installation.

(5) For engines equipped with an affected HPP driving gear identified in paragraph (c)(2) of this AD, within the compliance time specified in Table 1 to paragraph (g)(5) of this AD, as applicable, replace the HPP driving gear with an HPP driving gear eligible for installation.

Table 1 to Paragraph (g)(5) – HPP Driving Gear Replacement

Engine Group	Flight Hours (FHs) accumulated since first installation on the HPP	Compliance Time
1	40 FHs or more	Before next flight after the effective date of this AD
	Less than 40 FHs	Before exceeding 40 FHs since first installation on the HPP
2	80 FHs or more	Before next flight after the effective date of this AD
	Less than 80 FHs	Before exceeding 80 FHs since first installation on the HPP

(h) Definitions

(1) For the purpose of this AD, an HPP driving gear eligible for installation is:

(i) An HPP driving gear that is not identified in paragraph (c)(2) of this AD; or

(ii) An HPP driving gear that does not create a cylinder head and HPP driving gear combination identified in paragraph (c)(1) of this AD.

(2) For the purpose of this AD, an HPP shaft, cylinder head, camshaft gear, and inlet/outlet camshaft bushing eligible for installation is:

(i) An HPP shaft, cylinder head, camshaft gear, and inlet/outlet camshaft bushing that meets the acceptable condition criteria in paragraph 7. Appendix II, Table 7, of Austro Engine MSB-E4-036/1; or

(ii) An HPP shaft, cylinder head, camshaft gear, and inlet/outlet camshaft bushing that is a new (zero hour) part.

(3) For the purpose of this AD, Engine Group 1 is Austro Engine E4 model engines in configuration “-A” installed on single engine airplanes.

(4) For the purpose of this AD, Engine Group 2 is Austro Engine E4 model engines in configuration “-B” or “-C” and Austro Engine E4P model engines installed on twin-engine airplanes.

(i) No Reporting Requirement

The reporting instructions specified in paragraph 7. Appendix II, Tables 6 and 7, of Austro Engine MSB-E4-036/1 are not required by this AD.

(j) Special Flight Permit

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 to permit a single ferry flight to a location where the actions required by this AD can be accomplished on a twin-engine airplane that has one or two Austro Engine E4 model engines in configuration “-B” or “-C”, or Austro Engine E4P model engines, installed.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7134; fax: (781) 238-7199; email: wego.wang@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0274-E, dated December 9, 2021, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0013.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Austro Engine Mandatory Service Bulletin No. MSB-E4-036/1, Revision No. 1, dated December 14, 2021.

(ii) [Reserved]

(3) For Austro Engine service information identified in this AD, contact Austro Engine GmbH, Rudolf-Diesel-Strasse 11, 2700 Weiner Neustadt, Austria; phone: +43 2622 23000; website: <https://www.austroengine.at>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 19, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-01818 Filed 1-26-22; 11:15 am]



2022-03-07 Stemme AG: Amendment 39-21924; Docket No. FAA-2021-1010; Project Identifier MCAI-2020-00807-G.

(a) Effective Date

This airworthiness directive (AD) is effective March 2, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Stemme AG TSA-M Model S6 and S6-RT gliders, all serial numbers, certificated in any category, with a propeller gearbox tooth belt marked “Synchroforce Carbon” installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 6100, Propeller System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a new version of the propeller gearbox tooth belt with a reduced life limit. The FAA is issuing this AD to prevent a propeller gearbox tooth belt remaining in service beyond its fatigue life. The unsafe condition, if not addressed, could result in failure of the propeller gearbox tooth belt and reduced control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Before the propeller gearbox tooth belt accumulates 5 years since installation on a glider or within 30 days after the effective date of this AD, whichever occurs later, and thereafter at intervals not to exceed 5 years, remove the propeller gearbox tooth belt from service and install a propeller gearbox tooth belt with zero hours time-in-service.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2020-0140, dated June 23, 2020, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1010.

(j) Material Incorporated by Reference

None.

Issued on January 20, 2022.

Lance T. Gant,
Director, Compliance & Airworthiness Division, Aircraft Certification Service.
[FR Doc. 2022-01479 Filed 1-25-22; 8:45 am]