

The FAA is considering discontinuing the physical printing and mailing of this AD Biweekly Report. All FAA documents are available for free at [drs.faa.gov](https://www.faa.gov/ats/ats.cfm) and the AD Biweekly Reports will be added in the next few months. If you would like to provide feedback on this change, please contact rgl@faa.gov.

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2022-10

4/25/2022 - 5/8/2022



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

Biweekly 2022-01

2021-05-03		Airbus Helicopters	EC225LP
2021-23-01		Stemme AG	Stemme S 12
2021-23-06		Various Manufactures	234; CH-47D
2021-24-18		Viking Air Limited	DHC-3
2021-24-19		Flugzeugbau GmbH	DG-500MB and DG-1000M
2021-24-21		Embraer S.A.	EMB-500 and EMB-505
2021-24-22	R 2012-06-16	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-25-01		Leonardo S.p.a.	A109S and AW109SP
2021-25-08		Leonardo S.p.a.	AW189
2021-25-10		Daher Aerospace	TBM 700
2021-25-11	R 78-02-03	Piper Aircraft, Inc.	PA-23-250
2021-26-07	R 2020-11-05	Airbus Helicopters	EC120B
2021-26-08		Bell Textron Canada Limited	206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4
2022-01-05	R 2021-24-06	Airbus Helicopters	EC130T2

Biweekly 2022-02

2021-26-14	R 2018-11-01	Airbus Helicopters	AS332L2, EC225LP
2021-26-15		Vulcanair S.p.A.	P.68C, P.68C-TC, P.68 "OBSERVER," P.68 OBSERVER 2, P.68R, and P.68TC OBSERVER
2021-26-18	R 2020-21-01	Airbus Helicopters	AS-365N2, AS 365 N3, and SA-365N1; SA-365C1, SA-365C2, and SA-365N; EC 155B and EC155B1
2022-01-06		Cameron Balloons Ltd.	flange adapter
2022-01-09		Stemme AG	Stemme S 10-VT and Stemme S 12
2022-02-01		Sikorsky Aircraft Corporation	S-92A
2022-02-02	R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212

Biweekly 2022-03

2021-26-12		Stemme AG	Stemme S 12
2021-26-16		Various Restricted Category Helicopters	UH-1H
2021-26-21		Pilatus Aircraft Ltd.	PC-24
2021-26-24		Leonardo S.p.a.	A109A and A109A II
2021-26-25		Schempp-Hirth Flugzeugbau GmbH	Duo Discus; Duo Discus T
2021-26-26	R 2005-12-08	Safran Helicopter Engines, S.A.	Arrius 2B1, Arrius 2B1A, and Arrius 2B2
2021-26-29		Leonardo S.p.a.	AW169
2022-02-17		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-03-03	R 2021-22-20	Austro Engine GmbH	E4 and E4P
2022-03-07		Stemme AG	S6 and S6-RT

Biweekly 2022-04

2022-01-01		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; SA-365C1, SA-365C2, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2022-01-03		Umlaut Engineering GmbH	hand-held P3HAFEX fire extinguisher
2022-02-02	COR R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212
2022-02-04		Airbus Helicopters	AS350B, AS350B2, AS350B3, and AS350BA
2022-02-06		Airbus Helicopters	EC120B
2022-02-08		Leonardo S.p.a.	AB412 and AB412 EP
2022-02-12		Leonardo S.p.a.	AB139 and AW139
2022-02-13		Airbus Helicopters	EC120B
2022-02-19		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2022-02-20		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-03-01		Diamond Aircraft Industries GmbH	DA 42 NG; DA 42, and DA 42 M-NG

2022-03-04	R 80-13-10 R 80-13-12 R1 R 2008-03-01	Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-03-08		Fiberglas-Technik Rudolf Lindner GmbH & Co. KG	G102 ASTIR CS; G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, G103 C TWIN III ACRO, and G103 C TWIN III SL
2022-03-09 2022-03-23	A 2020-08-02	Sikorsky Aircraft Corporation Textron Aviation Inc.	S-76D 300, 300LW, B300, and B300C
Biweekly 2022-05			
2022-03-13 2022-03-15 2022-03-17 2022-03-18	R 2014-21-03	Airbus Helicopters Various Airplanes Airbus Helicopters British Aerospace (Operations) Limited and British Aerospace Regional Aircraft	AS332L2 Garmin G3X Touch Electronic Flight Instrument System AS332L2 and EC225LP Jetstream Series 200, Jetstream Model 3101, and Jetstream Model 3201
2022-04-01		DG Flugzeugbau GmbH and Schempp-Hirth Flugzeugbau GmbH	DG-1000T and Duo Discus T
2022-04-04		Continental Aerospace Technologies, Inc. and Continental Motors	C-125-1, C-125-2, C145-2, C145-2H, IO-360-C, IO-360-D, IO-360-DB, IO-360-H, IO-360-HB, IO-360-K, IO-360-KB, IO-470-E, IO-470-S, IO-550-B, IO-550-G, O-300-B, O-300-C, O-300-D, O-300-E, O-470-A, O-470-B, O-470-G, O-470-J, O-470-K, O-470-L, O-470-M, O-470-N, O-470-R, O-470-S, O-470-U, O-470-11, O-470-15, TSIO-360-E, TSIO-360-EB, TSIO-360-F, TSIO-360-FB, TSIO-360-GB, TSIO-360-LB, TSIO-360-MB, TSIO-360-SB, TSIO-520-C, TSIO-520-CE, TSIO-520-E, and TSIO-520-UB
2022-05-01 2022-05-02	R 2021-11-25	Learjet, Inc. Airbus Helicopters	35, 35A (C-21A), 36, 36A, 55, 55B, 55C, and 60 AS350B3 and EC130T2
Biweekly 2022-06			
2022-04-06 2022-04-09 2022-05-05	R 2021-06-06	Bell Textron Canada Limited AVOX Systems Inc. Schempp-Hirth Flugzeugbau GmbH	505 oxygen cylinder Ventus-2a and Ventus-2b
2022-05-11 2022-05-12 2022-05-14	R 2020-12-08	Viking Air Limited Embraer S.A. GROB Aircraft SE	DHC-3 EMB-505 G 115EG
Biweekly 2022-07			
2021-03-16R1	R 2021-03-16	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2022-05-10		Goodrich Externally-Mounted Hoist Assemblies	hoist assembly
2022-05-13 2022-06-01		Honda Aircraft Company LLC Airbus Helicopters Deutschland GmbH	HA-420 MBB-BK 117 D-3
2022-06-03 2022-06-05	R 2022-02-02 R 2021-15-52	Bell Textron Inc. Various Restricted Category Helicopters	204B, 205A, 205A-1, 205B, 210, and 212 Various Models
2022-06-13		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-06-20 2022-07-03 2022-07-05	R 2020-20-06 R 2022-05-09	Bell Textron Canada Limited Bell Textron Inc. MARS A.S.	429 412, 412EP, and 412CF ATL-88/90-1B
Biweekly 2022-08			
2022-06-04		Schempp-Hirth Flugzeugbau GmbH	Janus, Mini-Nimbus HS-7, Nimbus-2, and Standard Cirrus
2022-06-08	R 2017-18-10	Diamond Aircraft Industries GmbH	DA 42, DA 42 M-NG, and DA 42 NG
2022-06-12 2022-06-17 2022-06-19 2022-07-01 2022-07-02	R 2020-23-07	Airbus Helicopters Airbus Helicopters Leonardo S.p.a. Leonardo S.p.a. Bell Textron Inc.	SA330J EC130T2 AW109SP AB139 and AW139 205A and 205A-1; 205B; 210; 212i; 412 and 412EP; 412CF

2022-07-04		Pilatus Aircraft Ltd.	PC-12/47E
2022-07-09		Airbus Helicopters	AS332L2 and EC225LP
2022-07-11	R 2021-17-18	Leonardo S.p.a.	A109C, A109K2, A109E, A109S, and AW109SP
2022-07-12	R 2021-02-20	Hélicoptères Guimbal	Cabri G2
2022-07-14		Viking Air Limited	DHC-6-400

Biweekly 2022-09

2022-08-01	R 2020-22-01	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2022-08-02		Airbus Helicopters	EC 155B and EC155B1
2022-08-03		Textron Aviation Inc.	120 and 140; 140A
2022-08-10	R 2020-12-07	Hamilton Sundstrand Corporation	54H
2022-08-11		Bell Textron Canada Limited	429
2022-08-13		Pratt & Whitney Canada Corp.	PT6A-34, -34B, -34AG, -114, and -114A
2022-08-15		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2

Biweekly 2022-10

2022-09-04	R 2021-05-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2022-09-07	R 2019-11-05 A 2020-17-10	Bell Textron Canada Limited	429
2022-09-13		Piper Aircraft, Inc.	PA-34-200
2022-09-17		Scheibe-Aircraft-GmbH	SF 25 C
2022-10-51	E	Airbus Helicopters; Airbus Helicopters Deutschland GmbH	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3



2022-09-04 Airbus Helicopters: Amendment 39-22024; Docket No. FAA-2022-0102; Project Identifier MCAI-2021-00841-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 31, 2022.

(b) Affected ADs

This AD replaces AD 2021-05-05, Amendment 39-21448 (86 FR 13972, March 12, 2021) (AD 2021-05-05).

(c) Applicability

This AD applies to Airbus Helicopters Model SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1 helicopters, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 6500, Tail Rotor Drive System.

(e) Unsafe Condition

This AD was prompted by a report where during a landing phase, a helicopter lost tail rotor pitch control, which was caused by significant damage to the tail rotor gearbox (TGB) control rod double bearing (bearing). This AD was also prompted by the determination that reduced inspection intervals, updated corrective actions, and increased compliance time for replacement of affected parts are necessary to address the unsafe condition. The FAA is issuing this AD to prevent damage to the bearing, which if not addressed, could result in loss of yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For Model SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters: Except as specified in paragraph (h) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0171, dated July 19, 2021 (EASA AD 2021-0171).

(2) For Model SA-366G1 helicopters: Before further flight after the effective date of this AD, accomplish the actions (e.g., modify the helicopter by replacing the TGB control shaft guide bushes, do repetitive inspections of the TGB magnetic plug and applicable corrective actions; do repetitive

replacements of a certain bearing; and modify the helicopter by replacing the TGB) specified in paragraph (g)(1) of this AD using a method approved by the FAA.

(h) Exceptions to EASA AD 2021-0171

(1) Where EASA AD 2021-0171 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2021-0171 refers to flight hours (FH), this AD requires using hours time-in-service.

(3) Where EASA AD 2021-0171 requires action after the last flight of the day or “ALF,” this AD requires those actions before the first flight of the day.

(4) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0171.

(5) Where paragraph (2) of EASA AD 2021-0171 requires inspections (checks) to be done “in accordance with the instructions of Paragraph 3.B.1 of the applicable inspection ASB,” for this AD, those instructions are for reference only and are not required for the actions in paragraph (2) of EASA AD 2021-0171. The inspections (checks) required by paragraph (2) of EASA AD 2021-0171 may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9 (a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417 or 135.439.

(6) Where paragraph (5) of EASA AD 2021-0171 specifies “if any discrepancy is detected, as defined in the applicable inspection ASB, before next flight, accomplish the applicable corrective action(s) in accordance with the instructions of Paragraph 3.B.1 of the applicable inspection ASB,” for this AD, a qualified mechanic must add oil to the TGB to the “max” level if the oil level is not at maximum. The instructions are for reference only and are not required for the actions in paragraph (5) of EASA AD 2021-0171.

(7) Where paragraph (6) of EASA AD 2021-0171 refers to “any discrepancy,” for this AD, discrepancies include the presence of particles and other conditions such as abrasions, scales, flakes, and splinters.

(8) Where the service information referred to in EASA AD 2021-0171 specifies to perform a metallurgical analysis and contact the manufacturer if collected particles are not clearly characterized, this AD does not require contacting the manufacturer to determine the characterization of the particles collected.

(9) Although service information referenced in EASA AD 2021-0171 specifies to scrap parts, this AD does not include that requirement.

(10) Although service information referenced in EASA AD 2021-0171 specifies reporting information to Airbus Helicopters, filling in a “particle detection” follow-up sheet, and returning a “bearing monitoring sheet” to Airbus Helicopters, this AD does not include those requirements.

(11) Although service information referenced in EASA AD 2021-0171 specifies returning certain parts to an approved workshop and returning certain parts to Airbus Helicopters, this AD does not include those requirements.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0171 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 provided that there are no passengers onboard.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0171, dated July 19, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0171, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0102.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 14, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-08803 Filed 4-25-22; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2022-09-07 Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited): Amendment 39-22027; Docket No. FAA-2022-0145; Project Identifier MCAI-2021-00522-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 31, 2022.

(b) Affected ADs

(1) This AD replaces AD 2019-11-05, Amendment 39-19651 (84 FR 26546, June 7, 2019) (AD 2019-11-05).

(2) This AD affects AD 2020-17-10, Amendment 39-21215 (85 FR 49941, August 17, 2020) (AD 2020-17-10).

(c) Applicability

This AD applies to Bell Textron Canada Limited (type certificate previously held by Bell Helicopter Textron Canada Limited) Model 429 helicopters, certificated in any category, serial numbers 57001 through 57401 inclusive.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6720, Tail Rotor Control System.

(e) Unsafe Condition

This AD was prompted by a report of a worn pitch link. The FAA is issuing this AD to address a worn pitch link, which if not corrected, could result in pitch link failure and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Requirements

(1) For pitch link assembly part number (P/N) 429-012-112-101, 429-012-112-103, 429-012-112-101FM, and 429-012-112-103FM: Within 50 hours time-in-service (TIS) after July 12, 2019 (the effective date of AD 2019-11-05) and thereafter at intervals not to exceed 50 hours TIS:

(i) Perform a dimensional inspection of each inboard and outboard pitch link assembly for axial and radial bearing play. With a 10X or higher power magnifying glass, inspect the bearing liner for a crack, deterioration of the liner, and extrusion of the liner from the plane. If there is axial or radial

play that exceeds allowable limits, or if there is a crack, deterioration of the liner, or extrusion of the liner, before further flight, replace the bearing.

(ii) Inspect the pitch link assembly sealant for pin holes and voids and to determine if the sealant thickness is 0.025 inch (0.64 mm) or less, extends over the roll staked lip by 0.030 inch (0.76 mm) or more, and is clear of the bearing ball. If there is a pin hole or void, or if the sealant exceeds 0.026 inch (0.66 mm), does not extend over the roll staked lip by 0.030 inch (0.76 mm) or more, or is not clear of the bearing ball, before further flight, replace the bearing.

(2) For pitch link assembly P/N 429-012-112-101, 429-012-112-103, 429-012-112-101FM, and 429-012-112-103FM, within 200 hours TIS following the initial inspection required by paragraph (g)(1) of this AD, or if the hours TIS of a pitch link assembly exceed 250 hours TIS or are unknown, at the next 50-hour-TIS inspection required by paragraph (g)(1) of this AD:

(i) Replace each bearing P/N 429-312-107-103 with a date of manufacture before January 13, 2015, with a bearing P/N 429-312-107-103 that was manufactured on or after January 13, 2015.

(ii) Using a white permanent fine point marker or equivalent, re-identify the pitch link assembly:

(A) Re-identify P/N 429-012-112-101 and 429-012-112-101FM as 429-012-112-111FM.

(B) Re-identify P/N 429-012-112-103 and 429-012-112-103FM as 429-012-112-113FM.

(iii) Apply a coating of DEVCON 2-TON (C-298) or equivalent over the new P/N.

(h) New Requirements

For pitch link assemblies other than P/N 429-012-112-101, 429-012-112-103, 429-012-112-101FM, and 429-012-112-103FM: Within 50 hours TIS after the effective date of this AD and thereafter at intervals not to exceed 50 hours TIS:

(1) Perform a dimensional inspection of each inboard and outboard pitch link assembly for axial and radial bearing play. With a 10x or higher power magnifying glass, inspect the bearing liner for a crack, deterioration of the liner, and extrusion of the liner from the plane. If there is axial or radial play that exceeds allowable limits, or if there is a crack, deterioration of the liner, or extrusion of the liner, before further flight, replace the bearing.

(2) Inspect the pitch link assembly sealant for pin holes and voids and to determine if the sealant thickness is 0.025 inch (0.64 mm) or less, extends over the roll staked lip by 0.030 inch (0.76 mm) or more, and is clear of the bearing ball. If there is a pin hole or void, or if the sealant exceeds 0.026 inch (0.66 mm), does not extend over the roll staked lip by 0.030 inch (0.76 mm) or more, or is not clear of the bearing ball, before further flight, replace the bearing.

(i) Terminating Action for Certain Actions in AD 2020-17-10

Accomplishing the initial inspection required by paragraph (g)(1) or (h) of this AD constitutes terminating action for the inspections required by paragraph (f)(2) of AD 2020-17-10 for that pitch link assembly only.

(j) Optional Terminating Action

The repetitive inspections required by paragraph (h) of this AD are no longer required for helicopters that incorporate pitch link assemblies, P/N 429-012-212-105 or 429-012-212-107, in accordance with Part III of the Accomplishment Instructions of Bell Alert Service Bulletin No. 429-15-16, Revision C, dated October 16, 2020.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as

appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; phone: (202) 267-9167; email: hal.jensen@faa.gov.

(2) The subject of this AD is addressed in Transport Canada Civil Aviation AD CF-2015-16R3, dated April 30, 2021. You may view the Transport Canada AD at <https://www.regulations.gov> in Docket No. FAA-2022-0145.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Alert Service Bulletin No. 429-15-16, Revision C, dated October 16, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; phone: 1-450-437-2862 or 1-800-363-8023; fax: 1-450-433-0272; email: productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 15, 2022.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-08797 Filed 4-25-22; 8:45 am]



2022-09-13 Piper Aircraft, Inc.: Amendment 39-22033; Docket No. FAA-2022-0022; Project Identifier AD-2020-01264-A.

(a) Effective Date

This airworthiness directive (AD) is effective May 31, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Piper Aircraft, Inc. Model PA-34-200 airplanes, serial numbers 34-7250001 through 34-7450220, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3220, Nose/Tail Landing Gear.

(e) Unsafe Condition

This AD was prompted by the determination that the life limit for alternate bolts that attach the drag link to the nose gear were not included as airworthiness limitations. The FAA is issuing this AD to establish a life limit on bolt part numbers 693-215 and NAS6207-50D that attach the drag link to the nose gear trunnion. The unsafe condition, if not addressed, could result in failure of the nose landing gear and lead to loss of airplane control during take-off, landing, or taxi operations.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions

(1) Within 90 days after the effective date of this AD, incorporate into the maintenance records required by 14 CFR 91.417(a)(2) or 135.439(a)(2) for your airplane a life limit of 500 hours for bolt part numbers 693-215 and NAS6207-50D.

Note to paragraph (g)(1): Piper Seneca Service Manual, Airworthiness Limitations, 753-817, page 1-1, dated November 30, 2019, contains the life limit in paragraph (g)(1) of this AD.

(2) Thereafter, except as provided in paragraph (h)(1) of this AD, no alternative replacement times may be approved for these bolts.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Fred Caplan, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5507; email: frederick.n.caplan@faa.gov.

(2) For service information identified in this AD that is not incorporated by reference, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL 32960; phone: (772) 299-2141; website: <https://www.piper.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(j) Material Incorporated by Reference

None.

Issued on April 21, 2022.

Gaetano A. Sciortino,
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-08852 Filed 4-25-22; 8:45 am]



2022-09-17 Scheibe-Aircraft-GmbH: Amendment 39-22037; Docket No. FAA-2022-0506; Project Identifier MCAI-2022-00507-G.

(a) Effective Date

This airworthiness directive (AD) is effective May 23, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Scheibe-Aircraft-GmbH Model SF 25 C gliders, certificated in any category, that have Scheibe Modification 653E.41-S10 or 653C-41-S10.1 installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 2700, Flight Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as severe corrosion on the inner surface of the control stick tube. The FAA is issuing this AD to detect corrosion on the left-hand (LH) and right-hand (RH) control sticks, which, if not corrected, could lead to failure of the control stick tube and loss of control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Replacement

(1) Before further flight after the effective date of this AD and thereafter at intervals not to exceed 12 months or 100 hours time-in-service, whichever occurs first, inspect all control sticks (other than part number (P/N) 20093, P/N 20093/G, P/N 20094, and P/N 20094/G) for corrosion by following Action 1, step 1.4, in Scheibe Aircraft GmbH Service Bulletin 653-96/1, dated April 4, 2022 (SB 653-96/1), except you may use a borescope instead of an endoscope. If there is any corrosion, before further flight, replace the affected control stick with a LH control stick P/N 20093 or P/N 20093/G; or a RH control stick P/N 20094 or P/N 20094/G by following Action 3 (all steps) in SB 653-96/1.

(2) Replacing a control stick with LH control stick P/N 20093 or P/N 20093/G; or RH control stick P/N 20094 or P/N 20094/G, terminates the repetitive inspection for that control stick side only. Replacing both control sticks with LH control stick P/N 20093 or P/N 20093/G and RH control stick P/N 20094 or P/N 20094/G terminates the repetitive inspection for both sides.

(3) As of the effective date of this AD, do not install on any glider a control stick that has a P/N other than LH control stick P/N 20093 or P/N 20093/G; or RH control stick P/N 20094 or P/N 20094/G.

(h) Credit for Previous Actions

You may take credit for the action required by paragraph (g)(1) of this AD if you performed those actions before the effective date of this AD using Scheibe Aircraft GmbH Service Bulletin 653-96, dated March 2, 2022.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) Emergency AD 2022-0066-E, dated April 11, 2022, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2022-0506.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Scheibe Aircraft GmbH Service Bulletin 653-96/1, dated April 4, 2022.

Note 1 to paragraph (k)(2)(i): Page 4 of this service information is identified as 653-95.

Note 2 to paragraph (k)(2)(i): This service information contains German to English translation. EASA used the English translation in referencing the document from Scheibe Aircraft GmbH. For enforceability purposes, the FAA will cite the service information in English as it appears on the document.

(ii) [Reserved]

(3) For service information identified in this AD, contact Scheibe Aircraft GmbH, Am Flugplatz 5, Heubach, D-73540, Germany; phone: +49 07173 184286; email: info@scheibe-aircraft.de; website: <https://scheibe-aircraft.de/>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 22, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-09890 Filed 5-4-22; 4:15 pm]



DATE: May 3, 2022

AD #: 2022-10-51

Emergency Airworthiness Directive (AD) 2022-10-51 is sent to owners and operators of the following:

Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters.

Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters.

Background

This emergency AD was prompted by a supplier report of a non-conformity occurring during production. This emergency AD requires removing certain part-numbered and serial-numbered flight control Flexball cables from service and prohibits installing those flight control Flexball cables on any helicopter. This emergency AD also requires reporting certain information to Airbus Helicopters or AHD, as applicable. This condition, if not addressed, could result in increased friction inside the flight control Flexball cables, jamming of the flight controls, and subsequent loss of control of the helicopter.

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Emergency AD 2022-0077-E, dated April 29, 2022 (EASA AD 2022-0077-E), to correct an unsafe condition for Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale, Model AS 350 B, AS 350 B1, AS 350 B2, AS 350 B3, AS 350 BA, AS 350 BB, AS 350 D, AS 355 E, AS 355 F, AS 355 F1, AS 355 F2, AS 355 N, AS 355 NP, EC 130 B4, and EC 130 T2 helicopters, all serial numbers (S/Ns); and Airbus Helicopters Deutschland GmbH (AHD), formerly Eurocopter Deutschland GmbH, Eurocopter España S.A., Model EC 135 T1, EC 135 T2, EC 135 T2+, EC 135 T3, EC 135 P1, EC 135 P2, EC 135 P2+, EC 135 P3, EC 635 T1, EC 635 T2+, EC 635 T3, EC 635 P2+, EC 635 P3, MBB-BK 117 D-2, MBB-BK 117 D-3, MBB-BK 117 D-3m, and MBB-BK 117 C-2 helicopters, all S/Ns. EASA advises of reported occurrences of flight control Flexball cables which were not in compliance with the approved design. Airbus Helicopters, AHD, and the part supplier identified a batch of affected parts.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its emergency AD. The FAA is issuing this emergency AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type designs.

Related Service Information

EASA AD 2022-0077-E requires replacing affected flight control Flexball cables with a serviceable part and prohibits installing an affected flight control Flexball cable on any helicopter.

The FAA reviewed Airbus Helicopters Emergency Alert Service Bulletin (EASB) AS350 67.00.81, AS355 67.00.49, and EC130 67A023, which are co-published as one document along with AS550 67.00.45 (military) and AS555 67.00.34 (military), EASB EC135-67A-043, EASB EC135H-67A-016, EASB MBB-BK117 C-2-67A-032, and EASB MBB-BK117 D-2-67A-021, each Revision 0 and dated April 29, 2022. This service information specifies procedures for determining if an affected Flexball is installed. If an affected Flexball is installed, or if it cannot be determined if an affected Flexball is installed, this service information specifies procedures for replacing the Flexball, returning the removed Flexball to the supplier, and completing and emailing a reply form sheet to Airbus Helicopters Customer Support or Airbus Helicopters Service Bulletin Germany, depending on your model helicopter.

Emergency AD Requirements

This emergency AD requires accomplishing the actions specified in EASA AD 2022-0077-E, described previously, which is incorporated by reference (IBRed), except for any differences identified as exceptions in the regulatory text of this emergency AD and except as discussed under “Differences Between this Emergency AD and the EASA AD.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2022-0077-E is IBRed in this FAA emergency AD. This emergency AD, therefore, requires compliance with EASA AD 2022-0077-E in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this emergency AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022-0077-E does not mean that operators need comply only with that section. For example, where the emergency AD requirement refers to “all required actions and compliance times,” compliance with this emergency AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2022-0077-E.

Differences Between This Emergency AD and the EASA AD

EASA AD 2022-0077-E applies to Airbus Helicopters Model AS 350 BB helicopters and Airbus Helicopters Deutschland GmbH (AHD) Model EC 635 T1, EC 635 T2+, EC 635 T3, EC 635 P2+, EC 635 P3, and MBB-BK 117 D-3m helicopters. This emergency AD does not apply to those model helicopters because those models are not FAA type-certificated and are not included on the U.S. type certificate data sheet (TCDS), except where the TCDS explains that the Model EC635T2+ helicopter having serial number 0858 was converted from Model EC635T2+ to Model EC135T2+. The service information referenced in EASA AD 2022-0077-E specifies sending removed Flexball cables to the supplier; whereas, this emergency AD requires removing an affected part from service. EASA AD 2022-0077-E specifies that a single ferry flight without passengers is allowed to a maintenance location where the action required by the AD can be accomplished; whereas this emergency AD may allow a special flight permit or continuous authorization flight for a single flight, provided that there are no passengers onboard and that there is no noticeable increase in friction in

the flight control system. EASA AD 2022-0077-E does not require reporting information; whereas, this emergency AD does.

Costs of Compliance

The FAA estimates that this emergency AD affects up to 1,785 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this emergency AD.

Replacing a flight control Flexball cable takes about 8 work-hours and parts cost about \$804 to \$13,555, depending on part number, for an estimated cost of \$1,484 to \$14,235 per helicopter and up to \$437,780 to \$4,199,325 for the U.S. fleet (there are up to 295 affected flight control Flexball cables installed in the U.S. fleet). Reporting information takes about 0.5 work-hour for an estimated cost of \$43 per helicopter and up to \$76,755 for the U.S. fleet.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 0.5 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Presentation of the Actual AD

The FAA is issuing this AD under 49 U.S.C. Section 44701 according to the authority delegated to me by the Administrator.

2022-10-51 Airbus Helicopters and Airbus Helicopters Deutschland GmbH (AHD): Project Identifier MCAI-2022-00589-R.

(a) Effective Date

This emergency AD is effective upon receipt.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the helicopters identified in paragraphs (c)(1) and (2) of this AD, certificated in any category.

(1) Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters.

Note 1 to paragraph (c)(1): Helicopters with an AS350B3e designation are Model AS350B3 helicopters.

(2) Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters.

Note 2 to paragraph (c)(2): Helicopters with an EC135P3H designation are Model EC135P3 helicopters. Helicopters with an EC135T3H designation are Model EC135T3 helicopters. Helicopters with an MBB-BK117 C-2e designation are Model MBB-BK117 C-2 helicopters.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2700, Flight Control System.

(e) Unsafe Condition

This AD was prompted by a supplier report of a non-conformity occurring during production. The FAA is issuing this AD to address non-conforming flight control Flexball cables. The unsafe condition, if not addressed, could result in increased friction inside the flight control Flexball cables, jamming of the flight controls, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) Emergency AD 2022-0077-E, dated April 29, 2022 (EASA AD 2022-0077-E).

(h) Exceptions to EASA AD 2022-0077-E

(1) Where EASA AD 2022-0077-E refers to its effective date, this AD requires using the

effective date of this AD.

(2) Where the service information referenced in EASA AD 2022-0077-E specifies returning a part to the supplier, this AD requires removing an affected part from service.

(3) The note to paragraph (1) of EASA AD 2022-0077-E does not apply to this AD; instead, see the provisions in paragraph (j) of this AD.

(4) This AD does not mandate compliance with the “Remarks” section of EASA AD 2022-0077-E.

(i) Reporting Requirement

Within 10 days after accomplishing the actions required by paragraph (g) of this AD, report the information requested in Appendix 1 to this emergency AD to the email address identified in paragraph (i)(1) or (2) of this AD, depending on your helicopter model.

(1) For Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters: customersupport.helicopters@airbus.com.

(2) For Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters: support.technical-bulletins.ahd@airbus.com.

(j) Special Flight Permit

A special flight permit or continuous authorization flight for a single flight may be issued, provided that there are no passengers onboard and that there is no noticeable increase in friction in the flight control system.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

(2) For EASA AD 2022-0077-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(3) For Airbus Helicopters service information identified in this emergency AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

Appendix 1 to Emergency Airworthiness Directive 2022-10-51

Conformity of the Flexballs (sample format)

Provide the following information by email as follows:

For Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters:
customersupport.helicopters@airbus.com.

For Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters:
support.technical-bulletins.ahd@airbus.com.

Helicopter Model and Serial Number:	
Flexball Part Number:	
Flexball Serial Number:	

Issued on May 3, 2022.

Ross Landes, Deputy Director for Regulatory Operations,
Compliance & Airworthiness Division,
Aircraft Certification Service.