

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,  
BALLOONS, & AIRSHIPS**

**BIWEEKLY 2022-12**

*5/23/2022 - 6/5/2022*



Federal Aviation Administration  
Continued Operational Safety Policy Section, AIR-141  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

**Biweekly 2022-01**

2021-05-03		Airbus Helicopters	EC225LP
2021-23-01		Stemme AG	Stemme S 12
2021-23-06		Various Manufactures	234; CH-47D
2021-24-18		Viking Air Limited	DHC-3
2021-24-19		Flugzeugbau GmbH	DG-500MB and DG-1000M
2021-24-21		Embraer S.A.	EMB-500 and EMB-505
2021-24-22	R 2012-06-16	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-25-01		Leonardo S.p.a.	A109S and AW109SP
2021-25-08		Leonardo S.p.a.	AW189
2021-25-10		Daher Aerospace	TBM 700
2021-25-11	R 78-02-03	Piper Aircraft, Inc.	PA-23-250
2021-26-07	R 2020-11-05	Airbus Helicopters	EC120B
2021-26-08		Bell Textron Canada Limited	206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4
2022-01-05	R 2021-24-06	Airbus Helicopters	EC130T2

**Biweekly 2022-02**

2021-26-14	R 2018-11-01	Airbus Helicopters	AS332L2, EC225LP
2021-26-15		Vulcanair S.p.A.	P.68C, P.68C-TC, P.68 "OBSERVER," P.68 OBSERVER 2, P.68R, and P.68TC OBSERVER
2021-26-18	R 2020-21-01	Airbus Helicopters	AS-365N2, AS 365 N3, and SA-365N1; SA-365C1, SA-365C2, and SA-365N; EC 155B and EC155B1
2022-01-06		Cameron Balloons Ltd.	flange adapter
2022-01-09		Stemme AG	Stemme S 10-VT and Stemme S 12
2022-02-01		Sikorsky Aircraft Corporation	S-92A
2022-02-02	R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212

**Biweekly 2022-03**

2021-26-12		Stemme AG	Stemme S 12
2021-26-16		Various Restricted Category Helicopters	UH-1H
2021-26-21		Pilatus Aircraft Ltd.	PC-24
2021-26-24		Leonardo S.p.a.	A109A and A109A II
2021-26-25		Schempp-Hirth Flugzeugbau GmbH	Duo Discus; Duo Discus T
2021-26-26	R 2005-12-08	Safran Helicopter Engines, S.A.	Arrius 2B1, Arrius 2B1A, and Arrius 2B2
2021-26-29		Leonardo S.p.a.	AW169
2022-02-17		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-03-03	R 2021-22-20	Austro Engine GmbH	E4 and E4P
2022-03-07		Stemme AG	S6 and S6-RT

**Biweekly 2022-04**

2022-01-01		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; SA-365C1, SA-365C2, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2022-01-03		Umlaut Engineering GmbH	hand-held P3HAFEX fire extinguisher
2022-02-02	COR R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212
2022-02-04		Airbus Helicopters	AS350B, AS350B2, AS350B3, and AS350BA
2022-02-06		Airbus Helicopters	EC120B
2022-02-08		Leonardo S.p.a.	AB412 and AB412 EP
2022-02-12		Leonardo S.p.a.	AB139 and AW139
2022-02-13		Airbus Helicopters	EC120B
2022-02-19		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2022-02-20		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-03-01		Diamond Aircraft Industries GmbH	DA 42 NG; DA 42, and DA 42 M-NG

2022-03-04	R 80-13-10 R 80-13-12 R1 R 2008-03-01	Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-03-08		Fiberglas-Technik Rudolf Lindner GmbH & Co. KG	G102 ASTIR CS; G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, G103 C TWIN III ACRO, and G103 C TWIN III SL
2022-03-09 2022-03-23	A 2020-08-02	Sikorsky Aircraft Corporation Textron Aviation Inc.	S-76D 300, 300LW, B300, and B300C
<b>Biweekly 2022-05</b>			
2022-03-13 2022-03-15 2022-03-17 2022-03-18	R 2014-21-03	Airbus Helicopters Various Airplanes Airbus Helicopters British Aerospace (Operations) Limited and British Aerospace Regional Aircraft	AS332L2 Garmin G3X Touch Electronic Flight Instrument System AS332L2 and EC225LP Jetstream Series 200, Jetstream Model 3101, and Jetstream Model 3201
2022-04-01		DG Flugzeugbau GmbH and Schempp-Hirth Flugzeugbau GmbH	DG-1000T and Duo Discus T
2022-04-04		Continental Aerospace Technologies, Inc. and Continental Motors	C-125-1, C-125-2, C145-2, C145-2H, IO-360-C, IO-360-D, IO-360-DB, IO-360-H, IO-360-HB, IO-360-K, IO-360-KB, IO-470-E, IO-470-S, IO-550-B, IO-550-G, O-300-B, O-300-C, O-300-D, O-300-E, O-470-A, O-470-B, O-470-G, O-470-J, O-470-K, O-470-L, O-470-M, O-470-N, O-470-R, O-470-S, O-470-U, O-470-11, O-470-15, TSIO-360-E, TSIO-360-EB, TSIO-360-F, TSIO-360-FB, TSIO-360-GB, TSIO-360-LB, TSIO-360-MB, TSIO-360-SB, TSIO-520-C, TSIO-520-CE, TSIO-520-E, and TSIO-520-UB
2022-05-01 2022-05-02	R 2021-11-25	Learjet, Inc. Airbus Helicopters	35, 35A (C-21A), 36, 36A, 55, 55B, 55C, and 60 AS350B3 and EC130T2
<b>Biweekly 2022-06</b>			
2022-04-06 2022-04-09 2022-05-05	R 2021-06-06	Bell Textron Canada Limited AVOX Systems Inc. Schempp-Hirth Flugzeugbau GmbH	505 oxygen cylinder Ventus-2a and Ventus-2b
2022-05-11 2022-05-12 2022-05-14	R 2020-12-08	Viking Air Limited Embraer S.A. GROB Aircraft SE	DHC-3 EMB-505 G 115EG
<b>Biweekly 2022-07</b>			
2021-03-16R1	R 2021-03-16	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2022-05-10		Goodrich Externally-Mounted Hoist Assemblies	hoist assembly
2022-05-13 2022-06-01		Honda Aircraft Company LLC Airbus Helicopters Deutschland GmbH	HA-420 MBB-BK 117 D-3
2022-06-03 2022-06-05	R 2022-02-02 R 2021-15-52	Bell Textron Inc. Various Restricted Category Helicopters	204B, 205A, 205A-1, 205B, 210, and 212 Various Models
2022-06-13		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-06-20 2022-07-03 2022-07-05	R 2020-20-06 R 2022-05-09	Bell Textron Canada Limited Bell Textron Inc. MARS A.S.	429 412, 412EP, and 412CF ATL-88/90-1B
<b>Biweekly 2022-08</b>			
2022-06-04		Schempp-Hirth Flugzeugbau GmbH	Janus, Mini-Nimbus HS-7, Nimbus-2, and Standard Cirrus
2022-06-08	R 2017-18-10	Diamond Aircraft Industries GmbH	DA 42, DA 42 M-NG, and DA 42 NG
2022-06-12 2022-06-17 2022-06-19 2022-07-01 2022-07-02	R 2020-23-07	Airbus Helicopters Airbus Helicopters Leonardo S.p.a. Leonardo S.p.a. Bell Textron Inc.	SA330J EC130T2 AW109SP AB139 and AW139 205A and 205A-1; 205B; 210; 212i; 412 and 412EP; 412CF

2022-07-04		Pilatus Aircraft Ltd.	PC-12/47E
2022-07-09		Airbus Helicopters	AS332L2 and EC225LP
2022-07-11	R 2021-17-18	Leonardo S.p.a.	A109C, A109K2, A109E, A109S, and AW109SP
2022-07-12	R 2021-02-20	Hélicoptères Guimbal	Cabri G2
2022-07-14		Viking Air Limited	DHC-6-400
<b>Biweekly 2022-09</b>			
2022-08-01	R 2020-22-01	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2022-08-02		Airbus Helicopters	EC 155B and EC155B1
2022-08-03		Textron Aviation Inc.	120 and 140; 140A
2022-08-10	R 2020-12-07	Hamilton Sundstrand Corporation	54H
2022-08-11		Bell Textron Canada Limited	429
2022-08-13		Pratt & Whitney Canada Corp.	PT6A-34, -34B, -34AG, -114, and -114A
2022-08-15		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2
<b>Biweekly 2022-10</b>			
2022-09-04	R 2021-05-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2022-09-07	R 2019-11-05 A 2020-17-10	Bell Textron Canada Limited	429
2022-09-13		Piper Aircraft, Inc.	PA-34-200
2022-09-17		Scheibe-Aircraft-GmbH	SF 25 C
2022-10-51	E	Airbus Helicopters; Airbus Helicopters Deutschland GmbH	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
<b>Biweekly 2022-11</b>			
2022-08-09		Pilatus Aircraft Ltd.	PC-24
2022-10-01		Pilatus Aircraft Ltd.	PC-12/47E
2022-10-03		Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-10-07	R 89-24-06 R1	Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
<b>Biweekly 2022-12</b>			
2022-10-02	R 2002-03-01	Honeywell International Inc.	T5311A, T5311B, T5313B, T5317A, T5317A-1, T5317B, T5317BCV, and former military T53-L-11, T53-L-11A, T53-L-11B, T53-L-11C, T53-L-11D, T53-L-11A S/SA, T53-L-13B, T53-L-13B S/SA, T53-L-13B S/SB, and T53-L-703
2022-10-06	R 2017-18-14	Rolls-Royce Corporation	250-C20, 250-C20B, 250-C20C (T63-A-720), 250-C20F, 250-C20J, 250-C20R, 250-C20R/1, 250-C20R/2, 250-C20R/4, 250-C20W, 250-C300/A1, and 250-C300/B1
2022-10-09		Airbus Helicopters	SA-365C1 and SA-365C2
2022-10-51	E	Airbus Helicopters and Airbus Helicopters Deutschland GmbH	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-11-04	R 2020-26-13	Sikorsky Aircraft Corporation	S-92A
2022-11-06		Leonardo S.p.a.	A109S
2022-11-07		Airbus Helicopters Deutschland GmbH	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2, and MBB-BK117 D-2
2022-11-08	A 2011-22-05 R1 A 2016-25-20	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2
2022-11-09		Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-11-10		Piper Aircraft, Inc.	PA-46-600TP
2022-11-19		Bell Textron Inc.	212, 412, 412CF, and 412EP



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2022-10-02 Honeywell International Inc. (Type Certificate previously held by AlliedSignal, Inc. and Textron Lycoming):** Amendment 39-22040; Docket No. FAA-2021-1185; Project Identifier AD-2021-00339-E.

**(a) Effective Date**

This airworthiness directive (AD) is effective June 28, 2022.

**(b) Affected ADs**

This AD replaces AD 2002-03-01, Amendment 39-12642 (67 FR 6857, February 14, 2002).

**(c) Applicability**

This AD applies to Honeywell International, Inc. (Type Certificate previously held by AlliedSignal, Inc. and Textron Lycoming) T5311A, T5311B, T5313B, T5317A, T5317A-1, T5317B, T5317BCV, and former military T53-L-11, T53-L-11A, T53-L-11B, T53-L-11C, T53-L-11D, T53-L-11A S/SA, T53-L-13B, T53-L-13B S/SA, T53-L-13B S/SB, and T53-L-703 model turboshaft engines.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7600, Engine Controls.

**(e) Unsafe Condition**

This AD was prompted by reports of tachometer drive spur gear failure, resulting in potential engine overspeed, loss of power turbine speed (N2) instrument panel indication, and hard landings. The FAA is issuing this AD to prevent excessive vibrations produced by the reduction gearbox assembly that could cause failure of the tachometer drive spur gear. The unsafe condition, if not addressed, could result in failure of the engine, loss of thrust control, and damage to the aircraft.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Within 100 flight hours (FHs) after the effective date of this AD, or before further flight for a newly installed engine or newly installed reduction gearbox assembly, perform an initial special vibration test of the engine using the service information, as applicable to the engine model, listed in Table 1 to paragraph (g)(1) of this AD.

**Table 1 to paragraph (g)(1) –Applicable Service Information**

<b>Engine Model</b>	<b>Service Information</b>
Honeywell T5311A and T5311B	Accomplishment Instructions, paragraph 3.A. of AlliedSignal, Inc. Service Bulletin (SB) T5311A/B-0100, dated January 20, 2000.
Honeywell T5313B, T5317A, and T5317B	Accomplishment Instructions, paragraph 3.A. AlliedSignal, Inc. SB T5313B/17-0100, dated November 19, 1999, or paragraph 11.F of Honeywell Maintenance Manual Temporary Revision (TR) No. 165, dated July 29, 2020.
Honeywell T5317A-1	Accomplishment Instructions, paragraph 3.A. of Honeywell SB T53-0147, dated May 29, 2007, or paragraph 11.F of Honeywell Maintenance Manual TR No. 165, dated July 29, 2020.
Honeywell T5317BCV	Paragraph 11.F of Honeywell Maintenance Manual TR No. 165, dated July 29, 2020.
Honeywell T53-L-11, -11A, -11B, -11C, -11D, and -11A S/SA	Accomplishment Instructions, paragraph 3.A. of AlliedSignal, Inc. SB T53-L-11-0100, Revision 2, dated January 20, 2000.
Honeywell T53-L-13B, -13B S/SA, and -13B S/SB	Accomplishment Instructions, paragraph 3.A. of AlliedSignal, Inc. SB T53-L-13B-0100, Revision 2, dated May 11, 1999.
Honeywell T53-L-703	Accomplishment Instructions, paragraph 3.A. of AlliedSignal, Inc. SB T53-L-703-0100, Revision 2, dated May 11, 1999.

(2) Thereafter, within the following compliance times, perform repetitive special vibration tests of the engine:

(i) For engines that have tachometer drive spur gear part number (P/N) 1-070-062-04 installed, perform a repetitive special vibration test before exceeding 500 FHs since the last special vibration test.

(ii) For engines that have tachometer drive spur gear P/N 1-070-062-06 installed, perform a repetitive special vibration test before exceeding 1,000 FHs since the last special vibration test.

(3) If, during any special vibration test required by paragraph (g)(1) or (2) of this AD, an engine exceeds the 0.2 inches per second (IPS) limit for any peak RPM/frequency bands, before further flight, remove the reduction gearbox assembly or the engine from service.

#### **(h) No Reporting Requirement**

The reporting requirements in the Accomplishment Instructions, paragraph 3.A. or paragraph 11.F, of the service information, as applicable to the engine model, listed in Table 1 to paragraph (g)(1) of this AD, are not required by this AD.

#### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19,

send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved for AD 2002-03-01 (67 FR 6857, February 14, 2002) are approved as AMOCs for the corresponding provisions of this AD.

#### **(j) Related Information**

For more information about this AD, contact Jeffrey Chang, Aviation Safety Engineer, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: (562) 627-5263; fax: (562) 627-5210; email: jeffrey.chang@faa.gov.

#### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on June 28, 2022.

(i) Honeywell Service Bulletin (SB) T53-0147, dated May 29, 2007.

(ii) Honeywell Maintenance Manual Temporary Revision No. 165, dated July 29, 2020.

(4) The following service information was approved for IBR on March 21, 2002 (67 FR 6857, February 14, 2002).

(i) AlliedSignal, Inc. SB T5311A/B-0100, dated January 20, 2000.

(ii) AlliedSignal, Inc. SB T5313B/17-0100, dated November 19, 1999.

(iii) AlliedSignal, Inc. SB T53-L-11-0100, Revision 2, dated January 20, 2000.

(iv) AlliedSignal, Inc. SB T53-L-13B-0100, Revision 2, dated May 11, 1999.

(v) AlliedSignal, Inc. SB T53-L-703-0100, Revision 2, dated May 11, 1999.

(5) For service information identified in this AD, contact Honeywell International, Inc., 111 South 34th Street, Phoenix, AZ 85034; phone: (800) 601-3099; fax: (602) 365 5577; website: <https://myaerospace.honeywell.com/wps/portal>.

(6) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 5, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11059 Filed 5-23-22; 8:45 am]





**2022-10-06 Rolls-Royce Corporation:** Amendment 39-22044; Docket No. FAA-2021-1071; Project Identifier AD-2021-01055-E.

**(a) Effective Date**

This airworthiness directive (AD) is effective June 28, 2022.

**(b) Affected ADs**

This AD replaces AD 2017-18-14, Amendment 39-19023 (82 FR 42443, September 8, 2017).

**(c) Applicability**

This AD applies to Rolls-Royce Corporation (RRC) 250-C20, 250-C20B, 250-C20C (T63-A-720), 250-C20F, 250-C20J, 250-C20R, 250-C20R/1, 250-C20R/2, 250-C20R/4, 250-C20W, 250-C300/A1, and 250-C300/B1 model turboshaft engines with either a 3rd-stage turbine wheel, part number (P/N) 23065818, or a 4th-stage turbine wheel, P/N 23055944 or RR30000240, installed.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

**(e) Unsafe Condition**

This AD was prompted by in-service turbine blade failures that resulted in the loss of power and engine in-flight shutdowns. The FAA is issuing this AD to prevent failure of the 3rd-stage and 4th-stage turbine blades. The unsafe condition, if not addressed, could result in damage to the engine and damage to the aircraft.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

- (1) Within 1,775 hours since last visual inspection and fluorescent penetrant inspection (FPI), or at the next engine shop visit, whichever occurs first after the effective date of this AD, remove:
  - (i) 3rd-stage turbine wheel, P/N 23065818, and replace with a part eligible for installation.
  - (ii) 4th-stage turbine wheel, P/N 23055944, and replace with a part eligible for installation.
- (2) Within 2,025 hours since last visual inspection and FPI, or at the next engine shop visit, whichever occurs first after the effective date of this AD, remove 4th-stage turbine wheel, P/N RR30000240, and replace with a part eligible for installation.

**(h) Definitions**

(1) For this purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance in which the turbine module is separated from the exhaust collector, the gas-producer-support is separated from the power-turbine-support, or there is separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(2) For the purpose of this AD, a “part eligible for installation” is a 3rd-stage turbine wheel or 4th-stage turbine wheel that does not have a P/N listed in the Applicability, paragraph (c), of this AD.

**(i) Special Flight Permit**

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 to permit a one-time non-revenue ferry flight to operate the airplane to a maintenance facility where the engine can be removed from service. This ferry flight must be performed with only essential flight crew.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Chicago ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(k) Related Information**

For more information about this AD, contact John Tallarovic, Aviation Safety Engineer, Chicago ACO, FAA, 2300 E Devon Avenue, Des Plaines, IL 60018; phone: (847) 294-8180; email: john.m.tallarovic@faa.gov.

**(l) Material Incorporated by Reference**

None.

Issued on May 3, 2022.

Lance T. Gant,  
Director, Compliance & Airworthiness Division, Aircraft Certification Service.  
[FR Doc. 2022-11084 Filed 5-23-22; 8:45 am]



**2022-10-09 Airbus Helicopters:** Amendment 39-22047; Docket No. FAA-2022-0517; Project Identifier MCAI-2021-00356-R.

**(a) Effective Date**

This airworthiness directive (AD) becomes effective June 16, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Airbus Helicopters Model SA-365C1 and SA-365C2 helicopters, certificated in any category,

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

**(e) Unsafe Condition**

This AD was prompted by an accident involving a Model EC225LP helicopter in which the main rotor hub detached from the main gearbox (MGB). The FAA is issuing this AD to detect particles in the MGB and prevent planet gear seizure. The unsafe condition, if not addressed, could result in planet gear seizure resulting in the loss of the MGB and subsequent reduced control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0016, dated January 13, 2021 (EASA AD 2021-0016).

**(h) Exceptions to EASA AD 2021-0016**

(1) Where EASA AD 2021-0016 refers to its effective date or July 28, 2020 (the effective date of EASA AD 2020-0156, dated July 14, 2020), this AD requires using the effective date of this AD.

(2) Where EASA AD 2021-0016 requires actions during each “after last flight” of the day inspection, this AD requires those actions before the first flight of each day.

(3) Where EASA AD 2021-0016 refers to flight hours, this AD requires using hours time-in-service.

(4) Where the service information referenced in EASA AD 2021-0016 specifies to discard certain parts, this AD requires removing those parts from service.

(5) Where the service information referenced in EASA AD 2021-0016 specifies to return a certain part or send a certain part to an approved workshop, this AD requires removing that part from service.

(6) Where the service information referenced in EASA AD 2021-0016 specifies to use tooling, this AD allows the use of equivalent tooling.

(7) Where the service information referenced in EASA AD 2021-0016 specifies to contact Airbus Helicopters if further particles are collected during close monitoring, this AD requires, before further flight, accomplishing a repair in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(8) Where the service information referenced in EASA AD 2021-0016 specifies that certain requirements can be performed by a mechanical technician or pilot, this AD requires that the visual check of the MGB magnetic plugs be performed by a qualified mechanic.

(9) Where the service information referenced in EASA AD 2021-0016 specifies that if any 16NCD13 or 18NC16 particles are present you are to take a 1-liter sample of oil and send it to the manufacturer, this AD does not require those actions.

(10) Where the service information referenced in EASA AD 2021-0016 specifies to perform a metallurgical analysis and contact the manufacturer, this AD does require determining the characterization of particles collected but does not require contacting the manufacturer to determine the characterization of the particles collected.

(11) Where the service information referenced in EASA AD 2021-0016 specifies to contact Airbus Helicopters for details on the MGB history, this AD does not require this action.

(12) The "Remarks" section of EASA AD 2021-0016 does not apply to this AD.

#### **(i) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

#### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(k) Related Information**

For more information about this AD, contact Kristin Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email Kristin.Bradley@faa.gov. For service information identified in this AD that is not incorporated by reference, contact Airbus Helicopters,

2701 N Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0016, dated January 13, 2021.

(ii) [Reserved]

(3) For EASA AD EASA AD 2021-0016, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0517.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 6, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11553 Filed 5-31-22; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2022-10-51 Airbus Helicopters and Airbus Helicopters Deutschland GmbH (AHD):** Amendment 39-22050; Docket No. FAA-2022-0519; Project Identifier MCAI-2022-00589-R.

### **(a) Effective Date**

The FAA issued Emergency Airworthiness Directive (AD) 2022-10-51 on May 3, 2022, directly to affected owners and operators. As a result of such actual notice, that AD was effective for those owners and operators on the date it was provided. This AD contains the same requirements as that emergency AD and, for those who did not receive actual notice, is effective on June 7, 2022.

### **(b) Affected ADs**

None.

### **(c) Applicability**

This AD applies to the helicopters identified in paragraphs (c)(1) and (2) of this AD, certificated in any category.

(1) Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters.

Note 1 to paragraph (c)(1): Helicopters with an AS350B3e designation are Model AS350B3 helicopters.

(2) Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters.

Note 2 to paragraph (c)(2): Helicopters with an EC135P3H designation are Model EC135P3 helicopters. Helicopters with an EC135T3H designation are Model EC135T3 helicopters. Helicopters with an MBB-BK117 C-2e designation are Model MBB-BK117 C-2 helicopters.

### **(d) Subject**

Joint Aircraft System Component (JASC) Code: 2700, Flight Control System.

### **(e) Unsafe Condition**

This AD was prompted by a supplier report of a non-conformity occurring during production. The FAA is issuing this AD to address non-conforming flight control Flexball cables. The unsafe condition, if not addressed, could result in increased friction inside the flight control Flexball cables, jamming of the flight controls, and subsequent loss of control of the helicopter.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) Emergency AD 2022-0077-E, dated April 29, 2022 (EASA AD 2022-0077-E).

### **(h) Exceptions to EASA AD 2022-0077-E**

(1) Where EASA AD 2022-0077-E refers to its effective date, this AD requires using the effective date of this AD.

(2) Where the service information referenced in EASA AD 2022-0077-E specifies returning a part to the supplier, this AD requires removing an affected part from service.

(3) The note to paragraph (1) of EASA AD 2022-0077-E does not apply to this AD; instead, see the provisions in paragraph (j) of this AD.

(4) This AD does not mandate compliance with the “Remarks” section of EASA AD 2022-0077-E.

### **(i) Reporting Requirement**

Within 10 days after accomplishing the actions required by paragraph (g) of this AD, report the information requested in Appendix 1 to this AD to the email address identified in paragraph (i)(1) or (2) of this AD, depending on your helicopter model.

(1) For Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters: customersupport.helicopters@airbus.com.

(2) For Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters: support.technical-bulletins.ahd@airbus.com.

### **(j) Special Flight Permit**

A special flight permit or continuous authorization flight for a single flight may be issued, provided that there are no passengers onboard and that there is no noticeable increase in friction in the flight control system.

### **(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### **(l) Related Information**

For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA,

10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2022-0077-E, dated April 29, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0077-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0519.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**Appendix 1 to Airworthiness Directive 2022-10-51**

**Conformity of the Flexballs (sample format)**

Provide the following information by email as follows:

For Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters:  
customersupport.helicopters@airbus.com.

For Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters:  
support.technical-bulletins.ahd@airbus.com.

Helicopter Model and Serial Number:

Flexball Part Number:

**Flexball Serial Number:**

Issued on May 9, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11067 Filed 5-19-22; 11:15 am]





**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2022-11-04 Sikorsky Aircraft Corporation:** Amendment 39-22054; Docket No. FAA-2022-0146; Project Identifier AD-2021-00449-R.

### **(a) Effective Date**

This airworthiness directive (AD) is effective June 27, 2022.

### **(b) Affected ADs**

This AD replaces AD 2020-26-13, Amendment 39-21368 (85 FR 84201, December 28, 2020) (AD 2020-26-13).

### **(c) Applicability**

This AD applies to Sikorsky Aircraft Corporation Model S-92A helicopters, certificated in any category, with the following installed: Horizontal stabilizer root fitting FWD (forward root fitting) part number (P/N) 92209-07111-101 or 92070-20125-101; or stabilizer strut fitting P/N 92209-07403-041 or 92070-20117-041 installed on horizontal stabilizer assembly (stabilizer assembly) P/N 92070-20117-045, 92070-20117-046, 92070-20125-041, 92070-20125-042, 92070-20125-043, 92070-20125-044, 92205-07400-043, 92205-07400-045, or 92205-07400-047.

### **(d) Subject**

Joint Aircraft System Component (JASC) Code: 5510, Horizontal Stabilizer Structure.

### **(e) Unsafe Condition**

This AD was prompted by incidents of fatigue cracks in a forward root fitting and life limit recalculations for forward root fitting P/N 92209-07111-101 and 92070-20125-101. The FAA is issuing this AD to prevent a forward root fitting from remaining in service beyond its life limit, detect fatigue cracking in a forward root fitting, and prevent increased load and stress cracking in the stabilizer root fitting aft. The unsafe condition, if not addressed, could result in failure of a stabilizer root fitting, separation of the stabilizer assembly from the helicopter, and subsequent loss of control of the helicopter.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Required Actions**

(1) Within 50 hours time-in-service (TIS) after the effective date of this AD:

(i) Determine the total hours TIS of the forward root fitting P/N 92209-07111-101 or 92070-20125-101. If the total hours TIS of the forward root fitting is unknown, use the total hours TIS of the stabilizer assembly instead.

(A) If the forward root fitting has accumulated 7,900 or more total hours TIS, before further flight, remove the forward root fitting from service.

(B) If the forward root fitting has accumulated less than 7,900 total hours TIS, before exceeding 7,900 total hours TIS, remove the forward root fitting from service.

(ii) Thereafter following paragraph (g)(1)(i) of this AD, remove the forward root fitting from service before accumulating 7,900 total hours TIS.

(iii) For stabilizer assemblies with stabilizer strut fitting P/N 92070-20117-041 installed, perform the following actions:

(A) Determine the total hours TIS of stabilizer strut fitting P/N 92070-20117-041.

(B) If the stabilizer strut fitting has accumulated 19,100 or more total hours TIS, before further flight, remove the stabilizer strut fitting from service.

(C) If the stabilizer strut fitting has accumulated less than 19,100 total hours TIS, before exceeding 19,100 total hours TIS, remove the stabilizer strut fitting from service.

(iv) Thereafter following paragraph (g)(1)(iii) of this AD, remove the stabilizer strut fitting from service before accumulating 19,100 total hours TIS.

(2) For helicopters with stabilizer strut fitting P/N 92070-20117-041 or 92209-07403-041 installed, within 50 hours TIS after the effective date of this AD and thereafter at intervals not to exceed 50 hours TIS:

(i) Remove the support strut and using a cheese cloth (or similar cloth) and isopropyl alcohol, clean the upper and lower support strut rod ends, horizontal stabilizer attachment fitting, and the tail rotor pylon attachment fitting.

(ii) If installed, visually inspect the surface of each Mylar washer P/N 92070-20117-104 (Mylar washer). The surface should be smooth and continuous. If there is any visible damage such as any tear or scrape, remove the Mylar washer from the peelable-ply washer P/N 92070-20117-105 (peelable-ply washer) and remove the Mylar washer from service as follows:

(A) Dampen a low-lint cloth with 3M 6041 adhesive remover and place on the top of the Mylar washer.

(B) Allow the adhesive remover to soften the Mylar washer and peel the Mylar washer back.

(C) Repeat with more solvent until the Mylar washer and adhesive are removed.

(D) Clean the peelable-ply washer with cheese cloth moistened with isopropyl alcohol and adhere a new Mylar washer to the peelable-ply washer.

Note 1 to paragraph (g)(2)(ii): Stabilizer assembly P/Ns 92070-20125-041, 92070-20125-042, 92070-20125-043, and 92070-20125-044 do not utilize the Mylar washer. The inspection of the Mylar washer is not required on helicopters with stabilizer assembly P/N 92070-20125-041, 92070-20125-042, 92070-20125-043, or 92070-20125-044 installed.

(iii) Using a 10X or higher power magnifying glass, a flashlight, and a mirror, visually inspect the hat bushing and both upper fittings and lower fittings for a crack, corrosion, fretting, deformation, and wear. If there is a crack, corrosion, fretting, deformation, or wear on any part, before further flight, remove the part from service.

(iv) Using a 10X or higher power magnifying glass, a flashlight, and a mirror, visually inspect both upper and lower support strut rod ends, including each lug and conical fitting, and both upper and lower attachment fittings on the stabilizer and pylon including the bushings for a crack, corrosion, fretting, deformation, and wear. If there is a crack, corrosion, fretting, deformation, or wear on any part, before further flight, remove the part from service.

(3) Within 250 hours TIS or one year, whichever occurs first after the effective date of this AD, and thereafter at intervals not to exceed 250 hours TIS or one year, whichever occurs first:

(i) Remove the stabilizer assembly and visually inspect each stabilizer attachment bolt and barrel nut set for corrosion, a crack, and damage to the threads. For the purposes of this inspection, damage may be indicated by uneven threads, missing threads, or cross-threading.

(A) If there is corrosion within allowable limits, before further flight, treat for corrosion in accordance with FAA-approved procedures.

(B) If there is corrosion that exceeds allowable limits, or a crack, or damage to the threads, before further flight, remove the bolt and barrel nut set from service.

(ii) Inspect the forward root fitting and the aft attachment fitting by:

(A) Gaining access to the inside of the horizontal stabilizer.

(B) Using Brulin Cleaner SD 1291 (or equivalent) and a low-lint cloth, remove all traces of sealing compound, oil, and dirt from the stabilizer mounting surfaces.

(C) Using a 10X or higher magnifying glass, inspect for any crack, wear, and corrosion.

(1) If there is a crack, before further flight, remove the affected forward root fitting and the affected aft attachment fitting from service.

(2) If there is wear or corrosion that exceeds allowable limits, before further flight, remove the affected forward root fitting and the affected aft attachment fitting from service.

(3) If there is wear or corrosion within allowable limits, before further flight, treat for corrosion in accordance with FAA-approved procedures.

(D) Visually inspect each attachment fitting bolt hole and fastener hole for a crack, wear, and corrosion.

(1) If there is a crack, before further flight, remove the affected forward root fitting and the affected aft attachment fitting from service.

(2) If there is wear or corrosion that exceeds allowable limits, before further flight, remove the affected forward root fitting and the affected aft attachment fitting from service.

(3) If there is wear or corrosion within allowable limits, before further flight, treat for corrosion in accordance with FAA approved procedures.

(E) Inspect for loose or working fasteners. If there is a loose or working fastener, before further flight, remove the fastener from service.

(iii) As an alternative means to inspect for cracks in paragraphs (g)(3)(i) and (ii) of this AD, perform a florescent penetrant inspection (FPI).

(iv) Visually inspect each forward and aft attachment fitting mating surface for wear of the abrasion-resistant Teflon coating and degradation. For the purposes of this inspection, degradation may be indicated by fretting. Refer to Figure 204, of S-92 Maintenance Manual, SA S92A-AMM-000, Temporary Revision 55-33, Task 55-11-01-210-004, dated March 24, 2020 (TR 55-33), for a depiction of the area to be inspected. For the purposes of this inspection, wear may be indicated by less than 100% coverage of the abrasion-resistant Teflon coating. If there is wear to the abrasion-resistant Teflon coating or degradation, before further flight:

(A) Chemically strip the abrasion-resistant Teflon coating from the entire mounting pad in accordance with paragraph 7.A.(7)(a) of TR 55-33.

(B) FPI or eddy current inspect for a crack. If there is a crack, before further flight, remove the stabilizer assembly from service.

(C) If there is no crack, treat the affected area by applying alodine or equivalent. Apply abrasion-resistant Teflon coating in accordance with paragraphs 7.A.(7)(d) through (e) of TR 55-33.

(4) Installing stabilizer strut fitting P/N 92209-07404-041 is a terminating action for the requirements in paragraph (g)(2) of this AD.

(5) As of the effective date of this AD, do not install stabilizer assembly P/N 92205-07400-043, 92205-07400-045, or 92205-07400-047 on any helicopter.

#### **(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Boston ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

For more information about this AD, contact Dorie Resnik, Aerospace Engineer, Boston ACO Branch, 1200 District Avenue, Burlington, Massachusetts 01803; telephone 781-238-7693; email 9-AVS-AIR-BACO-COS@faa.gov.

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on February 1, 2021 (85 FR 84201, December 28, 2020).

(i) S-92 Maintenance Manual, SA S92A-AMM-000, Temporary Revision (TR) 55-33, dated March 24, 2020.

(ii) [Reserved]

(4) For Sikorsky Aircraft Corporation service information identified in this AD, contact Sikorsky's Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611, United States; phone: (800) 946-4337; email: wcs\_cust\_service\_eng.gr-sik@lmco.com; website: www.sikorsky360.com.

(5) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 16, 2022.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-10952 Filed 5-20-22; 8:45 am]



**2022-11-06 Leonardo S.p.a.:** Amendment 39-22056; Docket No. FAA-2022-0281; Project Identifier MCAI-2021-01315-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective July 6, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Leonardo S.p.a. Model A109S helicopters, serial number (S/N) 22735, 22736, and 22737, and equipped with Trekker Kit; and Model AW109SP helicopters S/N 22407, 22408, 22409, 22412, 22414 through 22427 inclusive, and 22429, certificated in any category.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 6700, rotorcraft Flight Control.

**(e) Unsafe Condition**

This AD was prompted by a report of a protective sheath, installed around a fixed flight control rod, which should have been removed during assembly. The FAA is issuing this AD to detect any foreign object contamination, which if not addressed, could affect the free movement of the flight controls and result in subsequent reduced control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0255, dated November 15, 2021, and corrected November 24, 2021 (EASA AD 2021-0255).

**(h) Exceptions to EASA AD 2021-0255**

(1) Where EASA AD 2021-0255 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021-0255 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (1) of EASA AD 2021-0255 specifies “inspect each affected part in accordance with the instructions of the applicable ASB,” for this AD replace “in accordance with the instructions of the applicable ASB” with “in accordance with the Accomplishment Instructions, Section 3, paragraph 5. of the applicable ASB.”

(4) Where paragraph (2) of EASA AD 2021-0255 specifies “if, during the inspection as required by paragraph (1) this AD, any foreign object is found on an affected part, before next flight, remove that foreign object in accordance with the applicable ASB,” this AD requires if any foreign object is found, before further flight, remove the foreign object. The instructions in the “applicable ASB” are for reference only and are not required for the actions in paragraph (2) of EASA AD 2021-0255.

(5) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0255.

#### **(i) Special Flight Permit**

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199, provided no passengers are onboard.

#### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(k) Related Information**

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

#### **(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0255, dated November 15, 2021, and corrected November 24, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0255, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the

AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0281.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 16, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11557 Filed 5-31-22; 8:45 am]



FAA  
Aviation Safety

## AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2022-11-07 Airbus Helicopters Deutschland GmbH (AHD):** Amendment 39-22057; Docket No. FAA-2022-0294; Project Identifier MCAI-2021-00550-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective July 8, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Airbus Helicopters Deutschland GmbH (AHD) Model MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2, and MBB-BK117 D-2 helicopters, certificated in any category.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

**(e) Unsafe Condition**

This AD was prompted by the FAA's determination that aging of the elastomeric material of certain tension torsion straps (TT-Straps), during the period since manufacturing date up to first flight on a helicopter, may affect its structural characteristics. The FAA is issuing this AD to address aging of the elastomeric material of certain TT-Straps. The unsafe condition, if not addressed, could result in premature failure of a TT-Strap, possibly resulting in loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0122, dated May 6, 2021 (EASA AD 2021-0122).

**(h) Exceptions to EASA AD 2021-0122**

(1) Where EASA AD 2021-0122 refers to its effective date, this AD requires using the effective date of this AD.



(2) Where EASA AD 2021-0122 specifies the “cure date” of a TT-Strap, the cure date can be determined using the information provided in the service information specified in EASA AD 2021-0122, or by contacting Airbus Helicopters Deutschland GmbH for applicable instructions. If the option of contacting Airbus Helicopters Deutschland GmbH for instructions is chosen, those instructions must be approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0122.

(4) Where the service information referenced in EASA AD 2021-0122 specifies scrapping a part, this AD requires removing that part from service.

(5) Where paragraph (1) of EASA AD 2021-0122 specifies to replace each Lord TT-Strap and Bendix TT-Strap “in accordance with the instructions of the applicable ASB,” for this AD, the replacement must be done using FAA-approved procedures.

(6) Where EASA AD 2021-0122 refers to the airworthiness limitations items of the airworthiness limitations section of the aircraft maintenance manual (AMM) for the definition of service life limit (SLL), this AD requires using the life limits specified in paragraphs (h)(6)(i) through (iii) of this AD, as applicable.

(i) For Bendix TT-Strap P/N 2604067 and P/N 117-14110: Before 10 years or 25,000 flight cycles on the part, whichever occurs first.

(ii) For Lord TT-Strap P/N J17322-1 and P/N 117-14111: Before 12 years or 40,000 flight cycles on the part, whichever occurs first.

(iii) For Lord TT-Strap P/N B622M10T1001: Before 12 years or 30,000 flight cycles on the part, whichever occurs first.

(7) Where table 1 of EASA AD 2021-0122 specifies a compliance time of “During the next helicopter periodical inspection or within 2 months, whichever occurs later after the effective date of this AD, but not exceeding the SLL,” for this AD, the compliance time is “Within 2 months after the effective date of this AD but not exceeding the applicable SLL specified in paragraphs (h)(6)(i) through (iii) of this AD.”

#### **(i) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

#### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(k) Related Information**

For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: (817) 222-5110; email: kristin.bradley@faa.gov.

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0122, dated May 6, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0122, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0294.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 17, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11936 Filed 6-2-22; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2022-11-08 Airbus Helicopters:** Amendment 39-22058; Docket No. FAA-2022-0297; Project Identifier MCAI-2021-01099-R.

### **(a) Effective Date**

This airworthiness directive (AD) is effective July 8, 2022.

### **(b) Affected ADs**

This AD affects AD 2011-22-05 R1, Amendment 39-17765 (79 FR 14169, March 13, 2014) (AD 2011-22-05 R1); and AD 2016-25-20, Amendment 39-18746 (81 FR 94954, December 27, 2016) (AD 2016-25-20).

### **(c) Applicability**

This AD applies to all Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2 helicopters, certificated in any category.

### **(d) Subject**

Joint Aircraft Service Component (JASC) Codes: 2400, Electrical Power System; 2800, Aircraft Fuel System; 2900, Hydraulic Power System; 5200, Doors; 5300, Fuselage Structure; 6200, Main Rotor System; 6300, Main Rotor Drive System; 6400, Tail Rotor System; 6500, Tail Rotor Drive System; and 6700, Rotorcraft Flight Control.

### **(e) Unsafe Condition**

This AD was prompted by the identification of certain parts needing maintenance actions, including life limits and maintenance tasks. The FAA is issuing this AD to address the failure of certain parts, which could result in the loss of control of the helicopter.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Required Actions**

Within 30 days after the effective date of this AD, incorporate into maintenance records required by 14 CFR 91.417(a)(2) or 135.439(a)(2), as applicable for your rotorcraft, the requirements (airworthiness limitations) specified in paragraph (1) of European Union Aviation Safety Agency (EASA) AD 2021-0194R1, dated October 8, 2021 (EASA AD 2021-0194R1).

**(h) Provisions for Alternative Requirements (Airworthiness Limitations)**

After the action required by paragraph (g) of this AD has been done, no alternative requirements (airworthiness limitations) are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2021-0194R1.

**(i) Terminating Action for ADs 2011-22-05 R1 and 2016-25-20**

(1) Accomplishing the actions required by this AD terminates all requirements of AD 2011-22-05 R1 for Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, and AS350D helicopters only.

(2) Accomplishing the actions required by this AD terminates all requirements of AD 2016-25-20 for Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2 helicopters only.

**(j) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are prohibited.

**(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(l) Related Information**

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0194R1, dated October 8, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0194R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the

AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0297.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 17, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11957 Filed 6-2-22; 8:45 am]



**2022-11-09 Viking Air Limited (Type Certificate Previously Held by Bombardier Inc. and de Havilland, Inc.):** Amendment 39-22059; Docket No. FAA-2020-1003; Project Identifier MCAI-2020-00962-A.

**(a) Effective Date**

This airworthiness directive (AD) is effective July 6, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Viking Air Limited (type certificate previously held by Bombardier Inc. and de Havilland, Inc.) Model DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes, all serial numbers, certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 5700, Wing Structure.

**(e) Unsafe Condition**

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as cracks and corrosion damage to the aileron internal structure. The FAA is issuing this AD to detect and correct cracks and other damage to the aileron internal structure. The unsafe condition, if not addressed, could result in progressive looseness of the aileron at the hinge support rib push-pull rod attachment, flutter condition, and degraded or loss of aileron control, which could lead to loss of control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection and Replacement of the Aileron**

At the compliance time specified in paragraph (g)(1) or (2) of this AD, inspect the left-hand (LH) and right-hand (RH) aileron internal structures for cracks, corrosion, and other damage and take any necessary corrective actions in accordance with the Accomplishment Instructions, steps II.A. through II.A.3. of Viking DHC-6 Twin Otter Service Bulletin V6/0066, Revision A, dated December 9, 2019 (Viking SB V6/0066, Revision A).

(1) For each LH or RH aileron that has accumulated 16,000 or more hours time-in-service (TIS), 32,000 or more flight cycles (FC), or 10 or more years since first installation on an airplane, whichever occurs first: Within 6 months after the effective date of this AD.

(2) For each LH or RH aileron that has accumulated less than 16,000 hours TIS, less than 32,000 FC, and less than 10 years since first installation on an airplane: Within 6 months after accumulating 16,000 hours TIS, 32,000 FC, or 10 years, whichever occurs first.

#### **(h) Reporting Requirement**

Within 30 days after the inspection required by paragraph (g)(1) or (2) of this AD or within 30 days after the effective date of this AD, whichever occurs later, report to Viking the information requested on the Inspection Reply Form, page 7, of Viking SB V6/0066, Revision A.

#### **(i) Credit for Previous Actions**

You may take credit for the actions required by paragraphs (g)(1) and (2) of this AD if you performed those actions before the effective date of this AD using Viking DHC-6 Twin Otter Service Bulletin V6/0066, Revision NC, dated August 29, 2019.

#### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(k) Related Information**

(1) For more information about this AD, contact Deep Gaurav, Aviation Safety Engineer, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7300; email: deep.gaurav@faa.gov.

(2) Refer to Transport Canada AD CF-2020-05, dated March 13, 2020, for more information. You may examine the Transport Canada AD at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1003.

#### **(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-6 Twin Otter Service Bulletin V6/0066, Revision A, dated December 9, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Viking Air Ltd., 1959 de Havilland Way, Sidney, British Columbia, Canada V8L 5V5; phone: (800) 663-8444; email: continuing.airworthiness@vikingair.com; website: <https://www.vikingair.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 17, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11559 Filed 5-31-22; 8:45 am]





**2022-11-10 Piper Aircraft, Inc.:** Amendment 39-22060; Docket No. FAA-2022-0021; Project Identifier AD-2020-01283-A.

**(a) Effective Date**

This airworthiness directive (AD) is effective June 27, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Piper Aircraft, Inc. Model PA-46-600TP airplanes, serial numbers 4698001, 4698004 through 4698146 inclusive, 4698148, and 4698150 through 4698157 inclusive, certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 5711, Wing Spar.

**(e) Unsafe Condition**

This AD results from testing that showed that the wing splice assembly could fail before the assembly reaches its established life limit. The FAA is issuing this AD to prevent failure of the wing splice assembly before the current established life limit. The unsafe condition, if not addressed, could result in loss of airplane control.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Action**

Within 90 days after the effective date of this AD, revise the Airworthiness Limitations section in the existing maintenance manual or instructions for continued airworthiness by reducing the life limit of the wing splice assembly part number 46W57A100-001 to 3,767 hours time-in-service.

Note 1 to paragraph (g): Section 4-00-00 of Piper Aircraft, Inc. PA-46-600TP, M600 Maintenance Manual, Airworthiness Limitations, Page 1, dated August 31, 2021, contains the life limit in paragraph (g) of this AD.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

(1) For more information about this AD, contact Fred Caplan, Aviation Safety Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5507; email: frederick.n.caplan@faa.gov.

(2) For service information identified in this AD, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL, 32960; phone: (772) 291-2141; website: <https://www.piper.com>.

**(j) Material Incorporated by Reference**

None.

Issued on May 17, 2022.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-10863 Filed 5-20-22; 8:45 am]



**2022-11-19 Bell Textron Inc.:** Amendment 39-22069; Docket No. FAA-2022-0387; Project Identifier AD-2021-01225-R.

**(a) Effective Date**

This airworthiness directive (AD) is effective July 6, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bell Textron Inc. Model 212, 412, 412CF, and 412EP helicopters, certificated in any category, with an engine oil check valve part number (P/N) 209-062-520-001 or fuel check valve P/N 209-062-607-001 manufactured by Circor Aerospace that:

- (1) Is marked "Circle Seal" and "CORONA CA," except not a check valve marked with "TQL," and
- (2) Has a manufacturing date code of, or prior to, "9/11" (September 2011), or does not have a manufacturing date code, installed.

**(d) Subject**

Joint Aircraft System Component (JASC) Code: 2800 Aircraft Fuel System and 7900 Engine Oil System (Airframe).

**(e) Unsafe Condition**

This AD was prompted by a report of a cracked check valve. The FAA is issuing this AD to detect a cracked check valve. The unsafe condition, if not addressed, could result in loss of lubrication or fuel to the engine, failure of the engine or a fire, and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

- (1) Within 25 hours time-in-service (TIS) or 30 days, whichever occurs first after the effective date of this AD, using a caliper or equivalent, measure the outside diameter (O.D.) of the check valve housing at the center, and the O.D. of the check valve housing at the inlet end where the threaded fitting is installed. If the dimension measured at the inlet end is greater than 0.003 inch (0.0762 mm) compared to the measurement at the center, do the following:

(i) Before further flight, and thereafter at intervals not to exceed 25 hours TIS or 30 days, whichever occurs first, using a flashlight, visually inspect the check valve for a crack and leak, paying particular attention to the area at the inlet end where the threaded fitting is installed. If there is a crack or leak, before further flight, remove the check valve from service. Removing the check valve from service terminates the repetitive inspections required by this AD for that check valve.

(ii) Within 600 hours TIS or 12 months, whichever occurs first, remove the check valve from service. Removing the check valve from service terminates the repetitive inspections required by this AD for that check valve.

(2) As of the effective date of this AD, do not install an engine oil or fuel check valve identified in paragraph (c) of this AD on any helicopter.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, DSCO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ASW-190-COS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

For more information about this AD, contact Kuethe Harmon, Safety Management Program Manager, Certification & Program Management Section, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5198; email kuethe.harmon@faa.gov.

**(j) Material Incorporated by Reference**

None.

Issued on May 25, 2022.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-11605 Filed 5-31-22; 8:45 am]