

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2022-14

6/20/2022 - 7/3/2022



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

Biweekly 2022-01

2021-05-03		Airbus Helicopters	EC225LP
2021-23-01		Stemme AG	Stemme S 12
2021-23-06		Various Manufactures	234; CH-47D
2021-24-18		Viking Air Limited	DHC-3
2021-24-19		Flugzeugbau GmbH	DG-500MB and DG-1000M
2021-24-21		Embraer S.A.	EMB-500 and EMB-505
2021-24-22	R 2012-06-16	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2021-25-01		Leonardo S.p.a.	A109S and AW109SP
2021-25-08		Leonardo S.p.a.	AW189
2021-25-10		Daher Aerospace	TBM 700
2021-25-11	R 78-02-03	Piper Aircraft, Inc.	PA-23-250
2021-26-07	R 2020-11-05	Airbus Helicopters	EC120B
2021-26-08		Bell Textron Canada Limited	206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4
2022-01-05	R 2021-24-06	Airbus Helicopters	EC130T2

Biweekly 2022-02

2021-26-14	R 2018-11-01	Airbus Helicopters	AS332L2, EC225LP
2021-26-15		Vulcanair S.p.A.	P.68C, P.68C-TC, P.68 "OBSERVER," P.68 OBSERVER 2, P.68R, and P.68TC OBSERVER
2021-26-18	R 2020-21-01	Airbus Helicopters	AS-365N2, AS 365 N3, and SA-365N1; SA-365C1, SA-365C2, and SA-365N; EC 155B and EC155B1
2022-01-06		Cameron Balloons Ltd.	flange adapter
2022-01-09		Stemme AG	Stemme S 10-VT and Stemme S 12
2022-02-01		Sikorsky Aircraft Corporation	S-92A
2022-02-02	R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212

Biweekly 2022-03

2021-26-12		Stemme AG	Stemme S 12
2021-26-16		Various Restricted Category Helicopters	UH-1H
2021-26-21		Pilatus Aircraft Ltd.	PC-24
2021-26-24		Leonardo S.p.a.	A109A and A109A II
2021-26-25		Schempp-Hirth Flugzeugbau GmbH	Duo Discus; Duo Discus T
2021-26-26	R 2005-12-08	Safran Helicopter Engines, S.A.	Arrius 2B1, Arrius 2B1A, and Arrius 2B2
2021-26-29		Leonardo S.p.a.	AW169
2022-02-17		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-03-03	R 2021-22-20	Austro Engine GmbH	E4 and E4P
2022-03-07		Stemme AG	S6 and S6-RT

Biweekly 2022-04

2022-01-01		Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; SA-365C1, SA-365C2, SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2022-01-03		Umlaut Engineering GmbH	hand-held P3HAFEX fire extinguisher
2022-02-02	COR R 2021-15-51	Bell Textron Inc.	204B, 205A, 205A-1, 205B, 210, and 212
2022-02-04		Airbus Helicopters	AS350B, AS350B2, AS350B3, and AS350BA
2022-02-06		Airbus Helicopters	EC120B
2022-02-08		Leonardo S.p.a.	AB412 and AB412 EP
2022-02-12		Leonardo S.p.a.	AB139 and AW139
2022-02-13		Airbus Helicopters	EC120B
2022-02-19		Airbus Helicopters Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3
2022-02-20		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-03-01		Diamond Aircraft Industries GmbH	DA 42 NG; DA 42, and DA 42 M-NG

2022-03-04	R 80-13-10 R 80-13-12 R1 R 2008-03-01	Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-03-08		Fiberglas-Technik Rudolf Lindner GmbH & Co. KG	G102 ASTIR CS; G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, G103 C TWIN III ACRO, and G103 C TWIN III SL
2022-03-09 2022-03-23	A 2020-08-02	Sikorsky Aircraft Corporation Textron Aviation Inc.	S-76D 300, 300LW, B300, and B300C
Biweekly 2022-05			
2022-03-13 2022-03-15 2022-03-17 2022-03-18	R 2014-21-03	Airbus Helicopters Various Airplanes Airbus Helicopters British Aerospace (Operations) Limited and British Aerospace Regional Aircraft	AS332L2 Garmin G3X Touch Electronic Flight Instrument System AS332L2 and EC225LP Jetstream Series 200, Jetstream Model 3101, and Jetstream Model 3201
2022-04-01		DG Flugzeugbau GmbH and Schempp-Hirth Flugzeugbau GmbH	DG-1000T and Duo Discus T
2022-04-04		Continental Aerospace Technologies, Inc. and Continental Motors	C-125-1, C-125-2, C145-2, C145-2H, IO-360-C, IO-360-D, IO-360-DB, IO-360-H, IO-360-HB, IO-360-K, IO-360-KB, IO-470-E, IO-470-S, IO-550-B, IO-550-G, O-300-B, O-300-C, O-300-D, O-300-E, O-470-A, O-470-B, O-470-G, O-470-J, O-470-K, O-470-L, O-470-M, O-470-N, O-470-R, O-470-S, O-470-U, O-470-11, O-470-15, TSIO-360-E, TSIO-360-EB, TSIO-360-F, TSIO-360-FB, TSIO-360-GB, TSIO-360-LB, TSIO-360-MB, TSIO-360-SB, TSIO-520-C, TSIO-520-CE, TSIO-520-E, and TSIO-520-UB
2022-05-01 2022-05-02	R 2021-11-25	Learjet, Inc. Airbus Helicopters	35, 35A (C-21A), 36, 36A, 55, 55B, 55C, and 60 AS350B3 and EC130T2
Biweekly 2022-06			
2022-04-06 2022-04-09 2022-05-05	R 2021-06-06	Bell Textron Canada Limited AVOX Systems Inc. Schempp-Hirth Flugzeugbau GmbH	505 oxygen cylinder Ventus-2a and Ventus-2b
2022-05-11 2022-05-12 2022-05-14	R 2020-12-08	Viking Air Limited Embraer S.A. GROB Aircraft SE	DHC-3 EMB-505 G 115EG
Biweekly 2022-07			
2021-03-16R1	R 2021-03-16	Airbus Helicopters	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2022-05-10		Goodrich Externally-Mounted Hoist Assemblies	hoist assembly
2022-05-13 2022-06-01		Honda Aircraft Company LLC Airbus Helicopters Deutschland GmbH	HA-420 MBB-BK 117 D-3
2022-06-03 2022-06-05	R 2022-02-02 R 2021-15-52	Bell Textron Inc. Various Restricted Category Helicopters	204B, 205A, 205A-1, 205B, 210, and 212 Various Models
2022-06-13		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2
2022-06-20 2022-07-03 2022-07-05	R 2020-20-06 R 2022-05-09	Bell Textron Canada Limited Bell Textron Inc. MARS A.S.	429 412, 412EP, and 412CF ATL-88/90-1B
Biweekly 2022-08			
2022-06-04		Schempp-Hirth Flugzeugbau GmbH	Janus, Mini-Nimbus HS-7, Nimbus-2, and Standard Cirrus
2022-06-08	R 2017-18-10	Diamond Aircraft Industries GmbH	DA 42, DA 42 M-NG, and DA 42 NG
2022-06-12 2022-06-17 2022-06-19 2022-07-01 2022-07-02	R 2020-23-07	Airbus Helicopters Airbus Helicopters Leonardo S.p.a. Leonardo S.p.a. Bell Textron Inc.	SA330J EC130T2 AW109SP AB139 and AW139 205A and 205A-1; 205B; 210; 212i; 412 and 412EP; 412CF

2022-07-04		Pilatus Aircraft Ltd.	PC-12/47E
2022-07-09		Airbus Helicopters	AS332L2 and EC225LP
2022-07-11	R 2021-17-18	Leonardo S.p.a.	A109C, A109K2, A109E, A109S, and AW109SP
2022-07-12	R 2021-02-20	Hélicoptères Guimbal	Cabri G2
2022-07-14		Viking Air Limited	DHC-6-400
Biweekly 2022-09			
2022-08-01	R 2020-22-01	Airbus Helicopters	AS332C, AS332C1, AS332L, and AS332L1
2022-08-02		Airbus Helicopters	EC 155B and EC155B1
2022-08-03		Textron Aviation Inc.	120 and 140; 140A
2022-08-10	R 2020-12-07	Hamilton Sundstrand Corporation	54H
2022-08-11		Bell Textron Canada Limited	429
2022-08-13		Pratt & Whitney Canada Corp.	PT6A-34, -34B, -34AG, -114, and -114A
2022-08-15		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2
Biweekly 2022-10			
2022-09-04	R 2021-05-05	Airbus Helicopters	SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1
2022-09-07	R 2019-11-05 A 2020-17-10	Bell Textron Canada Limited	429
2022-09-13		Piper Aircraft, Inc.	PA-34-200
2022-09-17		Scheibe-Aircraft-GmbH	SF 25 C
2022-10-51	E	Airbus Helicopters; Airbus Helicopters Deutschland GmbH	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
Biweekly 2022-11			
2022-08-09		Pilatus Aircraft Ltd.	PC-24
2022-10-01		Pilatus Aircraft Ltd.	PC-12/47E
2022-10-03		Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-10-07	R 89-24-06 R1	Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
Biweekly 2022-12			
2022-10-02	R 2002-03-01	Honeywell International Inc.	T5311A, T5311B, T5313B, T5317A, T5317A-1, T5317B, T5317BCV, and former military T53-L-11, T53-L-11A, T53-L-11B, T53-L-11C, T53-L-11D, T53-L-11A S/SA, T53-L-13B, T53-L-13B S/SA, T53-L-13B S/SB, and T53-L-703
2022-10-06	R 2017-18-14	Rolls-Royce Corporation	250-C20, 250-C20B, 250-C20C (T63-A-720), 250-C20F, 250-C20J, 250-C20R, 250-C20R/1, 250-C20R/2, 250-C20R/4, 250-C20W, 250-C300/A1, and 250-C300/B1
2022-10-09		Airbus Helicopters	SA-365C1 and SA-365C2
2022-10-51	E	Airbus Helicopters and Airbus Helicopters Deutschland GmbH	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3
2022-11-04	R 2020-26-13	Sikorsky Aircraft Corporation	S-92A
2022-11-06		Leonardo S.p.a.	A109S
2022-11-07		Airbus Helicopters Deutschland GmbH	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2, and MBB-BK117 D-2
2022-11-08	A 2011-22-05 R1 A 2016-25-20	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2
2022-11-09		Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-11-10		Piper Aircraft, Inc.	PA-46-600TP
2022-11-19		Bell Textron Inc.	212, 412, 412CF, and 412EP

Biweekly 2022-13

2022-11-12		Viking Air Limited	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400
2022-11-16		British Aerospace (Operations) Limited and British Aerospace Regional Aircraft	Jetstream Model 3101; Jetstream Model 3201
2022-11-18		Airbus Helicopters	AS355E, AS355F, AS355F1, AS355F2, AS-365N2, AS 365 N3, SA-365N, SA-365N1, EC 155B, and EC155B1
2022-12-06		Costruzioni Aeronautiche Tecnam S.P.A.	P2012 Traveller
2022-12-07	R 75-23-03	Alexander Schleicher GmbH & Co. Segelflugzeugbau	Ka2B, Ka 6, Ka 6 B, Ka 6 BR, Ka 6 C, Ka 6 CR, K 7, K 8, K 8 B, and AS-K 13
2022-12-08		Robinson Helicopter Company	R22 BETA; R44; R44 II
2022-12-09	R 2017-15-06	British Aerospace (Operations) Limited and British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Model 3101; Jetstream Model 3201
2022-13-01		Leonardo S.p.a	AW169
2022-13-03		Cameron Balloons Ltd.	fuel cylinder

Biweekly 2022-14

2022-11-20		Leonardo S.p.a.	AB139 and AW139
2022-13-07		AutoGyro Certification Limited	Calidus, Cavalon, and MTOsport 2017
2022-13-16		Aviation Czech s.r.o	M601D-11
2022-14-51	E	Airbus Helicopters	EC225LP



2022-11-20 Leonardo S.p.a.: Amendment 39-22070; Docket No. FAA-2022-0283; Project Identifier MCAI-2021-01285-R.

(a) Effective Date

This airworthiness directive (AD) is effective July 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category, with an affected part as identified in European Union Aviation Safety Agency (EASA) AD 2021-0259, dated November 17, 2021, and corrected November 22, 2021 (EASA AD 2021-0259).

(d) Subject

Joint Aircraft Service Component (JASC) Code: 5300, Fuselage Structure.

(e) Unsafe Condition

This AD was prompted by a large crack detected on the tail gearbox (TGB) fitting during a scheduled inspection and the determination that certain TGB fittings are required to be inspected by the use of a borescope. The FAA is issuing this AD to detect cracks on the TGB fitting. The unsafe condition, if not addressed, could result in crack propagation up to a critical length, reduced load capability of the TGB and tail rotor, and subsequent reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0259.

(h) Exceptions to EASA AD 2021-0259

(1) Where EASA AD 2021-0259 requires compliance in terms of flight hours (FH), this AD requires using hours time-in-service.

(2) Where EASA AD 2021-0259 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (1) of EASA AD 2021-0259 specifies “inspect, using a borescope, the affected part in accordance with the instructions of Section 3 Part I of the ASB,” for this AD replace “in accordance with the instructions of Section 3 Part I of the ASB” with “in accordance with the Accomplishment Instructions, Section 3 Part I, paragraphs 5. through 5.5 of the ASB.”

(4) Where paragraph (2) of EASA AD 2021-0259 specifies “if, during the inspection as required by paragraph (1) this AD, a crack or any discrepancy is detected, replace the affected part in accordance with the instructions of Section 3 Part II of the ASB,” this AD requires before further flight, removing the TGB fitting from service and replacing with an airworthy part, if any crack or discrepancy is detected. For this AD, discrepancies include damage, which includes scratches and dents on the outer surfaces of the forward and right-hand sides of the TGB fitting above the horizontal row of fastener holes. The instructions specified in paragraph (2) of EASA AD 2021-0259 are for reference only and are not required for the replacement required by this paragraph.

(5) Where paragraph (4) of EASA AD 2021-0259 allows (re)installing an affected part provided it is inspected as required by paragraph (1) of EASA AD 2021-0259, for this AD, the inspected part cannot be (re)installed if any crack or discrepancy is detected.

(6) This AD does not mandate compliance with paragraph (3) of EASA AD 2021-0259.

(7) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021-0259.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199, provided no passengers are onboard.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(2) For service information identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0283.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0259, dated November 17, 2021, and corrected November 22, 2021.

(ii) [Reserved]

(3) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating FAA-2022-0283.

(4) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 25, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13267 Filed 6-21-22; 8:45 am]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2022-13-07 AutoGyro Certification Limited (Type Certificate Previously Held by RotorSport UK Ltd): Amendment 39-22093; Docket No. FAA-2022-0685; Project Identifier MCAI-2022-00243-R.

(a) Effective Date

This airworthiness directive (AD) is effective July 7, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to AutoGyro Certification Limited (type certificate previously held by RotorSport UK Ltd) Model Calidus, Cavalon, and MTOsport 2017 gyroplanes, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6210, Main Rotor Blades.

(e) Unsafe Condition

This AD was prompted by reports of rotor blade longitudinal cracking and rotor blade attachment bolt hole fretting corrosion and cracking. The FAA is issuing this AD to prevent a rotor system from remaining in service beyond its fatigue life and detect fretting corrosion and cracking. The unsafe condition, if not addressed, could result in failure or loss of a rotor blade and subsequent loss of control of the gyroplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For a gyroplane with a Rotor System I, all part numbers and serial numbers, installed:

(i) That has accumulated 700 or more total hours time-in-service (TIS) on the rotor system, before further flight after the effective date of this AD, remove the rotor system, which includes the rotor bearing, from service.

(ii) That has accumulated less than 700 total hours TIS on the rotor system, before accumulating 700 total hours TIS after the effective date of this AD, remove the rotor system, which includes the rotor bearing, from service.

(iii) Thereafter following paragraph (g)(1)(i) or (ii) of this AD, remove the rotor system, which includes the rotor bearing, from service before accumulating 700 total hours TIS.

(2) For a gyroplane with a Rotor System II, all part numbers and serial numbers, installed:

(i) That has accumulated 2,500 or more total hours TIS on the rotor system, before further flight after the effective date of this AD, remove the rotor system, which includes the rotor bearing, from service.

(ii) That has accumulated less than 2,500 total hours TIS on the rotor system, before accumulating 2,500 total hours TIS after the effective date of this AD, remove the rotor system, which includes the rotor bearing, from service.

(iii) Thereafter following paragraph (g)(2)(i) or (ii) of this AD, remove the rotor system, which includes the rotor bearing, from service before accumulating 2,500 total hours TIS.

(3) For a gyroplane with a Rotor System I or II, all part numbers and serial numbers, installed, accomplish the actions required by paragraph (g)(4) of this AD within 10 hours TIS or 3 months after the effective date of this AD, whichever occurs first.

(4) For each rotor blade, starting with the rotor blade bolt closest to the rotor hub, sequentially remove each bolt and lock nut, remove the rotor blade, and remove the inner end cap.

(i) Using a dry cloth, wipe clean the rotor blade upper and lower surfaces within 100 mm of the circumference of each bolt hole.

(A) Dye penetrant inspect, or use a flashlight and 10X or higher power magnifying glass, to inspect the cleaned rotor blade upper and lower surfaces within 100 mm of the circumference of each bolt hole for a crack, split, dent, and fretting corrosion. If there is a crack, split, dent, or fretting corrosion at any point within 100 mm over the full circumference (360°) of a bolt hole, before further flight, remove the rotor system, which includes the rotor bearing, from service and install airworthy parts.

(B) Using a flashlight and 10X or higher power magnifying glass, inspect each plane on the cleaned upper and lower surfaces for bending within 100 mm of the circumference of the bolt hole. If there is any bending in any plane within 100 mm over the full circumference (360°) of a bolt hole, before further flight, remove the rotor system, which includes the rotor bearing, from service and install airworthy parts.

(ii) Dye penetrant inspect, or use a flashlight and 10X or higher power magnifying glass to inspect the rotor blade upper and lower inside surfaces at the rotor blade extrusion end (where the inner end cap was removed) for a crack, paying particular attention for a longitudinal crack adjacent to the bolted area. If there is a crack, before further flight, remove the rotor system, which includes the rotor bearing, from service and install airworthy parts.

Note 1 to paragraph (g)(4)(ii): Page 5 of RotorSport UK Ltd Service Information Letter SIL-028, Issue 1, dated June 17, 2019, includes a photo of a longitudinal blade root crack.

(iii) Using a flashlight and 10X or higher power magnifying glass, inspect each bolt hole in the rotor blade upper and lower surfaces for any burrs and fretting corrosion. If there is a burr or fretting corrosion, before further flight, remove the rotor system, which includes the rotor bearing, from service and install airworthy parts.

(iv) Using a dry cloth, wipe clean and dye penetrant inspect, or use a flashlight and 10X or higher power magnifying glass to inspect each bolt hole in the rotor blade upper and lower surfaces for a crack. If there is a crack, before further flight, remove the rotor system, which includes the rotor bearing, from service and install airworthy parts.

(5) Thereafter following paragraph (g)(3) of this AD, repeat the actions required by paragraph (g)(4) of this AD at intervals not to exceed the compliance time specified in paragraphs (g)(5)(i) through (iii) of this AD, as applicable to your rotor system.

(i) For a gyroplane with a Rotor System I, all part numbers and serial numbers, installed, at intervals not to exceed 100 hours TIS or 12 months, whichever occurs first.

(ii) For a gyroplane with a Rotor System II, all part numbers and serial numbers, installed, that has accumulated more than 1,500 total hours TIS on the rotor system, at intervals not to exceed 100 hours TIS or 24 months, whichever occurs first.

(iii) For a gyroplane with a Rotor System II, all part numbers and serial numbers, installed, that has accumulated 1,500 or less total hours TIS on the rotor system, at intervals not to exceed 500 hours TIS or 24 months, whichever occurs first.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Chirayu Gupta, Aerospace Engineer, Mechanical Systems & Administrative Services Section, New York ACO Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; email 9-avs-nyaco-cos@faa.gov.

(2) RotorSport UK Ltd Service Information Letter SIL-028, Issue 1, dated June 17, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Gerry Speich; Poplar Farm, Wentnor, Bishops Castle, South Shropshire, United Kingdom, SY9 5EJ; telephone +44-1588-505060; or at <http://www.auto-gyro.co.uk/>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this AD is addressed in United Kingdom (UK) Civil Aviation Authority (CAA) Mandatory Permit Directive (MPD) 2022-002, dated January 24, 2022. You may view the UK CAA MPD at <https://www.regulations.gov> in Docket No. FAA-2022-0685.

(j) Material Incorporated by Reference

None.

Issued on June 13, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13362 Filed 6-16-22; 4:15 pm]



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2022-13-16 GE Aviation Czech s.r.o (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.): Amendment 39-22102; Docket No. FAA-2022-0459; Project Identifier MCAI-2021-00266-E.

(a) Effective Date

This airworthiness directive (AD) is effective August 1, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to GE Aviation Czech s.r.o. M601D-11 model turboprop engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM) to include a visual inspection of the centrifugal compressor case for cracks. The FAA is issuing this AD to prevent failure of the centrifugal compressor case. The unsafe condition, if not addressed, could result in failure of the centrifugal compressor case, engine separation, and loss of the airplane.


(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 90 days after the effective date of this AD, revise the ALS of the existing EMM by incorporating Figure 1 to paragraph (g)(1) of this AD.

Figure 1 to Paragraph (g)(1) – Visual Inspection of the Centrifugal Compressor Case



(2) After revising the ALS of the existing EMM required by paragraph (g)(1) of this AD, no alternative inspection intervals may be used unless they are approved as provided in paragraph (h) of this AD.

(3) The action required by paragraph (g)(1) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD and email it to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0060, dated March 3, 2021, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0459.

(j) Material Incorporated by Reference

None.

Issued on June 17, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13503 Filed 6-24-22; 8:45 am]



DATE: July 1, 2022

AD #: 2022-14-51

Emergency Airworthiness Directive (AD) 2022-14-51 is sent to owners and operators of Airbus Helicopters Model EC225LP helicopters.

Background

This emergency AD was prompted by a report of a cracked main rotor head (MRH) sleeve. This emergency AD requires one-time visual inspections and, depending on the results, accomplishing additional inspections, repairing the MRH sleeve in accordance with a certain approval, and removing the MRH sleeve from service and installing an airworthy part. This emergency AD also prohibits installing an MRH sleeve unless certain inspections have been accomplished. This condition, if not addressed, could result in failure of an MRH sleeve, loss of a main rotor blade, and subsequent loss of the helicopter.

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Emergency AD 2022-0130-E, dated June 30, 2022 (EASA AD 2022-0130-E), to correct an unsafe condition for Airbus Helicopters (AH), formerly Eurocopter, Model EC 225 LP helicopters. EASA advises of a crack in an MRH sleeve that investigation determined was a fatigue crack that had initiated from a corrosion pit located in an area with chipped paint. Accordingly, EASA AD 2022-0130-E requires initial one-time detailed visual inspections of MRH sleeve part number (P/N) 332A31-3071-00 and depending on the results, follow-on repetitive inspections and corrective actions.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its emergency AD. The FAA is issuing this emergency AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type design.

Related Service Information

The FAA reviewed Airbus Helicopters Emergency Alert Service Bulletin No. 62A017, Revision 0, dated June 30, 2022. This service information specifies procedures for one-time detailed visual inspections of a certain area (identified as "Specific area" in Figure 3 of the service information) of MRH sleeve P/N 332A31-3071-00. Depending on the one-time inspection results, this service information specifies procedures for follow-on inspections, which include eddy current inspections, chemical stripping, and fluorescent penetrant inspections; and corrective actions, which include applying primer and paint protection, removing corrosion, applying a protective coating, contacting Airbus Helicopters for corrective action, and removing and returning the MRH sleeve to Airbus Helicopters.

Emergency AD Requirements

This emergency AD requires visually inspecting the “Specific area” of each MRH sleeve P/N 332A31-3071-00 for flaking and paint touch-up. If there is any flaking or paint touch-up, this emergency AD requires visually inspecting the “Specific area” of the MRH sleeve for a crack.

As a result of the visual inspection, if there is a crack, this emergency AD requires removing the MRH sleeve from service and installing an airworthy part. If there is not a crack, this emergency AD requires an inspector with a certain qualification using high-frequency eddy current (HFEC) to inspect the “Specific area” of the MRH sleeve for a crack.

As a result of the HFEC, if there is a crack, this emergency AD requires removing the MRH sleeve from service and installing an airworthy part. If there is not a crack, this emergency AD requires chemically stripping and fluorescent penetrant inspecting (FPI) the “Specific area” of the MRH sleeve for corrosion.

As a result of the FPI, if there is corrosion, this emergency AD requires removing the corrosion by hand and repeating the FPI of each affected area to inspect for corrosion, and depending on the subsequent results, removing the MRH sleeve from service and installing an airworthy part; or drying the MRH sleeve, applying a protective coating, primer, and paint protection, and having an inspector with a certain qualification using HFEC repetitively inspect the “Specific area” of the MRH sleeve for a crack. If there is a crack, this emergency AD requires removing the MRH sleeve from service and installing an airworthy part. However, if the corrosion cannot be removed by hand, this emergency AD requires removing the MRH sleeve from service and installing an airworthy part or repairing the MRH sleeve in accordance with a certain approved method.

As a result of the first FPI, if there is no corrosion, this emergency AD requires applying primer and paint protection.

As an option to the first FPI and its follow-on actions, if there is not a crack, this emergency AD allows applying primer and paint protection or, for any areas with flaking paint, applying only varnish instead of primer and paint protection on each flaking paint area; and having an inspector with a certain qualification using HFEC to repetitively inspect the “Specific area” of the MRH sleeve for a crack. If there is a crack, this emergency AD requires removing the MRH sleeve from service and installing an airworthy part.

This emergency AD also prohibits installing an MRH sleeve unless specified one-time visual inspections have been accomplished.

Differences Between This Emergency AD and the EASA AD

If there is corrosion in an MRH sleeve, EASA AD 2022-0130-E requires contacting Airbus Helicopters for approved repair instructions, whereas this emergency AD requires removing the MRH sleeve from service or repairing the MRH sleeve in accordance with a certain approved method.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Presentation of the Actual Emergency AD

The FAA is issuing this emergency AD under 49 U.S.C. Section 44701 according to the authority delegated to me by the Administrator.

2022-14-51 Airbus Helicopters: Project Identifier MCAI-2022-00873-R.

(a) Effective Date

This emergency AD is effective upon receipt.

(b) Affected ADs

None.

(c) Applicability

This emergency AD applies to Airbus Helicopters Model EC225LP helicopters, certificated in any category, with main rotor hub (MRH) sleeve part number 332A31-3071-00 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

(e) Unsafe Condition

This emergency AD was prompted by a report of a cracked MRH sleeve. The FAA is issuing this emergency AD to detect corrosion or cracking in an MRH sleeve. The unsafe condition, if not addressed, could result in failure of an MRH sleeve, loss of a main rotor blade, and subsequent loss of the helicopter.

(f) Compliance

Comply with this emergency AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before further flight after the effective date of this emergency AD, visually inspect the “Specific area” of each MRH sleeve as depicted in Figure 3 of Airbus Helicopters Emergency Alert Service Bulletin No. 62A017, Revision 0, dated June 30, 2022 (ASB 62A017), for flaking and paint touch-up.

(2) As a result of the actions required by paragraph (g)(1) of this emergency AD, if there is no flaking or paint touch-up, no further action is required. If there is any flaking or paint touch-up, before further flight, visually inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack.

(3) As a result of the actions required by paragraph (g)(2) of this emergency AD, if there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. If there is not a crack, within 15 hours time-in-service (TIS) or 3 months, whichever occurs first after accomplishing the actions required by paragraph (g)(1) of this emergency AD, use high-frequency eddy current (HFEC) to inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard.

(4) As a result of the actions required by paragraph (g)(3) of this emergency AD, if there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. If there is not a crack, before further flight, chemically strip and fluorescent penetrant inspect (FPI) the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for corrosion.

(i) If there is corrosion as a result of the actions required by the introductory text of paragraph (g)(4) of this emergency AD, before further flight, accomplish the actions required by paragraph (g)(4)(i)(A) or (B) of this emergency AD.

(A) Remove the corrosion by hand using 120-grit abrasive cloth, followed by 400-grit abrasive cloth. After removing the corrosion, perform an FPI of each affected area to inspect for corrosion, and accomplish the actions required by paragraph (g)(4)(i)(A)(1) or (2) of this emergency AD.

(1) If there is corrosion, before further flight, remove the MRH sleeve from service and replace it with an airworthy part or repair it in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters’ EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If there is no corrosion, before further flight, completely dry the MRH sleeve and apply a protective coating, primer, and paint protection. Following application, within 15 hours TIS and thereafter at intervals not to exceed 15 hours TIS, use HFEC to inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard. If there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. Accomplishment of the HFEC inspections with no detected cracks after 75 hours TIS since applying the coating, primer, and paint protection constitutes a terminating action for the repetitive inspections required by this paragraph.

(B) If the corrosion cannot be removed by hand as specified in paragraph (g)(4)(i)(A) of this emergency AD, before further flight, remove the MRH sleeve from service and replace it with an airworthy part or repair it in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters’ EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(ii) If there is no corrosion as a result of the actions required by the introductory text of paragraph (g)(4) of this emergency AD, before further flight, apply primer and paint protection.

(5) As an option to the actions required by paragraph (g)(4) of this emergency AD, if there is not a crack, accomplish the actions required by paragraphs (g)(5)(i) and (ii) of this emergency AD.

(i) Before further flight, apply primer and paint protection. If there is any area with flaking paint, you may apply only varnish instead of primer and paint protection on each flaking paint area.

(ii) Within 15 hours TIS after accomplishing the actions required by paragraph (g)(5)(i) of this emergency AD and thereafter at intervals not to exceed 15 hours TIS, HFEC inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard. If there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part.

(6) As of the effective date of this emergency AD, do not install an MRH sleeve identified in paragraph (c) of this emergency AD on any helicopter unless the actions required by paragraphs (g)(1) and (2) of this emergency AD have been accomplished.

(h) Special Flight Permits

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 provided that there are no passengers onboard and there is no crack or corrosion in an MRH sleeve.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this emergency AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this emergency AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this emergency AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

(2) For service information identified in this emergency AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this emergency AD is addressed in European Union Aviation Safety Agency (EASA) Emergency AD 2022-0130-E, dated June 30, 2022.

Issued on July 1, 2022.

Ross Landes, Deputy Director for Regulatory Operations,
Compliance & Airworthiness Division,
Aircraft Certification Service.