

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2022-16

7/18/2022 - 7/31/2022



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

Biweekly 2022-01

| | | | |
|------------|--------------|-----------------------------|--|
| 2021-05-03 | | Airbus Helicopters | EC225LP |
| 2021-23-01 | | Stemme AG | Stemme S 12 |
| 2021-23-06 | | Various Manufactures | 234; CH-47D |
| 2021-24-18 | | Viking Air Limited | DHC-3 |
| 2021-24-19 | | Flugzeugbau GmbH | DG-500MB and DG-1000M |
| 2021-24-21 | | Embraer S.A. | EMB-500 and EMB-505 |
| 2021-24-22 | R 2012-06-16 | Pilatus Aircraft Ltd. | PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 |
| 2021-25-01 | | Leonardo S.p.a. | A109S and AW109SP |
| 2021-25-08 | | Leonardo S.p.a. | AW189 |
| 2021-25-10 | | Daher Aerospace | TBM 700 |
| 2021-25-11 | R 78-02-03 | Piper Aircraft, Inc. | PA-23-250 |
| 2021-26-07 | R 2020-11-05 | Airbus Helicopters | EC120B |
| 2021-26-08 | | Bell Textron Canada Limited | 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4 |
| 2022-01-05 | R 2021-24-06 | Airbus Helicopters | EC130T2 |

Biweekly 2022-02

| | | | |
|------------|--------------|-------------------------------|---|
| 2021-26-14 | R 2018-11-01 | Airbus Helicopters | AS332L2, EC225LP |
| 2021-26-15 | | Vulcanair S.p.A. | P.68C, P.68C-TC, P.68 "OBSERVER," P.68 OBSERVER 2, P.68R, and P.68TC OBSERVER |
| 2021-26-18 | R 2020-21-01 | Airbus Helicopters | AS-365N2, AS 365 N3, and SA-365N1; SA-365C1, SA-365C2, and SA-365N; EC 155B and EC155B1 |
| 2022-01-06 | | Cameron Balloons Ltd. | flange adapter |
| 2022-01-09 | | Stemme AG | Stemme S 10-VT and Stemme S 12 |
| 2022-02-01 | | Sikorsky Aircraft Corporation | S-92A |
| 2022-02-02 | R 2021-15-51 | Bell Textron Inc. | 204B, 205A, 205A-1, 205B, 210, and 212 |

Biweekly 2022-03

| | | | |
|------------|--------------|---|--|
| 2021-26-12 | | Stemme AG | Stemme S 12 |
| 2021-26-16 | | Various Restricted Category Helicopters | UH-1H |
| 2021-26-21 | | Pilatus Aircraft Ltd. | PC-24 |
| 2021-26-24 | | Leonardo S.p.a. | A109A and A109A II |
| 2021-26-25 | | Schempp-Hirth Flugzeugbau GmbH | Duo Discus; Duo Discus T |
| 2021-26-26 | R 2005-12-08 | Safran Helicopter Engines, S.A. | Arrius 2B1, Arrius 2B1A, and Arrius 2B2 |
| 2021-26-29 | | Leonardo S.p.a. | AW169 |
| 2022-02-17 | | Airbus Helicopters Deutschland GmbH | MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 |
| 2022-03-03 | R 2021-22-20 | Austro Engine GmbH | E4 and E4P |
| 2022-03-07 | | Stemme AG | S6 and S6-RT |

Biweekly 2022-04

| | | | |
|------------|---------------------|-------------------------------------|---|
| 2022-01-01 | | Airbus Helicopters | AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2; AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP; SA-365C1, SA-365C2, SA-365N, SA-365N1, AS-365N2, and AS 365 N3 |
| 2022-01-03 | | Umlaut Engineering GmbH | hand-held P3HAFEX fire extinguisher |
| 2022-02-02 | COR R 2021-15-51 | Bell Textron Inc. | 204B, 205A, 205A-1, 205B, 210, and 212 |
| 2022-02-04 | | Airbus Helicopters | AS350B, AS350B2, AS350B3, and AS350BA |
| 2022-02-06 | | Airbus Helicopters | EC120B |
| 2022-02-08 | | Leonardo S.p.a. | AB412 and AB412 EP |
| 2022-02-12 | | Leonardo S.p.a. | AB139 and AW139 |
| 2022-02-13 | | Airbus Helicopters | EC120B |
| 2022-02-19 | | Airbus Helicopters Deutschland GmbH | EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 |
| 2022-02-20 | | Airbus Helicopters Deutschland GmbH | MBB-BK 117 C-2 and MBB-BK 117 D-2 |
| 2022-03-01 | | Diamond Aircraft Industries GmbH | DA 42 NG; DA 42, and DA 42 M-NG |

| | | | |
|--|---|---|---|
| 2022-03-04 | R 80-13-10 R 80-13-12 R1 R 2008-03-01 | Viking Air Limited | DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 |
| 2022-03-08 | | Fiberglas-Technik Rudolf Lindner GmbH & Co. KG | G102 ASTIR CS; G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, G103 C TWIN III ACRO, and G103 C TWIN III SL |
| 2022-03-09 2022-03-23 | A 2020-08-02 | Sikorsky Aircraft Corporation Textron Aviation Inc. | S-76D 300, 300LW, B300, and B300C |
| Biweekly 2022-05 | | | |
| 2022-03-13 2022-03-15 2022-03-17 2022-03-18 | R 2014-21-03 | Airbus Helicopters Various Airplanes Airbus Helicopters British Aerospace (Operations) Limited and British Aerospace Regional Aircraft | AS332L2 Garmin G3X Touch Electronic Flight Instrument System AS332L2 and EC225LP Jetstream Series 200, Jetstream Model 3101, and Jetstream Model 3201 |
| 2022-04-01 | | DG Flugzeugbau GmbH and Schempp-Hirth Flugzeugbau GmbH | DG-1000T and Duo Discus T |
| 2022-04-04 | | Continental Aerospace Technologies, Inc. and Continental Motors | C-125-1, C-125-2, C145-2, C145-2H, IO-360-C, IO-360-D, IO-360-DB, IO-360-H, IO-360-HB, IO-360-K, IO-360-KB, IO-470-E, IO-470-S, IO-550-B, IO-550-G, O-300-B, O-300-C, O-300-D, O-300-E, O-470-A, O-470-B, O-470-G, O-470-J, O-470-K, O-470-L, O-470-M, O-470-N, O-470-R, O-470-S, O-470-U, O-470-11, O-470-15, TSIO-360-E, TSIO-360-EB, TSIO-360-F, TSIO-360-FB, TSIO-360-GB, TSIO-360-LB, TSIO-360-MB, TSIO-360-SB, TSIO-520-C, TSIO-520-CE, TSIO-520-E, and TSIO-520-UB |
| 2022-05-01 2022-05-02 | R 2021-11-25 | Learjet, Inc. Airbus Helicopters | 35, 35A (C-21A), 36, 36A, 55, 55B, 55C, and 60 AS350B3 and EC130T2 |
| Biweekly 2022-06 | | | |
| 2022-04-06 2022-04-09 2022-05-05 | R 2021-06-06 | Bell Textron Canada Limited AVOX Systems Inc. Schempp-Hirth Flugzeugbau GmbH | 505 oxygen cylinder Ventus-2a and Ventus-2b |
| 2022-05-11 2022-05-12 2022-05-14 | R 2020-12-08 | Viking Air Limited Embraer S.A. GROB Aircraft SE | DHC-3 EMB-505 G 115EG |
| Biweekly 2022-07 | | | |
| 2021-03-16R1 | R 2021-03-16 | Airbus Helicopters | AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP |
| 2022-05-10 | | Goodrich Externally-Mounted Hoist Assemblies | hoist assembly |
| 2022-05-13 2022-06-01 | | Honda Aircraft Company LLC Airbus Helicopters Deutschland GmbH | HA-420 MBB-BK 117 D-3 |
| 2022-06-03 2022-06-05 | R 2022-02-02 R 2021-15-52 | Bell Textron Inc. Various Restricted Category Helicopters | 204B, 205A, 205A-1, 205B, 210, and 212 Various Models |
| 2022-06-13 | | Airbus Helicopters Deutschland GmbH | MBB-BK 117 C-2 and MBB-BK 117 D-2 |
| 2022-06-20 2022-07-03 2022-07-05 | R 2020-20-06 R 2022-05-09 | Bell Textron Canada Limited Bell Textron Inc. MARS A.S. | 429 412, 412EP, and 412CF ATL-88/90-1B |
| Biweekly 2022-08 | | | |
| 2022-06-04 | | Schempp-Hirth Flugzeugbau GmbH | Janus, Mini-Nimbus HS-7, Nimbus-2, and Standard Cirrus |
| 2022-06-08 | R 2017-18-10 | Diamond Aircraft Industries GmbH | DA 42, DA 42 M-NG, and DA 42 NG |
| 2022-06-12 2022-06-17 2022-06-19 2022-07-01 2022-07-02 | R 2020-23-07 | Airbus Helicopters Airbus Helicopters Leonardo S.p.a. Leonardo S.p.a. Bell Textron Inc. | SA330J EC130T2 AW109SP AB139 and AW139 205A and 205A-1; 205B; 210; 212i; 412 and 412EP; 412CF |

| | | | |
|-------------------------|---------------------------------|--|---|
| 2022-07-04 | | Pilatus Aircraft Ltd. | PC-12/47E |
| 2022-07-09 | | Airbus Helicopters | AS332L2 and EC225LP |
| 2022-07-11 | R 2021-17-18 | Leonardo S.p.a. | A109C, A109K2, A109E, A109S, and AW109SP |
| 2022-07-12 | R 2021-02-20 | Hélicoptères Guimbal | Cabri G2 |
| 2022-07-14 | | Viking Air Limited | DHC-6-400 |
| Biweekly 2022-09 | | | |
| 2022-08-01 | R 2020-22-01 | Airbus Helicopters | AS332C, AS332C1, AS332L, and AS332L1 |
| 2022-08-02 | | Airbus Helicopters | EC 155B and EC155B1 |
| 2022-08-03 | | Textron Aviation Inc. | 120 and 140; 140A |
| 2022-08-10 | R 2020-12-07 | Hamilton Sundstrand Corporation | 54H |
| 2022-08-11 | | Bell Textron Canada Limited | 429 |
| 2022-08-13 | | Pratt & Whitney Canada Corp. | PT6A-34, -34B, -34AG, -114, and -114A |
| 2022-08-15 | | Airbus Helicopters Deutschland GmbH | MBB-BK 117 C-2 |
| Biweekly 2022-10 | | | |
| 2022-09-04 | R 2021-05-05 | Airbus Helicopters | SA-365N1, AS-365N2, AS 365 N3, SA-366G1, EC 155B, and EC155B1 |
| 2022-09-07 | R 2019-11-05 A 2020-17-10 | Bell Textron Canada Limited | 429 |
| 2022-09-13 | | Piper Aircraft, Inc. | PA-34-200 |
| 2022-09-17 | | Scheibe-Aircraft-GmbH | SF 25 C |
| 2022-10-51 | E | Airbus Helicopters; Airbus Helicopters Deutschland GmbH | AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 |
| Biweekly 2022-11 | | | |
| 2022-08-09 | | Pilatus Aircraft Ltd. | PC-24 |
| 2022-10-01 | | Pilatus Aircraft Ltd. | PC-12/47E |
| 2022-10-03 | | Viking Air Limited | DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 |
| 2022-10-07 | R 89-24-06 R1 | Viking Air Limited | DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 |
| Biweekly 2022-12 | | | |
| 2022-10-02 | R 2002-03-01 | Honeywell International Inc. | T5311A, T5311B, T5313B, T5317A, T5317A-1, T5317B, T5317BCV, and former military T53-L-11, T53-L-11A, T53-L-11B, T53-L-11C, T53-L-11D, T53-L-11A S/SA, T53-L-13B, T53-L-13B S/SA, T53-L-13B S/SB, and T53-L-703 |
| 2022-10-06 | R 2017-18-14 | Rolls-Royce Corporation | 250-C20, 250-C20B, 250-C20C (T63-A-720), 250-C20F, 250-C20J, 250-C20R, 250-C20R/1, 250-C20R/2, 250-C20R/4, 250-C20W, 250-C300/A1, and 250-C300/B1 |
| 2022-10-09 | | Airbus Helicopters | SA-365C1 and SA-365C2 |
| 2022-10-51 | E | Airbus Helicopters and Airbus Helicopters Deutschland GmbH | AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2; EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 |
| 2022-11-04 | R 2020-26-13 | Sikorsky Aircraft Corporation | S-92A |
| 2022-11-06 | | Leonardo S.p.a. | A109S |
| 2022-11-07 | | Airbus Helicopters Deutschland GmbH | MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2, and MBB-BK117 D-2 |
| 2022-11-08 | A 2011-22-05 R1 A 2016-25-20 | Airbus Helicopters | AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350D, EC130B4, and EC130T2 |
| 2022-11-09 | | Viking Air Limited | DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 |
| 2022-11-10 | | Piper Aircraft, Inc. | PA-46-600TP |
| 2022-11-19 | | Bell Textron Inc. | 212, 412, 412CF, and 412EP |

Biweekly 2022-13

| | | | |
|------------|--------------|--|--|
| 2022-11-12 | | Viking Air Limited | DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 |
| 2022-11-16 | | British Aerospace (Operations) Limited and British Aerospace Regional Aircraft | Jetstream Model 3101; Jetstream Model 3201 |
| 2022-11-18 | | Airbus Helicopters | AS355E, AS355F, AS355F1, AS355F2, AS-365N2, AS 365 N3, SA-365N, SA-365N1, EC 155B, and EC155B1 |
| 2022-12-06 | | Costruzioni Aeronautiche Tecnam S.P.A. | P2012 Traveller |
| 2022-12-07 | R 75-23-03 | Alexander Schleicher GmbH & Co. Segelflugzeugbau | Ka2B, Ka 6, Ka 6 B, Ka 6 BR, Ka 6 C, Ka 6 CR, K 7, K 8, K 8 B, and AS-K 13 |
| 2022-12-08 | | Robinson Helicopter Company | R22 BETA; R44; R44 II |
| 2022-12-09 | R 2017-15-06 | British Aerospace (Operations) Limited and British Aerospace Regional Aircraft | HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Model 3101; Jetstream Model 3201 |
| 2022-13-01 | | Leonardo S.p.a | AW169 |
| 2022-13-03 | | Cameron Balloons Ltd. | fuel cylinder |

Biweekly 2022-14

| | | | |
|------------|---|--------------------------------|-------------------------------------|
| 2022-11-20 | | Leonardo S.p.a. | AB139 and AW139 |
| 2022-13-07 | | AutoGyro Certification Limited | Calidus, Cavalon, and MTOsport 2017 |
| 2022-13-16 | | Aviation Czech s.r.o | M601D-11 |
| 2022-14-51 | E | Airbus Helicopters | EC225LP |

Biweekly 2022-15

| | | | |
|------------|--|------------------------------------|--|
| 2022-13-06 | | Diamond Aircraft Industries Inc. | DA 40, DA 40 F, and DA 40 NG |
| 2022-13-14 | | Airbus Helicopters | AS-365N2, AS 365 N3, EC 155B, EC155B1, and SA-365N1 |
| 2022-13-15 | | Williams International Co., L.L.C. | FJ44-2A, FJ44-2C, FJ44-3A, and FJ44-3A-24 |
| 2022-14-03 | | Leonardo S.p.a. | AB412 and AB412 EP |
| 2022-14-11 | | Stemme AG | Stemme S 12 |
| 2022-14-12 | | GE Aviation Czech s.r.o. | M601F; M601E-11 and M601E-11A; M601D-11, M601E-11AS, and M601E-11S |

Biweekly 2022-16

| | | | |
|------------|--|--|-----------------------|
| 2022-14-14 | | Alexander Schleicher GmbH & Co. Segelflugzeugbau | ASW-15 |
| 2022-14-51 | | Airbus Helicopters | EC225LP |
| 2022-15-02 | | Cameron Balloons Ltd. | Stratus double burner |
| 2022-16-03 | | Continental Aerospace Technologies, Inc., Lycoming Engines, and Textron Lycoming/Subsidiary of Textron, Inc. Reciprocating Engines | Various Engine Models |



**FAA
Aviation Safety**

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2022-14-14 Alexander Schleicher GmbH & Co. Segelflugzeugbau: Amendment 39-22119; Docket No. FAA-2022-0288; Project Identifier MCAI-2021-00913-G.

(a) Effective Date

This airworthiness directive (AD) is effective August 25, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Alexander Schleicher GmbH & Co. Segelflugzeugbau Model ASW-15 gliders, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5712, Wing, Rib/Bulkhead.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as wing root rib damage. The FAA is issuing this AD to detect and correct damaged root ribs. The unsafe condition, if not addressed, could result in reduced structural integrity of the wing assembly, which could lead to loss of control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Action

(1) Within 30 days after the effective date of this AD and thereafter at intervals not to exceed 12 months, inspect all wing root ribs (4 places) for cracks, looseness, and damage, in accordance with the Action section in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Maintenance Instruction G, Issue 1, dated June 28, 2021. If there is a crack in any root rib, a loose rib or lift pin bushing, or any damage, before further flight, replace the root rib in accordance with Action paragraph (B) in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Technical Note No. 29, dated June 28, 2021, and steps 1 through 7 in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Repair instruction exchange of wing root ribs according to TN 29, dated June 28, 2021.

(2) Replacing all four wing root ribs is terminating action for the repetitive inspections required by this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0187, dated August 9, 2021, for more information. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2022-0288.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Maintenance Instruction G, Issue 1, dated June 28, 2021.

(ii) Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Repair instruction exchange of wing root ribs according to TN 29, dated June 28, 2021.

(iii) Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Technical Note No. 29, dated June 28, 2021.

(3) For service information identified in this AD, contact Alexander Schleicher GmbH & Co. Segelflugzeugbau, Alexander-Schleicher-Str. 1, Poppenhausen, Germany D-36163; phone: +49 (0) 06658 89-0; email: info@alexander-schleicher.de; website: <https://www.alexander-schleicher.de>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 1, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-15419 Filed 7-20-22; 8:45 am]



2022-14-51 Airbus Helicopters: Amendment 39-22124; Docket No. FAA-2022-0878; Project Identifier MCAI-2022-00873-R.

(a) Effective Date

The FAA issued Emergency Airworthiness Directive (AD) 2022-14-51 on July 1, 2022, directly to affected owners and operators. As a result of such actual notice, that AD was effective for those owners and operators on the date it was provided. This AD contains the same requirements as that emergency AD and, for those who did not receive actual notice, is effective on August 3, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model EC225LP helicopters, certificated in any category, with main rotor hub (MRH) sleeve part number 332A31-3071-00 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

(e) Unsafe Condition

This AD was prompted by a report of a cracked MRH sleeve. The FAA is issuing this AD to detect corrosion or cracking in an MRH sleeve. The unsafe condition, if not addressed, could result in failure of an MRH sleeve, loss of a main rotor blade, and subsequent loss of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before further flight after the effective date of this AD, visually inspect the “Specific area” of each MRH sleeve as depicted in Figure 3 of Airbus Helicopters Emergency Alert Service Bulletin No. 62A017, Revision 0, dated June 30, 2022 (ASB 62A017), for flaking and paint touch-up.

(2) As a result of the actions required by paragraph (g)(1) of this AD, if there is no flaking or paint touch-up, no further action is required. If there is any flaking or paint touch-up, before further flight, visually inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack.

(3) As a result of the actions required by paragraph (g)(2) of this AD, if there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. If there is

not a crack, within 15 hours time-in-service (TIS) or 3 months, whichever occurs first after accomplishing the actions required by paragraph (g)(1) of this AD, use high-frequency eddy current (HFEC) to inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard.

(4) As a result of the actions required by paragraph (g)(3) of this AD, if there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. If there is not a crack, before further flight, chemically strip and fluorescent penetrant inspect (FPI) the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for corrosion.

(i) If there is corrosion as a result of the actions required by the introductory text of paragraph (g)(4) of this AD, before further flight, accomplish the actions required by paragraph (g)(4)(i)(A) or (B) of this AD.

(A) Remove the corrosion by hand using 120-grit abrasive cloth, followed by 400-grit abrasive cloth. After removing the corrosion, perform an FPI of each affected area to inspect for corrosion, and accomplish the actions required by paragraph (g)(4)(i)(A)(1) or (2) of this AD.

(1) If there is corrosion, before further flight, remove the MRH sleeve from service and replace it with an airworthy part or repair it in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or European Union Aviation Safety Agency (EASA); or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If there is no corrosion, before further flight, completely dry the MRH sleeve and apply a protective coating, primer, and paint protection. Following application, within 15 hours TIS and thereafter at intervals not to exceed 15 hours TIS, use HFEC to inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard. If there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part. Accomplishment of the HFEC inspections with no detected cracks after 75 hours TIS since applying the coating, primer, and paint protection constitutes a terminating action for the repetitive inspections required by this paragraph.

(B) If the corrosion cannot be removed by hand as specified in paragraph (g)(4)(i)(A) of this AD, before further flight, remove the MRH sleeve from service and replace it with an airworthy part or repair it in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(ii) If there is no corrosion as a result of the actions required by the introductory text of paragraph (g)(4) of this AD, before further flight, apply primer and paint protection.

(5) As an option to the actions required by paragraph (g)(4) of this AD, if there is not a crack, accomplish the actions required by paragraphs (g)(5)(i) and (ii) of this AD.

(i) Before further flight, apply primer and paint protection. If there is any area with flaking paint, you may apply only varnish instead of primer and paint protection on each flaking paint area.

(ii) Within 15 hours TIS after accomplishing the actions required by paragraph (g)(5)(i) of this AD and thereafter at intervals not to exceed 15 hours TIS, HFEC inspect the “Specific area” of the MRH sleeve as depicted in Figure 3 of ASB 62A017 for a crack. This HFEC inspection must be accomplished by a Level II or III inspector certified in the eddy current fault detection method in the Aeronautics Sector according to the EN4179 or NAS410 standard. If there is a crack, before further flight, remove the MRH sleeve from service and replace it with an airworthy part.

(6) As of the effective date of this AD, do not install an MRH sleeve identified in paragraph (c) of this AD on any helicopter unless the actions required by paragraphs (g)(1) and (2) of this AD have been accomplished.

(h) Special Flight Permits

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 provided that there are no passengers onboard and there is no crack or corrosion in an MRH sleeve.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

(2) The subject of this AD is addressed in EASA Emergency AD 2022-0130-E, dated June 30, 2022. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2022-0878.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin No. 62A017, Revision 0, dated June 30, 2022.

(ii) [Reserved]

(3) For Airbus Helicopters service information identified in this AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 8, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-15387 Filed 7-14-22; 4:15 pm]



2022-15-02 Cameron Balloons Ltd.: Amendment 39-22121; Docket No. FAA-2022-0469; Project Identifier MCAI-2021-00124-Q.

(a) Effective Date

This airworthiness directive (AD) is effective August 25, 2022.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to hot air balloons, certificated in any category, with a Cameron Balloons Ltd. Stratus double burner assembly part number (P/N) CB8720 or P/N CB8721 installed.

(2) The affected burner assemblies may be installed on hot air balloon models including, but not limited to, those of the following design approval holders:

- (i) Aerostar International, Inc.;
- (ii) Ballonbau Worner GmbH;
- (iii) Balóny Kubíček spol. s.r.o.;
- (iv) Cameron Balloons Ltd.;
- (v) Eagle Balloons Corp.;
- (vi) JR Aerosports, Ltd (type certificate previously held by Sundance Balloons (US));
- (vii) Lindstrand Balloons Ltd.; and
- (viii) Michael D. McGrath (type certificate subsequently transferred to Andrew Philip Richardson, Adams Aerostats LLC).

(d) Subject

Joint Aircraft System Component (JASC) Code 7100, Powerplant System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as suspected fatigue cracking of the weld on affected burner hangers. The FAA is issuing this AD to prevent burners from separating from the balloon. The unsafe condition, if not addressed, could result in an uncontrolled cold descent and hard landing of the balloon.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For purposes of this AD, an “affected part A” is a Stratus double burner hanger P/N CB8504, Issue A, Issue B, or Issue C, except those installed on a Stratus double burner P/N CB8720 or P/N CB8721 with a doubler plate reinforcing the central part of the hanger bracket, as shown in figure 2 of Cameron Balloons Service Bulletin 28, Revision 3, dated February 3, 2021.

(2) For purposes of this AD, an “affected part B” is a Stratus double burner P/N CB8720 or P/N CB8721 with a doubler plate reinforcing the central part of the hanger bracket, as shown in figure 2 of Cameron Balloons Service Bulletin 28, Revision 3, dated February 3, 2021.

(3) For purposes of this AD, a “serviceable part” is a Stratus double burner hanger P/N CB8504, Issue D or later.

(h) Actions

(1) Within 10 hours time-in-service (TIS) or 30 days, whichever occurs first after the effective date of this AD, inspect the weld of each affected part A for cracks in accordance with paragraphs 3.1.2 through 3.1.4 and Figure 6 of Cameron Balloons SB28: Accomplishment Instructions, Stratus Double Burner; Mounting Hanger Inspection, CBL/TN/DCB/3191, Issue B, dated February 4, 2020.

(i) If there are no cracks, repeat the inspection in paragraph (h)(1) of this AD at intervals not to exceed 12 months.

(ii) If there is a crack, before further flight, remove the affected part A from service and install a serviceable part. Installation of a serviceable part on a Stratus double burner assembly constitutes terminating action for the repetitive inspections required by paragraph (h)(1) of this AD for that Stratus double burner assembly.

(2) Within 30 days or 10 hours TIS, whichever occurs first after the effective date of this AD, remove each affected part B from service and install a serviceable part.

(3) As of the effective date of this AD, do not install on any hot air balloon an affected part A.

(4) As of the effective date of this AD, do not install on any hot air balloon an affected part B, unless it is equipped with a serviceable part.

(i) Credit for Previous Actions

You may take credit for the initial inspection required by paragraph (h)(1) of this AD if you performed the inspection before the effective date of this AD using Cameron Balloons Service Bulletin 28, Revision 2, dated March 4, 2020; or Revision 3, dated February 3, 2021.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(2) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0042, dated January 29, 2021, for related information. This EASA AD may be found in the AD docket at <https://www.regulations.gov> under Docket No. FAA-2022-0469.

(2) For more information about this AD, contact Mike Kiesov, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4144; email: mike.kiesov@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Cameron Balloons SB28: Accomplishment Instructions, Stratus Double Burner; Mounting Hanger Inspection, CBL/TN/DCB/3191, Issue B, dated February 4, 2020.

(ii) Cameron Balloons Service Bulletin 28, Revision 3, dated February 3, 2021.

Note 1 to paragraph (l)(2)(ii): The document date is identified only on the first page of this document.

(3) For service information identified in this AD, contact Cameron Balloons Ltd., St. Johns Street, Bedminster, Bristol, BS3 4NH, United Kingdom; phone: +44 0 117 9637216; email: technical@cameronballoons.co.uk; website: <https://www.cameronballoons.co.uk>.

(4) You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on July 7, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-15421 Filed 7-20-22; 8:45 am]



2022-16-03 Continental Aerospace Technologies, Inc., Lycoming Engines, and Textron Lycoming/Subsidiary of Textron, Inc. Reciprocating Engines: Amendment 39-22132; Docket No. FAA-2022-0983; Project Identifier AD-2022-00614-E.

(a) Effective Date

This airworthiness directive (AD) is effective August 15, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to:

(1) Continental Aerospace Technologies, Inc. reciprocating engine models identified in Table 1 to paragraph (c) of this AD that are equipped with an S-1200 series magneto having a serial number (S/N) between F21EA057 and F21KA009R, inclusive, manufactured and sold between May and November 2021; and

(2) Lycoming Engines and Textron Lycoming/Subsidiary of Textron, Inc. reciprocating engine models identified in Table 2 to paragraph (c) of this AD that are equipped with an S-1200 series magneto authorized by Continental Aerospace Technologies, Inc. Parts Manufacturer Approval (PMA) Supplements 1-54, having an S/N between F21EA057 and F21KA009R, inclusive, manufactured and sold between May and November 2021.

Table 1 to Paragraph (c) – Continental Aerospace Technologies, Inc. Reciprocating Engine Models

| Make | Model |
|--|--|
| Continental Aerospace Technologies, Inc. | GTSIO-520-C, GTSIO-520-D, GTSIO-520-F, GTSIO-520-H, GTSIO-520-K, GTSIO-520-L, GTSIO-520-M, GTSIO-520-N, IO-346-A, IO-470-C, IO-470-D, IO-470-E, IO-470-F, IO-470-G, IO-470-H, IO-470-J, IO-470-K, IO-470-L, IO-470-M, IO-470-N, IO-470-P, IO-470-R, IO-470-S, IO-470-U, IO-470-V, IO-470-VO, IO-520-A, IO-520-B, IO-520-BA, IO-520-BB, IO-520-C, IO-520-CB, IO-520-D, IO-520-E, IO-520-F, IO-520-J, IO-520-K, IO-520-L, IO-520-P, IO-550-B, IO-550-C, IO-550-D, IO-550-E, IO-550-F, IO-550-L, LTSIO-520-AE, O-470-B, O-470-E, O-470-G, O-470-J, O-470-K, O-470-L, O-470-M, O-470-R, O-470-S, O-470-U, TSIO-520-A, TSIO-520-AE, TSIO-520-AF, TSIO-520-B, TSIO-520-BB, TSIO-520-C, TSIO-520-CE, TSIO-520-DB, TSIO-520-G, TSIO-520-H, TSIO-520-KB, TSIO-520-LB, TSIO-520-M, TSIO-520-NB, TSIO-520-P, TSIO-520-R, TSIO-520-T, TSIO-520-UB, TSIO-520-VB, TSIO-520-WB, TSIOL-550-A, TSIOL-550-B, TSIOL-550-C |

Table 2 to Paragraph (c) – Lycoming Engines and Textron Lycoming Reciprocating Engine Models

| Make | Model |
|--|--|
| Lycoming Engines | AEIO-320-D1B, AEIO-320-D2B, AEIO-360-A1B, AEIO-360-A1B6, AEIO-360-A2B, AEIO-360-B1F, AEIO-360-B2F, AEIO-360-B2F6, AEIO-540-D4B5, AIO-320-A1A, AIO-320-A1B, AIO-320-A2A, AIO-320-A2B, AIO-320-B1B, AIO-320-C1B, AIO-360-A1A, AIO-360-A1B, AIO-360-A2A, AIO-360-A2B, AIO-360-B1B, GO-480-G1J6, GSO-480-B1J6, HIO-360-C1B, HIO-360-D1A, HIO-540-A1A, IGO-480-A1A6, IGO-540-A1C, IGSO-480-A1G6, IGSO-540-A1A, IGSO-540-A1C, IGSO-540-A1D, IGSO-540-A1E, IGSO-540-A1F, IGSO-540-A1H, IGSO-540-B1A, IGSO-540-B1C, IO-320-B1D, IO-320-B1E, IO-320-D1A, IO-320-D1B, IO-320-D1C, IO-360-A1B, IO-360-A1B6, IO-360-A1C, IO-360-A1D6, IO-360-A2B, IO-360-A2C, IO-360-B1E, IO-360-B1F, IO-360-B2E, IO-360-B2F, IO-360-B2F6, IO-360-C1B, IO-360-C1C, IO-360-C1C6, IO-360-C1D6, IO-360-C1E6, IO-360-C1F, IO-360-D1A, IO-360-E1A, IO-360-F1A, IO-540-B1A5, IO-540-D4B5, IO-540-D4C5, IO-540-E1B5, IO-540-E1C5, IO-540-G1B5, IO-540-G1C5, IO-540-G1D5, IO-540-G1E5, IO-540-G1F5, IO-540-J4A5, IO-540-K1A5, IO-540-K1B5, IO-540-K1C5, IO-540-K1D5, IO-540-K1E5, IO-540-K1F5, IO-540-K1G5, IO-540-K1H5, IO-540-K1J5, IO-540-K1K5, IO-540-L1A5, IO-540-L1C5, IO-540-M1A5, IO-540-M1C5, IO-540-P1A5, IO-540-R1A5, IO-540-S1A5, IO-540-T4B5, IO-540-W1A5, IO-540-AA1A5, LIO-360-C1E6, LTIO-540-J2B, LTIO-540-U2A, LTIO-540-W2A, O-235-C2B, O-235-E2B, O-235-F2B, O-235-G2B, O-235-J2B, O-235-K2B, O-320-D1C, O-320-D1F, O-320-D2C, O-320-D2F, O-320-E1C, O-320-E1F, O-320-E1J, O-320-E2C, O-320-E2F, O-360-A1F, O-360-A1F6, O-360-A1G, O-360-A1G6, O-360-A2F, O-360-A2G, O-360-A4G, O-360-C1F, O-540-B1D5, O-540-B2C5, O-540-E4C5, O-540-G1A5, O-540-G2A5, TIGO-541-B1A, TIGO-541-C1A, TIGO-541-D1A, TIGO-541-D1B, TIGO-541-E1A, TIO-360-A1A, TIO-360-A1B, TIO-540-A1A, TIO-540-A1B, TIO-540-A1C, TIO-540-A2A, TIO-540-A2B, TIO-540-A2C, TIO-540-C1A, TIO-540-E1A, TIO-540-G1A, TIO-540-H1A, TIO-540-J2B, TIO-540-U2A, TIO-540-W2A, TIO-541-A1A, TIO-541-E1A4, TIO-541-E1B4, TIO-541-E1C4, TIO-541-E1D4, TVO-435-B1B, TVO-435-D1A, TVO-435-F1A, TVO-435-G1A, VO-435-B1A, VO-540-B1H3, VO-540-B2G, VO-540-C2C |
| Textron Lycoming/Subsidiary of Textron, Inc. | IO-720-A1B, IO-720-B1B, IO-720-C1B |

(d) Subject

Joint Aircraft System Component (JASC) Code 8500, Engine (RECIPROCATING).

(e) Unsafe Condition

This AD was prompted by a report of a manufacturing quality escape of improperly lubricated roller bearings installed in certain magnetos, which may result in overheating and magneto seizure. The FAA is issuing this AD to prevent failure of the magneto. The unsafe condition, if not addressed, could result in failure of one or more engines, in-flight shutdown, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

For any affected magneto, within 25 operating hours time-in-service (TIS) or, if any affected magneto has accumulated more than 25 operating hours TIS, before further flight after the effective date of this AD:

(1) Remove the affected magneto from the engine and replace with a part eligible for installation in accordance with the Corrective Action, paragraph III.A., of Continental Aerospace Technologies Critical Service Bulletin CSB673, Revision C, dated May 24, 2022 (the CSB); or

(2) Remove the affected magneto from the engine and disassemble and inspect the affected magneto in accordance with the Corrective Action, paragraphs III.B.1. through III.B.8.a., of the CSB.

(i) If, during the inspection required by paragraph (g)(2) of this AD, no white grease is detected, before further flight, inspect and replace the magneto components, as applicable, in accordance with the Corrective Action, paragraphs III.B.8.b.1 and III.B.8.b.2, of the CSB. Where the CSB specifies discarding the roller bearing, this AD instead requires removing the roller bearing from service.

(ii) Reassemble and install the magneto in accordance with the Corrective Action, paragraph III.C., of the CSB.

(h) Installation Prohibition

After the effective date of this AD, do not install onto any engine an S-1200 series magneto having a S/N between F21EA057 and F21KA009R, inclusive, manufactured and sold between May and November 2021; or any S-1200 series magneto authorized by Continental Aerospace Technologies, Inc. PMA Supplements 1-54, having an S/N between F21EA057 and F21KA009R, inclusive, manufactured and sold between May and November 2021, unless the magneto has first undergone corrective action and the data plate has been marked in accordance with the Corrective Action, paragraph III.C.3., of the CSB.

(i) Credit for Previous Actions

You may take credit for actions required by paragraph (g) of this AD if the actions were performed before the effective date of this AD using Continental Aerospace Technologies Critical Service Bulletin CSB673, Revision B, dated April 20, 2022; Continental Ignition Systems Service Bulletin (SB) SB673, Revision A, dated March 8, 2022; or Continental Ignition Systems SB SB673, Original Issue, dated January 31, 2022.

(j) Special Flight Permit

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 to permit a one-time non-revenue ferry flight to a location where this AD can be accomplished. This ferry flight must be performed with only essential flight crew.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Boyce Jones, Aviation Safety Engineer, Atlanta ACO, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5535; email: boyce.jones@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Continental Aerospace Technologies Critical Service Bulletin CSB673, Revision C, dated May 24, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Continental Aerospace Technologies, P.O. Box 90, Mobile, AL 36615; phone: (251) 436-8299; website: www.continental.aero.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 25, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-16371 Filed 7-27-22; 11:15 am]