

FEDERAL AVIATION ADMINISTRATION AIRWORTHINESS DIRECTIVES

**SMALL AIRCRAFT, ROTORCRAFT, GLIDERS
BALLOONS, AIRSHIPS, AND UAS**

BIWEEKLY 2023-09

04/10/2023 - 04/23/2023



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806

Facsimile: (202) 512-2250

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

Biweekly 2023-01

2022-26-01		GE Aviation Czech s.r.o.	M601D-11,M601E-11,M601E-11A,M601E-11AS,M601E-11S,M601F,H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2022-27-03		Leonardo S.p.a.	AB139,AW139
2022-27-08		Bell Textron Canada Limited	407

Biweekly 2023-02

2022-27-09		Airbus Helicopters	EC130T2
2023-01-02		Leonardo S.p.a.	A109,A109A,A109A II,A109C,A109E,A109K2,A109S,AW109SP

Biweekly 2023-03

2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-01-11		Safran Helicopter Engines S.A.	Makila 1A,Makila 1A1
2023-01-12		Safran Helicopter Engines S.A.	Arriel 1C,Arriel 1C1,Arriel 1C2
2023-02-03	R 2022-01-09	Stemme AG	Stemme S 10-VT,Stemme S 12
2023-02-04		Mooney International Corporation	M20C,M20D,M20E,M20F,M20G

Biweekly 2023-04

2023-01-04		Airbus Helicopters	AS350B,AS350BA,AS350B1,AS350B2,AS350B3,AS350D,AS355E,AS355F,AS355F1,AS355F2,AS355N,AS355NP
2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-01-08		Continental Aerospace Technologies GmbH	TAE 125-02-99,TAE 125-02-114
2023-01-10		GE Aviation Czech s.r.o.	M601E-11,M601E-11A,M601E-11AS,M601E-11S,M601F
2023-02-12		Continental Aerospace Technologies Inc.	GTSIO-520-C,GTSIO-520-D,GTSIO-520-E,GTSIO-520-F,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,IO-470-A,IO-470-C,IO-470-D,IO-470-E,IO-470-F,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-LO,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-520-N,IO-520-NB,IO-520-P,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,IOF-550-B,IOF-550-C,IOF-550-D,IOF-550-E,IOF-550-F,IOF-550-L,IOF-550-P,IOF-550-R,LIO-470-A,LIO-520-P,LTSIO-520-AE,O-470-A,O-470-E,O-470-G,O-470-G-CI,O-470-H,O-470-J,O-470-K,O-470-K-CI,O-470-L,O-470-L-CI,O-470-M,O-470-M-CI,O-470-N,O-470-P,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-470-B,TSIO-470-C,

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects			
			TSIO-470-D,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-N,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-U,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIOF-550-D,TSIOF-550-J,TSIOF-550-K,TSIOL-550-A,TSIOL-550-C
2023-03-01		Airbus Helicopters Deutschland GmbH	BO-105A,BO-105C,BO-105S,BO-105LS A-1,BO-105LS A-3,MBB-BK 117 A-1,MBB-BK 117 A-3,MBB-BK 117 A-4,MBB-BK 117 B-1,MBB-BK 117 B-2,MBB-BK 117 C-1,MBB-BK 117 C-2,MBB-BK 117 D-2
2023-03-10		Schempp-Hirth Flugzeugbau GmbH	Duo-Discus,Duo Discus T
Biweekly 2023-05			
2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-02-17		Textron Aviation Inc.	210N,210R,P210N,P210R,T210N,T210R,177,177A,177B,177RG,F177RG
2023-03-02		Pratt & Whitney Canada Corp.	PT6E-67XP
2023-03-03		Leonardo S.p.a.	AB139,AW139
2023-03-12	R 2004-04-09	Pratt & Whitney Canada Corp.	JT15D-1,JT15D-1A,JT15D-1B
2023-03-13		Airbus Helicopters	AS355E,AS355F,AS355F1,AS355F2,AS355N
2023-04-08		Continental Aerospace Technologies, Inc. (Continental®)	GTSIO-520-C,GTSIO-520-D,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,GTSIO-520-S,IO-360-A,IO-360-AB,IO-360-AF,IO-360-C,IO-360-CB,IO-360-D,IO-360-DB,IO-360-E,IO-360-ES,IO-360-G,IO-360-GB,IO-360-H,IO-360-HB,IO-360-J,IO-360-JB,IO-360-K,IO-360-KB,IO-470-D,IO-470-E,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,LTSIO-360-E,LTSIO-360-EB,LTSIO-360-KB,LTSIO-360-RB,LTSIO-520-AE,O-470-A,O-470-B,O-470-E,O-470-G,O-470-H,O-470-J,O-470-K,O-470-L,O-470-M,O-470-N,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-360-A,TSIO-360-AB,TSIO-360-B,TSIO-360-BB,TSIO-360-C,TSIO-360-CB,TSIO-360-D,TSIO-360-DB,

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

TSIO-360-E,TSIO-360-EB,TSIO-360-G,TSIO-360-GB,TSIO-360-H,TSIO-360-HB,TSIO-360-JB,TSIO-360-KB,TSIO-360-LB,TSIO-360-MB,TSIO-360-RB,TSIO-360-SB,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIO-550-N,TSIOF-550-K,TSIOL-550-A,TSIOL-550-B,TSIOL-550-C

Biweekly 2023-06

2023-03-14		Schempp-Hirth Flugzeugbau GmbH	Duo-Discus,Duo Discus T
2023-03-22	R 2015-09-04 R1	DG Flugzeugbau GmbH,Schempp-Hirth Flugzeugbau GmbH	DG-1000T,Duo Discus T
2023-04-20		Cirrus Design Corporation	SF50

Biweekly 2023-07

2023-05-03	R 2022-14-14	Alexander Schleicher GmbH & Co. Segelflugzeugbau	ASW -15,ASW-15B
2023-05-09		Airbus Helicopters Deutschland GmbH	EC135P3,EC135T3,MBB-BK 117 D-2,MBB-BK 117 D-3
2023-05-16	R 2023-04-08	Continental Aerospace Technologies Inc.	GTSIO-520-C,GTSIO-520-D,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,GTSIO-520-S,IO-360-A,IO-360-AB,IO-360-AF,IO-360-C,IO-360-CB,IO-360-D,IO-360-DB,IO-360-E,IO-360-ES,IO-360-G,IO-360-GB,IO-360-H,IO-360-HB,IO-360-J,IO-360-JB,IO-360-K,IO-360-KB,IO-470-A,IO-470-C,IO-470-D,IO-470-E,IO-470-F,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-LO,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,LTSIO-360-E,LTSIO-360-EB,LTSIO-360-KB,LTSIO-360-RB,LTSIO-520-AE,O-470-A,O-470-B,O-470-E,O-470-G,O-470-H,O-470-J,O-470-K,O-470-L,O-470-M,O-470-N,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-360-A,TSIO-360-AB,TSIO-360-B,TSIO-360-BB,TSIO-360-C,TSIO-360-CB,TSIO-360-D,TSIO-360-DB,TSIO-360-E,TSIO-360-EB,TSIO-360-F,TSIO-360-FB,TSIO-360-G,TSIO-360-

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

GB,TSIO-360-H,TSIO-360-HB,TSIO-360-JB,TSIO-360-KB,TSIO-360-LB,TSIO-360-MB,TSIO-360-RB,TSIO-360-SB,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIO-550-N,TSIOF-550-K,TSIOL-550-A,TSIOL-550-B,TSIOL-550-C

2023-06-11

Viking Air Limited

DHC-2 Mk.I

Biweekly 2023-08

2023-07-51

E

Leonardo S.p.a.

AB139,AW139

Biweekly 2023-09

2023-06-05

Bell Textron Canada Limited

206A,206A-1 (OH-58A),206B,206B-1,206L,206L-1,206L-3,206L-4
PC-12/47E

2023-07-08

Pilatus Aircraft Ltd.

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023-06-05 Bell Textron Canada Limited: Amendment 39-22391; Docket No. FAA-2022-1488; Project Identifier MCAI-2022-00788-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 19, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 206A, 206A-1 (OH-58A), 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4 helicopters, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6510, Tail Rotor Drive Shaft.

(e) Unsafe Condition

This AD was prompted by a loss of tail rotor (TR) drive due to a failure of an adhesively bonded joint between an adapter and a tube on one of the segmented TR drive shaft (TRDS) assemblies. The FAA is issuing this AD to detect degradation of the adhesive bond of the TRDS assembly. The unsafe condition, if not addressed, could result in loss of TR drive and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF-2022-33, dated June 15, 2022 (Transport Canada AD CF-2022-33).

(h) Exceptions To Transport Canada AD CF-2022-33

(1) Where Transport Canada AD CF–2022–33 requires compliance in terms of air time, this AD requires using hours time-in-service (TIS).

(2) Where Transport Canada AD CF–2022–33 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where Transport Canada AD CF–2022–33 defines “Affected TRDS,” for this AD replace each instance of the text “affected TRDS,” with “a TRDS with a part number (P/N) that is not one of the riveted TRDS P/Ns listed in the accomplishment instructions of Bell Alert Service Bulletin (ASB) 206–20–139, Revision A, dated August 21, 2020 (ASB 206–20–139 Rev A) or Bell ASB 206L–20–184, Revision C, dated January 14, 2021 (ASB 206L–20–184 Rev C) as applicable to your model helicopter.”

(4) Where Transport Canada AD CF–2022–33 defines “Serviceable part,” for this AD replace each instance of the text “serviceable part,” with “a riveted TRDS with a P/N that is listed in the accomplishment instructions of ASB 206–20–139 Rev A or ASB 206L–20–184 Rev C as applicable to your model helicopter; or an affected TRDS that has been inspected and proof load tested in accordance with the requirements of this AD within the past 300 hours TIS or within the last 12 months, whichever occurs first.”

(5) Where the service information referenced in Transport Canada AD CF–2022–33 specifies scrapping or discarding a part, this AD requires removing that part from service.

(6) Where the service information referenced in Transport Canada AD CF–2022–33 specifies in the event of a bond line failure, recording the torque value at which it failed, the affected shaft position, part number, serial number, and which end failed, and notifying Bell Product Support Engineering of the findings, this AD does not require recording any discrepancies or reporting any information to Bell Product Support Engineering.

(i) No Reporting Requirement

Although the service information referenced in Transport Canada AD CF–2022–33 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in . In accordance with , send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: .

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email .

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under and .

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF-2022-33, dated June 15, 2022.

(ii) [Reserved]

(3) For Transport Canada service information identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, CANADA; telephone 888-663-3639; email ; internet *tc.canada.ca/en/aviation*.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email , or go to: .

Issued on March 16, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-07779 Filed 4-13-23; 8:45 am]

BILLING CODE 4910-13-P

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023-07-08 Pilatus Aircraft Ltd.: Amendment 39-22410; Docket No. FAA-2022-1404; Project Identifier MCAI-2022-01044-A.

(a) Effective Date

This airworthiness directive (AD) is effective May 19, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC-12/47E airplanes, serial number (S/N) 1300 and S/Ns 1451 and higher, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3211, Main Landing Gear Attach Section; and JASC Code 3221, Nose/Tail Landing Gear Attach Section.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as corrosion leading to cracks on the actuator attachment lug areas underneath the anti-rotation pads of the main landing gear (MLG) and nose landing gear (NLG). The FAA is issuing this AD to address this condition. The unsafe condition, if not addressed, could result in loss of functionality of the MLG and NLG, which could result in damage to the airplane and injury to the occupants.

(f) Definitions

For the purposes of this AD, the following definitions apply:

(1) Affected parts are defined as MLG electro-mechanical actuators having part number (P/N) 959.56.01.823 or P/N 959.56.01.845 and NLG electro-mechanical actuators having P/N 959.56.01.824 or P/N 959.56.01.844.

(2) Serviceable parts are defined as one of the following:

(i) MLG electro-mechanical actuators having P/N 959.56.01.823 or P/N 959.56.01.845 and NLG electro-mechanical actuators having P/N 959.56.01.824 or P/N 959.56.01.844 that have been reworked (inspection and modification) in accordance with the instructions in Pilatus PC-12 Service Bulletin 32-030, Rev. 2, dated October 7, 2022; and Tamagawa Seiki Co., Ltd., Service Bulletin SB21-0001, Issue 3, dated August 25, 2022; or

(ii) MLG electro-mechanical actuators having P/N 959.56.01.853 and NLG electro-mechanical actuators having P/N 959.56.01.852.

(g) Compliance

Comply with this AD within the compliance times specified, unless already done.

(h) Required Actions

(1) Replace each affected part as defined in paragraph (f)(1) of this AD with a serviceable part as defined in either paragraph (f)(2)(i) or (ii) of this AD, as follows:

(i) For airplanes with S/Ns 1300 and 1451 through 1663 inclusive, within 3 months after the effective date of the AD.

(ii) For airplanes with S/Ns 1664 through 1719 inclusive, and S/Ns 1721 through 1942 inclusive, within 300 hours time-in-service (TIS) after the effective date of this AD or within 12 months after the effective date of this AD, whichever occurs first.

(iii) For airplanes with S/Ns 1720, 2001 through 2202 inclusive, 2204, and 2206, within 600 hours TIS after the effective date of this AD or within 12 months after the effective date of this AD, whichever occurs first.

(2) As of the effective date of this AD, do not install an affected part as defined in paragraph (f)(1) of this AD on any airplane unless it has been reworked (inspection and modification) and made a serviceable part as defined in paragraph (f)(2)(i) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (h)(1) of this AD if those actions were done before the effective date of this AD using Pilatus PC-12 Service Bulletin 32-030, dated June 27, 2022; and Tamagawa Seiki Co., Ltd., Service Bulletin SB21-0001, dated March 31, 2022.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in §39.19. In accordance with §39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (k)(2) of this AD or email to: . If mailing information, also submit information by email.

(k) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2022–0158, dated August 4, 2022, for related information. This EASA AD may be found in the AD docket at *regulations.gov* under Docket No. FAA–2022–1404.

(2) For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4059; email: .

(3) For Pilatus and Tamagawa Seki Co., Ltd. service information that is not incorporated by reference in this AD, contact Pilatus Aircraft Limited, Customer Support General Aviation, CH–6371 Stans, Switzerland; phone: +41 848 24 7 365; email: ; website: *pilatus-aircraft.com*. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(I) Material Incorporated by Reference

None.

Issued on April 8, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–07773 Filed 4–13–23; 8:45 am]

BILLING CODE 4910–13–P