

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRCRAFT, ROTORCRAFT, GLIDERS
BALLOONS, AIRSHIPS, AND UAS**

BIWEEKLY 2023-17

07/31/2023 - 08/13/2023



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806

Facsimile: (202) 512-2250

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

Biweekly 2023-01

2022-26-01		GE Aviation Czech s.r.o.	M601D-11,M601E-11,M601E-11A,M601E-11AS,M601E-11S,M601F,H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2022-27-03		Leonardo S.p.a.	AB139,AW139
2022-27-08		Bell Textron Canada Limited	407

Biweekly 2023-02

2022-27-09		Airbus Helicopters	EC130T2
2023-01-02		Leonardo S.p.a.	A109,A109A,A109A II,A109C,A109E,A109K2,A109S,AW109SP

Biweekly 2023-03

2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-01-11		Safran Helicopter Engines S.A.	Makila 1A,Makila 1A1
2023-01-12		Safran Helicopter Engines S.A.	Arriel 1C,Arriel 1C1,Arriel 1C2
2023-02-03	R 2022-01-09	Stemme AG	Stemme S 10-VT,Stemme S 12
2023-02-04		Mooney International Corporation	M20C,M20D,M20E,M20F,M20G

Biweekly 2023-04

2023-01-04		Airbus Helicopters	AS350B,AS350BA,AS350B1,AS350B2,AS350B3,AS350D,AS355E,AS355F,AS355F1,AS355F2,AS355N,AS355NP
2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-01-08		Continental Aerospace Technologies GmbH	TAE 125-02-99,TAE 125-02-114
2023-01-10		GE Aviation Czech s.r.o.	M601E-11,M601E-11A,M601E-11AS,M601E-11S,M601F
2023-02-12		Continental Aerospace Technologies Inc.	GTSIO-520-C,GTSIO-520-D,GTSIO-520-E,GTSIO-520-F,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,IO-470-A,IO-470-C,IO-470-D,IO-470-E,IO-470-F,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-LO,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-520-N,IO-520-NB,IO-520-P,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,IOF-550-B,IOF-550-C,IOF-550-D,IOF-550-E,IOF-550-F,IOF-550-L,IOF-550-P,IOF-550-R,LIO-470-A,LIO-520-P,LTSIO-520-AE,O-470-A,O-470-E,O-470-G,O-470-G-CI,O-470-H,O-470-J,O-470-K,O-470-K-CI,O-470-L,O-470-L-CI,O-470-M,O-470-M-CI,O-470-N,O-470-P,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-470-B,TSIO-470-C,

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects			
			TSIO-470-D,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-N,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-U,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIOF-550-D,TSIOF-550-J,TSIOF-550-K,TSIOL-550-A,TSIOL-550-C
2023-03-01		Airbus Helicopters Deutschland GmbH	BO-105A,BO-105C,BO-105S,BO-105LS A-1,BO-105LS A-3,MBB-BK 117 A-1,MBB-BK 117 A-3,MBB-BK 117 A-4,MBB-BK 117 B-1,MBB-BK 117 B-2,MBB-BK 117 C-1,MBB-BK 117 C-2,MBB-BK 117 D-2
2023-03-10		Schempp-Hirth Flugzeugbau GmbH	Duo-Discus,Duo Discus T
Biweekly 2023-05			
2023-01-07		GE Aviation Czech s.r.o.	H75-100,H75-200,H80,H80-100,H80-200,H85-100,H85-200
2023-02-17		Textron Aviation Inc.	210N,210R,P210N,P210R,T210N,T210R,177,177A,177B,177RG,F177RG
2023-03-02		Pratt & Whitney Canada Corp.	PT6E-67XP
2023-03-03		Leonardo S.p.a.	AB139,AW139
2023-03-12	R 2004-04-09	Pratt & Whitney Canada Corp.	JT15D-1,JT15D-1A,JT15D-1B
2023-03-13		Airbus Helicopters	AS355E,AS355F,AS355F1,AS355F2,AS355N
2023-04-08		Continental Aerospace Technologies, Inc. (Continental®)	GTSIO-520-C,GTSIO-520-D,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,GTSIO-520-S,IO-360-A,IO-360-AB,IO-360-AF,IO-360-C,IO-360-CB,IO-360-D,IO-360-DB,IO-360-E,IO-360-ES,IO-360-G,IO-360-GB,IO-360-H,IO-360-HB,IO-360-J,IO-360-JB,IO-360-K,IO-360-KB,IO-470-D,IO-470-E,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,LTSIO-360-E,LTSIO-360-EB,LTSIO-360-KB,LTSIO-360-RB,LTSIO-520-AE,O-470-A,O-470-B,O-470-E,O-470-G,O-470-H,O-470-J,O-470-K,O-470-L,O-470-M,O-470-N,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-360-A,TSIO-360-AB,TSIO-360-B,TSIO-360-BB,TSIO-360-C,TSIO-360-CB,TSIO-360-D,TSIO-360-DB,

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

TSIO-360-E,TSIO-360-EB,TSIO-360-G,TSIO-360-GB,TSIO-360-H,TSIO-360-HB,TSIO-360-JB,TSIO-360-KB,TSIO-360-LB,TSIO-360-MB,TSIO-360-RB,TSIO-360-SB,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIO-550-N,TSIOF-550-K,TSIOL-550-A,TSIOL-550-B,TSIOL-550-C

Biweekly 2023-06

2023-03-14		Schempp-Hirth Flugzeugbau GmbH	Duo-Discus,Duo Discus T
2023-03-22	R 2015-09-04 R1	DG Flugzeugbau GmbH,Schempp-Hirth Flugzeugbau GmbH	DG-1000T,Duo Discus T
2023-04-20		Cirrus Design Corporation	SF50

Biweekly 2023-07

2023-05-03	R 2022-14-14	Alexander Schleicher GmbH & Co. Segelflugzeugbau	ASW -15,ASW-15B
2023-05-09		Airbus Helicopters Deutschland GmbH	EC135P3,EC135T3,MBB-BK 117 D-2,MBB-BK 117 D-3
2023-05-16	R 2023-04-08	Continental Aerospace Technologies Inc.	GTSIO-520-C,GTSIO-520-D,GTSIO-520-H,GTSIO-520-K,GTSIO-520-L,GTSIO-520-M,GTSIO-520-N,GTSIO-520-S,IO-360-A,IO-360-AB,IO-360-AF,IO-360-C,IO-360-CB,IO-360-D,IO-360-DB,IO-360-E,IO-360-ES,IO-360-G,IO-360-GB,IO-360-H,IO-360-HB,IO-360-J,IO-360-JB,IO-360-K,IO-360-KB,IO-470-A,IO-470-C,IO-470-D,IO-470-E,IO-470-F,IO-470-G,IO-470-H,IO-470-J,IO-470-K,IO-470-L,IO-470-LO,IO-470-M,IO-470-N,IO-470-P,IO-470-R,IO-470-S,IO-470-T,IO-470-U,IO-470-V,IO-470-VO,IO-520-A,IO-520-B,IO-520-BA,IO-520-BB,IO-520-C,IO-520-CB,IO-520-D,IO-520-E,IO-520-F,IO-520-J,IO-520-K,IO-520-L,IO-520-M,IO-520-MB,IO-550-A,IO-550-B,IO-550-C,IO-550-D,IO-550-E,IO-550-F,IO-550-G,IO-550-L,IO-550-N,IO-550-P,IO-550-R,LTSIO-360-E,LTSIO-360-EB,LTSIO-360-KB,LTSIO-360-RB,LTSIO-520-AE,O-470-A,O-470-B,O-470-E,O-470-G,O-470-H,O-470-J,O-470-K,O-470-L,O-470-M,O-470-N,O-470-R,O-470-S,O-470-T,O-470-U,TSIO-360-A,TSIO-360-AB,TSIO-360-B,TSIO-360-BB,TSIO-360-C,TSIO-360-CB,TSIO-360-D,TSIO-360-DB,TSIO-360-E,TSIO-360-EB,TSIO-360-F,TSIO-360-FB,TSIO-360-G,TSIO-360-

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

GB,TSIO-360-H,TSIO-360-HB,TSIO-360-JB,TSIO-360-KB,TSIO-360-LB,TSIO-360-MB,TSIO-360-RB,TSIO-360-SB,TSIO-520-A,TSIO-520-AE,TSIO-520-AF,TSIO-520-B,TSIO-520-BB,TSIO-520-BE,TSIO-520-C,TSIO-520-CE,TSIO-520-D,TSIO-520-DB,TSIO-520-E,TSIO-520-EB,TSIO-520-G,TSIO-520-H,TSIO-520-J,TSIO-520-JB,TSIO-520-K,TSIO-520-KB,TSIO-520-L,TSIO-520-LB,TSIO-520-M,TSIO-520-NB,TSIO-520-P,TSIO-520-R,TSIO-520-T,TSIO-520-UB,TSIO-520-VB,TSIO-520-WB,TSIO-550-A,TSIO-550-B,TSIO-550-C,TSIO-550-E,TSIO-550-G,TSIO-550-K,TSIO-550-N,TSIOF-550-K,TSIOL-550-A,TSIOL-550-B,TSIOL-550-C

2023-06-11

Viking Air Limited

DHC-2 Mk.I

Biweekly 2023-08

2023-07-51

E

Leonardo S.p.a.

AB139,AW139

Biweekly 2023-09

2023-06-05

Bell Textron Canada Limited

206A,206A-1 (OH-58A),206B,206B-

2023-07-08

Pilatus Aircraft Ltd.

1,206L,206L-1,206L-3,206L-4
PC-12/47E

Biweekly 2023-10

2023-06-14

Pratt & Whitney Canada Corp.

PW308A,PW308C

2023-07-03

Leonardo S.p.a.

AB412,AB412 EP

Biweekly 2023-11

2023-08-06

A 2020-20-08

Airbus Helicopters

AS332C,AS332C1,AS332L,AS332L1,AS332
L2,EC225LP

2023-08-07

Allied Ag Cat Productions Inc.

G-164A,G-164B

Biweekly 2023-12

2023-09-07

R 2022-02-01

Sikorsky Aircraft Corporation

S-92A

2023-09-12

Pilatus Aircraft Ltd.

PC-12,PC-12/45,PC-12/47,PC-12/47E

2023-10-02

R 2021-23-12

The Boeing Company,Airbus SAS,Bombardier Inc.,Embraer S.A.,Gulfstream Aerospace Corporation,Gulfstream Aerospace LP,Textron Aviation Inc.,Pilatus Aircraft Limited,Fokker Services B.V.,Saab AB Support and Services,De Havilland Aircraft of Canada Limited,Airbus Canada Limited Partnership,ATR - GIE Avions de Transport Régional,MHI RJ Aviation ULC,BAE Systems (Operations) Limited,Lockheed Martin Corporation,Lockheed Martin Aeronautics Company,Viking Air Limited,Dassault Aviation

18,23,35,36,50,58,60,65,70,76,77,95,99,100,111,120,140,150,152,170,172,175,177,180,182,185,188,190,195,200,206,207,208,210,300,314,320,321,335,336,337,340,382,390,400,401,402,404,406,408,411,414,421,425,441,500,501,510,525,550,551,552,560,650,680,700,750,1900,2000,4000,1049-54,1049B-55 (Navy R7V-1),1049C-55,1049D-55,1049E-55,1049F-55 (USAF C-121C),1049H-82,1049G-82,1125 Westwind Astra,1329-23A,1329-23E,1329-25,1329-23D,150A,150B,150C,150D,150E,150F,150G,150H,150J,150K,150M,150L,

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

170A,170B,172A,172B,172C,172D,172E,172G,172F (USAF T-41A),172H (USAF T-41A),172I,172K,172L,172M,172N,172P,172Q,172R,172RG,172S,175A,175B,175C,177A,177B,180A,180B,180C,180D,180F,180E,180G,180H,180J,180K,182A,182B,182C,182D,182E,182F,182G,182H,182J,182K,182L,182M,182N,182P,182Q,182R,182S,182T,185A,185B,185C,185D,185E,188A,188B,188C,18D,18S (Army C-45C),1900C,1900C (C-12J),1900D,195B,19A,200C,200CT,200T,206H,207A,210-5 (205),210-5A (205A),210A,210B,210C,210D,210E,210F,210G,210H,210J,210K,210L,210M,210N,210R,300LW,320-1,320A,320B,320C,320D,320E,320F,337A,337B,337C,337D,337E,337F,337G,337H,340A,35-33,35-A33,35-B33,35-C33,35-C33A,35R,382B,382E,382G,382J,382F,3N,3NM,400A,400T,401A,401B,402A,402B,402C,411A,414A,421A,421B,421C,49-46,525A,525B,525C,560XL,56TC,58A,58P,58PA,58TCA,58TC,649-79,649A-79,65-80,65-88,65-90,65-A80,65-A80-8800,65-A90,65-A90-1,65-A90-2,65-A90-3,65-A90-4,65-B80,680A,707-100 Long Body,707-100B Long Body,707-200,707-300 Series,707-300C Series,707-400 Series,707-100B Short Body,707-300B Series,717-200,720 Series,727 Series,727-100C Series,727-200 Series,727-200F Series,727-100 Series,727C Series,737-100 Series,737-200 Series,737-200C Series,737-300 Series,737-400 Series,737-500 Series,737-600 Series,737-700 Series,737-700C Series,737-800 Series,737-900 Series,737-900ER Series,737-8200,737-8,737-9,747-100 Series,747-100B Series,747-100B SUD Series,747-200B Series,747-200C Series,747-200F Series,747-300 Series,747-400 Series,747-400D Series,747-400F Series,747SP Series,747SR Series,747-8 Series,747-8F Series,749-79,749A-79,75 (Army PT-13),757-200 Series,757-200CB Series,757-200PF Series,757-300 Series,767-2C Series,767-200 Series,767-300 Series,767-300F Series,767-400ER Series,777-200 Series,777-200LR Series,777-300 Series,777-300ER Series,777F Series,787-8,787-9,787-10,80-A,95-55,95-A55,95-B55,95-B55A,95-B55B,95-C55,95-C55A,99A,A100,A100-1 (U-21J),A100A,A100C,A150K,A150L,A150M,A152,A185E,A185F,A188,A188B,A188A,A18A,A18D,A200 (C-12A),A200 (C-

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

12C),A200C (UC-12B),A200CT (C-12D),A200CT (C-12F),A200CT (FWC-12D),A200CT (RC-12D),A200CT (RC-12G),A200CT (RC-12H),A200CT (RC-12K),A200CT (RC-12P),A200CT (RC-12Q),A23,A23-19,A23A,A23-24,A24,A24R,A300 B2-1A,A300 B2-1C,A300 B2-203,A300 B2K-3C,A300 B4-2C,A300 B4-103,A300 B4-203,A300 B4-601,A300 B4-603,A300 B4-605R,A300 B4-620,A300 B4-622,A300 B4-622R,A300 C4-605R Variant F,A300 F4-605R,A300 F4-622R,A310-203,A310-204,A310-221,A310-222,A310-304,A310-322,A310-324,A310-325,A-314,A318-111,A318-112,A318-121,A318-122,A319-111,A319-112,A319-113,A319-114,A319-115,A319-131,A319-132,A319-133,A319-151N,A319-153N,A319-171N,A320-211,A320-212,A320-214,A320-216,A320-231,A320-232,A320-233,A320-251N,A320-252N,A320-253N,A320-271N,A320-272N,A320-273N,A321-111,A321-112,A321-131,A321-211,A321-212,A321-213,A321-231,A321-232,A321-251N,A321-251NX,A321-252N,A321-252NX,A321-253N,A321-253NX,A321-271N,A321-271NX,A321-272N,A321-272NX,A330-201,A330-202,A330-203,A330-223,A330-223F,A330-243,A330-243F,A330-301,A330-302,A330-303,A330-321,A330-322,A330-323,A330-341,A330-342,A330-343,A330-841,A330-941,A340-211,A340-212,A340-213,A340-311,A340-312,A340-313,A340-541,A340-642,A35,A350-941,A350-1041,A36,A36TC,A380-841,A380-842,A380-861,A45 (Military T-34A; B-45),A56TC,A65,A65-8200,A75 (Army PT-13A; -13B; -13C),A75J1 (Army PT-18),A75L3,A75L300,A75N1 (Army PT-17; -17A; Navy N2S-1; -4),A99,A99A,Army AT-11,Astra SPX,AT-6 (SNJ-2),AT-6A (SNJ-3),AT-6B,AT-6C (SNJ-4),AT-6D (SNJ-5),AT-6F (SNJ-6),ATR42-200,ATR42-300,ATR42-320,ATR42-500,ATR72-101,ATR72-102,ATR72-201,ATR72-202,ATR72-211,ATR72-212,ATR72-212A,Avro 146-RJ70A,Avro 146-RJ85A,Avro 146-RJ100A,B100,B19,B200,B200C,B200C (C-12F),B200C (C-12R),B200C (UC-12F),B200C (UC-12M),B200CGT,B200CT,B200GT,B200T,B23,B24R,B300,B300C,B300C (MC-12W),B300C (UC-12W),B35,B36TC,B50,B60,B75 (Navy N2S-5),B95,B95A,B99,BAC 1-11 400 Series,BAC 1-11 200 Series,BAe 146-100A,BAe 146-200A,BAe 146-300A,BAe.125 Series 800A,BAe.125 Series 800A (C-29A),BAe.125 Series 800A

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

(U-125),BAe.125 Series 800B,BAe.125 Series 1000A,BAe.125 Series 1000B,BC-1A,BD-500-1A10,BD-500-1A11,BD-700-1A10,BD-700-1A11,BD-700-2A12,Beagle B.121 Series 1,Beagle B.121 Series 2,Beagle B.121 Series 3,BH.125 Series 400A,BH.125 Series 600A,C23,C24R,C35,C-45G,C-45H,C50,C54-DC,C54A-DC,C54B-DC,C54D-DC,C54G-DC,C54E-DC,C90,C90A,C90GT,C90GTi,C99,CL-215-1A10,CL-215-6B11 (CL-215T Variant),CL-215-6B11 (CL-415 Variant),CL-44J,CL-600-1A11 (CL-600),CL-600-2A12 (CL-601),CL-600-2B16 (CL-601-3A),CL-600-2B16 (CL-601-3R),CL-600-2B16 (CL-604),CL-600-2B19 (Regional Jet Series 100),CL-600-2B19 (Regional Jet Series 440),CL-600-2C10 (Regional Jet Series 701),CL-600-2C10 (Regional Jet Series 702),CL-600-2C11 (Regional Jet Series 550),CL-600-2D15 (Regional Jet Series 705),CL-600-2D24 (Regional Jet Series 900),CL-600-2E25 (Regional Jet Series 1000),D18C,D18S,D35,D45 (Military T-34B),D50,D50A,D50B,D50C,D50E,D50E-5990,D55,D55A,D75N1 (Army PT-27),D95A,DC-10-10,DC-10-10F,DC-10-15,DC-10-30,DC-10-30F (KC-10A KDC-10),DC-10-40F,DC-10-40,DC3A-S1C3G,DC3A-S1CG,DC3A-S4C4G,DC3A-SC3G,DC3A-SCG,DC3C-R-1830-90C,DC3C-S1C3G,DC3C-SC3G,DC3C-S4C4G,DC3D-R-1830-90C,DC3-G102,DC3-G102A,DC3-G103A,DC3-G202A,DC-4,DC-6B,DC-7B,DC-7C,DC-6,DC-6A,DC-7,DC-8-11,DC-8-12,DC-8-21,DC-8-31,DC-8-32,DC-8-33,DC-8-41,DC-8-42,DC-8-43,DC-8-51,DC-8-52,DC-8-53,DC-8-55,DC-8-61,DC-8-61F,DC-8-62,DC-8-62F,DC-8-63,DC-8-63F,DC-8-71,DC-8-71F,DC-8-72,DC-8-72F,DC-8-73,DC-8-73F,DC-8F-54,DC-8F-55,DC-9-11,DC-9-12,DC-9-13,DC-9-14,DC-9-15,DC-9-15F,DC-9-21,DC-9-31,DC-9-32,DC-9-32 (VC-9C),DC-9-32F,DC-9-32F (C-9A),DC-9-32F (C-9B),DC-9-33F,DC-9-34,DC-9-34F,DC-9-41,DC-9-51,DC-9-81 (MD-81),DC-9-82 (MD-82),DC-9-83 (MD-83),DC-9-87 (MD-87),DH.125 Series 1A,DH.125 Series 1A-522,DH.125 Series 1A/R-522,DH.125 Series 1A/S-522,DH.125 Series 3A,DH.125 Series 3A/R,DH.125 Series 3A/RA,DH.125 Series 400A,DHC-2 Mk.I,DHC-2 Mk.II,DHC-2 Mk.III,DHC-4,DHC-4A,DHC-6-1,DHC-6-100,DHC-6-200,DHC-6-300,DHC-6-400,DHC-7-1,DHC-7-100,DHC-7-101,DHC-7-102,DHC-7-103,E17B (Army

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

UC-43D),E17L,E18S,E18S-9700,E310H,E310J,E33,E33A,E33C,E35,E50,E55,E55A,E75 (Army PT-13D; Navy N2S-5; PT-13D/N2S-5),E75N1 (Army PT-13D; Navy N2S-5; PT-13D/N2S-5),E90,E95,EMB-110P1,EMB-110P2,EMB-120,EMB-120FC,EMB-120QC,EMB-120RT,EMB-120ER,EMB-135,EMB-135BJ (Legacy 600),EMB-135BJ (Legacy 650),EMB-135BJ,EMB-135ER,EMB-135KE,EMB-135KL,EMB-135LR,EMB-145EP,EMB-145ER,EMB-145LR,EMB-145MP,EMB-145MR,EMB-145XR,EMB-500,EMB-505,EMB-545,EMB-550,ERJ 170-100 LR,ERJ 170-100 SE,ERJ 170-100 STD,ERJ 170-100 SU,ERJ 170-200 LL,ERJ 170-200 LR,ERJ 170-200 STD,ERJ 170-200 SU,ERJ 190-100 ECJ,ERJ 190-100 IGW,ERJ 190-100 LR,ERJ 190-100 STD,ERJ 190-200 IGW,ERJ 190-200 LR,ERJ 190-200 STD,ERJ 190-300,ERJ 190-400,F150F,F150G,F150H,F150J,F150K,F150L,F150M,F152,F172D,F172E,F172F,F172G,F172H,F172K,F172L,F172M,F172N,F172P,F172D (UC-43C),F27 Mark 050,F27 Mark 100,F27 Mark 200,F27 Mark 300,F27 Mark 400,F27 Mark 500,F27 Mark 600,F27 Mark 700,F28 Mark 0070,F28 Mark 0100,F28 Mark 1000,F28 Mark 2000,F28 Mark 3000,F28 Mark 4000,F33,F33A,F33C,F337E,F337F,F337G,F337H,F35,F50,FA150K,FA150L,FA150M,FA152,Falcon 7X,Falcon 900EX,FALCON 2000,FALCON 2000EX,Falcon 10,Fan Jet Falcon,Fan Jet Falcon Series C,Fan Jet Falcon Series D,Fan Jet Falcon Series E,Fan Jet Falcon Series F,Fan Jet Falcon Series G,FP172D,FR172E,FR172F,FR172G,FR172H,FR172J,FR172K,FRA150L,FRA150M,FT337E,FT337F,FT337GP,FT337HP,G-1159,G-1159A,G-1159B,G18S,G33,G50,G58,G-IV,GIV-X,Gulfstream 100,Gulfstream 200,GV,GV-SP,GVI,GVII-G500,GVII-G600,H18,H35,H50,H90,Hawker 750,Hawker 800,Hawker 800 (U-125A),Hawker 800XP,Hawker 850XP,Hawker 900XP,Hawker 1000,HS 748 Series 2A,HS 748 Series 2B,HS.125 Series 1B,HS.125 Series 1B-522,HS.125 Series 1B/R-522,HS.125 Series 1B/S-522,HS.125 Series 3B,HS.125 Series 3B/R,HS.125 Series 3B/RA,HS.125 Series 3B/RB,HS.125 Series 3B/RC,HS.125 Series 400A,HS.125 Series 400B,HS.125 Series 400B/1,HS.125 Series 401B,HS.125 Series 403A(C),HS.125 Series 403B,HS.125 Series 600A,HS.125 Series 600B,HS.125 Series 600B/1,HS.125 Series

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

600B/2,HS.125 Series 600B/3,HS.125 Series
 700A,HS.125 Series 700B,HS.125 Series
 F3B,HS.125 Series F3B/RA,HS.125 Series
 F400B,HS.125 Series F403B,HS.125 Series
 F600B,IB75A,J35,JRB-6,K35,L-1011-385-
 1,L-1011-385-1-14,L-1011-385-1-15,L-1011-
 385-3,LC40-550FG,LC40-550G,LC41-
 550FG,M19A,M337B,M35,MD-10-10F,MD-
 10-30F,MD-11,MD-11F,MD-88,MD-90-
 30,MU-300-10,MU-300,Mystere-Falcon 20 -
 C5,Mystere-Falcon 20 - D5,Mystere-Falcon 20
 - E5,Mystere-Falcon 20 - F5,Mystere-Falcon
 50,Mystere-Falcon 200,Mystere-Falcon
 900,N35,Navy R6D-1,Navy R6D-
 1Z,P172D,P206,P206A,P206B,P206C,P206D,
 P206E,P210N,P210R,P337H,P35,R172E,R17
 2F,R172G,R172H,R172J,R172K,R182,R4D-
 8,R4D-8Z,RC-
 45J,S18A,S18D,S35,SA18A,SA18D,SA-
 307B,SA-307B-1,SAAB 340B,340A (SAAB
 SF340A),SAAB 2000,SC-7 Skyvan Series
 2,SC-7 Skyvan Series 3,SD17S,SD3-30,SD3-
 60,SD3-60 SHERPA,SD3-SHERPA,Super
 DC-
 3,T182,T182T,T188C,T206H,T207,T207A,T2
 10F,T210G,T210H,T210J,T210K,T210L,T210
 M,T210N,T210R,T240,T310P,T310Q,T310R,
 T337B,T337C,T337D,T337E,T337F,T337G,T
 337H,T337H-SP,T-6G,TC-45G,TC-45H,TC-
 45J,TP206A,TP206B,TP206C,TP206D,TP206
 E,TR182,TU206A,TU206B,TU206C,TU206D
 ,TU206E,TU206F,TU206G,U206,U206A,U20
 6B,U206C,U206D,U206E,U206F,U206G,UC-
 45J,USAF C-118A,V35,V35A,V35B,12-
 B,140A,149-46,1649A-
 98,177RG,18A,195A,203-B,208B,247-D
 (Army C-73),300-50A-01 (USAF C-
 141A),3TM,402-2,45 (Military YT-34),720B
 Series,80-A1,99A (FACH),A60,ATP,B18S
 (Army F-2),B75N1 (Navy N2S-3),B90,BD-
 100-1A10 (Challenger 300),C18S,CL-
 44D4,D17A (Army UC-43F),D17R (Army
 UC-43A),D17S,DHC-3,Electra 10-
 E,F177RG,F90,FR182,G-
 159,G17S,G35,G36,Galaxy,Gulfstream
 G150,Gulfstream G280,HU-16D,J50,Jetstream
 Model 4101,LC42-550FG,NA-260,Navy
 SNB-1,O-47B,PC-24,S-
 307,S550,SE17B,SF17D,SNJ-7,Super
 Universal,T303,T-34C,TR-1

2023-10-05

R 2023-07-51

Leonardo S.p.a.

AB139,AW139

2023-11-03

Honda Aircraft Company LLC

HA-420

Biweekly 2023-13

2023-09-09

Aerostar Aircraft Corporation,B-N Group
 Ltd.,Commander Aircraft

PA-60-600 (Aerostar 600),PA-60-601
 (Aerostar 601),PA-60-601P (Aerostar

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

<p>Corporation,Cirrus Design Corporation,Continental Aerospace Technologies Inc.,Costruzioni Aeronautiche Tecnam S.P.A.,Daher Aerospace,Diamond Aircraft Industries Inc.,The Enstrom Helicopter Corporation,Helio Aircraft LLC,Helio Alaska Inc.,The King's Engineering Fellowship,Lycoming Engines,Maule Aerospace Technology Inc.,Merlyn Products Inc.,Mooney International Corporation,Piper Aircraft Inc.,Revo Incorporated,Scotts-Bell 47 Inc.,Siam Hiller Holdings Inc.,SST FLUGTECHNIK GmbH,Textron Aviation Inc.,Triton Aerospace LLC,Twin Commander Aircraft LLC,Vulcanair S.p.A.</p>	<p>601P),PA-60-602P (Aerostar 602P),PA-60- 700P (Aerostar 700P),BN-2,BN-2A,BN-2A- 6,BN-2A-8,BN-2A- 9,112TC,112TCA,114TC,SR22,SR22T,LTSI O-360-E,LTSIO-360-EB,LTSIO-360- KB,LTSIO-360-RB,TSIO-360-E,TSIO-360- EB,TSIO-360-F,TSIO-360-FB,TSIO-360- KB,TSIO-360-LB,TSIO-360-MB,TSIO-360- RB,TSIO-360-SB,TSIO-520-BE,TSIO-520- L,TSIO-520-LB,TSIO-520-T,TSIO-520- WB,TSIO-550-A,TSIO-550-B,TSIO-550- C,TSIO-550-E,TSIO-550-G,TSIO-550- J,TSIO-550-K,TSIO-550-N,TSIOF-550- D,TSIOF-550-J,IO-520-B,IO-520-BA,IO-520- BB,IO-520-D,IO-550-B,IO-550-E,IO-550- N,P2012 Traveller,TB 21,DA 40,F-28C,F- 28C-2,F-28C-2R,F-28F,F-28F- R,280C,280F,280FX,500,H-295 (USAF U10D),H-395 (USAF L-28A or U-10B),4500- 300,4500-300 Series II,IO-540-AA1A5,IO- 540-AG1A5,IO-540-S1A5,TIO-540- AE2A,TIO-540-AH1A,LTIO-540-J2BD,TO- 360-C1A6D,TO-360-E1A6D,LTO-360- A1A6D,LTO-360-E1A6D,TIO-540-J2BD,M- 5-210TC,IO-540- MX1,M20J,M20K,M20M,M20TN,M20V,PA- 23,PA-23-160,PA-23-235,PA-23-250,PA-23- 250 (Navy UO-1),PA-E23-250,PA-24- 250,PA-24-260,PA-24-400,PA-28-201T,PA- 28R-201T,PA-28RT-201T,PA-30,PA-31,PA- 31-325,PA-31-350,PA-31P,PA-31P-350,PA- 32-260,PA-32R-300,PA-32RT-300T,PA-32R- 301 (SP),PA-32-301T,PA-32R-301T,PA-34- 200,PA-34-200T,PA-34-220T,PA-39,PA-44- 180T,PA-46-310P,PA-46-350P,Lake LA- 4,Lake LA-4A,Lake LA-4-200,Lake 250,47G- 3B,47G-3B-1,47G-3B-2,47G-3B-2A,UH- 12L,UH-12L4,EA 400-500,35-33,35-A33,35- B33,35-C33,35- C33A,E33,E33A,E33C,F33,F33A,F33C,H35,J 35,K35,M35,N35,P35,S35,V35,V35A,V35B,3 6,A36,A36TC,B36TC,D55,E55,56TC,A56TC, 58,G58,60,A60,B60,95,95- C55,B95,B95A,D95A,E95,185,185A,185B,18 5C,185D,185E,A185E,A185F,A188,A188A,A 188B,T182,T182T,TR182,T188C,206,P206A, P206,P206B,P206C,P206D,P206E,T206H,TP 206A,TP206B,TP206C,TP206D,TP206E,TU2 06A,TU206B,TU206C,TU206D,TU206E,TU2 06F,TU206G,U206,U206A,U206B,U206C,U2 06D,U206E,U206F,U206G,T207,T207A,210, 210A,210B,210C,210-5 (205),210-5A (205A),P210N,T210G,T210H,T210J,T210K,T 210L,T210M,T210N,T240,T303,310,310B,31 0C,310D,310E,310F,310G,310H,310I,310J,T3 10P,T310Q,T310R,320,320A,320B,320C,320 D,320E,320F,320-</p>
--	--

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

1,321,335,340,340A,LC40-550FG,LC41-550FG,LC42-550FG,FT337E,FT337F,FT337GP,FT337HP,P337H,T337B,T337C,T337D,T337E,T337F,T337G,T337H,T337H-SP,401,401A,401B,402,402A,402B,402C,404,411,411A,414,414A,421,421A,421B,421C,A500,500-A,500-B,500-S,500-U,560-A,560-E,685,P.68C-TC,P.68TC Observer,EA-400

2023-11-05 R 2021-10-28

Pilatus Aircraft Ltd.

PC-24

2023-11-12

DAHER AEROSPACE

TBM 700

Biweekly 2023-14

2023-11-07 R 2021-23-13

Airbus Helicopters,Airbus Helicopters Deutschland GmbH,Air Space Design and Manufacturing LLC,Bell Textron Canada Limited,Bell Textron Inc.,Brantly International Inc.,Centerpointe Aerospace Inc.,Columbia Helicopters Inc.,The Enstrom Helicopter Corporation,Erickson Air-Crane Incorporated DBA Erickson Air-Crane,Erickson Incorporated DBA Erickson Air-Crane,Hélicoptères Guimbal,Siam Hiller Holdings Inc.,Kaman Aerospace Corporation,Leonardo S.p.a.,MD Helicopters Inc.,PZL-Swidnik S.A.,Robinson Helicopter Company,Schweizer RSG LLC,Scotts-Bell 47 A Inc.,Sikorsky Aircraft Corporation

47,206,210,212,222,230,234,280,305,369,407,412,427,429,430,480,505,1100,107-II,204B,205A,205A-1,205B,206A,206A-1,206A-1 (OH-58A),206B,206B-1,206L,206L-1,206L-3,206L-4,222B,222U,269A,269A-1,269B,269C,269C-1,269D,280C,280F,280FX,369A,369D,369E,369F,369FF,369H,369HE,369HM,369HS,412CF,412EP,47B,47B3,47D,47D1,47E,47G,47G-2,47G-2A,47G-2A-1,47G-3,47G-3B,47G-3B-1,47G-3B-2,47G-3B-2A,47G-4,47G-4A,47G-5,47G-5A,47H-1,47J,47J-2,47J-2A,47K,480B,500N,600N,A109,A109A,A109A II,A109C,A109E,A109K2,A109S,A119,AB139,AB412,AB412 EP,AS332C,AS332C1,AS332L,AS332L1,AS332L2,AS350B,AS350B1,AS350B2,AS350B3,AS350BA,AS350C,AS350D,AS350D1,AS355E,AS355F,AS355F1,AS355F2,AS355N,AS355NP,AS-365N2,AS-365N3,AW109SP,AW119 MKII,AW139,AW169,AW189,B-2,B-2A,B-2B,BO-105A,BO-105C,BO-105LS A-1,BO-105LS A-3,BO-105S,CABRI G2,CH-47D,CH-54A,EC155B,EC120B,EC130B4,EC130T2,EC155B1,EC225LP,F-28,F-28A,F-28C,F-28C-2,F-28C-2R,F-28F,F-28F-R,FH-1100,K-190A,K-240,K-600,MBB-BK 117 A-1,MBB-BK 117 A-3,MBB-BK 117 A-4,MBB-BK 117 B-1,MBB-BK 117 B-2,MBB-BK 117 C-1,MBB-BK 117 C-2,MBB-BK 117 D-2,MBB-BK 117 D-3,MD900,OH-13E,OH-13H,PZL W-3A,R22,R22 ALPHA,R22 BETA,R22 MARINER,R44,R44 II,R66,S-51,S-52,S-55,S-55B,S-55C,S-58A,S-58B,S-58BT,S-58C,S-58D,S-58DT,S-58E,S-58ET,S-58F,S-58FT,S-58G,S-58H,S-58HT,S-58J,S-58JT,S-61A,S-61D,S-61E,S-61L,S-61N,S-61NM,S-61R,S-61V,S62A,S-64A,S-64E,S-64F,S-70,S-70A,S-70C,S-70C(M),S-70C(M1),S-70M,S-76A,S-76B,S-76C,S-76D,S-92A,SA 3180-Alouette Astazou,SA 318B-Alouette

SMALL AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E- Emergency; COR - Correction; R - Replaces, A- Affects

Astazou,SA 318C-Alouette Astazou,SA.315B Alouette III,SA.316B Alouette III,SA.316C Alouette III,SA.319B Alouette III,SA330J,SA341G,SA342J,SA-365C,SA-365C1,SA-365C2,SA-365N,SA-365N1,SA-366G1,SE 313B-Alouette II,SE 3130-Alouette II,SE.3160 Alouette III,TH-1L,TH-28,UH-12,UH-12A,UH-12B,UH-12C,UH-12E,UH-12E-L,UH-12L,UH-12L4,UH-1E,UH-1L,K-225

2023-13-51

E

Airbus Helicopters

SA341G,SA342J

Biweekly 2023-15

2023-12-04

Pilatus Aircraft Ltd.

PC-24

2023-12-17

R 2022-19-03

Pilatus Aircraft Ltd.

PC-12,PC-12/47,PC-12/45,PC-12/47E

2023-12-24

GE Aviation Czech s.r.o.

M601E-11AS,M601E-11S,H75-100,H80-100,H85-100

2023-12-26

R 2021-24-04

Bell Textron Canada Limited

505

2023-13-14

2023-01-12

Safran Helicopter Engines S.A.

Arriel 1C,Arriel 1C1,Arriel 1C2,Arriel 1K1

Biweekly 2023-16

2023-13-08

R 2021-05-03

Airbus Helicopters

EC225LP

2023-13-51

R 2022-19-08

Airbus Helicopters

SA341G,SA342J

Biweekly 2023-17

2023-14-06

Airbus Helicopters

EC120B,EC130B4,EC130T2

2023-14-07

Airbus Helicopters

EC155B1

2023-15-03

Safran Helicopter Engines S.A.

Arrius 2B2

2023-15-07

Air Tractor Inc.

AT-802,AT-802A

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023–14–06 Airbus Helicopters: Amendment 39–22506; Docket No. FAA–2023–0016; Project Identifier MCAI–2022–00416–R.

(a) Effective Date

This airworthiness directive (AD) is effective September 8, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model EC120B, EC130B4, and EC130T2 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 3213, Main Landing Gear Strut, Axle, Truck.

(e) Unsafe Condition

This AD was prompted by a report of corrosion detected on certain part-numbered landing gear assemblies. The FAA is issuing this AD to detect corrosion and cracks on the landing gear tubes. The unsafe condition, if not addressed, could result in the landing gear collapsing, damage to the helicopter, and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 13 months after the effective date of this AD, for Model EC120B helicopters with landing gear assembly part number (P/N) C321A2106102, P/N C321A2501101, P/N C321A2501102, P/N C321A2601051AA, P/N C321A2601051CA, or P/N C321A2601052 installed, and for Model EC130B4 and EC130T2 helicopters with landing gear assembly P/N 350A41–0077–0201, P/N 350A41–0080–1102, P/N 350A41–0080–1103, P/N 350A41–0081–0201, P/N 350A41–0082–0101, or P/N 350A41–0082–0102 installed, except those having a date of first installation on a helicopter of February 16, 2022 or later; and for

helicopters with a landing gear assembly having a P/N specified in this paragraph, with an unknown installation date, do the following:

(i) Remove the landing gear fairing from the rear crossbeam and clean the external areas of each of the landing gear tubes item a, item c, item d, and item e, including Zones B1, B2, C1, C2, D, E, F, and M as depicted in Detail A, Figure 3, and Details B and C, Figure 4 of Airbus Helicopters Alert Service Bulletin (ASB) No. EC120-32A014 (ASB EC120-32A014 Rev 1), or as depicted in Detail A, Figure 4, and Details B and C, Figure 5 of Airbus Helicopters ASB No. EC130-32A013 (ASB EC130-32A013 Rev 1), both Revision 1, and both dated October 17, 2022, as applicable to your model helicopter.

(ii) Visually inspect the external areas of each of the landing gear tubes item a, item c, item d, and item e, including Zones B1, B2, C1, C2, D, E, F, and M for corrosion (including, but not limited to leafing and exfoliant corrosion) and cracks.

(A) If any crack or leafing or exfoliant corrosion is detected, before further flight, remove the affected part from service and replace it with an airworthy part.

(B) If any corrosion is detected in Zone C1, C2, or E, other than leafing or exfoliant corrosion, before further flight, disassemble the landing gear and remove all corrosion from all zones.

(C) If any corrosion is detected in only Zone B1, B2, D, F, or M, other than leafing or exfoliant corrosion, before further flight, remove all corrosion from all zones.

(iii) Borescope inspect the internal side of each of the landing gear tubes item a, item c, item d, and item e, including Zones B1, B2, C1, C2, D, E, F, and M for corrosion (including, but not limited to leafing and exfoliant corrosion) and cracks.

(A) If any crack, leafing corrosion, or exfoliant corrosion is detected, before further flight, remove the affected part from service and replace it with an airworthy part.

(B) If any corrosion is detected in Zone C1, C2, or E, other than leafing or exfoliant corrosion, before further flight, disassemble the landing gear and remove all corrosion from all zones.

(C) If any corrosion is detected in only Zone B1, B2, D, F, or M, other than leafing or exfoliant corrosion, before further flight, remove all corrosion from all zones.

(iv) Before further flight after performing the inspections required by paragraphs (g)(1)(ii) and (iii) of this AD, if any corrosion was detected during any inspection required by paragraphs (g)(1)(ii) and (iii) of this AD other than leafing or exfoliant corrosion, using an ultrasonic thickness gauge, measure the remaining thickness of the landing gear tubes in the zones where any corrosion was removed. Interpret the results of the measurement using the criteria specified in Table 3 of ASB EC120-32A014 Rev 1 or Table 3 of ASB EC130-32A013 Rev 1, as applicable to your model helicopter. If the remaining thickness does not meet the permitted criteria as specified, before further flight, remove each affected sub-assembly from service and replace it with an airworthy part. If the remaining thickness meets the permitted criteria as specified, before further flight, accomplish the actions required by paragraph (g)(1)(v) of this AD.

(v) Apply a chemical conversion coating (Alodine 1200) or equivalent, and a double layer of chromate Primer P05 and Primer P20, or equivalent, below the collar in Zones F and M and to any reworked zone.

(2) For Model EC120B helicopters, as of the effective date of this AD, do not install landing gear assembly P/N C321A2106102, P/N C321A2501101, P/N C321A2501102, P/N C321A2601051AA, P/N C321A2601051CA, or P/N C321A2601052, previously installed with an unknown installation date or a date of first installation on a helicopter before February 16, 2022; and do not install a front crossbeam, rear

crossbeam, left-hand (LH) skid assembly, or right-hand (RH) skid assembly having a P/N identified in Table 2 of ASB EC120–32A014 Rev 1, previously installed with an unknown installation date, or a date of first installation on a helicopter before February 16, 2022, on any helicopter; unless the actions required by paragraphs (g)(1)(i) through (v) of this AD, as applicable, have been accomplished on the part.

(3) For Model EC130B4 and EC130T2 helicopters, as of the effective date of this AD, do not install landing gear assembly P/N 350A41–0077–0201, P/N 350A41–0080–1102, P/N 350A41–0080–1103, P/N 350A41–0081–0201, P/N 350A41–0082–0101, or P/N 350A41–0082–0102, previously installed with an unknown installation date or a date of first installation on a helicopter before February 16, 2022, and do not install a front crossbeam, rear crossbeam, LH skid assembly, or RH skid assembly, having a P/N identified in Table 2 of ASB EC130–32A013 Rev 1, previously installed with an unknown installation date, or a date of first installation on a helicopter before February 16, 2022, on any helicopter, unless the actions required by paragraphs (g)(1)(i) through (v) of this AD, as applicable, have been accomplished on the part.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in . In accordance with , send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may be emailed to: .

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2022–0053, dated March 23, 2022, for related information. This EASA AD may be found in the AD docket at *regulations.gov* under Docket No. FAA–2023–0016.

(2) For more information about this AD, contact Stephanie Sunderbruch, Aviation Safety Engineer, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (817) 222–4659; email: .

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under and .

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin (ASB) No. EC120–32A014, Revision 1, dated October 17, 2022.

(ii) Airbus Helicopters ASB No. EC130–32A013, Revision 1, dated October 17, 2022.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at *airbus.com/en/products-services/helicopters/hcare-services/airbusworld*.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: , or go to: .

Issued on July 12, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

Footnotes

1. This comment does not appear in the docket because it was marked “proprietary information.”

[FR Doc. 2023-16555 Filed 8-3-23; 8:45 am]

BILLING CODE 4910-13-P

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023–14–07 Airbus Helicopters: Amendment 39–22507; Docket No. FAA–2023–0937; Project Identifier MCAI–2022–00134–R.

(a) Effective Date

This airworthiness directive (AD) is effective September 7, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model EC155B1 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main rotor gearbox.

(e) Unsafe Condition

This AD was prompted by reports of failure of the main gearbox (MGB) oil cooling fan hub (fan hub). The FAA is issuing this AD to inspect for cracks on and around the fan hub. The unsafe condition, if not addressed, could result in an undetected loss of lubrication of the MGB or engine and reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0006R2, dated January 31, 2022 (EASA AD 2022–0006R2).

(h) Exceptions to EASA AD 2022–0006R2

- (1) Where EASA AD 2022–0006R2 requires compliance in terms of flight hours, this AD requires using hours time-in-service (TIS).
- (2) Where EASA AD 2022–0006R2 refers to its effective date, this AD requires using the effective date of this AD.
- (3) Where paragraph (2.2) of EASA AD 2022–0006R2 requires within 50 FH [flight hours] after crack detection around the attachment screw, replace the affected part [fan hub] with a serviceable part, for this AD, within 50 hours TIS after crack detection around the attachment screw, remove the affected fan hub from service, and replace it with a serviceable fan hub.
- (4) Where paragraph (3) of EASA AD 2022–0006R2 requires replacing an affected part with a serviceable part before next flight if any crack is detected in any area other than around the attachment screw, for this AD, if any crack is detected in any area other than around the attachment screw, before further flight, remove the affected fan hub from service, and replace it with a serviceable fan hub.
- (5) Where the service information referenced in EASA AD 2022–0006R2 specifies to “make sure that there is no crack,” this AD requires inspecting the area for a crack.
- (6) Where the service information referenced in EASA AD 2022–0006R2 specifies to discard certain parts, this AD requires removing those parts from service.
- (7) Where the service information referenced in EASA AD 2022–0006R2 specifies creating a Technical Event and sending certain information to Airbus Helicopters, this AD does not include those requirements.
- (8) Where the service information referenced in EASA AD 2022–0006R2 specifies to use tooling, this AD allows the use of equivalent tooling.
- (9) This AD does not adopt the “Remarks” section of EASA AD 2022–0006R2.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0006R2 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in . In accordance with , send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: .

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Additional Information

For more information about this AD, contact Kevin Kung, Aviation Safety Engineer, FAA, 1600 Stewart Ave, Suite 410, Westbury, NY 11590; telephone (781) 238-7244; email: .

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under and .

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022-0006R2, dated January 31, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0006R2, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ; internet *easa.europa.eu*. You may find the EASA material on the EASA website at: *ad.easa.europa.eu*.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: , or go to: .

Issued on July 27, 2023.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-16554 Filed 8-2-23; 8:45 am]

BILLING CODE 4910-13-P

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023–15–03Safran Helicopter Engines, S.A.: Amendment 39–22515; Docket No. FAA–2023–1043; Project Identifier MCAI–2022–01295–E.

(a) Effective Date

This airworthiness directive (AD) is effective September 7, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Safran Helicopter Engines, S.A. Model Arrius 2B2 engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7200, Engine (Turbine/Turboprop).

(e) Unsafe Condition

This AD was prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM), introducing new and more restrictive tasks and limitations for certain life-limited parts. The FAA is issuing this AD to prevent failure of life-limited parts. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 90 days after the effective date of this AD, revise the ALS of the existing EMM or instructions for continued airworthiness and the existing approved maintenance or inspection program, as applicable, by incorporating the actions specified in paragraph (1) of European Union Aviation Safety Agency (EASA) AD 2022–0203, dated September 30, 2022 (EASA AD 2022–0203).

(2) The action required by paragraph (g)(1) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with and . The record must be maintained as required by , , or .

(h) Provisions for Alternative Actions and Intervals

After the actions required by paragraph (g) of this AD have been done, no alternative actions and associated thresholds and intervals, including life limits, are allowed unless they are approved as specified in the provisions of the “Ref. Publication” section of EASA AD 2022–0203.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in . In accordance with , send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD and email to: .

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Kevin Clark, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238–7088; email: .

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under and .

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency AD 2022–0203, dated September 30, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0203, contact EASA, Konrad Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: . You may find this material on the EASA website at *ad.easa.europa.eu*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: , or go to: .

Issued on July 25, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-16539 Filed 8-2-23; 8:45 am]

BILLING CODE 4910-13-P

PART 39-AIRWORTHINESS DIRECTIVES

The authority citation for part 39 continues to read as follows:

[Amended]

The FAA amends §39.13 by adding the following new airworthiness directive:

2023–15–07 Air Tractor, Inc.: Amendment 39–22519; Docket No. FAA–2023–1653; Project Identifier AD–2023–00899–A.

(a) Effective Date

This airworthiness directive (AD) is effective August 9, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Air Tractor, Inc. Model AT–802 and AT–802A airplanes, all serial numbers, certificated in any category, that have Wipaire, Inc. Supplemental Type Certificate (STC) No. SA01795CH installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 5510, Horizontal Stabilizer Structure; 5511 Horizontal stabilizer, Spar/Rib; 5514, Horizontal Stabilizer Miscellaneous Structure; 5530, Vertical Stabilizer Structure.

(e) Unsafe Condition

This AD was prompted by reports of cracks found in at least one forward horizontal stabilizer spar on 24 of the affected airplanes where the vertical finlets tie to the forward horizontal stabilizer spar. The FAA is issuing this AD to prevent structural failure of the forward horizontal stabilizer spars. The unsafe condition, if not addressed, could result in structural failure of the horizontal tail with consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) At the compliance times in paragraphs (g)(1)(i) through (iii) of this AD, as applicable, and thereafter at intervals not to exceed 200 hours time-in-service (TIS), inspect the left and right forward horizontal stabilizer spars for cracks in accordance with Steps 1 through 9 of the Work Instructions of Wipaire, Inc. Service Letter 253, Revision B, dated July 27, 2023.

(i) *For STC configuration 7D1-4399-01:* Within 3 days or 24 hours TIS after the effective date of this AD or before the accumulation of 200 hours TIS since installation of STC No. SA01795CH, whichever occurs later.

(ii) *For STC configuration 7D1-4399-02:* Within 5 days or 24 hours TIS after the effective date of this AD or before the accumulation of 300 hours TIS since installation of STC No. SA01795CH, whichever occurs later.

(iii) *For STC configuration 7D1-4399-03:* Within 15 days or 24 hours TIS after the effective date of this AD or before the accumulation of 600 hours TIS since installation of STC No. SA01795CH, whichever occurs later.

(2) If any crack is found in a forward horizontal stabilizer spar during any inspection required by paragraph (g)(1) of this AD, before further flight, replace the cracked forward horizontal stabilizer spar. Replacement of the cracked forward horizontal stabilizer spar starts the initial and repetitive inspections over.

(3) Within 10 days after each inspection required by paragraph (g)(1) of this AD or within 10 days after the effective date of this AD, whichever occur later, report the following to the FAA at the address in paragraph (j)(1) of this AD. Report this information regardless of whether cracks are found.

(i) Model, engine configuration (with horsepower limits), and propeller type;

(ii) Serial number and N number;

(iii) Total hours TIS on airframe;

(iv) Total hours TIS operated with floats, if known;

(v) STC configuration and total hours with STC installed;

(vi) Crack location (right or left, upper/lower caps inboard/outboard hole);

(vii) Crack size;

(viii) Photos of cracks found, if available; and

(ix) Any additional operator/mechanic comments

(h) Credit for Previous Actions

You may take credit for the initial inspection required by paragraph (g)(1) of this AD if, before the effective date of this AD, you complied with Wipaire, Inc. Service Letter 253, Revision A, dated April 5, 2023.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Central Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in . In accordance with , send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Certification Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Tim Eichor, Aviation Safety Engineer, Central Certification Branch, FAA, 1801 S Airport Road, Wichita, KS 67209; phone: (847) 294–7141; email: .

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under and .

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Wipaire, Inc. Service Letter 253, Revision B, dated July 27, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact Wipaire, Inc., 1700 Henry Ave, Fleming Field (KSGS), South St. Paul, MN 55075; phone: (651) 451–1205; email: ; website: *wipaire.com*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: , or go to: .

Issued on July 28, 2023.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–16964 Filed 8–7–23; 11:15 am]

BILLING CODE 4910–13–P