

**CT7-2E Maintenance INCREMENTAL CHANGE  
MM 72-00-00, FAULT ISOLATION 002  
NON-FADEC FAULT ISOLATION (CT7-2E1)**

Release Notification Date: 08/08/2024

## DISCLAIMER

The Incremental Changes published by GE Aerospace are considered Instructions for Continued Airworthiness. These Incremental Changes, along with the current Manual revision and published Temporary Revisions, constitute the latest Instructions for Continued Airworthiness.

**GE Designated: -CONFIDENTIAL-**

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2024) General Electric Company, U.S.A.

## HIGHLIGHTS

### HIGHLIGHT REFERENCE

### DESCRIPTION OF CHANGE

tk72-00-00-810-810      [Technical Change: Changed the chip detector inspection criteria in Figure 116, Sheet 5.](#)

\* \* \* FOR CT7-2E1

#### TASK 72-00-00-810-810

##### 1. General Information.

###### A. Purpose.

The fault isolation procedures provided in this section are to be used as a guide for locating and correcting faults. Use of these procedures will reduce delays and maintenance downtime. It will also reduce unnecessary replacement of engine parts.

###### B. Procedures.

NOTE: Two basic things are assumed in these procedures:

\* The correct operating procedures have been followed.

\* The fault isolation is caused by a single failure or malfunction.

- (1) Get as much information as possible from the flight crew that reports the problem. In many cases, this information will describe the fault completely. If possible, the fault should be confirmed by a ground test run, if there is no danger of causing engine damage.
- (2) The fault isolation procedures are given in logic diagram format. The logic diagrams are organized by specific symptoms and ask a question which is answered by either a yes or a no. The answer will lead either to another question or to a final solution.

(a) See [DESCRIPTION AND OPERATION](#) for a schematic diagram of the engine electrical system.

- (b) See system and component checks ([TEST](#)) for electrical checks, circuit checks at S39 connector, etc. whenever such checks are called for by the logic diagrams.
  - (c) Many faults, particularly if intermittent and not corrected by paragraph C., are best isolated by swapping with known good parts from other engine with suspect parts, one at a time. When fault follows suspect part onto known good engine, isolation is assured.
- (3) Use the following procedural guidelines when doing fault isolation:
- (a) If possible, confirm the reported fault with a ground test run.
  - (b) Troubleshoot according to the symptoms.
  - (c) Complete the checks required ([TEST](#)).
  - (d) Confirm fault has been fixed with a ground test run.
- C. Any fluctuation of engine related parameters, such as Ng speed, Np speed, torque, or TGT, may be due to dirty or inadequately secured electrical connectors. Contamination, moisture or looseness is particularly suspect when fault is intermittent. Such engine and airframe electrical connectors will be disconnected, inspected ([74-00-00, INSPECTION](#)), and cleaned ([74-00-00, CLEANING](#)) prior to the next engine test and prior to any line replaceable unit (LRU) component removal.
- D. Unusual Engine Noise.
- (1) If an unusual high-pitched whining sound is heard, do the following:
- NOTE: \* Certain compressor damage can cause a high-pitched whining sound. The noise will vary with gas generator speed and should be much higher than usual engine noise level.
- \* Compressor rotors with repaired stage 1 blades produce a higher pitched noise than is present on undamaged compressor rotors. This higher pitch is not harmful to personnel or material, and should not be cause for engine removal from an aircraft.
- (a) Reduce power and stop running the engine as soon as practical to avoid damaging compressor.
  - (b) Review engine records to determine if stage 1 compressor rotor blades have been repaired.
  - (c) If stage 1 blades have not been repaired, borescope the compressor ([INSPECTION](#)).
- (2) Before break-in, a new gas generator rotor and stator could emit a rubbing sound from the outer balance piston seal, this is normal.
2. Symptom Index.
- A. See [Table 101](#) for a list of fault isolation symptoms.

TABLE 101. SYMPTOM INDEX

| Symptom                                                                                                                                                           | Figure                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| Engine Flames Out (Combustion Stops Indicated by a Drop in TGT)                                                                                                   | <a href="#">Figure 101</a> |
| Np Does Not Accelerate to Flight Idle Speed (EECU Will Not Allow the Engine to Go to 70% Ng Speed)                                                                | <a href="#">Figure 102</a> |
| Np Low at Ground Idle Speed (Idle Speed is below Limits in <a href="#">TEST</a> )                                                                                 | <a href="#">Figure 103</a> |
| Uncontrolled Deceleration (Ng) (Ng and TGT Decrease Without Switching SIF Switch or Collective Pitch)                                                             | <a href="#">Figure 104</a> |
| Stall Above Ground Idle Speed (Acceleration or Deceleration Above Ground Idle Speed)                                                                              | <a href="#">Figure 105</a> |
| Starting Stalls (Audible Popping or Whining During Ng Acceleration to Ground Idle Speed)                                                                          | <a href="#">Figure 106</a> |
| Abnormally High TGT During Start                                                                                                                                  | <a href="#">Figure 107</a> |
| Combustor Rumble During Start                                                                                                                                     | <a href="#">Figure 108</a> |
| No Start (Fuel Mist Seen Coming From Tailpipe; No Rise in TGT)                                                                                                    | <a href="#">Figure 109</a> |
| No Start (No Compressor Rotor Rotation)                                                                                                                           | <a href="#">Figure 110</a> |
| No Start (No Fuel Mist Seen Coming From Tailpipe; No Rise)                                                                                                        | <a href="#">Figure 111</a> |
| Slow or Hung Start (TGT Increases But Hangs) (On a Hung Start, Engine Lights Off But Does Not Accelerate To Idle Speed. Speed Hangs Up Between Lightoff and Idle) | <a href="#">Figure 112</a> |
| Engine Exceeds TGT Operating Limits                                                                                                                               | <a href="#">Figure 113</a> |
| Excessive Fuel Leaking from Overboard Drain While Engine is Operating at Ground Idle Speed                                                                        | <a href="#">Figure 114</a> |
| Fuel Filter Bypass Light On                                                                                                                                       | <a href="#">Figure 115</a> |
| Electrical Chip Detector Light On During Engine Operation                                                                                                         | <a href="#">Figure 116</a> |

|                                                                                                                                                                       |                            |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| Excessive Oil Leakage at Overboard Drain                                                                                                                              | <a href="#">Figure 117</a> |
| Excessive Leakage at Service Port Scupper                                                                                                                             | <a href="#">Figure 118</a> |
| High Oil Consumption                                                                                                                                                  | <a href="#">Figure 119</a> |
| High Oil Level                                                                                                                                                        | <a href="#">Figure 120</a> |
| High Oil Pressure                                                                                                                                                     | <a href="#">Figure 121</a> |
| No Oil Pressure                                                                                                                                                       | <a href="#">Figure 122</a> |
| Oil Filter Impending Bypass Light Comes On Without a Fault Code                                                                                                       | <a href="#">Figure 123</a> |
| Oil Pressure Below Limits                                                                                                                                             | <a href="#">Figure 124</a> |
| Oil Pressure Fluctuates                                                                                                                                               | <a href="#">Figure 125</a> |
| Oil Temperature Exceeds Limits (Exceeds Normal Operating Temperatures for Affected Engine)                                                                            | <a href="#">Figure 126</a> |
| Smoke in Exhaust                                                                                                                                                      | <a href="#">Figure 127</a> |
| Low Engine Performance (Indication of Low Margin by Power Assurance Check) (Torque Indicator is Low for a Given Ng and TGT, with Possible Torque Split at High Power) | <a href="#">Figure 128</a> |
| Torque Split                                                                                                                                                          | <a href="#">Figure 129</a> |
| Unstable Operation at Flight on Ground (Ng, TGT, Torque and Np Fluctuate Greater Than 5% With Engine at Flight)                                                       | <a href="#">Figure 130</a> |
| No Ng Signal from Engine to Aircraft AMMC                                                                                                                             | <a href="#">Figure 131</a> |


---

\* Refer to para 1.C. before you start troubleshooting procedures.

\* \* \* FOR CT7-2E1

**NOTE**


Flameout can be caused by a compressor stall or FOD. See if there are P3 fault codes on the cockpit display caused by P3 sensor failure, tube damage, cracks or blockage.



1367753-01

Figure 101 (Sheet 1) Engine Flames Out (Combustion Stops Indicated by a Drop in TGT)


\*\*\* FOR CT7-2E1



1367754-01

Figure 101 (Sheet 2) Engine Flames Out (Combustion Stops Indicated by a Drop in TGT)

\*\*\* FOR CT7-2E1




1367755-01

Figure 102 Np Does Not Accelerate to Flight Idle Speed (EECU Will Not Allow the Engine to Go to 70% Ng Speed)

\*\*\* FOR CT7-2E1


**NOTE**  
 If rotor break is ON, expect idle to be 65-70%.



1367756-01

Figure 103 Np Low at Ground Idle Speed (Idle Speed is below Limits in TEST)

\*\*\* FOR CT7-2E1



1367758-01


Figure 104 Uncontrolled Deceleration (Ng) (Ng and TGT Decrease Without Switching SIF Switch or Collective Pitch)

\*\*\* FOR CT7-2E1



**NOTE**


A stall is indicated by an audible rumble or bang and may not cause a rise in TGT.  
 • If an unusually high-pitched whining sound is heard, see paragraph 1.D.



1367762-01

Figure 105 (Sheet 1) Stall Above Ground Idle Speed (Acceleration or Deceleration Above Ground Idle Speed)


\*\*\* FOR CT7-2E1



1367763-01

Figure 105 (Sheet 2) Stall Above Ground Idle Speed (Acceleration or Deceleration Above Ground Idle Speed)

\*\*\* FOR CT7-2E1




1368504-00

Figure 105 (Sheet 3) Stall Above Ground Idle Speed (Acceleration or Deceleration Above Ground Idle Speed)

\* \* \* FOR CT7-2E1

**CAUTION**  
 IF TGT EXCEEDS 963°C (1765°F) BEFORE IDLE SPEED IS REACHED, RETARD SIF TO OFF. TURN IGNITION SWITCH OFF. MOTOR ENGINE UNTIL TGT DECREASES BELOW 540°C (1004°F).


**NOTE**  
 Starting system should be able to motor engine to at least 24% Ng (10,728 RPM). Starter must not cut out below 51.6% Ng (23,065 RPM). This can be checked by using cockpit instruments.



1368463-01

Figure 106 (Sheet 1) Starting Stalls (Audible Popping or Whining During Ng Acceleration to Ground Idle Speed)

\*\*\* FOR CT7-2E1



1367764-01

Figure 106 (Sheet 2) Starting Stalls (Audible Popping or Whining During Ng Acceleration to Ground Idle Speed)


\*\*\* FOR CT7-2E1

**CAUTION**

IF TGT EXCEEDS 983°C (1765°F) BEFORE IDLE SPEED IS REACHED, RETARD SIF TO OFF. TURN IGNITION SWITCH OFF. MOTOR ENGINE UNTIL TGT DECREASES BELOW 540°C (1004°F).

**NOTE**

- Starting system should be able to motor engine to at least 24% Ng (10,728 RPM). Starter must not cut out below 51.6% Ng (23,065 RPM). This can be checked by using cockpit instruments.
- Check for environmental factors and TGT less than 150°C when start was initiated.




1367765-01

Figure 107 Abnormally High TGT During Start

\*\*\* FOR CT7-2E1

**NOTE**

- Combustor rumble is a low frequency noise often described as a howl that may be heard intermittently during engine start .
- Combustor rumble may be more pronounced during cold weather and/or during engine acceleration to ground idle.



1367768-01


Figure 108 Combustor Rumble During Start

\*\*\* FOR CT7-2E1

**WARNING**

**IGNITION PLUGS**

- BEFORE ENERGIZING THE IGNITION CIRCUIT, BE CERTAIN THAT NO FUEL OR OIL IS PRESENT. HAVE FIRE EXTINGUISHING EQUIPMENT PRESENT.
- HIGH VOLTAGE IS PRESENT. BE CERTAIN THE IGNITION UNIT AND PLUGS ARE GROUNDED BEFORE ENERGIZING THE CIRCUIT.
- NEVER TOUCH OR MAKE CONTACT WITH THE ELECTRICAL OUTPUT CONNECTOR WHEN OPERATING ANY IGNITION COMPONENT.
- NEVER HOLD OR MAKE CONTACT WITH THE IGNITER PLUG WHEN ENERGIZING THE IGNITION COMPONENT.




1367769-01

Figure 109 (Sheet 1) No Start (Fuel Mist Seen Coming From Tailpipe; No Rise in TGT)

\*\*\* FOR CT7-2E1






5002674-00

Figure 109 (Sheet 2) No Start (Fuel Mist Seen Coming From Tailpipe; No Rise in TGT)

\*\*\* FOR CT7-2E1

**NOTE**


Starting system should be able to motor engine to at least 24% Ng (10,728 rpm.)  
 Starter must not cut out below 51.6% Ng (23,065 rpm).  
 This can be checked by using cockpit instruments.



1367772-01

Figure 110 (Sheet 1) No Start (No Compressor Rotor Rotation)


\*\*\* FOR CT7-2E1



1367773-01

Figure 110 (Sheet 2) No Start (No Compressor Rotor Rotation)

\*\*\* FOR CT7-2E1



1367774-01

Figure 111 No Start (No Fuel Mist Seen Coming From Tailpipe; No Rise)


\* \* \* FOR CT7-2E1

**WARNING**

- IF ANTI-ICING BLEED AND START VALVE DOES NOT OPEN, COMPRESSOR WILL PROBABLY STALL AT ABOUT 40% NG (17,880 RPM). WHEN COMPRESSOR STALLS, A RUMBLE OR BANG WILL BE HEARD, BUT TGT MAY NOT RISE.
- IF AN UNUSUALLY HIGH-PITCHED WHINING SOUND IS HEARD SEE PARAGRAPH 1.D. FOR POSSIBLE BENT BLADE.

**NOTE**


See if there are P3 fault codes on the cockpit display caused by P3 sensor failure, tube damage, cracks or blockage.



1367775-01

Figure 112 Slow or Hung Start (TGT Increases But Hangs) (On a Hung Start, Engine Lights Off But Does Not Accelerate To Idle Speed. Speed Hangs Up Between Lightoff and Idle)

\*\*\* FOR CT7-2E1




5001342-01

Figure 113 Engine Exceeds TGT Operating Limits

\*\*\* FOR CT7-2E1

**NOTE**


Make sure aircraft fuel shutoff valve is open and SIF is at idle.



1369497-01

Figure 114 (Sheet 1) Excessive Fuel Leaking from Overboard Drain While Engine is Operating at Ground Idle Speed

\*\*\* FOR CT7-2E1




1369498-01

Figure 114 (Sheet 2) Excessive Fuel Leaking from Overboard Drain While Engine is Operating at Ground Idle Speed

\* \* \* FOR CT7-2E1






1367777-00

Figure 115 Fuel Filter Bypass Light On

\*\*\* FOR CT7-2E1

**NOTE**


- If chip light comes on and if debris is allowed (see sheets 3 and 4), a series of 15 minute ground runs at flat pitch, 100% Nr should be made to clean engine oil system of debris.
- If no chip light comes on during a 15 minute run, continue to operate.
- If chip light comes on, and if debris is allowed but is not present in large quantities, continue making runs until a 15 minute run is made without light coming on.
- If chip detector light comes on for three runs, replace engine. If allowed chips continue to generate and if quantity of debris is increasing, replace engine.



1367778-01

Figure 116 (Sheet 1) Electrical Chip Detector Light On During Engine Operation

\*\*\* FOR CT7-2E1



1367779-01

Figure 116 (Sheet 2) Electrical Chip Detector Light On During Engine Operation

\*\*\* FOR CT7-2E1




Figure 116 (Sheet 3) Electrical Chip Detector Light On During Engine Operation

\*\*\* FOR CT7-2E1


**NOTE**

- All debris must be examined with a 10x magnifying glass.
- Characteristics of chips of the allowable category are as follows:
  - Machining debris. This type of material is left over from the manufacturing operations used to make the engine parts. Typical characteristics include spiral shaped curls, semi-circular curls, or section of curls. Section of curls will appear as tiny rectangular shapes. One side of the chip may be stained or blued more than the other. Usually non-magnetic, as with nickel based steels such as the INCO series, aluminum, etc. But can also be magnetic.
  - Non-magnetic metal chips. Except relatively large pieces of non-magnetic material (chunks) which appear to have fractured away from larger structure as evidenced by a machined surface on one side, irregular and jagged on the other surfaces.
  - Non-metals, such as preformed packing and carbon seal material.
  - Long, hair-like, bronze colored slivers, non-magnetic, typical of sump labyrinth seal material.
  - Long, hair-like, slivers, magnetic, typical of driveshaft bearing locknut threads.
  - Wire shaped pieces.
  - Soft, ductile, silvery colored material, typical of silver plating. Can be deformed by hand. May have copper tint on one side.
  - Fuzz-like accumulation on chip detector, particularly on a new or recently overhauled engine. Under magnification fuzz will appear as tiny slivers or a fine powder.
  - Non-metallic, black, gritty particles, carbon-like in appearance, typical of coked oil.
  - Chunks of carbon seal, or chunks of hard black plastic are allowable as long as oil consumption is within limits and oil temperatures and pressures are normal.
- Machining chips or debris are typically found during the first few hours of operation on a new engine, but experience has shown that it is possible for them to be dislodged hundreds of operating hours later. Typically this is a one time occurrence, with no subsequent reights of the chip detector after being cleaned.
- Chips less than 0.010 inch (0.25 mm) are considered too small to be interpreted by visual means; however, if the chip detector repeatedly accumulates large quantities of extremely small chips, this is to be considered an unacceptable condition.

1367792-01

Figure 116 (Sheet 4) Electrical Chip Detector Light On During Engine Operation

\*\*\* FOR CT7-2E1



**NOTE**


- All debris must be examined with a 10x magnifying glass.
- Unallowable chips are from power unit bearings, including driveshaft, power takeoff, and accessory gearbox bearings. The inner and outer races, balls, and rollers are made from M50, M50 NIL, or 52100 steel. Unallowable chips can also be from the accessory/PTO gears which are manufactured from AISI 9310. Any chip identified as unallowable debris, either visually or by laboratory analysis, is cause for immediate engine disassembly.
- The following visual characteristics can be used to distinguish these types of chips:
  - Many chips of similar size and shape.
  - Magnetic material is an indication that the chips are unallowable. (Some types of allowable chips are also magnetic).
  - Smooth and reflective (silvery) on one side, rough on the other, typical of M50 material.
  - Roughly circular or elliptical flakes, thinner around edges, typical of a spalling-type bearing distress.
  - Material that is hard and brittle, rather than soft and ductile. Chunks of metal, as small dark irregular particles, or individual larger chunks.
  - Pieces of bearing cage material, which appear as chunks of silver plated steel.
- The types of material that are considered unallowable, as determined by laboratory analysis, are as follows:
  - M50 (AMS 6491) and M50 NIL (AMS 6278) steel, the main material in all bearings.
  - SAE 52100 (AMS 6444), accessory bearing material.
  - AISI 4340 steel (AMS 6414) with silver plating (AMS 2412), bearing cage material.
  - AISI 9310 (AMS 6265), gear material.
- **NOTE:** GEK 113993 (Field Guide for Lubrication System Debris) and T700/CT7 Lube System Debris Analysis Handbook can help to identify the source of material and/or the contamination.

6051005-00

Figure 116 (Sheet 5) Electrical Chip Detector Light On During Engine Operation

\*\*\* FOR CT7-2E1


**NOTE**  
 Overboard drain collects fluids from both engine and aircraft systems.



1368432-01

Figure 117 (Sheet 1) Excessive Oil Leakage at Overboard Drain

\*\*\* FOR CT7-2E1




1368429-01

Figure 117 (Sheet 2) Excessive Oil Leakage at Overboard Drain

\*\*\* FOR CT7-2E1






1368433-01

Figure 118 (Sheet 1) Excessive Leakage at Service Port Scupper

\*\*\* FOR CT7-2E1



1368437-01

Figure 118 (Sheet 2) Excessive Leakage at Service Port Scupper

\*\*\* FOR CT7-2E1

### WARNING

THE MAXIMUM OIL CONSUMPTION, INCLUDING ALL FORMS OF OIL LOSS, SHALL NOT BE GREATER THAN 0.3 POUNDS PER HOUR (MIL-PRF-23699) OR 0.5 POUNDS PER HOUR (MIL-PRF-7808), EXCEPT FOR THE FOLLOWING CONDITIONS:

- (A) DURING CONTINUOUS WINDMILLING AT GAS GENERATOR ROTOR SPEED OF 2500 RPM AND OUTPUT SHAFT SPEED OF 4000 RPM.
- (B) DURING OPERATION AT AN ATTITUDE OF 40 DEGREES (0.7 RADIANS) ABOVE HORIZONTAL (INLET END UP).
- (C) DURING QUALIFICATION ENDURANCE TEST CYCLES WITH AUXILIARY OIL HEATING REQUIRED TO MAINTAIN MAXIMUM OIL TEMPERATURE.

THE MAXIMUM OIL CONSUMPTION FOR CONDITIONS (A), (B), AND (C) SHALL NOT BE GREATER THAN 1.0 POUNDS PER HOUR. IF THE AVERAGE OIL CONSUMPTION RATE DURING THE QUALIFICATION TESTS IS LESS THAN ONE-THIRD OF THE SPECIFIED VALUE, THE SPECIFICATION OIL CONSUMPTION RATE SHALL BE ADJUSTED TO A VALUE NO GREATER THAN THREE TIMES THE QUALIFICATION TEST AVERAGE.

ENGINE OPERATION IS NOT PERMITTED UNLESS OVER SERVICEABLE LIMIT EXTENSIONS REQUIREMENTS ARE MET, OR OIL CONSUMPTION IS REDUCED BELOW CONSUMPTION LIMITS.

ENGINES THAT ARE BEING MONITORED FOR HIGH ENGINE OIL CONSUMPTION OR FOR KNOWN OIL LEAKAGE MUST HAVE OIL LEVEL CHECKED AT LEAST DAILY UNTIL THE PROBLEM IS CORRECTED.

IF THE ENGINE REQUIRES MORE THAN 3.8 QUARTS (3.6 LITERS) OF OIL DURING ANY SINGLE OIL SERVICING EVENT, AND THE ENGINE HAS BEEN OPERATED ABOVE FLIGHT IDLE, IT MUST BE REPLACED (REFER TO APPLICABLE AIRCRAFT MAINTENANCE MANUAL) DUE TO THE POSSIBILITY OF OIL FROTHING/STARVATION RESULTING IN BEARING DISTRESS.

IF THE ENGINE REQUIRES 3.0-3.8 QUARTS (2.8-3.6 LITERS) DURING ANY SINGLE OIL SERVICING EVENT, AND THE ENGINE HAS BEEN OPERATED ABOVE FLIGHT IDLE, THEN AN "ENGINE LOW OIL LEVEL CLEARING PROCEDURE" (REFER TO [SPECIAL PROCEDURES](#)) MUST BE DONE.

### NOTE


ACCORDING TO STANDARD PROCEDURE, ADDITION OF OIL IN WHOLE QUART QUANTITIES MAY RESULT IN APPARENT HIGH OIL CONSUMPTION. IF EXCESSIVE OIL CONSUMPTION IS SUSPECTED, MAINTAIN A LOG OF QUARTS OF OIL USED AND OF ENGINE OPERATING TIME.

IF ENGINE OIL SYSTEM IS SERVICED AND ENGINE IS TIPPED DURING REMOVAL OR INSTALLATION, OIL WILL SEEP (OIL FORMING DROPS, PUDDLES OR STREAKS) FROM A-SUMP, DOWN STAGE 1 BLADES, AND INTO BOTTOM OF THE MAIN FRAME. THIS IS NO CAUSE TO REJECT THE ENGINE.

5001572-01

Figure 119 (Sheet 1) High Oil Consumption


\* \* \* FOR CT7-2E1



5001584-01

Figure 119 (Sheet 2) High Oil Consumption


\*\*\* FOR CT7-2E1



5001585-01

Figure 119 (Sheet 3) High Oil Consumption


\*\*\* FOR CT7-2E1



5001586-00

Figure 119 (Sheet 4) High Oil Consumption

\* \* \* FOR CT7-2E1




1368438-01

Figure 120 High Oil Level

\* \* \* FOR CT7-2E1

**NOTE**

- A sudden increase in oil pressure of 10 psig (69kPa) over pressure that is normal for the engine is cause for investigation. It is expected to have an oil spike during cold start. It should return to normal after 5 minutes at idle speed.
- Engine high oil pressure is displayed in the cockpit CWP with X ENG OIL P and MFD with POIL\_HIGH\_MSG when X engine oil pressure is higher 200 psid.
- The oil pressure transducer produces a voltage output proportional to the differential between engine lube pump discharge and B-ump reference pressure. The sensor is mounted on the lube pump drive pad. It is a low-level output device: (100 mV) full scale. The excitation is conditioned 10Vdc provided by the EECU. Continuous remote indications of oil pressure are provided to the aircraft on the Data bus.




1368439-01

Figure 121 (Sheet 1) High Oil Pressure

\*\*\* FOR CT7-2E1






1368440-01

Figure 121 (Sheet 2) High Oil Pressure

\*\*\* FOR CT7-2E1


**CAUTION**  
 IF ENGINE RUNS FOR MORE THAN 1 MINUTE WITH NO OIL PRESSURE  
 AND IF AIRCRAFT INDICATING SYSTEM IS OK, REPLACE ENGINE.



1369312-01

Figure 122 (Sheet 1) No Oil Pressure

\*\*\* FOR CT7-2E1




1369313-01

Figure 122 (Sheet 2) No Oil Pressure

\*\*\* FOR CT7-2E1

**NOTE**

Engine oil filter bypass is displayed in the cockpit CWP with X ENG OIL P and MFD with ENG X OIL FILTER BYPASS.



1367793-01

Figure 123 Oil Filter Impending Bypass Light Comes On Without a Fault Code

\*\*\* FOR CT7-2E1


**CAUTION**

IF ENGINE RUNS MORE THAN 1 MINUTE WITH OIL PRESSURE BELOW MINIMUM, REFER TO (TEST),  
 AND IF AIRCRAFT INDICATING SYSTEM IS OK, REPLACE ENGINE.

**NOTE**

Engine oil low pressure is displayed in the cockpit CWP with X ENG OIL P and MFD with ENGX LOW OIL PRESSURE when low oil pressure switch indicating low pressure, including engine shutdown.


The low oil pressure switch is a gearbox-mounted component that senses the differential between engine lube pump discharge and B-sump reference pressure and is activated at 21+/-1 psi d. The switch assembly incorporates an integral relief valve, which actuates under cold oil conditions to limit maximum positive oil pressure. The oil pressure transducer produces a voltage output proportional to the differential between engine lube pump discharge and B-sump reference pressure. The sensor is mounted on the lube pump drive pad. It is a low-level output device: (100 mV) full scale. The excitation is conditioned 10Vdc provided by the EECU. Continuous remote indications of oil pressure are provided to the aircraft on the Data bus. Cross checking between the oil pressure switch and the oil pressure transducer serves to distinguish transducer failure from actual low-pressure events. The oil pressure switch and transducer are wired to different EECU channels and therefore can continue to provide a low lube pressure signal after any single failure.



1368441-01

Figure 124 (Sheet 1) Oil Pressure Below Limits


\*\*\* FOR CT7-2E1



1366442-01

Figure 124 (Sheet 2) Oil Pressure Below Limits

\*\*\* FOR CT7-2E1




1368443-01

Figure 124 (Sheet 3) Oil Pressure Below Limits

\*\*\* FOR CT7-2E1

**NOTE**

A change of  $\pm 5$  psig ( $\pm 34$  kPa) is cause for investigation. Oil pressure will change during transient conditions. These changes should stop about 1 minute after to return to steady state Ng conditions.




1368444-01

Figure 125 (Sheet 1) Oil Pressure Fluctuates

\*\*\* FOR CT7-2E1






1368445-01

Figure 125 (Sheet 2) Oil Pressure Fluctuates


\*\*\* FOR CT7-2E1



1368446-00

Figure 126 (Sheet 1) Oil Temperature Exceeds Limits (Exceeds Normal Operating Temperatures for Affected Engine)


\*\*\* FOR CT7-2E1



1368447-01

Figure 126 (Sheet 2) Oil Temperature Exceeds Limits (Exceeds Normal Operating Temperatures for Affected Engine)

\*\*\* FOR CT7-2E1




1368448-01

Figure 126 (Sheet 3) Oil Temperature Exceeds Limits (Exceeds Normal Operating Temperatures for Affected Engine)

\*\*\* FOR CT7-2E1

**NOTE**


White mist coming out of tailpipe before engine light off is fuel mist.  
Smoke may be visible during the start cycle, especially at low ambient temperatures.  
During locked rotor operation, exhaust smoke may be present.



1367794-01

Figure 127 (Sheet 1) Smoke in Exhaust


\*\*\* FOR CT7-2E1



1367795-01

Figure 127 (Sheet 2) Smoke in Exhaust


\*\*\* FOR CT7-2E1



1367796-01

Figure 127 (Sheet 3) Smoke in Exhaust

\*\*\* FOR CT7-2E1




1367797-01

Figure 128 (Sheet 1) Low Engine Performance (Indication of Low Margin by Power Assurance Check) (Torque Indicator is Low for a Given Ng and TGT, with Possible Torque Split at High Power)

\*\*\* FOR CT7-2E1






1367798-01

Figure 128 (Sheet 2) Low Engine Performance (Indication of Low Margin by Power Assurance Check) (Torque Indicator is Low for a Given Ng and TGT, with Possible Torque Split at High Power)

\*\*\* FOR CT7-2E1




1367799-00

Figure 128 (Sheet 3) Low Engine Performance (Indication of Low Margin by Power Assurance Check) (Torque Indicator is Low for a Given Ng and TGT, with Possible Torque Split at High Power)

\*\*\* FOR CT7-2E1

**NOTE**

For engines that show >5% torque difference while running on torque load share.




1369314-01

Figure 129 Torque Split

\*\*\* FOR CT7-2E1


**NOTE**  
 If fuel filter impending bypass light is on, refer to figure 115. If aircraft fuel inlet pressure is low, refer to aircraft system and applicable aircraft maintenance manual.



1367804-01

Figure 130 Unstable Operation at Flight on Ground (Ng, TGT, Torque and Np Fluctuate Greater Than 5% With Engine at Flight)

\*\*\* FOR CT7-2E1



5001655-01

Figure 131 No Ng Signal from Engine to Aircraft AMMC

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media