

YTL POWER GENERATION SDN BHD

DOCUMENT TITLE:	AIRCRAFT MAINTENANCE PROGRAMME	AIRCRAFT TYPE:	LEONARDO HELICOPTER AW139				
PAGE TITLE:	CAAM AD REQUIREMENTS	REFERENCE:	YTLPG/CAMO/AMP/AW139	ISSUE:	2	REVISION:	0
CHAPTER:	18.0	PAGE:	3 of 3	DATE:	12 AUGUST 2022		

NO.	AD REFERENCE	DESCRIPTION	SB REFERENCE	TASK	RECURRING INTERVAL	REMARK
2.	EASA AD NO 2019-0235	Arc Electronics, Inc. - Ata 25- Equipment/ Furnishings- Emergency Locator Transmitter- Inspection/ Modification/ Replacement	ACR ELECTRONICS, INC. ACR SB1000 REV. A	<ul style="list-style-type: none"> i. Remove the affected part and test the longitudinal one-axis G-switch for correct activation. ii. Inspect each affected part for proper installation, operation of the control, and accomplish a check for sufficient signal radiated from its antenna. 	Every 12 Months	-
3.	EASA AD NO 2020-0271 *OR LATER APPROVED REVISION	ATA 62 – Main Rotor – Swashplate Boot - Inspection	LEONARDO HELICOPTER S.p.A. ASB NO. 139-654 NEW ISSUE (Part II) (or later approved revision)	Recurrent inspection of the boot rings for cracks and corrosion and of the adhesive for condition and restore the correct installation in case of damage (Part II)	Every 50 FH	-
4.	EASA AD NO.2021-0044	ATA 24 – Electrical Power – Overhead Panel - Inspection	LEONARDO HELICOPTER S.p.A. ASB NO. 139-661 NEW ISSUE (Part II) (or later approved revision)	Recurrent inspection inside the overhead panel in order to check the tape condition and absence of chaffing.	Every 300FH or 1 Year whichever occurs first.	-
5.	EASA AD NO. 2022-0152-E	ATA 64 – Tail Rotor – Duplex Bearing – Inspection / Replacement	LEONARDO HELICOPTER S.p.A. ASB NO. 139-725 NEW ISSUE (Part I & II) (or later approved revision)	<ul style="list-style-type: none"> I. Repetitive inspection of the tail rotor duplex bearing for absence of rotation of the parts. II. Repetitive inspection of the tail rotor duplex bearing for condition, absence of particles within bearing grease and to perform roughness check. 	<ul style="list-style-type: none"> I. Every 10FH until bearing is replaced. II. Every 50FH until bearing is replaced. 	-