

Leonardo S.p.A. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) Italy Tel.: +39 0331 229111 - Fax: +39 0331 229605/222595

AgustaWestland Products

**SERVICE BULLETIN** 

**OPTIONAL** 

<sub>N°</sub> 139-683

DATE: February 22, 2023

**REV.:** A July 18, 2024

# TITLE

### ATA 52 - COCKPIT DOOR POCKET LH INSTALLATION

# **REVISION LOG**

Revision A is issued in order to introduce the following changes:

- Update lateral balance values in the weight and balance table.
- Introduce a note in part list.

Revision bars identify changes.



# 1. PLANNING INFORMATION

# A. EFFECTIVITY

All AW139 helicopters equipped with high visibility doors and NOT equipped with HEELS.

#### **B. COMPLIANCE**

At Customer's option.

# C. CONCURRENT REQUIREMENTS

N.A.

### D. REASON

This Service Bulletin provides the necessary instruction to install the Cockpit Door Pocket LH Installation Kit P/N 4G2580F00511.

LH issued this SB for the following reason:

Helicopter Reliability/Maintainability	
Product Improvement	
Obsolescence	
Customization	<b>✓</b>
Product/Capability Enhancement	

## E. DESCRIPTION

The Cockpit Door Pocket LH Kit introduces a pocket on the copilot door (LH side) that provides additional storage space in the cockpit area. The kit is compatible with high visibility doors NOT equipped with HEELS.

### F. APPROVAL

The technical content of this Service Bulletin is approved under the authority of DOA nr. EASA.21.J.005. For helicopters registered under other Aviation Authorities, before applying the Service Bulletin, applicable Aviation Authority approval must be checked within Leonardo Helicopters customer portal.

EASA states mandatory compliance with inspections, modifications or technical directives and related time of compliance by means of relevant Airworthiness Directives.



If an aircraft listed in the effectivity embodies a modification or repair not LHD certified and affecting the content of this Service Bulletin, it is responsibility of the Owner/Operator to obtain a formal approval by Aviation Authority having jurisdiction on the aircraft, for any adaptation necessary before incorporation of the present Service Bulletin.

## G. MANPOWER

To comply with this Service Bulletin, approximately 8 (eight) MMH are deemed necessary.

MMH are based on hands-on time and can change with helicopter configuration, personnel and facilities available. MMH are not comprehensive of the overall hours necessary to get access to work areas and to remove all the equipment that interferes with the application of the prescribed instructions.

### H. WEIGHT AND BALANCE

WEIGHT (Kg)		1.43
	ARM (mm)	MOMENT (kg·mm)
LONGITUDINAL BALANCE	2642	3778.06
LATERAL BALANCE	-1058	-1512.94

### I. REFERENCES

## I.1 PUBLICATIONS

Following Data Modules refer to AMP:

DATA MODULE		<u>DESCRIPTION</u>	<u>PART</u>		
DM01	39-A-00-20-00-00A-120A-A	Helicopter on ground for a safe maintenance.	-		

#### I.2 ACRONYMS & ABBREVIATIONS

AMDI	Aircraft Material Data Information
AMP	Aircraft Maintenance Publication
AR	As Required
DM	Data Module
DOA	Design Organization Approval
EASA	European Aviation Safety Agency
FWD	Forward
IPD	Illustrated Parts Data
ITEP	Illustrated Tools and Equipment Publication
LH	Leonardo Helicopters
MMH	Maintenance Man Hours



N.A. Not Applicable

P/N Part Number

SB Service Bulletin

S/N Serial Number

# I.3 ANNEX

N.A.

# J. PUBLICATIONS AFFECTED

AW139 AMP

AW139 IPD

# K. SOFTWARE ACCOMPLISHMENT SUMMARY

N.A.



# 2. MATERIAL INFORMATION

## A. REQUIRED MATERIALS

#### A.1 PARTS

#	P/N	ALTERNATIVE P/N	DESCRIPTION	Q.TY	LVL	NOTE	LOG P/N
1	4G2580F00511		COCKPIT DOOR POCKET LH INSTALLATION KIT	REF			-
2	3G2580A87131		Fabric cover assy LH FWD	1		(1)	139-683L1
3	3G2580A87231		Fabric cover assy LH rear	1		(1)	139-683L1
4	3G2580A87331		Cockpit door pocket assy LH	1		(1)	139-683L1
5	A428A3C07		Screw	10		(1)	139-683L1

Refer also to IPD for the spares materials required to comply with the AMP DMs referenced in the accomplishment instructions.

#### **A.2 CONSUMABLES**

The following consumable materials, or equivalent, are necessary to accomplish this Service Bulletin:

#	# SPEC./LHD CODE NUMBER DESCRIPTION		Q.TY	NOTE	PART
6	Commercial	Adhesive tape 3M 8561 (C048)	AR	(2)	-

Refer also to AMDI for the consumable materials required to comply with the AMP DMs referenced in the accomplishment instructions.

#### **A.3 LOGISTIC MATRIX**

In order to apply this Service Bulletin, the following Logistic P/N can be ordered in accordance with the applicable notes:

LOGISTIC P/N	Q.TY (PER HELO)	NOTE	PART
139-683L1	1	-	-

# **NOTES**

- (1) This item can be provided as part of P/N 4G2580F00511A1.
- (2) Item to be procured as local supply.

#### **B. SPECIAL TOOLS**

Refer also to ITEP for the special tools required to comply with the AMP DMs referenced in the accomplishment instructions.

### C. INDUSTRY SUPPORT INFORMATION

Customization.



# 3. ACCOMPLISHMENT INSTRUCTIONS

#### **GENERAL NOTES**

- a) Place an identification tag on all components that are re-usable, including the attaching hardware that has been removed to gain access to the modification area and adequately protect them until their later reuse.
- b) Exposed thread surface and nut must be protected using a layer of tectyl according to MIL-C-16173 grade I.
- c) All lengths are in mm.
- 1. In accordance with DM 39-A-00-20-00-00A-120A-A, prepare the helicopter on ground for a safe maintenance. Disconnect the battery, all electrical power sources and/or the external power supply.
- 2. With reference to Figure 1 View A, remove n°10 screws P/N A428A3C05.
- 3. With reference to Figure 2 Detail B, install the adhesive tape 3M 8561 (C048) as shown in the figure on the window glass LH.
- 4. With reference to Figure 1 View A, install the cockpit door pocket assy LH P/N 3G2580A87331 by means of n°10 screws P/N A428A3C07.
- 5. With reference to Figure 1 View A and Figure 2 Section C-C, install the fabric cover assy LH rear P/N 3G2580A87231.
- 6. With reference to Figure 1 View A and Figure 2 Section D-D, install the fabric cover assy LH FWD P/N 3G2580A87131.
- 7. Return the helicopter to flight configuration and record for compliance with this Service Bulletin on the helicopter logbook.
- 8. Gain access to My Communications section on Leonardo WebPortal and compile the "Service Bulletin Application Communication".


As an alternative, send the attached compliance form to the following mail box:

engineering.support.lhd@leonardo.com

and (for North, Central and South America) also to:

AWPC.Engineering.Support@leonardocompany.us









Figure 1








Figure 2



Please send to the following address:		SERVICE BULLETIN COMPLIANCE FORM		Date:		
LEONARDO S.p.A.						
CUSTOMER SUPPORT & SE		Number:				
PRODUCT SUPPORT ENGINEE	RING & LICENSES DEPT.					
Via Giovanni Agusta, 520 21017 Cascina Costa di Samara	ate (VA) - ITALY	Revision:				
Tel.: +39 0331 225036 Fax: +39	0331 225988					
Customer Name and Addre	ess:			Telephone:		
				Fax:		
				B.T. Compli	iance Date:	
Helicopter Model	S/N		Total N	umber	Total Hours	T.S.O.
Remarks:						
Information:						
We request your cooperation in its parts and sent to the above	n filling this form, in order to address or you can commu	keep out sta	atistical data rel oplication also v	evant to aircrai ia Technical Bi	ft configuration up-to-date. Thulletin Application Communic	ne form should be filled in all ation Section placed in

Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.