

**Summary of Pratt & Whitney Canada Maintenance Manual Model(s): PT6C-67C/-67C1 MANUAL PART NO.:3045332**

No.	Description	Task No. ASK No. / Spares Catalog Item	Applicability (YES /N/A)						Remarks
			ENGINE M72-01		ENGINE M70-02		ENGINE M70-03		
			SN PCE-KB0742	PCE-KB0739	SN PCE-KB0740	SN PCE-KB0732	SN PCE-	SN 24125	
1	Service Bulletin list has been updated to add SB41106R1.	SERVICE BULLETIN LIST	N/A						Not applicable due to aircraft crashed
				N/A					Not applicable due to aircraft crashed
					N/A				Not applicable due to aircraft fitted with engine SN PCE-KB0740 and T1 sensor harness P/N 3049261-04 S/N EM149265
						N/A			Not applicable due to aircraft fitted with engine SN PCE-KB0732 and T1 sensor harness P/N 3049261-04 S/N EM148671.
							N/A		Not applicable due to aircraft fitted with engine SN PCE-KB0715 and T1 sensor harness P/N 3049261-04 S/N EM147441.
								N/A	Not applicable due to aircraft fitted with engine SN PCE-KB0707 A and T1 sensor harness P/N 3049261-04 S/N EM147440.
2	The table for scheduled maintenance checks is revised to update action and to add notes for fuel nozzles, and editorial correction done.	05.20.00	YES	YES	YES	YES	YES	YES	Applicable. Technical Services to amend AMP and include notes in AMP under 600FH inspection task 17. CAMO Planner to amend worksheet to include note 5.
3	The procedure for oil level check has been revised to add a note for engine oil level check.	72-00-00	YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to follow the latest procedure for engine oil level check
4	Special tools list is updated to add the clamp (PWC50735).		YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to include clamp for engine removal/installation
5	The procedure and graphic for removal/installation of power section/module (PS/PSM) is revised to add clamp (PWC50735) and give callouts to the bolt and nut.		YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to follow the latest procedure incorporating the clamp
6	The graphic for oil scavenge and pressure tubes - rotation has been revised to update BS963 (Post-SB41056) left hand configuration view.	72.00.50	N/A	N/A	N/A	N/A	N/A	N/A	Not applicable due to all engine is PRE-SB41056
7	The graphic for removal/installation of compressor wash ring has been revised to show the hexagonal bolts and nuts and the procedure of installation of the rear fireseal has been revised to update the correct callouts for fireseal section and bolts.	72.30.02	YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to refer the latest procedure of rear fireseal installation.

8	The procedure for acceptable damage limits has been revised to correct the damage limit of the leading and trailing edge of blades.	72.30.05	YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to refer the latest procedure of acceptable damage limits.
9	The procedure of fuel nozzle cleaning has been revised to update functional check with functional test.	73.10.05	YES	YES	YES	YES	YES	YES	Noted. For info only. Maintenance to follow the latest procedure of fuel nozzles cleaning
10	The procedure of functional check has been deleted.		YES	YES	YES	YES	YES	YES	Noted. For info only.
11	The procedure for installation of DCU has been revised to change the reference of the testing procedure to follow after the installation of DCU.	77.40.01	YES	YES	YES	YES	YES	YES	Noted. Maintenance to follow the latest procedure of DCU installation.