SAFRAN
Turbomeca USA

CUSTOMER NAME: TSF

WO NUMBER: MDO6600

VARIANT: ARRIEL 2C1 S/N: 24593

N° CN			AIRWORTHINESS DIRECTIVES SUPPLEMENT	*			
EASA / AD	FAA / AD	SERVICE BULLETINS	METHOD OF COMPLIANCE	N/A	V	A	R
2014-0036	2014-19-05	N/A	C/W through level 4 test.			X	
2013-0170	2014-12-05	292 73 2822 RF	C/W check of wear on HMU drive gear shaft splines per the SB.			X	
2011-0249	2012-12-20	A292 73 2845	This AD is N/A due to DECU not with engine at time of repair.	X			
2002-127(A)	2003-03-12	292 72 2054	Verified the installation of a sleeve in the bleed valve boss TU 54		X		
N/A	N/A	292 72 2815	C/W visual inspection of coupling sleeve for wear between modules 4 and 5.			X	
N/A	N/A	292 72 2829	C/W inspection of the Reduction Gearbox rear casing.			X	
N/A	N/A	292 73 2835 RA	C/W inspection of the jet bonding on LP pump ejector assembly.			X	
2007-0117	N/A	N/A	Return to service for Civil Use from an Operator Not Controlled by Civil Authority	X			

* N/A - Moteur Non Concerne / Engine not Concerned
V - Verification de l'application / Verification of the application
A - Application au cours de le reparation / Application during repair
R - Reocurring

Date: 17 JUL 2015

Stamp: TECAMTI Quality Dept. Accept 5