



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD  
39, LOYANG WAY, SINGAPORE 508735  
TEL : 65 65421121 FAX : 65 65425383  
E-MAIL : michael\_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.  
ATTN : Nor Izzati Azmi  
SUBJECT : Quotation

REF. : F24-056  
PAGES : 1/3  
DATE : 30/07/2024

Work Order No.	: MMA-24-1072		
Description	: Main Rotor Blade	Serial No.	: 8058
Part No.	: 365A11-0050-08	Job No.	: 16553
<b>Inspection Revealed</b>			
Receiving / Inspection		US\$	658
Replace #4 L/E Strip		US\$	6,240
Repair Bonding Foil		US\$	2,738
Replace Lower Surface PU (Root PU Inclusive)		US\$	4,770
Replace All Trim Tabs		US\$	4,914
Replace Tip Cap Support		US\$	3,668
Repair, Repaint and balance Tip Cap		US\$	2,635
Repaint & Static Balance		US\$	6,863
		US\$	32,486
<b>Inspection Revealed</b>			
Lower Surface PU, Root PU reverted, Trim Tabs corroded Tip Cap Support corroded, Tip Cap Rib cracked Bonding Foil cracked & debonded, #4 L/E strip debonded Surface Paint on blade and tip cap eroded			
<b>Terms &amp; Condition</b>			
Incoterms	: Ex-works CTIPL		
TAT	: <u>6 weeks</u> from receipt of parts from AH. (Parts will be ordered from AH upon your approval)		
Validity	: 30th Sep 2024		
Payment terms	: <b>Full payment prior to commencement of work</b>		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$658		
CAAM release will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached			

Please advise cost approval. Thank you

Best Regards

Michael Tay  
Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
Name/Signature	Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD  
39, LOYANG WAY, SINGAPORE 508735  
TEL : 65 65421121 FAX : 65 65425383  
E-MAIL : michael\_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.  
ATTN : Nor Izzati Azmi  
SUBJECT : Quotation

REF. : F24-056  
PAGES : 2/3  
DATE : 30/07/2024

Work Order No.	: MMA-24-1072		
Description	: Main Rotor Blade	Serial No.	: 9793
Part No.	: 365A11-0050-08	Job No.	: 16554
<b>Inspection Revealed</b>			
Receiving / Inspection		US\$	658
Replace #1 L/E Erosion Strip		US\$	5,992
Replace #3 L/E Erosion Strip		US\$	6,748
Replace Lower Surface PU (Root PU Inclusive)		US\$	4,770
Replace All Trim Tabs		US\$	4,914
Replace Tip Cap		US\$	5,918
Repaint & Static Balance		US\$	6,863
		US\$	35,863
<b>Inspection Revealed</b>			
Multiple cracks on #1 and #3 L/E Strips, Lower Surface PU & Root PU reverted			
Trim Tabs corroded, Tip Cap L/E Strip debonded			
Surface Paint eroded			
Note : Scratch on Attachment Bushing (Upper L/E) - Within tolerance			
<b>Terms &amp; Condition</b>			
Incoterms	: Ex-works CTIPL		
TAT	: <u>6 weeks</u> from receipt of parts from AH. (Parts will be ordered from AH upon your approval)		
Validity	: 30th Sep 2024		
Payment terms	: <b>Full payment prior to commencement of work</b>		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$658		
CAAM release will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached			

Please advise cost approval. Thank you

Best Regards

Michael Tay  
Dy. General Manager, Operations.

Cost Accepted	<input type="text"/>
RAI (Return As Is)	<input type="text"/>
Name/Signature	Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD  
39, LOYANG WAY, SINGAPORE 508735  
TEL : 65 65421121 FAX : 65 65425383  
E-MAIL : michael\_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.  
ATTN : Nor Izzati Azmi  
SUBJECT : Quotation

REF. : F24-056  
PAGES : 3/3  
DATE : 30/07/2024

Work Order No.	: MMA-24-1072		
Description	: Main Rotor Blade	Serial No.	: 12501
Part No.	: 365A11-0050-09	Job No.	: 16555
<b>Inspection Revealed</b>			
Receiving / Inspection		US\$ 658	
Replace Lower Surface PU (Root PU Inclusive)		US\$ 4,770	
Replace All Trim Tabs		US\$ 4,914	
Replace Tip Cap Support		US\$ 3,668	
Repair, Repaint and balance Tip Cap		US\$ 2,635	
Repaint & Static Balance		US\$ 6,863	
		US\$ 23,508	
<b>Inspection Revealed</b>			
Lower Surface PU, Root PU reverted			
Trim tabs soft - replacement requested			
Tip Cap Support corroded			
Surface Paint on blade and tip cap eroded			
<b>Terms &amp; Condition</b>			
Incoterms	: Ex-works CTIPL		
TAT	: <u>6 weeks</u> from receipt of parts from AH. (Parts will be ordered from AH upon your approval)		
Validity	: 30th Sep 2024		
Payment terms	: <b>Full payment prior to commencement of work</b>		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$658		
CAAM release will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached			

Please advise cost approval. Thank you

Best Regards

Michael Tay  
Dy. General Manager, Operations.

Cost Accepted	<input type="text"/>
RAI (Return As Is)	<input type="text"/>
_____ Name/Signature	_____ Date