

COMPONENT REPAIR REPORT

1. Customer: Galaxy Aerospace	4. Cust PO#: GAM/PO/19/110	7. TSN /CSN: - / -
2. WO #: 287	5. Qty: 1	8. TSO /CSO : - / -
3. PN #: 0230390-202	6. SN: 102103	9. TSR /CSR : - / -
<u>A. Removal Reason</u>		
Unable to retract		
<u>B. Receiving Findings</u>		
<ol style="list-style-type: none"> 1. Unit receiving inspection found no external shipping damage. 2. Unit external condition dirty. 3. Unit received in extended position. 		
<u>C. Shop Findings</u>		
<ol style="list-style-type: none"> 1. Carry out trouble shooting and found extend/retract motor (PN 932-130-00) faulty. 2. Replaced extend/retract (PN 932-130-00) and the related limit switch (PN 40404000) with new. 3. Other hardware inspected and found normal. 4. Unit repaired and final test found serviceable. 5. No SB or AD required to comply in this shop visit. 		
D. This component repair report is prepared by (Name & Date): Samhari / 02 Apr 2019		

Attachment 1: Material Report

PART NUMBER	DESCRIPTION	REPAIR QTY	REPLACE QTY	REASON
932-130-00	Motor, extend / retract		1	Faulty. Replace new
40404000	Limit switch, bifucated		1	Replace new at extend/retract motor side