

## COMPONENT REPAIR REPORT

1. Customer: Galaxy Aerospace	4. Cust PO#: PO-21-2995	7. TSN /CSN: - / -
2. WO #: 585	5. Qty: 1	8. TSO /CSO : - / -
3. PN #: 930-500-25-1	6. SN: 121748	9. TSR /CSR : - / -
<b><u>A. Removal Reason</u></b>		
Repair – unable to extend		
<b><u>B. Receiving Findings</u></b>		
<ol style="list-style-type: none"> <li>1. The unit received in normal condition.</li> <li>2. External condition is dusty.</li> </ol>		
<b><u>C. Shop Findings</u></b>		
<ol style="list-style-type: none"> <li>1. Carry out trouble shooting and confirmed the removal reason “Unable to extend”. The defects were due to ext/ret motor (PN 932-130-00) defective.</li> <li>2. The extend/retract motor (PN 932-130-00) and limit switch (PN 404-040-00) are replaced new in this shop visit.</li> <li>3. Other hardware found satisfactory.</li> <li>4. The unit is repaired and final test found satisfactory.</li> <li>5. No SB or AD required to comply in this shop visit.</li> </ol>		
<b>D. This component repair report is prepared by (Name &amp; Date) : Samhari Abdul Majid / 17 Jun 2021</b>		

### Attachment 1: Material Report

PART NUMBER	DESCRIPTION	QTY	REASON
404-040-00	Limit switch	2	Replaced with motor.
932-130-00	Ext /Ret motor	1	Defective. Replaced new