

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152.x) D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

QUOTATION

To

10.		
GALAXY AEROSPACE (M) SDN BHD	From	: Kasim Hj Ismail
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,		
Ara Damansara, 47301 Petaling Jaya, Selangor	Pages	: 01
Tel: +603-7887 0426	Date	: 8-Feb-2022
Faks: +603-7887 0526	Currency	: USD
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple	AC Type/SN	: AW139
	Reference	: GALAXY039/02/2022_1

RE: SPARE QUOTATION

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	3G6210A01152 (request P/N	POCKET COVER	EA	1	522.89	522.89	30
2	3G6210A01151) 3G1010G00131	ENGINE AIR INTAKE COVER,LH	EA	3	376.26	1,128.78	90
3	(request P/N 3G1005G00232) 3G1010G00231	ENGINE AIR INTAKE COVER, RH	EA	3	368.60	1,105.80	90
	(request P/N 3G1005G00332)						
4	3G1005G04131 (request P/N 3G1005G00431)	ENGINE EXHAUST AIR DUCT COVER LH/RH	EA	3	250.04	750.12	90
5	3G1005G00431) 3G1005G00431	ENGINE EXHAUST AIR DUCT COVER LH/RH	EA	3	558.43	1,675.29	90
					Grand Total :	5,182.88	

Note:

Offer validity

2) Terms of payment

3) Cancellation

4) Delivery

5) Condition

6) Confirmation

: 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

: To be made in full before delivery.

: There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

: Subject to prior sale

: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

Warranty period shall be as follows:

1) New condition

2) Repair condition

: 12 months against manufacturer faults except for consumable items.

: 6 months or 500 hrs against manufacturer faults

