

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370 797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

No. 5607850

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: MUZDALIFAH SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE SULTAN ABDUL AZIZ SHAH AIRPORT SUBANG 47200 MALAYSIA Tel. : +60377347226

Our Ref	: SO# 5604573
Your Ref	: PO-23-7337
Terms	: PREPAID WIRE TRANSFR
Our Contact	: Ratan Pandey
eMail	: rpandey@heliparts.com : Feb-25-2024
Valid Until	: Feb-25-2024
Incoterms	: FCA - FREE CARRIER (ORIGIN)
Quote Date	: Jan-26-2024 ``

VENTILATION FAN ALT#: 70-279 Serial No(s): 121354 Schedule B: 8803.30.0030 ECCN: 9A991.d Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in fair condition Unit failed incoming tests Control PCB found corroded, requires replacement Motor bearings are worm, requires replacement Unit requires replacement of parts and standard repair Standard Repair USD 2,850.00 Corrective Action: Unit is to be Repaired per CMM and tested and recertified. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: Date:	Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
		VENTILATION FAN ALT#: 70-279 Serial No(s).: 121354 Schedule B: 8803.30.0030 ECCN: 9A991.d Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in fair condition Unit failed incoming tests Control PCB found corroded, requires replacement Motor bearings are worn. requires replacement Fuse found blown, requires replacement Unit requires replacement of parts and standard rep Standard Repair USD 2,850.00 Corrective Action: Unit is to be Repaired per CMM and tested and reconstruction NOTE- This unit is on hold pending your faxed/ema any applicable taxes, freight or customs charges. T during the course of the repairs listed above. If add	pair ertified. ailed au his esti 'l repair	thorization to proceed. T mate does not include a s are needed, we will co	his estimate do	es not include	\$ 2,850.00
						Sub Total:	\$ 2,850.00
							\$ 2.850.00
	RIDZUAN	I BIN YA'AKOB,					φ 2,030.00

ORIGINAL (COPY.)

Pg:1/1