

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSÍA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

(SST NO: B16-2207-32100006)

: Kasim Hj Ismail

QUOTATION

To

GALAXY AEROSPACE (M) SDN BHD

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426 Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

Pages : 01

From

Date : 18-Sep-2024 Currency : **USD**

AC Type/SN : AW139

Reference : GALAXY230/09/2024

RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email dated 13/09/2024

Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
3G6220A05353	DAMPER ANTI-ROTATION BLOCK	N	5	344.16	1,720.80	90
3G6220A05451	PEELING SHIM	N	1	150.39	150.39	90
	3G6220A05353	3G6220A05353 DAMPER ANTI-ROTATION BLOCK	3G6220A05353 DAMPER ANTI-ROTATION BLOCK N	3G6220A05353 DAMPER ANTI-ROTATION BLOCK N 5	3G6220A05353 DAMPER ANTI-ROTATION BLOCK N 5 344.16	3G6220A05353 DAMPER ANTI-ROTATION BLOCK N 5 344.16 1,720.80

Grand Total : ______1,871.19

Note:

1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

2) Terms of payment : To be made in full before delivery.

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the
official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

Warranty period shall be as follows:

1) New condition : 12 months against manufacturer faults except for consumable items.

2) Repair condition : 6 months or 500 hrs against manufacturer faults