



Leonardo Malaysia Sdn. Bhd.

Blade Repair Workshop Inspection Report

Customer:	Galaxy Aerospace
Part Number:	3G6410A00133
Serial Number:	V4738
TTSN:	3912.60
Date:	23 October 2023

The above blade has been inspected by LM Blade Repair Workshop with the following findings noted:

Inspection findings:

1. Wear mark found on L/S bonding strip contact area.



1.1 Rectification required:

- Reinforcement shield to be installed.
- Identification Plate P/N A016A002C1 to be installed in conjunction with reinforcement shield installation.


2. Pitch control arm found corroded.



2.1 Rectification required:

- Pitch control arm to be replaced.

3. AFT root rib found cracks.





3.1 Rectification required:

- Root rib to be repaired on crack areas.

Name: Justin Kok

Signature: