



406 Dividend Drive
 Peachtree City, Georgia 30269
 Phone (770) 632-1851
 Fax: (770) 632-1852

Repair Estimate

LOG CARD:	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
SPECIAL INSTRUCTION:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
UNIT MISUSED:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PICTURES:	<input type="checkbox"/>	<input checked="" type="checkbox"/>

DATE:	17-Jan-2022
PRIME REFERENCE:	49803
CUSTOMER REFERENCE:	PO-21-3940
PART NUMBER:	400-015525-5611
SERIAL NUMBER:	51029
DESCRIPTION:	TRANSCEIVER
WORK REQUESTED:	REPAIR

EVALUATIONS / FINDINGS:

NO HIDDEN DAMAGE. CONFIRMED CUSTOMER COMPLAINT.NO POWER SUPPLY OUTPUT.
 A1 IS DAMAGED. REQUIRES REPLACEMENT OF POWER SUPPLY AND MOTHERBOARD.
 REQUIRES HW40 SW32 UPDATE TO REPLACE OBSOLETE PARTS. FAILS NARROW BAND RX.

CORRECTIVE ACTIONS TO BE CARRIED OUT:

MINOR REPAIR PLUS MOD 40

PARTS REPLACED OR REPAIRED

EXCLUSIONS: **CONDITION AFTER COMPLETION:**

PART NUMBER	DESCRIPTION	STATUS	QUANTITY	PRICE
MOD 40	FLEXCOMM MOD 40	IMPLEMENTED	1	\$27,500.00

FLAT RATE:

TOTAL QUOTE

TOTAL QUOTE OPTION #1

TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)

COMMENTS:

Approval Signature: _____

Name: _____ Date: _____