

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

EXCHANGE QUOTE

10:56 PM



Print No. : Pg:1/1

Printed By: RIDZUAN BIN YA'AKOB

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHÀR KHAN

SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Print Date: Dec-03-2023

Tel.: +603-7455 0555

In response to your request, we are pleased to quote you the following:

No. 5607604

:Q5607604 Our Ref

Terms :PREPAID WIRE TRANSFR

Our Contact : Ratan Pandey

: rpandey@heliparts.com : Jan-02-2024 eMail Valid Until

: FCA - FREE CARRIER (ORIGIN) Incoterms

[USD]

Total:

Quote Date : Dec-03-2023

1 2-1576 BRAKE ASSEMBLY ALT#: 101-380096-1 MFG: (GOODRICHW/B3) UTC AEROSPACE SYSTEMS - TROY Note: ** Exchange Charge- Core Return Required ** ALT#: 101-380096-1 MFG: (GOODRICHW/B3) UTC AEROSPACE SYSTEMS - TROY ALT#: 101-380096-1 MFG: (GOODRICHW/B3) UTC AEROSPACE SYSTEMS - TROY Note: ** Core Charge [\$ 15,000.00]** Certification Type: FAA8130 Exchange Policy Exchange prices are based on the customer returning a repairable core of the same part number option to reject any returned unit that has been damaged from abnormal causes, such as cannibalization, unauthorized repair or excessive wear. Units found to be economically non-round of any repair above normal charges which is found, either at the time of the exchange of will be billed in addition to the exchange or later during overhaul. If an acceptable core is not	\$ 1,795.00 EA \$ 3,590.0
2 2-1576 BRAKE ASSEMBLY ALT#: 101-380096-1 MFG: (GOODRICHW/B3) UTC AEROSPACE SYSTEMS - TROY Note: ** Core Charge [\$ 15,000.00]** Certification Type: FAA8130 Exchange Policy Exchange prices are based on the customer returning a repairable core of the same part num the option to reject any returned unit that has been damaged from abnormal causes, such as cannibalization, unauthorized repair or excessive wear. Units found to be economically non-rouse of any repair above normal charges which is found, either at the time of the exchange	
Exchange Policy Exchange prices are based on the customer returning a repairable core of the same part number the option to reject any returned unit that has been damaged from abnormal causes, such as cannibalization, unauthorized repair or excessive wear. Units found to be economically non-root of any repair above normal charges which is found, either at the time of the exchange of	
Exchange prices are based on the customer returning a repairable core of the same part nun the option to reject any returned unit that has been damaged from abnormal causes, such as cannibalization, unauthorized repair or excessive wear. Units found to be economically non-record of any repair above normal charges which is found, either at the time of the exchange of	
the option to reject any returned unit that has been damaged from abnormal causes, such as cannibalization, unauthorized repair or excessive wear. Units found to be economically non-record of any repair above normal charges which is found, either at the time of the exchange of	
of date of invoice, the applicable core charge will be due.	as fire, crash, submersion, -repairable will be returned. or later during overhaul.
All units quoted are subject to prior sale	
Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the cual Any costs incurred by PAG including freight, Dangerous goods, customs clearance or deliver will be recharged to the customer.	customer. ery fees
	Sub Total: \$ 3,590.00

\$3,590.00

RIDZUAN BIN YA'AKOB.