

Your Ref:
 OurRef : TLGS/L/2022-(32)
 Date : 20 October 2022

To:
 Galaxy Aerospace (M) Sdn Bhd,
 Suite 14-11, Helicopter Center,
 Malaysia International Aerospace Centre,
 SAAS Airport, 47200 Subang, Selangor

TITLE: Sheet Metal, Composite Repair And Paint Touch Up Aircraft M72-03

We are pleased to quote you as follow;

NO	ITEM	DESCRIPTION OF TASK	MAN HOUR	UNIT PRICE (Per Hour)	TOTAL (RM)
1	Left lower panel rivet found corrosion (STA 3711.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	10.0	80.00	800.00
2	Right lower fuselage/ outboard edge found heavy surface corrosion (STA 4475.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	16.0	80.00	1280.00
3	Right lower fuselage panel found heavy surface corrosion (STA 5210.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	16.0	80.00	1280.00
4	Right lower fuselage drain hole found heavy surface corrosion (STA 5495.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	16.0	80.00	1280.00




5	Right lower panel (external side aft) rivet found corrosion (STA 5288.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	16.0	80.00	1280.00
6	Left lower panel (external side center) rivet found corrosion (STA 5288.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	16.0	80.00	1280.00
7	Right lower fuselage found heavy surface corrosion near float device edge (STA 7200.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	30.0	80.00	2400.00
8	Left lower fuselage found heavy surface corrosion near float device edge (STA 7200.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	30.0	80.00	2400.00
9	Center lower fuselage edge panel found heavy surface corrosion (STA 6701.5 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	15.0	80.00	1200.00
10	Left lower fuselage/ outboard edge found heavy surface corrosion (STA 4475.0 REF) EXTERNAL SIDE	To carry out corrosion treatment & Re paint	30.0	80.00	2400.00



11	Cabin frame rear section found multiple heavy surface corrosion (STA 5392.0 REF) INTERNAL SIDE	To carry out corrosion treatment & Re paint	20.0	80.00	1600.00
12	Left angle frame support for fuel tank area found crack at the edges (STA 5795.0, BL -550.0) FUEL TANK UPPER SUPPORT FRAME AREA	To replace new external doubler, anchor nut & primer	40.0	80.00	3200.00
13	Right angle frame support for fuel tank area found crack at the edges (STA 5795.0, BL +550.0) FUEL TANK UPPER SUPPORT FRAME AREA	To replace new external doubler, anchor nut & primer	40.0	80.00	3200.00
14	Right lower panel found delamination and corrosion on the edges (STA 2500.0, BL 100.0) EXTERNAL SIDE	Panel To be repair & re paint	20.0	80.00	1600.00
15	Left lower panel found delamination and corrosion on the edges (STA 2500.0, BL -100.0) EXTERNAL SIDE	Panel To be repair & re paint	30.0	80.00	2400.00



16	Left lower profile skin and frame found light corrosion on the curve edge (STA 3200.0, BL +950.0) EXTERNAL SIDE	Structure to be repair & re Paint	40.0	80.00	3200.00
17	Right lower profile skin and frame found light corrosion on the curve edge (STA 3200.0, BL -950.0) EXTERNAL SIDE	Structure to be repair & re Paint	40.0	80.00	3200.00
18	Right lower 2nd frame (forward side frame) found light corrosion near lightning hole (STA 4803.0, BL +700.0) EXTERNAL SIDE	Structure to be repair & re Paint	40.0	80.00	3200.00
19	Right lower 4th frame (vertical bracket, reinforced frame) found light corrosion on the main frame (STA 5700.0, BL -800.0) EXTERNAL SIDE	Structure to be repair & re Paint	30.0	80.00	2400.00
20	Right hand cabin air diffuser assembly found crumple at the edge and broken (STA 5700.0, BL +500.0) CABIN SIDE, ENVIROMENTAL DUCTING ASSY	Assembly to be fiberglass repair & re paint	30.0	80.00	2400.00



TLGS GLOBAL RESOURCES

TLGS GLOBAL RESOURCES (SA0277120-D)
 NO 39-G, JALAN ALFA B U6/B,
 PUSAT PERDAGANGAN SUBANG PERMAI
 SEKS.U6, 40150 SHAH ALAM, SELANGOR
 E mail: tlgsglobalresources@gmail.com

21	Right angle FORWARD frame support for fuel tank area found crack at the edges (STA 5795.0, WL +2470.0) FUEL TANK UPPER SUPPORT FRAME AREA	Replace new external STEEL doubler, anchor nut & primer	20.0	80.00	1600.00
22	Left angle FORWARD frame support for fuel tank area found crack at the edges (STA 5795.0, WL -2470.0) FUEL TANK UPPER SUPPORT FRAME AREA	Replace new external STEEL doubler, anchor nut & primer	30.0	80.00	2400.00
23	Installation of new Aft Cabin Floor from old floor board to new floor board (STA 5100.0, BL 000.0) CABIN FLOOR	Require transfer fastener hole from old to new board	50.0	80.00	4000.00
TOTAL					RM 50,000.00

Payment

50 Percent Payment Need To Be Made Before Start Working Date
 Can Be Made Either Cash or Cheque To

ACCOUNT : TLGS GLOBAL RESOURCES

BANK : AFFIN BANK BERHAD

ACCOUNT NO : 106810002370

Prepared by:

Amran Musa
 Manager

TLGS GLOBAL RESOURCES (SA0277120 D)

Received by:

Name :
 Company :
 Date :