




Q ANTI COLLISION



Compose

Inbox

1,812



**Ainna**

to ika, Muzdalifah, Kasim, Admin, Procurement

Dear Muz,

As per requested :

NO.	PN	DESCRIPTION	SN	AIRCRAFT	AIRCRAFT SN	DEFECT
1.	0189-2006-0220	INVERTER	50036	AW139	9M-BOC (31289)	CABIN LT NOT ILLUMINATE DUE TO UNSERVICEABLE INVERTER REPAIRABLE
2.	3G6420V00455	TAIL ROTOR DAMPER	LK10987	AW139	9M-BOC (31289)	TORN RUBBER
3.	3G3250V00132	NLG CENTRE LOCK ASSY	592	AW139	M72-02 (31315)	INOPERATIVE

We will advise the repair capability soon.

**Thank you.**

**Best regards,**

Nur Ainna Binti Samsul Anwar | [ainna@kesumatech.com.my](mailto:ainna@kesumatech.com.my)

Kesuma Technology Sdn Bhd,  
D-7-02, Capital 4 Oasis Square,  
No.2 Jalan PJU 1A/7A, Ara Damansara,

Labels