

KESUMA TECHNOLOGY SDN.BHD

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel: +603-7832 2998/7398

Fax: +603-7832 4998

To

GALAXY AEROSPACE (M) SDN BHD

Suite 11-14, Helicopter Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia

Phone +603 7734 7226 : +603 7734 7526 Fax

Attn : Ashila Naja Mohd Zulkaple

From

: Kasim Hj Ismail

Date

: 24/10/2023

Currency

USD

Reference

: GALAXY/R/0060/2023

: QUOTATION FOR REPAIR

Please find our quotation with regards to your Purchase Order No: MMA-23-796

No.	Part No	Description	Serial No	Qty	Total Cost	Delivery (Status)
1	3G6410A00133	TAIL ROTOR BLADE ASSY	V4819	1	24,280.00	30 days after your PO

<u>Breakdown</u>

- 1) Refer to the attached Blade Repair Workshop Inspection Report
- 2) Detailed Inspection:
- 2a) Reinforcement Shield installation (Fretting damage found on L/S at lightning strip contact area)
- 2b) Replace Data Tag (In conjunction with mod)
- 2c) Replace Pitch Control Arm (Found corroded)
- 2d) Complete Refinish and Static Balance
- 2e) Superficial damage repair (Crack found at T/E root rib)

Total Cost

24,280.00

Estimated / Price of New

USD 57,291.26

Note:

1) Offer Validity

30 days from the date of quotation

2) Terms of Payment

To be made in full before delivery

3) Cancellation

There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery

Subject to prior sale

5) Condition 6) Confirmation : NEW/REPAIRED/OVERHAULED with Leonardo's Certificate of Conformance / EASA certificate 3 Confirmation of availability of goods will be given within 5 working days upon receipt of the

official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2

working days for confirmation of purchase

Warranty period shall be as follows:

1) New Condition

: 12 months against manufacturer faults except for consumable items.

2) Repair Condition

: 6 Months or 500 hrs against manufacturer faults.

