



technologies

257 Helicopter Circle, Corona, California 92880-2532

*** REPAIR QUOTE ***

REPAIR QUOTATION : 315948

Fax Log #: GUT 1800705

Customer : GALAXY AEROSPACE

Attn : BOB

Tel : 603 7887 0426

Fax : 603 7887 0526

Terms : PAYMENT IN ADVANCE

drj technologies
257 Helicopter Circle
Corona, CA. 92880-2532 USA
FAA CRS# QKXR998L - EASA.145.4611
Tel: (951) 372-2870
Fax: (951) 372-2876
drj Contact:
STEVE MILLER - Customer Service

Signed :

<< THIS QUOTE IS VALID FOR 30 DAYS FROM SUBMITTAL DATE OF 18-Jan-18 >>

This quotation is submitted for your approval for work to be accomplished I.A.W.CMM-70-279 DATED 05MAY15

Customer Ref : GAM-PO-17-145

Part Number : 109-0718-46-103

Description : FAN, BRUSHLESS

Serial Number : 10132

REPAIR	\$1,805.00
Total Charges :	\$1,805.00

Reason for Removal : UNABLE TO POWER ON, FAN IMOP.

Evaluation : INSPECTION SHOWS MOTOR ASSY BEARINGS SEIZED, FUSE BLOWN. COMPONENTS REPLACED TO EFFECT REPAIR, TEST, RE-CERTIFY.

Est. completion three working days from approval

Final invoice will reflect any incoming freight charges incurred by drj.

APPROVAL

KL049 em:Y

SYAFRIUL YAMANI BIN SAFRUDDIN
Engineering Manager
Galaxy Aerospace (M) Sdn Bhd (1040262-D)

Repair Station Number FAA/QKXR998L EASA.145.4611

951-372-2870

Form drj001

www.drj.aero

FAX 951-372-2876



drj technologies

257 Helicopter Circle, Corona, California 92880-2532

*** REPAIR QUOTE ***

REPAIR QUOTATION : 315947

Fax Log #: OUT 18 00705

Customer : GALAXY AEROSPACE

Attn : BOB

Tel : 603 7887 0426

Fax : 603 7887 0526

Terms : PAYMENT IN ADVANCE

drj technologies
257 Helicopter Circle
Corona, CA. 92880-2532 USA
FAA CRS# QKXR998L - EASA.145.4611
Tel: (951) 372-2870
Fax: (951) 372-2876
drj Contact:
STEVE MILLER - Customer Service

Signed : 

<< THIS QUOTE IS VALID FOR 30 DAYS FROM SUBMITTAL DATE OF 18-Jan-18 >>

This quotation is submitted for your approval for work to be accomplished I.A.W.CWN-70-279 DATED 05MAY15

Customer Ref : GAM-PO-17-145

Part Number : 109-0718-46-103

Description : FAN, BRUSHLESS

Serial Number : 10092

REPAIR	\$1,805.00
Total Charges :	\$1,805.00

Reason for Removal : UNABLE TO POWER ON, FAN IMOP.

Evaluation : INSPECTION SHOWS MOTOR ASSY BEARINGS SEIZED, FUSE BLOWN. COMPONENTS REPLACED TO EFFECT REPAIR. TEST, RE-CERTIFY.

Est. completion three working days from approval

Final invoice will reflect any incoming freight charges incurred by drj.

APPROVAL

KL049 em:Y


SYAFRUL YAMANI BIN SAFRUDDIN
Engineering Manager
Galaxy Aerospace (M) Sdn Bhd (1040262-D)

Repair Station Number FAA/QKXR998L EASA.145.4611

951-372-2870

Form drj001

www.drj.aero

FAX 951-372-2876