

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: GAM AMO Dept, GAM CAMO Dept, GAM APMM.	FROM: Deputy CMM
CC: GAM AM, GAM QAM	DATE: 03.12.2021
REFERENCE NO.: CAMO/MEMO/2021/98	

INCORRECT ATTACHMENT OF FUEL FILLER CAP LANYARD

Dear all,

It was found that one of AW139 aircraft under GAM have a fuel filler cap lanyard that was not attached properly to the filler neck. A Safer Card was raised, and a Crisis Management meeting have been held to address this issue.

The outcome of the meeting requires inspection of the condition and correct attachment of the fuel filler cap lanyard for all AW139 fleet under GAM.

Instruction have been issued to all CAMO Planner to issue work order for the accomplishment of the inspection task at first opportunity.

Please coordinate and accomplish the task accordingly.

Your cooperation on this matter is very much appreciated.

Thank you and stay safe!



'AMIR BIN ABDULLAH
DEPUTY CMM,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.