

## CONTINUING AIRWORTHINESS MANAGEMENT ORGANIZATION MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 16.12.2021
<b>REFERENCE NO.:</b> CAMO/MEMO/2021/105	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	LEONARDO	T-AW139-21-007 NEW ISSUE	10.12.2021	AW139	MODIFICATION OF ENGINE BREATHER AIR TUBE INSTALLATION	<a href="#">1</a>
2.	AIRBUS	IN NO. 3738-I-63 REVISION 0	10.12.2021	EC155B	MAIN ROTOR DRIVE - OIL LEAK FROM THE FAN SEAL: NEW SEAL INSTALLATION	<a href="#">2</a>
3.	AIRBUS	IN NO. 2957-I-00 REVISION 1	13.12.2021	ALL AIRBUS PRODUCTS	REMINDER OF THE RULES FOR COMPLETING LOG CARDS	<a href="#">3</a>
4.	CAAM	AI 19/2021 NEW ISSUE	13.12.2021	ALL OPERATORS IN MALAYSIA	GUIDELINES TO ACCESS INTEGRATED AERONAUTICAL INFORMATION PACKAGE (IAIP) OF MALAYSIA	<a href="#">4</a>
5.	MECAER AVIATION	SUPP. NO: 6AB1RFM-1-4 REV. AG	12.11.2021	AW139 (9M-JPM, 9M-SAAS)	RFM SUPPLEMENT VIP 43 INTERIORS P/N 6AB1AD006-001	<a href="#">5</a>
6.	LEONARDO	T-109E-21-001 NEW ISSUE	14.12.2021	A109E	INSPECTION OF MAIN ROTOR SCISSOR CHAIN	<a href="#">6</a>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**NUR NABILLA MOHD HASNAN  
TECHNICAL PUBLICATION,  
CAMO DEPARTMENT,  
GALAXY AEROSPACE (M) SDN. BHD.**