

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 10.11.2023
REFERENCE NO.: CAMO/MEMO/2023/73	

Dear all,
Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	AIRBUS HELICOPTERS	DN NO: DN.105.0018.0 REV 0	23.10.2023	EC155B1	DELIVERY NOTE - TECH DATA – COMPLEMENTARY INSTRUCTION FOR CONTINUED AIRWORTHINESS	1
2	LEONARDO	TMI 139-573 NEW ISSUE	20.10.2023	AW139	TEMPORARY MAINTENANCE INSTRUCTION - ROTATING CONTROL INSTALLATION - SLIDER BUSHING - DETAILED INSPECTION	2
3	PRATT AND WHITNEY CANADA	REV. 5.9	24.10.2023	PT6C-67C	FAST MONITOR TM SOFTWARE - DOC REF.: P/N: 3076108	3
4	GENERAL ELECTRIC	SPM 70-00-07 REV. 112	18.10.2023	GENERAL	COMMERCIAL ENGINE STANDARD PRACTICES MANUAL - INCREMENTAL CHANGE - REPAIR CODES	4
5	AIRBUS	DN NO: DN.008.0023.0 REV 0	23.10.2023	EC120B	DELIVERY NOTE – TECH DATA – COMPLEMENTARY INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (ICA)	5

6	AIRBUS	SIN NO. 3890-S-00 REVISION 0	26.10.2023	GENERAL	SAFETY INFORMATION NOTICE - GENERAL - OSCILLATIONS AND/OR VIBRATIONS DURING HELICOPTER EXTERNAL SLING LOAD OPERATIONS (HESLO)	6
7	SAFRAN HELICOPTER ENGINES	GSL NO. 2316/04 ISSUE 6	24.10.2023	GENERAL	GENERAL SERVICE LETTER - RETURN TO SERVICE FOR A CIVIL OPERATION OF ENGINES FROM AN OPERATOR THAT WAS NOT UNDER A CIVIL AUTHORITY (MILITARY, PARA- MILITARY)	7
8	LEONARDO	TIL NO. T-139-23-007 NEW ISSUE	31.10.2023	AW139	TECHNICAL INFORMATION LETTER - AW139 – COMPONENT OVERHAUL REQUIREMENT CO26-01	8
9	TEXTRON	MTL-53-05 REV. 2	31.10.2023	B300	SERVICE LETTER - FUSELAGE - FILLER SHIM OR FASTENER INSTALLATION AT FUSELAGE STATION 221	9
10	SAFRAN ENGINES	DOC. REF.: No. X292N46002 UPDATE NO. 50	15.06.2023	ARRIEL 2C1	ILLUSTRATED PARTS CATALOGUE	10
11	EASA	SIB NO. 2022-02 REV. 2	7.11.2023	GENERAL	SAFETY INFORMATION BULLETIN - GLOBAL NAVIGATION SATELLITE SYSTEM OUTAGE AND ALTERATIONS LEADING TO NAVIGATION / SURVEILLANCE DEGRADATION	11
12	TEXTRON	MTL-36-01 NEW ISSUE	7.11.2023	B300	B300 SERVICE LETTER - PNEUMATIC-ENGINE FLOW PACK T-FITTING INSPECTION	12

13	LEONARDO	SIL NO. S-GEN-23-005 NEW ISSUE	7.11.2023	GENERAL	GENERAL SERVICE INFORMATION LETTER - CUSTOMER SERVICES IMPROVEMENTS	13
14	LEONARDO	TMI109-540 REV A	2.11.2023	A109E	TEMPORARY MAINTENANCE INSTRUCTIONS - MAIN ROTOR DUPLEX 109-0110- 35 INSPECTION AND INSTALLATION PROCEDURE	14
15	ROBINSON	SL-45 NEW ISSUE	9.11.2023	R66	SERVICE LETTER - SYMMETRICAL HORIZONTAL STABILIZER RETROFIT KIT	15
16	SAFRAN HELICOPTER ENGINES	DOC. REF. X 319 L6 301 2 UPDATE NO. 49	15.10.2023	ARRIUS 2F	ENGINE MAINTENANCE MANUAL	16
17	SAFRAN HELICOPTER ENGINES	DOC. REF. X 319 L6 800 2 UPDATE NO. 34	15.10.2023	ARRIUS 2F	MAINTENANCE TOOLS CATALOG	17
18	SAFRAN HELICOPTER ENGINES	DOC. REF. X 319 L6 700 2 UPDATE NO. 46	15.10.2023	ARRIUS 2F	MAINTENANCE SPARE PARTS CATALOG	18
19	SAFRAN HELICOPTER ENGINES	DOC. REF. X 319 L6 301 2 UPDATE NO. 49	15.10.2023	ARRIUS 2F	TROUBLESHOOTING	19

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



DEANNA IZZATY BINTI AHMAD SHOUFIK
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.